



**Presentation 12:  
Vegetated Earth Spillways — Inspection,  
Maintenance, and Monitoring**

# Vegetated Earth Spillways Inspection – Maintenance & Monitoring

Denver, CO  
August 26-27, 2003


**OUTLET SECTION - EXIST. AUXILIARY SPILLWAY**





















Hickory Creek Site 11 - Hay feeding on control section, cattle working pens in exit section






Vegetation –  
when was the  
last time the  
spillway was  
mowed?



 NRCS Natural Resources  
Conservation Service

High Hazard Dam





Dam overtopped about  
0.5' and the spillway had  
about a 5.2' Hp on it.





 NRCS Natural Resources  
Conservation Service

5.2' Hp on crest of this spillway  
– little or no damage



 NRCS Natural Resources  
Conservation Service







Headcut  
erosion  
from  
flow  
event.



 NRC Natural Resources  
Conservation Service

**The End**