



Picture 1: Current Conditions of Original Physical Plant Building #11 Facing South



Picture 2: Current Conditions of Original Physical Plant Building #11 Facing North



Picture 3: Current Conditions of Original Physical Plant Building #11 Facing East



Picture 4: Current Conditions of Original Jani King Building Facing Southwest



Picture 5: Current Conditions of Original Jani King Building Facing South



Picture 6: Current Conditions of Original Jani King Building Facing East



Picture 7: Current Conditions of Original Jani King Building Facing East



Picture 8: Current Conditions of Proposed Location for the Consolidated Building Facing Northwest



Picture 9: Current Conditions of Original Jani King Building Facing Southeast



Picture 10: Current Conditions of Proposed Location for the Consolidated Building Adjacent to Crescent Plywood Building




Picture 11: Current Conditions of the Crescent Plywood Building, Alternate Location for the Consolidated Building



Picture 12: Current Conditions of the Crescent Plywood Building, Rear of the Building



Picture 13: Southeast Side of the Crescent Plywood Building Facing Northwest



Picture 14: Southeast Side of the Crescent Plywood Building