

APPENDIX A
STUDY AREA PHOTOGRAPHS

ATTACHMENT A - PHOTO LOG



PHOTO 1: View of Lake Bella Vista, facing northeast towards the overflow.



PHOTO 2: View of the dam and west spillway facing northeast.
Note the varying width of the concrete deck.




PHOTO 3: View of the top of the dam facing toward east spillway.



PHOTO 4: View of dam facing west.



PHOTO 5: View of west spillway, facing southwest.



PHOTO 6: View of west spillway, facing south. Note the different construction of the pier walls.



PHOTO 7: View of west spillway facing west towards western-most bay of the spillway and concrete wingwalls and abutments.



PHOTO 8: View of east spillway facing southwest toward the remaining original abutment wall. This spillway was reconfigured following the 1928 flood and in the 1950s.



PHOTO 9: View of east spillway and retaining wall facing east. The proposed construction staging area is pictured in the background.



PHOTO 10: View of east spillway facing northwest.



PHOTO 11: View of east spillway facing southeast. The substantial amount of concrete was added in the 1950s.



PHOTO 12: View of retaining walls downstream of the dam with poured concrete to stabilize embankments, facing west.



PHOTO 13: Downstream view towards Little Sugar Creek, facing northwest. Note concrete patching in attempts to stabilize embankment.



PHOTO 14: Downstream view facing southwest.