

Environmental
Assessment
Cole Hollow Road
Realignment Project

Appendix – I

Site Photos



Photograph 3) View of a hedgerow of trees between the field and residence within the proposed roadway alignment.



Photograph 4) View of the wooded area that is found on the property but upslope of the Project Area and roadway alignment.



Photograph 5) View of the proposed roadway alignment along the toe-of-slope of the bordering hillside. Spur Road is visible in the background.



Photograph 6) View looking east at the fallow field from the same location as photograph #5.




Photograph 7) View of the proposed roadway alignment through the open field.




Photograph 8) View of the wetland along the toe-of-slope of the hillside.




Photograph 9) View of the edge of the emergent wetland.



Photograph 10) View of the edge of the wetland near the intersection of Spur Road and Cole Hollow Road.



Photograph 11) View looking southwest at Cole Hollow Road from the intersection with Spur Road.



Photograph 12) View of where the proposed roadway will enter the Project Area off of Cole Hollow Road.



Photograph 1) View the existing driveway at the upper portion of the roadway alignment.



Photograph 2) View of the residence at the upper portion of the Project Area. Cole Hollow Road is visible to the right.