

Appendix F – Aerial Photography

Aerial photography was taken during and after the flooding from military helicopters called in to assist with rescue efforts. The photographs helped assess the flooding situation and were sent to emergency personnel in the basement of the El Paso City Hall, which was set up as a central command center during the flooding crisis. These aerial photos were obtained from the El Paso City and County Office of Emergency Management. The photographs are not accompanied by any locality reference but are included to show an aerial view of the flooding extent and aftermath.









