



Photograph 8. West end of the project area at the Mescalero and Village border facing east



Photograph 9. Overview of damage within project area facing east

Project Area Photographs

***Environmental Assessment for the Sewer Line
in the Village of Ruidoso and Ruidoso Downs,
Lincoln County, New Mexico***

Photographs taken by



755 S. Telshor Blvd., Suite F-201 / Las Cruces, New Mexico 88011
phone: (575) 532-1526 / fax: (575) 532-1587

THIS PAGE WAS INTENTIONALLY LEFT BLANK.



Photograph 10. Overview of project area damage facing east



Photograph 11. Exposed sewer line within project area facing north

Project Area Photographs

***Environmental Assessment for the Sewer Line
in the Village of Ruidoso and Ruidoso Downs,
Lincoln County, New Mexico***

Photographs taken by



755 S. Telshor Blvd., Suite F-201 / Las Cruces, New Mexico 88011
phone: (575) 532-1526 / fax: (575) 532-1587

THIS PAGE WAS INTENTIONALLY LEFT BLANK.



Photograph 12. Overview of project area from Reese Drive facing east



Photograph 13. Cliff openings outside project area

Project Area Photographs

***Environmental Assessment for the Sewer Line
in the Village of Ruidoso and Ruidoso Downs,
Lincoln County, New Mexico***

Photographs taken by



755 S. Telshor Blvd., Suite F-201 / Las Cruces, New Mexico 88011
phone: (575) 532-1526 / fax: (575) 532-1587

THIS PAGE WAS INTENTIONALLY LEFT BLANK.



Photograph 14. Overview of project area damage near the Cemex plant facing east



Photograph 15. Overview of project area at the racetrack

Project Area Photographs

***Environmental Assessment for the Sewer Line
in the Village of Ruidoso and Ruidoso Downs,
Lincoln County, New Mexico***

Photographs taken by



755 S. Telshor Blvd., Suite F-201 / Las Cruces, New Mexico 88011
phone: (575) 532-1526 / fax: (575) 532-1587

THIS PAGE WAS INTENTIONALLY LEFT BLANK.



Photograph 16. Overview of project area facing west



Photograph 17. Eastern end of project area at the Waste Treatment Plant facing north

Project Area Photographs

***Environmental Assessment for the Sewer Line
in the Village of Ruidoso and Ruidoso Downs,
Lincoln County, New Mexico***

Photographs taken by



755 S. Telshor Blvd., Suite F-201 / Las Cruces, New Mexico 88011
phone: (575) 532-1526 / fax: (575) 532-1587

THIS PAGE WAS INTENTIONALLY LEFT BLANK.



Photograph 18. Roadway disturbance - Western end of Singing Pines Road facing east



Photograph 19. Roadway disturbance – Fox Drive facing west

Project Area Photographs

**Environmental Assessment for the Sewer Line
in the Village of Ruidoso and Ruidoso Downs,
Lincoln County, New Mexico**

Photographs taken by



755 S. Telshor Blvd., Suite F-201 / Las Cruces, New Mexico 88011
phone: (575) 532-1526 / fax: (575) 532-1587

THIS PAGE WAS INTENTIONALLY LEFT BLANK.



Photograph 20. Lift Station 1 Location facing southwest



Photograph 21. Lift Station 2 Location facing northwest



Photograph 22. Lift Station 3 Location facing southeast



Photograph 23. Lift Station 4 direction of flow facing northeast



Photograph 24. Lift Station 5 direction of flow facing south

Project Area Photographs

**Environmental Assessment for the Sewer Line
in the Village of Ruidoso and Ruidoso Downs,
Lincoln County, New Mexico**

Photographs taken by



755 S. Telshor Blvd., Suite F-201 / Las Cruces, New Mexico 88011
phone: (575) 532-1526 / fax: (575) 532-1587

THIS PAGE WAS INTENTIONALLY LEFT BLANK.



Photograph 25. Lift Station 6 Location facing west



Photograph 26. Lift Station 7 Location facing west



Photograph 27. Lift Station 8 Location facing south



Photograph 28. Lift Station 9 Location facing northeast



Photograph 29. Lift Station 10 Location facing southwest

Project Area Photographs

**Environmental Assessment for the Sewer Line
in the Village of Ruidoso and Ruidoso Downs,
Lincoln County, New Mexico**

Photographs taken by



755 S. Telshor Blvd., Suite F-201 / Las Cruces, New Mexico 88011
phone: (575) 532-1526 / fax: (575) 532-1587

THIS PAGE WAS INTENTIONALLY LEFT BLANK.



Photograph 30. Ruidoso Downs Racetrack disturbance facing west



Photograph 31. Ruidoso Downs – Project Area facing southwest

Project Area Photographs

***Environmental Assessment for the Sewer Line
in the Village of Ruidoso and Ruidoso Downs,
Lincoln County, New Mexico***

Photographs taken by



755 S. Telshor Blvd., Suite F-201 / Las Cruces, New Mexico 88011
phone: (575) 532-1526 / fax: (575) 532-1587

THIS PAGE WAS INTENTIONALLY LEFT BLANK.



Photograph 32. Ruidoso Downs – disturbed grazing lands facing southwest



Photograph 33. Ruidoso Downs – Exposed sewer line being repaired facing southwest

Project Area Photographs

***Environmental Assessment for the Sewer Line
in the Village of Ruidoso and Ruidoso Downs,
Lincoln County, New Mexico***

Photographs taken by



755 S. Telshor Blvd., Suite F-201 / Las Cruces, New Mexico 88011
phone: (575) 532-1526 / fax: (575) 532-1587

THIS PAGE WAS INTENTIONALLY LEFT BLANK.