

## Appendix B

---



Photograph #1: View of distinctive 6<sup>th</sup> Street corner of historic Administrative Building on Public Works Site



Photograph #2: View of Solid Waste Building on Public Works Site from parking lot on 6<sup>th</sup> Street side of the site



Photograph #3: View of 1950s factory addition from the intersection of 4<sup>th</sup> Street SW and 12<sup>th</sup> Avenue SW



Photograph #4: View of existing damage resulting from muck-out process within Administrative Building



Photograph #5: View of unrepaired mucked-out Administrative Building interior



Photograph #6: View of interior of factory additions within the existing Public Works building



Photograph #7: View of interior of factory additions within the existing Public Works building



Photograph #8: View of existing cold storage building and equipment/material stored at the Public Works Site from 4<sup>th</sup> Street SW