

Project Name: City of Bixby 90 th East Avenue Drainage Project		Site Location: Bixby, OK	Project No.: 15702509
Photo No.: 1	Date: Unknown		
Direction Photo Taken: South			
Description: Intersection of 111 th Street and 90 th East Avenue looking South toward proposed project area.			

Photo No.: 2	Date: Unknown	
Direction Photo Taken: South		
Description: View of unnamed tributary to Fry Creek from 111 th Street. 89 th East Avenue culvert in distance.		

Project Name: City of Bixby 90 th East Avenue Drainage Project	Site Location: Bixby, OK	Project No.: 15702509
---	------------------------------------	---------------------------------

Photo No.: 3	Date: Unknown
Direction Photo Taken: South	

Description:
89th East Avenue 42-inch RCP to be replaced.



Photo No.: 4	Date: Unknown
Direction Photo Taken: South	

Description:
Intersection of 90th East Avenue and 89th East Avenue.



Project Name: City of Bixby 90 th East Avenue Drainage Project	Site Location: Bixby, OK	Project No.: 15702509
---	------------------------------------	---------------------------------

Photo No.: 5	Date: Unknown
------------------------	-------------------------

Direction Photo Taken:
South

Description:
Picture taken standing approximately 25 feet south of 90th East Avenue and 89th East Avenue intersection. Home in background is Schall Property Acquisition.



Photo No.: 6	Date: Unknown
------------------------	-------------------------

Direction Photo Taken:
South

Description:
Picture taken standing on 90th East Avenue. Home pictured on the right of photo is Schall Property Acquisition.



Project Name: City of Bixby 90 th East Avenue Drainage Project		Site Location: Bixby, OK	Project No.: 15702509
Photo No.: 7	Date: Unknown		
Direction Photo Taken: Southeast			
Description: Picture taken standing at 90 th East Avenue and 113 th Street intersection.			

Photo No.: 8	Date: Unknown	
Direction Photo Taken: South		
Description: Picture taken standing upstream of 113 th Street 36-inch RCP to be replaced.		

Project Name: City of Bixby 90 th East Avenue Drainage Project	Site Location: Bixby, OK	Project No.: 15702509
---	------------------------------------	---------------------------------

Photo No.: 9	Date: Unknown	
Direction Photo Taken: West		
Description: Sanitary Sewer Crossing. Looking West across property.		

Photo No.: 10	Date: Unknown	
Direction Photo Taken: South		
Description: Sanitary Sewer Crossing looking West across of unnamed tributary to Fry Creek.		

Project Name: City of Bixby 90 th East Avenue Drainage Project		Site Location: Bixby, OK	Project No.: 15702509
Photo No.: 11	Date: Unknown		
Direction Photo Taken: South			
Description: Sanitary Sewer Crossing.			

Photo No.: 12	Date: Unknown	
Direction Photo Taken: Southeast		
Description: Picture of Mullin Property Acquisition. Photo taken at the intersection of 90 th East Avenue and 113 th Street.		

Project Name: City of Bixby 90 th East Avenue Drainage Project	Site Location: Bixby, OK	Project No. 15702509
---	------------------------------------	--------------------------------

Photo No. 13	Date Unknown
------------------------	------------------------

Direction Photo Taken:
West

Description:
Picture of Schaul Property Acquisition. Photo taken standing on 90th East Avenue.

