

Appendix B



Photograph #1: Infiltration of flood waters through exterior door.

Source: NYULMC



Photograph #2: Sample interior damage.

Source: NYULMC




Photograph #3: Sample interior damage suggesting force of water pressure on secured door.

Source: NYULMC



Photograph #4: Standing water in newly renovated auditorium.

Source: NYULMC



Photograph #5: Damaged auditorium post-flooding showing watermarks.

Source: NYULMC



Photograph #6: Pre-demolition activities at Rubin Hall.

Source: NYULMC



Photograph #7: Site preparation activities for the new Energy Building.

Source: NYULMC



Photograph #8: View of Rusk and Perelman with Amtrak Ventilation Tower in right foreground.



Photograph #9: Construction staging at site of proposed Kimmel Pavilion.



Photograph #10: In-progress construction of Emergency Department with Perelman in background.



Photograph #11: View of Bellevue Hospital Psychiatric Building on the southeast corner of 1st Avenue and 30th Street



Photograph #12: Loading bay and gap between Office of the Medical Examiner and NYULMC buildings; below-grade entrance to the Schwartz Lecture Hall obscured by vehicles and equipment in the foreground