FINDING OF NO SIGNIFICANT IMPACT

Environmental Assessment for the
Pheasant Branch Creek Trail, Bridges, and Streambank Restoration Project
Middleton, Dane County, Wisconsin
Public Assistance Program
Federal Emergency Management Agency, Department Of Homeland Security
Disaster #DR-4402-WI, Project # 88229, PW 593

The Department of Homeland Security's (DHS) Federal Emergency Management Agency (FEMA) proposes to provide funding to the City of Middleton (subrecipient), to restore the Pheasant Branch Creek trail, bridges, and streambank. The subrecipient applied for funding from FEMA's Public Assistance Program (PA) to fund the proposed project. The PA Program is authorized under Section 404 of the Robert T. Stafford Disaster Relief and Emergency Assistance Act, 42 U.S.C. § 5170c. FEMA's PA Program provides disaster recovery funds to repair damage caused by natural or manmade disasters and to help prevent similar future damages.

The proposed project is located within and adjacent to Pheasant Branch Creek in T7N, R8E, sections 1, 2, 11, and 12, in the City of Middleton, Dane County Wisconsin, commencing at the Deming Way bridge, eastward to the Century Avenue bridge, then northward (downstream) approximately 0.4 miles, parallel to Conservancy Lane.

The Proposed Action consists of three components: (1) repairs and improvements to recreational trails and pedestrian bridges, (2) stream stabilization, and (3) channel work including stream realignment and associated bank stabilization. All work will be conducted in and adjacent to Pheasant Branch Creek, within the City of Middleton, between the Deming Way bridge and an area approximately 0.4 miles downstream (north) of the Century Avenue Bridge. Worksites and staging areas will be accessed using existing recreational trails and maintenance-access roads within developed rights-of-way owned by the subrecipient, the City of Middleton.

FEMA prepared the EA pursuant to the National Environmental Policy Act (NEPA), 42 U.S.C. §§ 4321–4347 (2000), as implemented by the regulations promulgated by the President's Council on Environmental Quality (40 Code of Federal Regulations [C.F.R.] 30 §§ 1500–1508) and in accordance with FEMA Directive 108-1, *Environmental Planning and Historic Preservation Responsibilities and Program Requirements* and DHS Instruction Manual 023-01-001-01, *Implementation of the National Environmental Policy Act*. The purpose of the EA was to analyze the potential individual and cumulative environmental impacts of the construction of the proposed project and to determine whether to prepare an Environmental Impact Statement or this Finding of No Significant Impact.

The Proposed Action, as described in the EA, would not result in any significant adverse impacts on geology, soils, topography, water resources, floodplains, air quality, biological resources, wetlands, hazardous materials, zoning and land use, traffic and circulation, public services and utilities, environmental justice populations, historic structures, archaeological resources, or tribal and religious sites. Based on a preliminary screening of resources and the project's geographic location, the EA found that the following resources were not present in the project area and did not require a detailed assessment: coastal resources, seismic hazards, sole source aquifers, essential fish habitat, and wild and scenic rivers.

During the construction period, short-term impacts on soils, water resources, floodplain, wetlands, air quality, biological resources, noise, hazardous materials, safety and security, and archaeological, tribal, and religious sites are anticipated. All potential short-term impacts require conditions to avoid, minimize, and mitigate impacts. With the implementation of these conditions, none of the potential impacts will be significant. In the long-term, the project will have beneficial effects on several resources. FEMA coordinated with the Wisconsin State Historic Preservation Office, Wisconsin Department of Natural Resources, US Fish and Wildlife Service, US Army Corps of Engineers, US Environmental Protection Agency, and federally recognized Indian tribes with interests in the area.

PROJECT CONDITIONS

The subrecipient is responsible for compliance with federal, state, and local laws and regulations, including obtaining any necessary permits prior to beginning construction activities, and adhering to any conditions laid out in these permits. Any substantive change to the scope of work would require re-evaluation by FEMA for compliance with NEPA and any other laws or Executive Orders.

The subrecipient must adhere to the following conditions should the Proposed Action be implemented. Failure to comply with FEMA grant conditions may jeopardize federal funding. FEMA requires the following standard conditions for the Proposed Action:

General Project Conditions

- 1. The subrecipient is responsible for obtaining and complying with all required local, state, and federal permits and approvals.
- 2. Develop and implement erosion control and post-construction storm water management plan to be submitted to WDNR.
- 3. If deviations from the proposed scope of work result in substantial design changes, the need for additional ground disturbance, additional removal of vegetation, or any other unanticipated changes to the physical environment, the subrecipient must contact FEMA so that the revised project scope can be evaluated for compliance with NEPA and other applicable environmental laws.

Water Resources and Water Quality

4. Prior to beginning work, the subrecipient will prepare for implementation an Erosion and Sediment Control Plan and a Storm Water Management Plan as required in the Wisconsin Pollutant Discharge Elimination System (WPDES) General Permit for Storm Water Associated with Land Disturbing Construction Activity, Permit No. WI-S067831-6.

Air Quality

- 5. To reduce the emission of criteria pollutants, construction equipment engine idling will be minimized to the extent practicable, and engines will be kept properly maintained.
- 6. Open construction areas will be minimized and watered as needed to minimize particulates such as fugitive dust.

Noise

7. Substantial use of construction equipment may occur only between the hours of 7:00 am and 6:00 pm Monday through Saturday.

Hazardous Materials

- 8. Contingency plans will be prepared that detail the procedures that the contractors will follow to identify, manage, and dispose of source materials, or other heavily contaminated materials, in accordance with all local, state, and federal regulations in the event hazardous source materials are encountered during creekbank excavation/re-sloping, creekbank infrastructure removal/replacement, bridge repair/relocation, pedestrian trail removal/replacement, or other construction activities. These specifications sections should include, but are not limited to, procedures that address Safety, Health, and Emergency Response Procedures; Environmental Protection Procedures; Contaminated Soil Excavation; Transportation and Disposal of Contaminated Material; and Contaminated Dewatering and Drainage.
- 9. WDNR will be notified if source material or other heavily contaminated material is encountered.

Threatened and Endangered Species

- 10. To minimize effects of the Rusty Patched Bumble Bee, the following (BMPs) should be followed: minimize the spread of invasive species, avoid or minimize soil compaction.; Avoid or minimize soil disturbance and heavy equipment operation during overwintering (mid-October through mid-March); avoid or minimize forest management that may destroy spring blooming flowers during their bloom periods; consider thinning or single tree selection and dense invasive shrub removal that may improve overwintering and spring foraging habitat; use native trees, shrubs and flowering plants in landscaping, provide plants that bloom from spring through fall; remove and control invasive plants in any habitat used for foraging, nesting, or overwintering.
- 11. To minimize impacts to state listed species the City will provide the construction contractor a copy of the May 27, 2022, Wisconsin Department of Natural Resource Endangered Resource Review so that voluntary conservation measures may be incorporated into the project construction as appropriate.

Migratory Birds

12. Tree removal should be avoided during the migratory bird nesting season (approximately March 1 to October 10) to the extent practicable.

Invasive Species

- 13. Graded areas will be revegetated with native grasses and forbs, or native seed mixes.
- 14. All equipment will be cleaned (including but not limited to vehicles, clothing, and gear) at a site prior to moving to another site. All soil, aggregate material, mulch, vegetation, seeds, animals, etc. need to be removed using a hand tool, brush, compressed air, pressure washer, or otherwise.
- 15. If equipment is not disinfected before arriving to the work site, then equipment will be cleaned in the parking or staging area where equipment is loaded and unloaded, ensuring no material is deposited at the worksite or carried away to a new site. Material cleaned from equipment should be disposed of legally.
- 16. All equipment that enters the waters of Pheasant Branch Creek will be thoroughly drained of all water before moving to another site.

Safety and Security

- 17. To minimize risks to safety and human health, construction activities will be performed using qualified personnel properly trained to use the required equipment properly.
- 18. The construction site will be secured from public access.
- 19. All construction activities will be conducted in accordance with the standards specified in the Occupational Safety and Health Administration (OSHA) regulations.
- 20. All conditions of the project Health and Safety Plan will be adhered to.

Architectural, Tribal, and Religious Sites

- 21. The subrecipient will monitor ground disturbance during the construction phase. Should human skeletal remains or historic or archaeological materials be discovered during construction, all ground-disturbing activities on the project site shall cease and the City of Middleton will notify the coroner's office (in the case of human remains), the Wisconsin State Police, and FEMA. FEMA will notify the SHPO, the Miami Tribe of Oklahoma, and the Wisconsin Historical Society (WHS, State Archaeologist).
- 22. All borrow or fill material must come from pre-existing stockpiles, material reclaimed from maintained roadside ditches (provided the designed width or depth of the ditch is not increased), or commercially procured material from a source existing prior to the event. For any FEMA-funded project requiring the use of a non-commercial source or a commercial source that was not permitted to operate prior to the event (e.g. a new pit, agricultural fields, road ROWs, etc.) in whole or in part, regardless of cost, the City of Middleton must notify FEMA prior to extracting material. FEMA must review the source for compliance with all applicable federal environmental planning and historic preservation laws and executive orders prior to a subrecipient or their contractor commencing borrow extraction. Consultation and regulatory permitting may be required. Non-compliance with this requirement may jeopardize receipt of federal funding. Documentation of borrow sources utilized is required at closeout.

FINDINGS

Based upon the conditions and information contained in the EA and in accordance with FEMA Directive 108-1, *Environmental Planning and Historic Preservation Responsibilities and Program Requirements*, and Executive Orders 11988 (Floodplain Management), 11990 (Protection of Wetlands), and 12898 (Environmental Justice), FEMA has determined that the Proposed Action will not have any significant impacts on the quality of the natural and human environment. As a result of this FONSI, an Environmental Impact Statement will not be prepared.

APPROVAL

DUANE D CASTALDI CASTALDI

Digitally signed by DUANE D

Date: 2022.08.10 07:43:06 -05'00'

Duane Castaldi

Date

Regional Environmental Officer, FEMA Region 5

AMANDA C RATLIFF RATLIFF

Digitally signed by AMANDA C

Date: 2022.08.10 08:52:44 -05'00'

Amanda Ratliff Date

Public Assistance Branch Chief, FEMA Region 5





Final Environmental Assessment

Pheasant Branch Creek Trail, Bridges, and Streambank Restoration Project – Deming Way to North of Century Avenue

City of Middleton, Dane County, WI August 2022

Prepared by
SERCO PMO
1479 Gillespie Street
Building 131 – Suite 302
Rock Island, IL 61201

Prepared for FEMA Region 5 536 South Clark Street, Sixth Floor Chicago, IL 60605 Disaster #DR-4402-WI, Project # 88229, PW 593



List of Acronyms, Chemical Formulas, and Abbreviations

APE	Area of Potential Effect	NO _x	Nitrogen Oxides
ACS	American Community Survey		National Oceanic and Atmospheric
BGEPA	Bald and Golden Eagle Protection		Administration
	Act	NPDES	/SDS National Pollution Discharge
BCC	Birds of Conservation Concern		Elimination System/State Disposal
BMP	Best Management Practice		System
CAA	Clean Air Act	NPS	National Park Service
CBRS	Coastal Barrier Resource System	NRCS	Natural Resources Conservation
CERCL	A Comprehensive Environmental		Service
	Response, Compensation and	NRHP	National Register of Historic Places
	Liability Act	NWI	National Wetland Inventory
CEQ	Council on Environmental Quality	O ₃	Ozone
C.F.R.	Code of Federal Regulations	OSHA	Occupational Safety and Health
CO	Carbon Monoxide		Administration
CWA	Clean Water Act	PA	FEMA's Public Assistance Program
CZMA	Coastal Zone Management Act	Pb	Lead
DHS	United States Department of	PM	Particulate Matter
	Homeland Security	PMP	Private Nonprofit Organizations
EA	Environmental Assessment	P.L.	Public Law
EFH	Essential Fish Habitat	RCRA	Resource Conservation and
EFPO	Eastern Fringed Prairie Orchid		Recovery Act
EJ	Environmental Justice	SFHA	Special Flood Hazard Area
EO	Executive Order	SHPO	Wisconsin State Historic
ESA	Endangered Species Act		Preservation Office
FEMA	Federal Emergency Management	SO_2	Sulfur Dioxide
	Agency	SWPPF	Stormwater Pollution Prevention
FHA	Federal Highway Administration		Plan
FIRM	Flood Insurance Rate Map	THPO	Tribal Historic Preservation Office
FPPA	Farm Protection Policy Act		Total Daily Maximum Load
FONSI	Finding of No Significant Impact	TSS	Total Suspended Solids
IPaC	Information for Planning and	USACE	United States Army Corp of
	Consultation		Engineers
MBTA	Migratory Bird Treaty Act	U.S.C.	United States Code
NAAQ:	S National Ambient Air Quality	USDA	United States Department of
	Standards		Agriculture
NEPA	National Environmental Policy Act	USEPA	United States Environmental
NHPA	National Historic Preservation Act		Protection Agency
NLEB	Northern Long-eared Bats	USFWS	S United States Fish and Wildlife
NO_2	Nitrogen Dioxide		Service

USGS United States Geological Survey
VOC Volatile Organic Compound
WDNR Wisconsin Department of Natural
Resources

WEM Wisconsin Emergency Management WGNHS Wisconsin Geological and Natural History Survey

WHS Wisconsin Historical Society (State Archaeologist)
WisDOT Wisconsin Department of Transportation

Table of Contents

1	BAC	KGROUND	1
	1.1	Project Authority	1
	1.2	Project Location	2
	1.3	Purpose and Need	3
2	ALT	ERNATIVE ANALYSIS	3
_		Alternative 1 – No Action	
		Action Alternative 2 – Proposed Action	
		Alternatives Considered and Eliminated from Further Consideration	
3	AFF	ECTED ENVIRONMENT AND CONSEQUENCES	9
		Preliminary Screening of Assessment Categories	
		Physical Environment	
		3.2.1 Geology, Soils, and Topography	11
		3.2.2 Water Resources and Water Quality	15
		3.2.3 Floodplain Management (Executive Order 11988)	19
		3.2.4 Air Quality	
	3.3	Biological Environment	24
		3.3.1 Terrestrial and Aquatic Environment	
		3.3.2 Wetlands (EO 11990)	26
		3.3.3 Threatened and Endangered Species	29
		3.3.4 Migratory Birds	35
		3.3.5 Invasive Species	37
	3.4	Hazardous Materials	38
	3.5	Socioeconomics	40
		3.5.1 Zoning and Land Use	40
		3.5.2 Noise	42
		3.5.3 Public Services and Utilities	42
		3.5.4 Traffic and Circulation	43
		3.5.5 Environmental Justice (Executive Order 12898)	44
		3.5.6 Safety and Security	
	3.6	Historic and Cultural Resources	47
		3.6.1 Historic Structures	48
		3.6.2 Archaeological Resources	49
		3.6.3 Tribal Coordination and Religious Sites	50
	3.7	Comparison of Alternatives	
4	CUN	MULATIVE IMPACTS	54
5	PUP	SLIC PARTICIPATION	55

	5.1	Subrecipient Outreach	.56
6	MIT	IGATION MEASURES AND PERMITS	.57
		Permits	
	6.2	Project Conditions	.59
7	CON	SULTATIONS AND REFERENCES	.61
		Federal, State, and Local Agencies	
		Tribal Nations	
	7.3	References	. 63
8	LIST	OF PREPARERS	. 69
ΑP	PEND	DICES	. 70

List of Tables

Table 1-1: Proposed Work Area General Location and Coordinates	2
Table 3-1: Evaluation Criteria for Potential Impacts	9
Table 3-2: Soil Types within the Proposed Project Area	12
Table 3-3: USFWS Birds of Conservation Concern or That Warrant Attention	36
Table 3-4: Low-Income Populations, 2022 Estimate	45
Table 3-5: Minority Populations, Census 2010	45
Table 3-6: Comparison of Alternatives	51
Table 5-1: Public Survey Results	56
Table 6-1: Permit Summary	58
Table 8-1: Federal Emergency Management Agency Preparers	69

List of Figures

Figure 1: Project Location	2
Figure 2: Bridge Locations	5
Figure 3: Geological Map	11
Figure 4: Soil Types	12
Figure 5: Impaired Waterways	17
Figure 6: Flood Insurance Rate Map 1	20
Figure 7: Flood Insurance Rate Map 2	20
Figure 8: Flood Insurance Rate Map 3	21
Figure 9: Flood Insurance Rate Map 4	22
Figure 10: Wetlands	28
Figure 11: City of Middleton Zoning Map	40

1.1 Project Authority

Between August 17 to September 14, 2018, severe storms, tornadoes, and straight-line winds resulted in flooding and landslides in fifteen counties throughout the state of Wisconsin. Effects of these storms in the City of Middleton, located in Dane County, included significant erosion and slope failure to non-engineered creekbanks and damage to existing creekbank-stabilization infrastructure from heavy rains, high flooding water levels, and extreme overbank flow of the Pheasant Branch Creek. Additionally, several existing maintenance-access trails, adjacent asphalt recreational trails, stormwater outfall structures, and pedestrian bridges over Pheasant Branch Creek were severely damaged from erosion caused by flooding. President Trump issued disaster declaration DR-4402-WI for the State of Wisconsin on October 18, 2018, which made disaster recovery assistance available through the Federal Emergency Management Agency (FEMA). The City of Middleton, the subrecipient, applied for funding from FEMA's Public Assistance (PA) Program, through Wisconsin Emergency Management (WEM), to repair damaged infrastructure and mitigate against future damages by adding improved creekbank stabilization and recreational infrastructure. FEMA's PA grant program provides federal assistance to government organizations and certain private nonprofit (PNP) organizations following a Presidential disaster declaration. PA is authorized by Section 406 of the Robert T. Stafford Disaster Relief and Emergency Assistance Act (Public Law [P.L.] 93-288), 42 United States Code [U.S.C.] §§ 5121-5207.


This environmental assessment (EA) was prepared in accordance with the National Environmental Policy Act (NEPA) of 1969, 42 U.S.C. §§ 4321 - 4370h; President's Council on Environmental Quality (CEQ) regulations to implement NEPA (40 Code of Federal Regulations [C.F.R.] Parts 1500 to 1508); U.S. Department of Homeland Security (DHS) Directive No. 023-01; rev. 1, Implementation of the National Environmental Policy Act (Oct. 31, 2014); DHS Instruction Manual No. 023-01-001-01, rev. 1, Implementation of the National Environmental Policy Act (Nov. 6, 2014); FEMA Directive No. 108-01, Environmental Planning and Historic Preservation Responsibilities and Program Requirements (Aug. 22, 2016); and FEMA Instruction 108-01-1, Instruction on Implementation of the Environmental and Historic Preservation Responsibilities and Program Requirements (Aug. 22, 2016). FEMA is required to consider potential environmental impacts before funding or approving actions and projects. The purpose of this EA is to meet FEMA's responsibilities under NEPA and to analyze the potential environmental impacts of the proposed project. FEMA will use the findings in this EA to determine whether to prepare an environmental impact statement for the proposed project or to issue a finding of no significant impact (FONSI).

In accordance with federal laws and FEMA regulations, the EA process for a proposed federal action must include an evaluation of alternatives and a discussion of the potential environmental impacts. As part of this NEPA review, the requirements of executive orders and other environmental laws are addressed.

1.2 Project Location

The proposed project is located within and adjacent to Pheasant Branch Creek in T7N, R8E, sections 1, 2, 11, and 12, in the City of Middleton, Dane County, Wisconsin (**Figure 1, Table 1-1**), commencing at the Deming Way bridge, eastward to the Century Avenue bridge, then northward (downstream) approximately 0.4 miles (mi.), parallel to Conservancy Lane. The City of Middleton consists of 8.98 square mi. with a population of 21,827 based on the 2020 Census (U.S. Census Bureau 2020).

Figure 1: Project Location



Pheasant Branch Greek Trail, Bridges, and Streamhank Restoration Project Deming Way to North of Gentury Avenue DR-4402-WI Project #88229 PW 593



Table 1-1: Proposed Work Area General Location and Coordinates

Waterway	Start	End	
Pheasant Branch Creek	43.102522, -89.518287	43.10945, -89.49057	

1.3 Purpose and Need

FEMA's PA Grant Program provides disaster recovery funds to repair damage cause by natural or man-made disasters and to help prevent similar future damages. The proposed project is needed because high-velocity channel flows and surface water flooding caused historically unprecedented creekbank erosion and infrastructure damage resulting in unsafe conditions and unusable recreational trails and bridges. Data collected from the flood on August 20, 2018, indicated that in less than 24 hours, over 11 inches (in.) of rain fell in the Middleton and Cross Plains area, causing damage throughout the Pheasant Branch Creek corridor and the adjacent public trails system within the City of Middleton. Creek discharge was measured at 3,000 cubic feet per second (cfs); three to four times higher than any water flow recorded in this watershed over the last 43 years (WDNR 2022a).1 The results of these storm events were loosening of creekbank soil structure, scouring, and destruction of previous creekbank stabilization infrastructure, overtopping of pedestrian bridge superstructure and decking which caused damage to bridge railings, undermining of bridge support piers, and erosion damage to adjacent recreational trails. Future storms events without the proposed infrastructure repairs and improvements will result in further creekbank erosion, reducing water and habitat quality, and additional damage to remaining infrastructure. Furthermore, the City of Middleton needs these damaged pedestrian bridges and recreational trails returned to safe and usable conditions to restore public recreational opportunities lost due to these storm events.

The purpose of this proposed project is to ensure improved water quality and aquatic habitat and reduce the risk of future damages to recreational trails, pedestrian bridges, and other infrastructure adjacent to and within the project area by repairing and stabilizing heavily eroded creekbanks, completely relocating the creek bed in two locations, elevating pedestrian bridges, and in-stream modifications. Proposed work includes grading and reshaping the eroded land and replacing or installing stone toe protection, root wad composite, and toewood-sod mat erosion-reduction infrastructure. All creek banks requiring grading will be stabilized by the installation of erosion control blankets followed by the application of a native grass/forb seeding mix. That proposed work will reduce bank erosion and sediment load in the creek, which will improve aquatic habitat for fish and macroinvertebrates. At several locations where pedestrian bridges cross Pheasant Branch Creek, the creek bed will be excavated to a lower elevation to increase the potential volume of water flow under those structures during flood events. Additionally, several pedestrian bridges will be raised on new concrete piers to reduce their vulnerability to damage from future flood events.

2 ALTERNATIVE ANALYSIS

NEPA requires FEMA to evaluate alternatives to the proposed project and describe the environmental impacts of each alternative. NEPA also requires an evaluation of the No Action alternative, which is the future condition without the project being executed. This section

¹ Section 7.3 of this Environmental Assessment lists the referenced documents by author or agency, and year.

describes the No Action alternative, the Proposed Action, and alternatives that were previously considered but eliminated from further consideration.

2.1 Alternative 1 – No Action

Under the No Action alternative, no proposed stream stabilization, channel work, or bridge and trail restoration work of areas that were washed out during the disaster events will be executed along these two miles of Pheasant Branch Creek. Without the proposed infrastructure repairs and improvements, future excessive rain events and floodwaters would continue to cause further creekbank erosion and flooding throughout this section of Pheasant Branch Creek. That erosion will cause siltation and higher turbidity in Pheasant Branch Creek, reducing water and habitat quality of the creek and its distributary, Lake Mendota. Furthermore, the structural stability of roadway crossings, recreational trails, and pedestrian bridges would remain threatened, which would pose safety concerns. Over time, continued damage to existing infrastructure will cause additional closures or structural failures.

Loss of significant recreational benefits previously provided by Pheasant Branch Creek, its surrounding natural areas, and the trail and bridge system will continue to affect the community because of the limitations of the current temporary repairs of these areas.

2.2 Action Alternative 2 – Proposed Action

The Proposed Action includes scope items from a previously defined five-year restoration plan by the City of Middleton. That plan includes the protection of the Pheasant Branch Creek corridor from future stormwater damage, restoring multi-modal transportation and recreation opportunities, and improving ecological biodiversity throughout the Pheasant Branch Creek corridor.

The proposed project will be a combination of several eligible federally funded disaster repair and mitigation projects, and several additional improved projects. Required non-federal matching monies from the subrecipient will fund portions of the Proposed Action, but some additional work not eligible for federal funds will also be performed in conjunction with the federally funded work. Regardless of funding source, all contemporaneous work being proposed within the project area is included in the description of the Proposed Action.

The Proposed Action consists of three components: (1) repairs and improvements to recreational trails and pedestrian bridges, (2) stream stabilization, and (3) channel work including stream realignment and associated bank stabilization. All work will be conducted in and adjacent to Pheasant Branch Creek, within the City of Middleton, between the Deming Way bridge and an area approximately 0.4 mi. downstream (north) of the Century Avenue bridge. Worksites and staging areas will be accessed using existing recreational trails and maintenance-access roads within developed rights-of-way owned by the subrecipient, the City of Middleton.

Trails and Bridges:

Six flood-damaged pedestrian bridges and numerous washed-out pedestrian trail segments will be repaired or improved. Bridges are designated from the most upstream location of the project area (Deming Way), progressing downstream (towards Lake Mendota) (Figure 2).

Figure 2: Bridge Locations



Pheasant Branch Creek Trail, Bridges, and Streamhank Restoration Project Deming Way to North of Century Avenue DR-4402-WI Project #88229 PW 593

Cardno, Inc. Pheasant Branch Corridor and Improvements Master Plan February, 2020 GIS ShapefilesCardno, Inc.



Proposed work includes rebuilding 277 linear feet (lf.) washout of crushed limestone recreation trail 1,300 lf. downstream of Century Avenue bridge, and repair to 6 pedestrian bridges and associated trails. Each bridge will have the railing repaired and be elevated between 3 and 6 ft. above its current location on new concrete abutments. In addition, at each location, the following trail repairs will be made to existing asphalt and gravel trails. Two bridges will be relocated, as noted below.

- First pedestrian bridge (Bridge #6) (43.103016, -89.509429): repair 55 lf. of trail at both ends of the bridge, and repair additional 250 lf. of trail east of the bridge.
- Second pedestrian bridge (Bridge #5) (43.104170, -89.507500): repair 189 lf. of trail at both ends of the bridge.

- Third pedestrian bridge (Bridge #4) (43.104287, -89.505070): relocate and re-align bridge 10 lf. downstream from the original location and repair 15 lf. of trail at both ends of the bridge.
- Fourth pedestrian bridge (Bridge #3) (43.101879, -89.501156): repair 20 lf. of trail at both ends of the bridge and an additional 235 lf. of trail east of the bridge.
- Fifth pedestrian bridge (Bridge #2) (43.103065, -89.498190): repair 40 lf. of trail at both ends of the bridge, and 279 lf. of trail beyond both sides of bridge approach repairs.
- Sixth pedestrian bridge (Bridge #1) (43.103350, -89.495906): relocate and re-align bridge 14 lf. downstream from the original location, repair 20 lf. of trail at both ends of the bridge and 250 lf. of trail beyond both sides of bridge approach repairs.

Stream Bank Stabilization:

Stream Stabilization will include ecological enhancements such as natural channel design techniques to improve aquatic habitat including slope re-shaping using natural stone, native vegetation seeding, and tree-root wad/log installation. Site selection was based on need for stabilization to protect existing infrastructure and recreation amenities (Figure 4). Four specific stabilization methods will be implemented:

- **Slope Grading/Native Seeding:** creekbank slope grading and re-shaping followed by slope stabilization through the installation of erosion control blankets and subsequent application of native grass/forb seeding mix at all disturbed creekbank slope grading locations. In total, 3.71 acres (ac.) of native seeding will be installed.
- **Stone Toe Protection:** creekbank slope grading and re-shaping followed by slope stabilization through the installation of erosion control blankets and subsequent application of native grass/forb seeding mix and natural stone on the creekbank slope and toe.
- Root Wad Composite: creekbank slope grading and re-shaping followed by slope stabilization through the installation of erosion control blankets and subsequent application of native grass/forb seeding mix and a natural stone and tree root/log composite structure on the creekbank slope, toe, and within the creek channel. Root wad logs will be keyed into the creekbank 8-12 ft. Stone will be placed into the creekbank at its base to a depth of at least 2 ft. to stabilize and anchor the logs.
- Toewood–Sod Mat Composite: creekbank slope grading and re-shaping followed by slope stabilization through the installation of erosion control blankets and subsequent application of native grass/forb seeding mix and a tree root/log and vegetation/soil mat composite structure on the creekbank slope and toe, and within the creek channel. Footer logs (without root wad) will be keyed into the bank at 15-20 degrees to bank tangent and arranged in an interlocking pattern for reinforcement. A layer of root wad logs, limbs, and coarse woody material will be placed above the footer logs and interwoven into footers where possible to serve as revetment for a live brush layer. Live brush will be applied and staked with willow or other appropriate posts.

Stream Stabilization Locations: The following locations include replacing or removing eroded non-classified fill, installing from 20 lf. and up to 500 lf. of stone toe protection, from 30 lf. and up to 500 lf. of slope grading and installing from 70 up to 270 lf. root wad and/or toewood-sod mat composite:

- Deming Way bridge downstream to U.S. Highway 12 bridge.
- First pedestrian bridge (Bridge #6) downstream to second pedestrian bridge crossing.
- Second pedestrian bridge (Bridge #5) downstream to third pedestrian bridge crossing.
- Third pedestrian bridge (Bridge #4) downstream to Park Street bridge crossing.
- Park Street bridge downstream to fourth pedestrian bridge crossing.

In addition to non-classified fill, stone toe protection, slope grading, and installation of root wad and/or sod mat composite, the following locations have the following additional scope:

- U.S. Highway 12 bridge downstream to Parmenter Street:
 - Stabilize stone culvert outfall.
- Parmenter Street downstream to first pedestrian bridge crossing:
 - o Stabilize Clark Street culvert outfall.
- Fourth pedestrian bridge (Bridge #3) downstream to fifth pedestrian bridge crossing:
 - o Remove 50 lf. of gabion wall and sheet pile.
 - Remove eroded erosion control blankets.
 - Stabilize Nina Court culvert outfall.
- Fifth pedestrian bridge (Bridge #2) downstream to sixth pedestrian bridge crossing:
 - Replace stone gabion basket.
- Sixth pedestrian bridge (Bridge #1) downstream to Century Avenue bridge crossing:
 - Stabilize Santa Maria Court culvert outfall.
- Downstream of Century Avenue Bridge crossing:
 - o Remove eroded erosion control blankets, unclassified fill, and root wads at four locations.
 - o Remove failed gabions at Century Avenue Bridge.

Channel Work:

Instream work will be completed during low flow conditions. The Proposed Action consists of three specific types of channel work:

Creek Bottom Excavation: the creek bottom will be excavated to a lower elevation at the first, second, third, and sixth pedestrian bridges to increase the capacity of creek flow underneath those bridges during flood events. The channel will be lowered by 1 ft, 0.5 ft, 1 ft, and 0.9 ft, respectively. Additionally, commencing 200 lf. downstream of Century Avenue bridge, an 80 lf. in-channel silt bar will be removed.

Stone Riffle Structures: placement of natural stone into the creek bottom comprising in-channel boulder cluster/glide/riffle structures and converging boulder cross vanes will reduce shear stress on creekbanks and minimize the size and volume of stone protection needed. Five boulder cluster/glide/riffle structures will be installed throughout the project area at 900 lf. and 1,560 lf.

downstream of the second pedestrian bridge, 300 lf. upstream of Park Street bridge, and 1,550 lf. and 1,700 lf. downstream of Century Avenue bridge. Two converging boulder cross vanes will be constructed at 175 lf. and 750 lf. downstream of Century Avenue bridge.

These structures provide significant benefits for both bank protection and aquatic habitat. Constructed riffles and rock vanes work to modify stream flows, providing a variety of flow conditions and microhabitats for fish, ranging from scouring channels and pools to slower backwater refuges. The rock placed within the stream channel will provide substrate for colonization by macroinvertebrates and provide benthic habitat for small fish. Where installed, the riffle and vane structures will reduce ongoing erosion, which contributes to instream siltation and embeddedness.

Creek Realignment: at two locations where creekbank erosion is severe because of adjacent, abrupt, steep elevation differences (cutbanks), Pheasant Branch Creek will be completely realigned to reduce erosion of adjacent high slopes into the creek. Near the third pedestrian bridge and 500 lf. upstream of the Park St. bridge, former creekbank stabilization structures have failed, necessitating creek realignment. A 2,885 square ft. (sf.) (210 lf.) and 3,820 sf. (290 lf.) toewood-sod mat composite structure will be placed into the existing creek channel to force the realigned creek to remain in its newly excavated channel. Additionally, upstream of the Park Street bridge, 80 lf. of a damaged sheet pile wall will be buried in place and a dead cottonwood tree within channel relocation work area will be removed. (See Appendix A: Project Plans.)

2.3 Alternatives Considered and Eliminated from Further Consideration

The City of Middleton performed a comprehensive analysis of trail alignment, trail materials, bridge designs, and stream restoration alternatives. The subrecipient also completed several public meetings to solicit feedback on preferred approach and best design solution for the proposed project.

The following options were considered:

Option A – Maintain existing alignment and trail cross-section

This alternative consists of using the existing alignment and trail cross-section with only minor deviations to improve some blind spots and to adjust to match elevated bridges. Per this option, no bridges would be eliminated.

Option B - Widen the existing trails and trail cross-section

This alternative consists of using the existing alignment and trail cross-section but widening it from 10 ft. to 12 ft. Recreational trail surfacing would be standard asphalt instead of porous asphalt.

Option C – Pathway Realigned with Split-Use Side Paths

This alternative consists of the realignment of the recreational trail in two areas. The proposed pathway would be approximately 5,765 ft. long and would have 3 bridges on the mainline,

including bridge realignments. The path would remain a 10 ft. wide asphalt surface with turf shoulders.

Option C was eliminated for further analysis based on public input. The subrecipient decided to apply elements of the other approaches to reduce possible environmental impacts and to meet public concerns. Options A and B will be used on different segments of the trail.

3 AFFECTED ENVIRONMENT AND CONSEQUENCES

This section describes the natural and human environment of the study area potentially affected by the alternatives, evaluates potential impacts, and recommends measures to avoid or reduce those impacts. The description of the study area represents current conditions and serves as a baseline from which to identify and evaluate environmental changes that may occur because of the Proposed Action. When possible, quantitative information is provided to establish potential impacts, but qualitative information may also be used where data are unavailable. Potential impacts are then evaluated qualitatively based on the criteria listed in **Table 3.1**.

Table 3-1: Evaluation Criteria for Potential Impacts

Impact Scale	Criteria
None / Negligible	The resource area would not be affected, or changes or benefits would be either nondetectable or, if detected, would have effects that would be slight and local. Impacts would be well below regulatory standards, as applicable.
Minor	Changes to the resource would be measurable, although the changes would be small and localized. Impacts or benefits would be within or below regulatory standards, as applicable. Mitigation measures would reduce any potential adverse effects.
Moderate	Changes to the resource would be measurable and have either localized or regional scale impacts/benefits. Impacts would be within or below regulatory standards, but historical conditions would be altered on a short-term basis. Mitigation measures would be necessary, and the measures would reduce any potential adverse effects.
Major	Changes would be readily measurable and would have substantial consequences on a local or regional level. Impacts would exceed regulatory standards. Mitigation measures to offset the adverse effects would be required to reduce impacts, but long-term changes to the resource would be expected.

The "study area" generally includes the project work area and access and staging areas needed to complete the Proposed Action. If the study area for a particular resource category is different from the project area, the differences will be described in the appropriate subsection. The proposed project work area is located along Pheasant Branch Creek within the City of Middleton, Dane County, Wisconsin. The portion of the Pheasant Branch Creek corridor where the proposed

project would occur is in an environment of both natural areas and maintained infrastructure including the creek and recreational trails, bridges, and maintained rights-of-way.

Pheasant Branch Creek is a small waterway that meanders and scours through loamy soils on its side slopes. Through much of the City of Middleton and the entire study area, the Pheasant Branch Creek floodplain is developed and maintained by the City's Parks and Recreation Department as a public outdoor recreation area for walkers, cyclists, alternative transportation, and other passive activities such as birding or education. The damaged portions of the recreational trails and pedestrian bridges proposed to be repaired or improved through this project are part of a 27 mi. recreational trail system throughout the City of Middleton. The study area along the Pheasant Branch Creek corridor from Deming Way to Parmenter Street is mostly open and surrounded by development and major roads including a crossing of U.S. Highway 12. The study area downstream of Parmenter Street to its terminus 0.4 mi. downstream of Century Drive is the Pheasant Branch Creek floodplain consisting of river bottom forest habitat with a mostly closed tree canopy and fairly steep side slopes surrounded by urban development.

3.1 Preliminary Screening of Assessment Categories

Based on a preliminary screening of resources and the project's geographic location, the following resources do not require a detailed assessment.

- Coastal Barrier Resources System (CBRS). The Coastal Barrier Resources Act, 16 U.S.C. §§ 3501-3510, is not applicable because the project is not within or near a CBRS unit (U.S. Fish and Wildlife Service [USFWS] 2019a).
- Coastal Zone Management. The Coastal Zone Management Act (CZMA), 16 U.S.C. §§
 1451-1464, ch. 33, enacted in 1972, is not applicable because the project is not near a
 coast.
- Essential Fish Habitat (EFH). The Magnuson-Stevens Fishery Conservation and Management Act, 16 U.S.C. §§ 1801 et seq., does not apply because there are no Habitat Areas of Particular Concern and no EFH Areas identified at the project site according to the National Oceanic and Atmospheric Administration (NOAA) Essential Fish Habitat (EFH) Mapper (NOAA 2022).
- Seismic Risks. Executive Order (EO) 12699, Seismic Safety of Federal and Federally
 Assisted or Regulated New Building Construction, does not apply because there is low
 seismic risk in the project area based on seismic hazard maps developed by the U.S.
 Geological Survey (USGS). This includes less than 1 percent chance of potentially minordamage (equivalent to Modified Mercalli Intensity VI) ground shaking in the 2018 ShortTerm Seismicity Model (USGS 2018a), and the lowest hazard in the 2018 Long-Term
 National Seismic Hazard Map (USGS 2018b).
- Sole Source Aquifers. There are no sole-source aquifers regulated by the Safe Drinking Water Act of 1974, 42 U.S.C. §§ 300f et seq., within Wisconsin (United States Environmental Protection Agency [USEPA] 2020).
- Wild and Scenic Rivers. The Wild and Scenic Rivers Act, 16 U.S.C. §§ 1271 et seq., is not applicable because no federally designated wild and scenic rivers occur near or in the

project area based on a review of the National Wild and Scenic Rivers System website maintained by the National Park Service (NPS 2022). The closest federally designated wild and scenic river is the Wolf River, approximately 124 mi. north-northeast of the project area.

3.2 Physical Environment

3.2.1 Geology, Soils, and Topography

Bedrock geology was characterized using the Wisconsin Geological and Natural History Survey (WGNHS) map of Preliminary Bedrock Geology of Dane County, Wisconsin (Plate 1) (WGNHS 2013). The geology in the project area is formed from rocks of Late Cambrian age (541 to 485.4 million years ago) consisting of sandstones that are shaly, silty, and dolomitic. The average stratigraphic thickness is about 800 ft. Erosion has cut into sandstones of Cambrian age in many places in Dane County. Recent Pleistocene drainage eroded the sandstones in the northwest and the Yahara River valley. In the Wisconsin River valley, the stratigraphic thickness is about 300 ft. and 380 ft. in a well in Madison. The sandstones of the Cambrian age are a single water-yielding unit consisting of five formations. The formations laid from the oldest and deepest upwards are Mount Simon Sandstone, Eau Claire Sandstone, Galesville Sandstone (belonging to the Dresbach Group), and lastly the Franconia Sandstone and Trempealeau Group (USGS 1965, WGNHS 2013, Figure 3).

Figure 3: Geological Map



Soils in the proposed project area were identified using the U.S. Department of Agriculture (USDA) Natural Resource and Conservation Service (NRCS) Web Soil Survey (accessed February 2022(a)). The thirteen soil types underlying the proposed project area are identified in **Figure 4** and **Table 3-2**.

Figure 4: Soil Types



Pheasant Branch Creek Trail, Bridges, and Streambank Restoration Project Deming Way to North of Century Avenue DR-4402-WI Project #88229 PW 593



Table 3-2: Soil Types within the Proposed Project Area

Soil Type	Percent of Project Area
BbA—Batavia silt loam, gravelly substratum, 0 to 2 percent slopes	0.4%
DrD2—Dresden loam, 12 to 20 percent slopes, eroded	0.3%
DsC2—Dresden silt loam, 6 to 12 percent slopes, eroded	3.6%
Ev—Elvers silt loam, 0 to 2 percent slopes	2.5%
GP—Gravel pit	0.3%
Gn—Granby loamy sand, 0 to 2 percent slopes	1.0%
GsB—Grays silt loam, 2 to 6 percent slopes	0.9%
Ho—Houghton muck, 0 to 2 percent slopes	19.6%

Soil Type	Percent of Project Area
KeB—Kegonsa silt loam, 2 to 6 percent slopes	1.8%
RpE—Rodman sandy loam, 12 to 35 percent slopes	71.3%
SaA—Sable silly clay loam, 0 to 2 percent slopes	2.5%
Wa—Wacousta silty clay loam, 0 to 2 percent	0.6%
Wt—Watseka loamy sand	0.2%

Between Deming Way and Century Drive, the Pheasant Branch Creek corridor is mostly comprised of the most prevalent soil type throughout the entire proposed project area, Rodman sandy loam (71.3%). This soil type consists of very deep, excessively drained soils that are shallow to calcareous, stratified sandy and gravelly outwash that formed in sandy and gravelly outwash slopes ranging from 12 to 35 percent (NRCS 2021). This includes much of the area where significant erosion has occurred due to the presence of steep, loamy side-slopes.

North of Century Avenue, the Pheasant Branch Creek corridor is mostly comprised of the second-most common soil type present within the proposed project area, Houghton muck (19.6 %). Houghton muck consists of very deep, very poorly drained soils formed in herbaceous organic materials more than 51 in. thick in depressions and drainageways on lake plains, outwash plains, ground moraines, end moraines, till plains, and floodplains with slope ranges from 0 to 2 percent (NRCS 2021).

Another feature of soils is their suitability for farming. The purpose of the Farmland Protection Policy Act (FPPA) of 1981, 7 U.S.C. §§ 4201 et seq., is to minimize the extent that federal programs contribute to the unnecessary and irreversible conversion of prime and important farmland to non-agricultural uses. The conversion of prime or unique farmland must be considered whenever Federal funding or time is used in the direct or indirect conversion of prime farmland unless an exemption exists. Houghton muck is a soil type designated as farmland of statewide importance (USDA 2021).

The topography of Dane County at the project area is rolling to moderately hilly and poorly drained, containing many lakes and swamps (USGS 1965). Topography consists of the Pheasant Branch Creek basin, steeply sloped banks, and relatively flat upland areas above the basin, interspersed with other steeply sloped ravines. The existing alignment of the recreational trail is within the basin, but riverbanks are not far from the trails in most locations.

Due to development in the area over the past century, this portion of the Pheasant Branch Creek watershed now consists of urban impervious surfaces and residential lawns. These types of land uses increase surface runoff which, in combination with the steep terrain in some areas and erodible soils, has led to active erosion along the creek banks and within the channel causing slope failures on adjacent lands.

Alternative 1 – No Action

Under the No Action alternative, proposed stream stabilization, channel work, or bridge and trail improvements along Pheasant Branch Creek would not be performed; therefore, no direct short-or long-term effects to the geology, soils, topography, or prime or unique farmland within the proposed project area would occur from project construction activities.

However, the No Action alternative would cause moderate long-term impacts to the soils and topography because of continued channel and stream bank erosion. Erosion caused by excessive rain events and floodwaters would continue to wash away creekbank soils and prime or unique farmland, and high slope cutbanks would continue to collapse into Pheasant Branch Creek.

Action Alternative 2 – Proposed Action

Proposed Action construction activities consist of excavation, re-shaping, and re-sloping of Pheasant Branch creekbanks, deposition of clean soil fill, stone boulders, and timber logs along creekbanks and within the channel, removal of creek bed soils under several bridges, removal of an 80 lf. in-channel silt bar, and complete creek bed realignment at two locations. Earthwork will include relocation of soils, adding fill materials, grading to slope, and reshaping creekbanks to match the surrounding topography. Those proposed construction activities would have moderate short-term impacts on soils and topography.

The reconstruction of asphalt and gravel recreational trails and repair and elevating of pedestrian bridges would have minor short-term impacts on soils and topography resulting from the excavation of the existing asphalt trails, bridge approaches and associated aggregate base material and subsequent placement of clean fill and aggregate base material.

Geology, soils, and topography would not be negatively impacted over the long-term from construction activities performed through the Proposed Action. Measures that would curtail soil erosion and improve creekbank stability would provide moderate long-term benefits to soils and topography in the project area. Furthermore, the native plantings associated with the proposed creekbank stabilization would further stabilize soils.

The depth to bedrock is 0 to 45 ft. in this area and it is not anticipated that the geology would be impacted by the Proposed Action (U.S. Geological Survey 2004).

Though a portion of the project area (north of Century Drive) contains Houghton muck, a prime and important farmland soil, work where that soil type exists will be repair of soft infrastructure (existing gravel pedestrian trail) within the urbanized center of the City of Middleton and no irreversible conversion as defined by FPPA (2022b) of any land containing designated prime farmland soil will occur. Therefore, FEMA determines that the Proposed Action is not subject to the FPPA.

3.2.2 Water Resources and Water Quality

Water resources include surface water, groundwater, stormwater, and drinking water (wetlands are evaluated in Section 3.3.2). The Clean Water Act (CWA) of 1972, 33 U.S.C. §§ 1251 et seq., is the primary federal law in the United States that regulates the discharge of pollutants into water, with various sections falling under the authority of United States Army Corps of Engineers (USACE) and the United States Environmental Protection Agency (USEPA) or as delegated to the states. Section 404 of the CWA establishes USACE permit requirements for discharge of dredged or fill materials into waters of the United States. Furthermore, USACE regulation of activities within navigable waters are authorized under the 1899 Rivers and Harbors Act, Section 10 (33 U.S.C. §§ 403 et seg). Section 401 of the CWA is administered by WDNR and provides regulations for the protection of water quality on projects that involve dredge or fill in waters of the United States (Wis. Statutes, § 283.01(20)). The CWA made it unlawful to discharge any pollutant from a point source into navigable waters unless permitted. Under the National Pollution Discharge Elimination System/State Disposal System (NPDES/SDS) (Section 402 of the CWA), USEPA's regulation of both point and nonpoint pollutant sources, including stormwater and stormwater runoff, has been delegated to the state and is administered by the WDNR. Therefore, the City must apply for and obtain coverage under the Wisconsin Pollutant Discharge Elimination System (WPDES) General Permit for Storm Water Associated with Land Disturbing Construction Activity (Permit No. WI-S067831-6) from WDNR. This general permit regulates the discharges of pollutants to waters of the state as provided in Wis. Statutes, § 283.33, and Wis. Adm. Code subch. III of § NR 216.

The proposed project area is located within and adjacent to the Pheasant Branch Creek, which is regulated as a water of the United States and water of the state of Wisconsin under federal and state law. Pheasant Branch Creek is a 7-mile-long stream that drains 22.7 square mi. of west-central Dane County and is part of the Rock River and greater Mississippi River Watershed. The Pheasant Branch watershed has 145.61 stream mi., 9,959.08 lake ac., and 2,759.80 wetland ac. It begins in the glacial moraine area of the Town of Springfield, WI, and flows south and east through the City of Middleton, entering Lake Mendota on its western lobe. The North Fork drainage area is agricultural until its confluence with the South Fork at the western edge of the City of Middleton near U.S. Highway 12. Several portions of the creek have been straightened and most adjacent wetlands have been drained for agricultural and residential development. The creek is adversely influenced by poor base flow and excessive peak runoff, causing high sediment load that threatens remaining adjacent marsh areas. The main source of sediment is the erosion of unconsolidated, unstable glacial deposits at the creek's headwaters that is intensified by local land development.

As early as 1995, channel manipulation of Pheasant Branch Creek commenced with relocation of the South Fork of the creek from the city limits of Middleton to its confluence with the North Fork and construction of a detention pond which is a 22-ac. sedimentation basin with filtering system to reduce sedimentation influx. The goal of that project was to reduce extreme natural influences within the 100-year floodplain and improve flood control. The system was designed

with gabions running perpendicular to the flow to prevent streambank erosion and trap nutrients, sediment, and heavy metals before entering the pond (WDNR 2022b).

Pheasant Branch is classified as both Cool-Warm Headwater and Cool-Cold Headwater community-types under the WDNR's Natural Community Determinations. Cool (Warm-Transition) Headwaters are small, sometimes intermittent streams with cool to warm summer temperatures., Cool (Cold-Transition) Headwaters are small, usually perennial streams with cold to cool summer temperatures.

The USEPA defines "water quality" as "the condition of a water body as it relates to purposes such as recreation, scenic enjoyment, aquatic habitat, and human health." Water quality is regulated by both the CWA and Wisconsin State Statutes.

Stormwater runoff affects water quality in surface waters, such as Pheasant Branch Creek. The overall watershed in which the project area is located is predominantly rural with adjacent upland areas are in agricultural use. Contaminants, including eroded soils, fertilizers (synthetic and manure), herbicides, pesticides and road chemicals can be transported from adjacent farm fields and roads to the upper portion of the watershed and tributary creeks during storm events and flooding. Furthermore, the segment of Pheasant Branch Creek where the proposed project is located is the rapidly growing area of the City. Pollutants commonly found in urban stormwater runoff include sediment, nutrients, pesticides, wear metals, organic pollutants, and oil and grease (USEPA 2022a).

WDNR manages the Total Daily Maximum Load (TMDL) List and Inventory of Impaired Waters per Section 303(d) of the CWA. Water quality of Pheasant Branch Creek is negatively impacted by moderately high alkalinity and urban runoff flows containing significant amounts of sediments and phosphorus polluting and contributing to algae blooms. Also, unusually high levels of chloride are measured in the stream despite receiving no known point-source municipal or industrial discharges. WDNR considers Pheasant Branch Creek's general condition as poor and classifies the waterbody as impaired due to one or more pollutants and associated water quality impacts. The Pheasant Branch (805900, miles 0 - 8.09) segment of Pheasant Branch Creek has been on the Wisconsin's 303(d) impaired waters list since 1998 for non-compliant measurements of phosphorus and sediment. An additional listing for chloride was added in 2016. Assessments in 2018, 2020, and 2022 confirmed pollutants such as phosphorus, chloride, Total Suspended Solids (TSS)/sediment. Impairments include chronic aquatic toxicity, low dissolved oxygen (DO), degraded biological community, acute aquatic toxicity, and degraded habitat (WDNR 2022b, Figure 5). A TMDL Plan for phosphorus and TSS and an overall Water Quality Management Plan for Six Mile and Pheasant Branch Creeks Watershed was developed by WDNR and approved by USEPA in 2011.

The Pheasant Branch Creek basin is underlain by the Mount Simon aquifer. The Mt. Simon aquifer is the most important aquifer in Dane County for high-capacity municipal wells. The aquifer ranges in thickness from about 100 feet to over 700 feet, with an average thickness of 500 feet. This aquifer consists of sandstone in the Mt. Simon and lower Eau Claire Formations.

The lower boundary of the aquifer is Precambrian granite which is located about 1,0000 feet below the land 's surface. Impermeable shale in the Eau Claire formation forms the upper boundary. This layer is thicker in the western portion of the county. Because the Mt. Simon aquifer is bounded by relatively impermeable layers, it is called a confined aquifer and its contents can be under pressure.

Figure 5: Impaired Waterways



Pheasant Branch Greek Trail, Bridges, and Streambank Restoration Project Deming Way to North of Century Avenue

DR-4402-WI Project #88229 PW 593



The WDNR evaluated groundwater pollution sensitivity within the Pheasant Branch Creek watershed and determined that it has a medium susceptibility for groundwater contamination based on WDNR groundwater susceptibility mapping (WDNR 2015a).

Alternative 1 - No Action

Under the No Action alternative, erosion of the creekbanks of Pheasant Branch Creek will continue, causing moderate long-term impacts on water quality because of sedimentation and increased turbidity of the stream and Lake Mendota. Flooding would continue to threaten the structural stability of roadway and pedestrian bridge crossings. Possible failure of roadway and pedestrian bridge crossings and resulting soil disturbance would cause soil and construction debris to wash downstream, further impacting water quality.

The No Action Alternative would have no impact on any surface water pollutant conditions, or groundwater or drinking water resources.

Alternative 2 - Proposed Action

The Proposed Action would have moderate short-term adverse impacts on water quality associated with construction activities and an increased risk of erosion. During construction, exposed soil is vulnerable to erosion by wind and water. Eroded soil endangers water resources by reducing water quality and causing the siltation of aquatic species habitat. Clearing and grading during construction would cause the temporary loss of vegetation and exposure of soil to the elements. For all in-stream work, construction will occur from upstream to downstream to minimize effects on completed work. Impacts on water resources and water quality from construction runoff would be minimized with the implementation of Best Management Practices (BMPs). In-channel work will be performed in a manner to minimize siltation into the stream by performing heavy equipment operations from outside of the stream as much as feasible. All exposed creekbank grading and re-sloping areas will be revegetated by installation of soil erosion control blankets and seeding with a native seed mix.

To mitigate potential impacts from erosion during construction, the City must apply for and obtain coverage under the WPDES General Permit for Storm Water Associated with Land Disturbing Construction Activity (Permit No. WI-S067831-6) from the WDNR. The general permit requires the permittee to implement BMPs to control storm water runoff in accordance with site-specific erosion control and storm water management plans to reduce sediment and other pollutants from entering waters of the state. Waters of the state include surface waters, groundwater, and wetlands.

The Proposed Action would have moderate long-term benefits to surface water resources and water quality. The stream stabilization and in-channel work would improve water quality in the creek watershed and the downstream watershed by reducing erosion and sedimentation. The City specifically designed the project to incorporate Nature Based Solutions as opposed to hard armoring to improve the water quality and water habitat. Placement of in-channel natural stone vanes and riffle structures will reduce shear stress minimizing the size and volume of the creekbank protection needed. These structures provide benefits for both bank protection and aquatic habitat. Constructed riffles and stone vanes modify stream flow, increasing variability of flow conditions and microhabitats for fish. In-channel stone structures will also improve conditions necessary for colonization by macroinvertebrates and provide benthic habitat for small fish. Additionally, the Proposed Action would reduce the likelihood of failure of roadway and pedestrian bridge crossings, that would result in soil disturbance, and soil and construction debris washing downstream, preventing those potential adverse impacts to water quality.

To support this work, the City applied for authorization from the USACE to permanently discharge fill material below the Ordinary High Water Mark of Pheasant Branch Creek. The St. Paul District authorized the discharge on June 21, 2001, under Nationwide Permit No. 13, Bank Stabilization (File No. MVP-2021-00848-SJW). The regulated activities associated with this project include the permanent discharge of fill material (rock riprap) below the plane of the

OHWM along 3,935 linear feet of Pheasant Branch. In addition, the project would include the permanent discharge of fill material below the plane of the OHWM onto 3,200 square feet (0.07 acre) of aquatic bed for the installation of toe wood/root wad structures, five boulder clusters, two cross vane structures, and for repairs to one riffle structure. On June 23, 2021, the Wisconsin DNR issued Individual Permit No. IP-SC-2021-13-01703-04 for the bank stabilization and stream course changes proposed as part of this undertaking. On August 1, 2022, the Wisconsin DNR issued an acceptance of the Applicant General Permit Certification (GP-SC-2022-13-02398, 2408-12) regarding the placement of the 6 bridge spans.

The Proposed Action would have no impact on groundwater or drinking water resources.

3.2.3 Floodplain Management (Executive Order 11988)

Executive Order (EO) 11988, Floodplain Management, requires federal agencies to minimize occupancy and modification of the floodplain. Specifically, EO 11988 prohibits federal agencies from funding construction in the 100-year floodplain unless there are no practicable alternatives. FEMA's regulations for complying with EO 11988 are promulgated in 44 C.F.R Part 9. Based on those regulations, analysis through a Floodplain Management checklist is required. The eightstep decision-making process to ensure compliance with EO 11988 is provided in **Appendix D**.

The bank of Pheasant Branch Creek within the proposed project area has experienced significant erosion due to scouring during storm events and flooding. The current effective Flood Insurance Rate Map (FIRM) panels 55025C0382G and 55025C0401G, effective on 01/02/2009 (Figures 6-9) show the location of the proposed work in relation to and within the floodplain. The proposed project is completely located within the Zone AE, which is the designated Special Flood Hazard Area (SFHA) subject to inundation by the 100-year flood. In addition, all of the proposed channel work is located within the FEMA Regulatory Floodway. FEMA defines the Regulatory Floodway as the channel of a river or other watercourse and the adjacent land areas that must be reserved in order to discharge the base flood without cumulatively increasing the water surface elevation more than a designated height.

Figure 6: Flood Insurance Rate Map 1





Figure 7: Flood Insurance Rate Map 2



Pheasant Branch Creek Trail, Bridges, and Streambank Restoration Project – Deming Way to North of Century Avenue Final Environmental Assessment


To ensure an appropriate project design, a new model that utilized better topographic data and conveyance structure information as well as increased flow rates within the main stem was developed during the planning and design phase of this project. For purposes of this analysis, FEMA will consider this model the corrected effective model. At the time of the writing of this Environmental Assessment, the City is working with the DNR to approve the new model.

Coordination with the local floodplain administrator would be required to ensure compliance with local floodplain ordinances. All necessary floodplain permitting will be the responsibility of the City of Middleton, and any necessary floodplain permits will be obtained prior to construction. Floodplain permit responsibilities and mitigation requirements are detailed in **Section 6, Mitigation Measures and Permits**.

Figure 8: Flood Insurance Rate Map 3

Deming Way to North of Century Avenue DR-4402-WI Project #88229 PW 593

Figure 9: Flood Insurance Rate Map 4



Alternative 1 - No Action

The No Action alternative would cause no short-term impacts to the floodplain because no construction activities or other direct modification of the floodplain would occur. However, moderate long-term impacts to the floodplain from continued erosion, bank destabilization and collapse of additional cutbanks and trees into Pheasant Branch Creek bank will occur.

Action Alternative 2 - Proposed Action

Portions of the construction activities of the Proposed Action will take place within the Regulatory Floodway. Although the project engineer finds that the project itself will not increase Base Flood Elevations, there are locations within the Pheasant Branch where corrected effective BFEs are higher due to an increase in the flow rate. To reduce future damage to the pedestrian bridges within the project area, the following universal measures will occur:

- 1. The bridges will all now be supported by concrete abutments placed on helical piles.
- 2. The channel section under each bridge will be excavated to provide additional flow area. This typically includes riprap slopes to the channel bottom. The riprap berm slopes are as steep as standards allow. Areas of excavation as well as the reconstructed bridge abutments are to be protected from erosion by riprap.
- 3. Bridge deck elevations will be raised to provide one foot of freeboard between the bridge's low chord at the abutment relative to 100-yr headwater elevations. The raising of the bridge decks requires changes to the bridge approaches which were designed at a maximum 12:1 slope (maintaining existing). Collectively this changes

the balance between the portion of flood flow that passes under each bridge and the flood flow that passes through the floodplain valley. This typically raises the bridge flow velocity some. However, in certain locations, additional modifications will be necessary with regard to the bridge alignments, but in general these are within a few feet of existing positions.

In addition, the project proposes use of numerous bio-engineering techniques to stabilize the banks to reduce the future risk of flood damage to the existing trail system.

The Proposed Action would result in minor short-term impacts on the floodplain because of soil disturbance by excavation and other heavy equipment and the removal of vegetation in the mapped floodplain. There would be moderate long-term benefits resulting from reduced erosion and improved stability of the creek channel.

3.2.4 Air Quality

The Clean Air Act (CAA), 42 U.S.C. §§ 7401 *et seq.*, requires the USEPA to set National Ambient Air Quality Standards (NAAQS) for pollutants considered harmful to public health and the environment. The CAA established two types of national air quality standards. Primary standards set limits to protect public health, including the health of sensitive populations such as asthmatics, children, and the elderly. Secondary standards set limits to protect public welfare, including protection against decreased visibility and damage to animals, crops, vegetation, and buildings. Current criteria pollutants are carbon monoxide (CO), nitrogen dioxide (NO₂), ground-level ozone (O₃), lead (Pb), particulate matter (PM), and sulfur dioxide (SO₂).

Federally funded or permitted actions in nonattainment and maintenance areas are subject to USEPA conformity regulations, 40 C.F.R. §§ 51 and 93. The air conformity analysis process ensures that emissions of air pollutants from planned federally funded and permitted activities would not affect the state's ability to achieve the CAA goal of meeting the NAAQS. Section 176(c) of the CAA requires that federally funded or permitted projects must not cause any violations of the NAAQS, increase the frequency or severity of NAAQS violations, or delay timely attainment of the NAAQS or any interim milestone. Activities that would cause emissions to exceed the NAAQS or cause an area to fall out of attainment status would be considered a significant impact. The emissions from construction activities are subject to air conformity review.

Under the general conformity regulations, a determination for federal actions is required for each criteria pollutant or precursor in nonattainment or maintenance areas where the action's direct and indirect emissions have the potential to emit one or more of the six criteria pollutants at rates equal to or exceeding the prescribed *de minimis* rates for that pollutant. The prescribed annual rates are 50 tons of volatile organic compounds (VOCs) and 100 tons of nitrogen oxides (NO_X) (O₃ precursors), and 100 tons of PM_{2.5}, SO₂, or NO_X (PM_{2.5} and precursors).

An area is classified as nonattainment when it does not meet NAAQS standards. According to USEPA's NAAQS county attainment record, Dane County is in attainment for all NAAQS criteria pollutants (USEPA 2022b).

Alternative 1 - No Action

Construction activities would not occur under the No Action alternative. Public use of existing recreation trails and pedestrian bridges would remain reduced because they have only been repaired to meet minimal safety purposes. This would have a minor long-term negative impact on air quality due to decreased opportunities for commuting by walkers or bicyclists and the resultant increase in emissions from motor vehicles used as a local commuting alternative.

Action Alternative 2 - Proposed Action

The Proposed Action would have minor short-term impacts on air quality because of the use of construction equipment with diesel and gasoline engines. During the construction phase, exposed soil could temporarily increase airborne particulate matter into the project area. Emissions from construction equipment could have minor temporary effects on the levels of some pollutants, including CO, VOCs, NO₂, O₃, and PM. Emissions would be temporary and localized, and only minor impacts to air quality in the project area would occur. BMPs and mitigation measures for air quality impacts are provided in **Section 6.2**.

The returned availability of fully repaired pedestrian trails and bridges to walking and bicycling commuters will reduce emissions from motor vehicles used as a local commuting alternative. Creekbank stabilization of this segment of Pheasant Branch Creek assures that the repaired pedestrian trail system will remain usable into the future, providing minor long-term benefits to air quality through a continuing reduction of local commuting motor vehicle emissions.

The Proposed Action will have no long-term adverse impacts on air quality, and an air permit will not be required.

3.3 Biological Environment

3.3.1 Terrestrial and Aquatic Environment

Most of the land (approximately 76 percent) in Dane County consists of agricultural land uses. However, the proposed project area is located within the urban portion of the City of Middleton. While the area surrounding the proposed project area is predominantly developed urban space comprised of streets and commercial and residential structures, areas along Pheasant Branch Creek include riverine open water, wetlands, shrub/grassland, and forested zones. Most of the Pheasant Branch Creek corridor and floodplain slopes are dominated by forested overstory with a mostly closed tree canopy.

The immediate area of the proposed project is zoned for conservation and are public lands owned by the City of Middleton. The proposed project area is managed to maintain or improve natural vegetation, habitat, water quality, and passive recreation.

Aquatic habitat in the project area includes Pheasant Branch Creek and creekbank areas, and adjacent lowland/wetland areas subject to periodic flooding. Pheasant Branch Creek is a spring and run-off fed 7-mi.-long stream that drains 22.7 square mi. of west-central Dane County. Downstream of the confluence of the North and South forks at the western edge of the City of

Middleton, the stream passes through the city and project area with a fairly steep gradient until it enters Pheasant Branch Marsh just upstream of its mouth at Lake Mendota. Much of the creek has been straightened and most adjacent wetlands have been drained for agricultural and residential development (WDNR 2022b). One important wetland that remains largely intact is the 311-ac. Pheasant Branch Marsh just downstream of the proposed project area (Day, et al. 1985). The proposed project area segment of Pheasant Branch has been on the State of Wisconsin's 303(d) impaired waters list since 1998 (WDNR 2022b).

Within the proposed project area, the Pheasant Branch Creek fishery consists of tolerant forage fish upstream of the Pheasant Branch Marsh. Downstream of the proposed project area, from the marsh to Lake Mendota, a diverse warm water fishery exists. Northern pike (*Esox lucius*) have used the marsh as a spawning site, but sediment carried by the proposed project area and upstream is impairing this fishery use (WDNR 2022b). Known fish species in Pheasant Branch Creek include bowfin (*Amia calva*), northern pike, northern pike x muskie (*Esox lucius* x *masquinongy*), common carp (*Cyprinus carpio*), southern redbelly dace (*Chrosomus erythrogaster*), fathead minnow (*Pimephales promelas*), blacknose dace (*Rhinichthys atratulus*), creek chub (*Semotilus atromaculatus*), white sucker (*Catostomus commersonii*), bullhead (unsp.), brook stickleback, crappie (unsp. Ictalurid), pumpkinseed (*Lepomis gibbosus*), blueglll (*Lepomis macrochirus*), largemouth bass (*Micropterus salmoides*), and walleye (*Sander vitreus*). (Day, et al. 1985).

The majority of the terrestrial habitat of the proposed project area (Parmenter Drive to the project terminus north of Century Drive) consists of river bottom forests with pine and northern hardwood forests along slopes, interspersed with smaller areas of sand prairie and emergent wetland. River bottom forest consists of tree species such as silver maple (*Acer saccharinum*), Tamarack (*Larix laricina*), and cottonwood (*Populus* sect. *Aigeiros*), with subcanopy trees such as willows (*Salix* spp.), green ash (*Fraxinus pennsylvanica*), hackberry (*Celtis occidentalis*), American elm (*Ulmus americana*), and boxelder (*Acer negundo*). Pine and northern hardwood land cover includes white pine (*Pinus strobus*) and red pine (*Pinus resinosa*), northern pin oak (*Quercus ellipsoidalis*), black oak (*Quercus velutina*), northern red oak (*Quercus rubra*), white oak (*Quercus alba*), bur oak (*Quercus macrocarpa*), sugar maple (*Acer saccharum*), green ash, black ash (*Fraxinus nigra*), red elm (*Ulmus rubra*), and birch (*Betula* spp.).

The proposed project area from Deming Way to Parmenter Drive is mostly open and surrounded by development and major roads. That segment is dominated by invasive herbaceous plants such as reed canary grass (*Phalaris arundinacea*) and shallow rooted trees such as willow, boxelder and silver maple (CARDNO 2020).

The Pheasant Branch creek corridor is home to a diverse array of mammals, insects, and birds that depend on the variety of habitats present along the creek. The Friends of Pheasant Branch Conservancy guides to Birds, Mammals, and Butterflies were used to match species with habitat types within the project area (UW – Madison 2019, Watermolen et al. 2003, Watermolen et al. 2005, Watermolen 2005).

According to the Birds of Pheasant Branch Conservancy Guide (Watermolen et al. 2003), over 191 bird species have been spotted along the Pheasant Branch Creek corridor and in the Conservancy. Woodpeckers, great-horned owls (*Bubo virginianus*), barred owls (*Strix varia*), and chimney swifts (*Chaetura pelagica*) nest in large cavities of trees. Wood thrushes (*Hylocichla mustelina*) and wood-warblers including Cerulean warblers (*Dendroica cerulea*), common yellowthroat (*Geothlypis trichas*), and Blackburnian warblers (*Dendroica fusca*) utilize forest habitat. The emergent wetlands are used by waterfowl (*Anseriformes*), sandpipers (*Scolopacidae*), and heron (*Ardeidae*).

River bottom forests of the Pheasant Branch Creek corridor provide habitat to a wide array of mammals including bats, coyotes (*Canis latrans*), grey fox (*Urocyon cinereoargenteus*), red fox (*Vulpes vulpes*), deer (*Cervidae*), weasels (*Mustela spp.*), beaver (*Castor canadensis*), groundhog (*Marmota monax*), muskrat (*Ondatra zibethicus*), squirrels (*Sciuridae*), and mice (*Dasyuridae*). (Watermolen 2005). Finally, the flowering plants of the river bottom forest provide habitat for dragonflies (*Anisoptera*) and butterflies (*Rhopalocera*). Eastern Tiger Swallowtail (*Papilio polyxenes asterius*) and Spring Azure (*Celastrina ladon*) are examples of butterflies that use habitat in the corridor.

In general, the creek corridor is important for pollinators, with over 58 species of butterflies recorded in the area (Watermolen et al. 2005). Dragonflies and Eastern Tiger Swallowtail, Spring Azure, Monarch (*Danaus plexippus*) and Painted Lady (*Vanessa cardui*) butterflies take advantage of the many flowering plants present from spring until fall.

Alternative 1 - No Action

Under the No Action alternative, there would be moderate long-term, adverse impacts on the terrestrial and aquatic environment resulting from continued erosion of the creekbank adjacent to Pheasant Branch Creek. This is a naturally occurring process which will damage and destroy adjacent terrestrial areas while degrading the aquatic environment because of additional sediment loads contributing to high turbidity.

Alternative 2 - Proposed Action

The Proposed Action would cause minor short-term impacts on terrestrial and aquatic habitat, such as soil disturbance, removal of vegetation, and potential sediment runoff while construction activities are occurring. The Proposed Action will cause minor long-term impacts on terrestrial habitat through the removal of some mature trees and shrubs, and the permanent loss of some forested areas. All disturbed areas where grading and re-sloping would occur will be seeded with a native seed mix, resulting in a moderate long-term benefit.

3.3.2 Wetlands (EO 11990)

EO 11990, Protection of Wetlands, requires federal agencies to take action to minimize the loss of wetlands. FEMA regulation 44 C.F.R. Part 9, *Floodplain Management and Protection of Wetlands*, sets forth the policy, procedures, and responsibilities to implement and enforce EO 11990. EO 11990 prohibits FEMA from funding activities in a wetland unless no practicable

alternatives are available. The NEPA compliance process requires federal agencies to consider direct and indirect impacts on wetlands which may result from federally funded actions. Based on the requirements of 44 C.F.R. Part 9, a Floodplain Management Checklist to ensure compliance with EO 11990 is required (**Appendix D**).

USACE and USEPA define wetlands as "areas that are inundated or saturated by surface or groundwater at a frequency and duration sufficient to support, and that under normal circumstances do support, a prevalence of vegetation typically adapted for life in saturated soil conditions" (40 C.F.R. § 122.2). In 2008, USEPA and the USACE, through joint rulemaking, expanded the Clean Water Act (CWA) Section 404(b)(1) Guidelines to include more comprehensive standards for compensatory mitigation. The rule addresses the sequence for mitigating unavoidable impacts to aquatic resources that result from work authorized by permits under the Corps' (USACE) Regulatory Program. Activities that disturb jurisdictional wetlands require a permit from USACE under Section 404 of the CWA of 1977 (33 U.S.C. § 1344). Permit applicants are required to describe how they will avoid, minimize, and compensate for impacts to waters of the United States. Compensatory mitigation for unavoidable impacts is required to replace the loss of wetland, stream, and/or other aquatic resource functions.

The U.S. Fish & Wildlife Service's (USFWS) National Wetlands Inventory (NWI) was reviewed to identify potential wetlands in the project area (USFWS 2022a). The wetlands classifications of Pheasant Branch Creek were reviewed in more detail utilizing the Surface-water Data Viewer of the Wisconsin Department of Natural Resources (WDNR-SWDV 2022) and descriptions of the NWI codes (USFWS 2022a). The NWI classifies the Pheasant Branch Creek as Riverine habitat with applicable codes PEM1A, PEM1C, PFO1A, PFO1B, PFO1Bd, PFO1C, PSS1/EM1Bd, PUBG, PUBKr, and R2UB2H (for NWI Code definitions, see **Appendix D**). **Figure 10**, below, depicts the NWI wetlands within the project area.

Figure 10: Wetlands



This type of forested wetland is dominated by trees, shrubs, persistent emergent, emergent mosses, or lichens. Woody vegetation is 6 m. (19.8 ft.) tall or taller, consisting of woody angiosperms (trees and shrubs) with relatively wide, flat leaves that are shed in the cold or dry season. Surface water is present for brief periods (several days to several weeks) during the growing season, but the water table usually lies well below the ground surface most of the season.

Alternative 1 - No Action

Under the No Action alternative, there would be no project-related short- or long-term impacts on the identified wetlands because there would be no construction activities. Natural erosion would be expected to continue, adding sediment to Pheasant Branch Creek and Lake Mendota, contributing to high turbidity. Some of this material would likely be deposited in wetland areas alongside the river channel.

Alternative 2 - Proposed Action

The Proposed Action would result in minor short-term impacts to project area wetlands. These activities would disturb creekbank soils during removal of damaged infrastructure, grading/re-

sloping of creekbanks, and in-channel work. Effective best management practices (BMPs) initiated during construction would decrease construction-related impacts below the level of significance. All disturbed areas will have erosion control blankets installed and be seeded with a native seed mix to stabilize soils. Coordination with the USACE has resulted in the determination that the project will have no permanent impact on wetlands.

3.3.3 Threatened and Endangered Species

The Endangered Species Act (ESA) of 1973, 16 U.S.C. §§ 1531 - 1544, provides a framework for the conservation and protection of threatened and endangered species listed under the act in addition to their habitats. Federal agencies are required to ensure that actions they fund, authorize, permit, or carry out are not likely to jeopardize the continued existence of any listed species (including plant species) or result in the destruction or adverse modification of designated critical habitats for such species. In accordance with Section 7 of the ESA, the proposed project area was evaluated for potential impacts to listed threatened and endangered species.

In May 2021 and April 2022, via the USFWS Information for Planning and Consultation (IPaC) tool, FEMA obtained a list of species with the potential to occur in the project vicinity (**Appendix B**). The official species list included no designated critical habitat in the project area. The species list did identify one listed mammal – the northern long-eared bat (NLEB) (*Myotis septentrionalis*), one listed bird – the whooping crane (*Grus americana*), one listed insect – the rusty patched bumble bee (*Bombus affinis*), and three listed plants – the eastern prairie fringed orchid (*Platanthera leucophaea*), Mead's milkweed (*Asclepias meadii*), and the prairie bush-clover (*Lespedeza leptostachya*) as potentially occurring in the project area.

Northern Long-Eared Bat (threatened):

The threatened NLEB is a medium-sized bat found across much of the eastern and north central United States and all Canadian provinces from the Atlantic coast west to the southern Northwest Territories and British Columbia. NLEB are found throughout the state of Wisconsin, but they are never abundant (Jackson 1961, WDNR 2015b). The NLEB has been affected by white-nose syndrome (WNS), a fungal disease known to cause mortality due to increased arousals during torpor, which deplete fat reserves and cause starvation (Reeder et al. 2012) and dehydration (Cryan et al. 2010). Range wide, population sizes of NLEB have declined by more than 90% at monitored hibernacula within the decade since WNS affected this species (Cheng et al. 2021). As of March 2015, WNS has been confirmed in five counties in Wisconsin, and the fungus that causes WNS (*Pseudogymnoascus destructans*, [Lorch et al. 2011, Minnis and Lindner 2013]) has been discovered in an additional three counties (WDNR 2017a). Additional threats to NLEB include mortality from impacts to hibernacula (caves and mines), loss or degradation of summer roosting and foraging habitat, and wind farm operation.

During summer months, the NLEB often roosts under bark close to the tree trunk, cavities, or in crevices of both live and dead tree species such as maples, oaks, and ashes (Foster and Kurta

1999, WDNR 2015b). NLEB prefer to roost in tall trees with a dynamic forest structure including old growth and some young trees (Foster and Kurta 1999).

Suitable summer habitat for this species is defined by the USFWS as a wide variety of forested/wooded habitats where NLEB roost, forage, and travel and may also include some adjacent and interspersed non-forested habitats such as emergent wetlands and adjacent edges of agricultural fields, old fields and pastures. This includes forests and woodlots containing potential roosts (i.e., live trees and/or snags ≥ 3 in. diameter at breast height (dbh) that have exfoliating bark, cracks, crevices, and/or cavities), as well as linear features such as fencerows, riparian forests, and other wooded corridors. These wooded areas may be dense or loose aggregates of trees with variable amounts of canopy closure. NLEB seem to prefer intact mixed-type forests with small gaps (i.e., forest trails, small roads, or forest-covered creeks) in forest with sparse or medium vegetation for foraging and commuting rather than fragmented habitat or areas that have been clear cut. Individual trees may be considered suitable habitat when they exhibit characteristics of suitable roost trees and are within 1,000 ft. of other forested/wooded habitat. NLEBs typically occupy their summer habitat from mid-May through mid-August each year and the species may arrive or leave some time before or after this period (USFWS 2022b).

The USFWS listed NLEB as a threatened species under the ESA in April 2015. On January 14, 2016, the USFWS published a final 4(d) rule in the Federal Register, establishing prohibitions that focus on protecting the bat's sensitive life stages in areas affected by WNS which went into effect on February 16, 2016. For all areas within the range of the NLEB, nearly all purposeful take is prohibited with a few specific exceptions. For areas of the country not affected by WNS, there are no prohibitions on incidental take. For areas of the country impacted by WNS (Dane County, WI included), incidental take is prohibited under the following circumstances: if it occurs within a known hibernaculum, if it results from alteration of a known hibernaculum's entrance or interior environment, if it results from tree removal activities and the activity occurs within 0.25 mi. of a known hibernaculum; or, the activity cuts or destroys a known, occupied maternity roost tree or any other trees within a 150-ft. radius from the maternity roost tree during the pup season from June 1 through July 31 (USFWS 2015).

On March 23, 2022, the USFWS published a proposed rule to reclassify the NLEB as an endangered species instead of its current listing as threatened. If the USFWS publishes a final rule listing the NLEB endangered as proposed, the species specific 4(d) rule would be nullified because 4(d) rules are only allowable for species listed as threatened. However, as of this time the 4(d) rule published in 2016 remains valid (USFWS 2022c).

Whooping Crane (endangered):

A nonessential experimental population of the endangered whooping crane has been established in Wisconsin. For the purposes of ESA section 7(a)(2), if any designated nonessential experimental population is located outside of a National Wildlife Refuge or National Park, they are treated as a species proposed for listing, and the agency is not required to consult with the USFWS.

Rusty Patched Bumble Bee (endangered):

The endangered Rusty Patched Bumble Bee (RPBB) is a social species that experienced a widespread and steep decline since its listing in 2017. Historically, the RPBB was broadly distributed across the eastern United States and the upper Midwest as well as southern Quebec and Ontario, Canada. The exact cause of the decline is unknown, but evidence suggests a synergistic interaction between an introduced pathogen and exposure to pesticides, specifically insecticides and fungicides. Remaining populations are exposed to several interacting stressors, including pathogens, pesticides, habitat loss and degradation, non-native and managed bees, the effects of climate change and small population biology. These stressors likely operate independently and synergistically. For example, dietary stress due to insufficient floral resources may reduce an individual's resiliency to pathogens and pesticides, exposure to insecticides can reduce resistance to disease and exposure to fungicides can increase insecticide toxicity. Survival and successful recruitment require floral resources (for food) from early spring through fall, undisturbed nest sites in proximity to foraging resources, and overwintering sites for the next year's queens (USFWS 2016).

The RPBB has been observed and collected in a variety of habitats, including prairies, woodlands, marshes, agricultural landscapes, and residential parks and gardens (Colla and Packer 2008, Colla and Dumesh 2010). RPBB requires areas that support sufficient food (nectar and pollen from diverse and abundant flowers), undisturbed nesting sites in proximity to floral resources, and overwintering sites for hibernating queens (Goulson et al. 2015, Potts et al. 2010).

RPBB suitable habitat can be divided into nesting and wintering based on the species life cycle and availability of nectar and pollen resources. The former corresponds to the RPBB active season and the latter to RPBB winter hibernation period. Nesting habitat can include upland grassland and shrublands with presence of forage and as far as 30 meters into the edges of forest and woodlands where they interface with upland grassland and shrublands (USFWS 2019b). Typically, bumble bees forage within a few hundred meters of their nest with maximum forage distance of about one kilometer (Knight et al. 2005). Wintering habitat can include upland forest and woodlands with undisturbed soil (USFWS 2019b).

Eastern Prairie Fringed Orchid (threatened):

The threatened Eastern Prairie Fringed Orchid (EPFO) is a showy orchid species with populations in Illinois, Indiana, Iowa, Maine, Michigan, Missouri, Ohio, Virginia, and Wisconsin (USFWS 2021a). As of 2020, ninety-six populations were known to exist throughout the entire range of the species; seventeen populations (six are highly viable) are located within fourteen counties of Wisconsin, including Dane County. (USFWS 2021a, WDNR 2022c). The main threats to the EPFO are the lack of land management of high-quality wetland habitats on which this species depends, including increased development, spread of exotic species, and fire suppression.

In Wisconsin, EPFO are found in moist, undisturbed, deep-soiled and/or calcareous prairies and rarely in tamarack fens (WDNR 2022c). This species is associated with Bog Relict or more commonly Wet-mesic Prairie natural communities in Wisconsin which sometimes occurred in

large wetland complexes with wet prairies, southern sedge meadows, calcareous fens, and emergent marshes (WDNR 2022c). Wet-mesic Prairies are most abundant on level or gently rolling glacial moraine or outwash landforms where there are few natural barriers to wildfire, and where the upland vegetation is composed mostly of fire-dependent communities such as Mesic Prairies and oak openings (WDNR 2022c). EPFO requires full sun for optimum growth and flowering along with a grassy habitat with little or no woody encroachment.

Mead's Milkweed (threatened):

The threatened Mead's Milkweed is long-lived perennial herb with an 8-16 in. tall single stalked plant topped with a solitary umbel of 6-15 greenish, cream-colored flowers. This species is threatened by habitat fragmentation and destruction by historic conversion to agriculture and current land development.

Mead's milkweed requires a moderately wet (mesic) to moderately dry (dry mesic) upland tallgrass prairie or glad/barren habitat characterized by vegetation adapted for drought and fire, and the plant will persist in stable late-successional prairie (USFWS 2003). As of 2003, Mead's milkweed had been extirpated from Wisconsin, with restoration and reintroduction efforts being underway (USFWS 2003). All Mead's milkweed sites in Wisconsin are reintroduction attempts and occur on protected conservation lands (WDNR 2015b).

Prairie Bush-Clover (threatened):

The threatened prairie bush-clover is a long-lived, dry-prairie plant that can grow to 3 ft. in height. Main threats to the species include the conversion of remnant prairie to cropland or developed sites, spread of non-native invasive plant species, the encroachment of dominant vegetation, prolonged drought, and hybridization. (USFWS 1988, USFWS 2021b).

Prairie bush-clover occurs on remnant prairie sites and disturbed sites, or prairie habitats that have been previously mowed, burned, cultivated, or grazed (USFWS, 1988). In Wisconsin, the prairie-bush clover can be found in gravelly or sandy hillside prairies and has a significant association with Dry Prairie and Dry-mesic Prairie natural communities, and a moderate association with Mesic Prairie natural communities (WNDR 2020).

State Listed Species:

In June 2022, the Wisconsin DNR Endangered Resource Review (ERR) results recommended additional conservation measures for state-listed species. The measures listed below are voluntary, and FEMA will encourage the applicant to consider these measures. In order to best facilitate compliance with these measures, FEMA will provide the applicant a copy of the ERR.

- Natural Communities:
 - Stream fast, hard, warm
 Implement erosion control measures; implement invasive species BMPs.
 - Springs and spring runs
 Implement erosion control measures; implement invasive species BMPs.
- State Special Concern:

- Swamp Darner (Epiaeschna heros)
 It is recommended to implement erosion and runoff prevention measures and to minimize shoreline disturbance during the flight period, early-June to late-July.
- Lake sturgeon (*Acipenser fulvescens*)
 It is recommended to implement erosion and runoff prevention measures throughout the duration of the project.
- Blanding's turtle (*Emydoidea blandingii*)
 Minimize the disturbance to water bodies with standing water at least three feet deep at all times. For wetlands / water bodies shallower than three feet at the deepest point, conduct work outside of the March 5 November 15. Avoid work in sandy and/or well-drained soils within 275 m (900 ft) of a wetland or water body from May 20 October 15.

The installation and maintenance of exclusion fencing using the WDNR Amphibian and Reptile Exclusion Fencing Protocol is an avoidance option that can be used during this period as long as the exclusion fencing is installed between October 16 and May 19. Work can then be conducted within the fenced area at any time of year as long as the fencing is maintained.

If avoidance dates and fencing cannot be implemented, it is recommended to walk through or gently disturb the project area immediately prior to disturbance. While this will not protect nests, it may allow turtles to move out of the area and avoid take. If a turtle is found, please carefully move it to suitable habitat outside the project area.

Pickerel Frog (Lithobates palustris)
 Recommended avoidance and minimization efforts include 1) conducting work when the pickerel frog is active and not breeding (September 1 - October 31), 2) conducting site surveys to confirm presence/absence of the species or 3) avoiding/minimizing impacts to areas of suitable habitat. It is also recommended to implement erosion and runoff prevention measures.

State Threatened:

Little brown bat (*Myotis lucifugus*)
 Avoid tree removal from June 1 – August 15.

Alternative 1 - No Action

Under the No Action alternative, no construction or habitat modification would occur; therefore, that alternative would not directly impact federally listed threatened or endangered species.

Alternative 2 - Proposed Action

Tree-clearing would occur to allow workspace for creekbank stabilization work, and some felled trees from that work will be used as log material for toewood-sod mat and root wad structures. NLEB are known to make use of tree roosts during the summer, especially near water sources.

Loose bark, broken tree limbs, cavities, and cracks in a tree can all be used by bats as roosting sites. The removal of upland trees could remove existing or potential bat summer roosting sites. This would be considered a minor, permanent impact to a threatened species.

On June 3, 2022, FEMA submitted the NLEB 4(d) IPaC key. This IPaC key assists users in determining whether a Federal action is consistent with the activities analyzed in the Service's January 5, 2016, Programmatic Biological Opinion (PBO).

The June 3, 2022, verification letter (**Appendix B**) states in part, this Federal Action may affect the northern long-eared bat in a manner consistent with the description of activities addressed by the Service's PBO dated January 5, 2016. Any taking that may occur incidental to this Action is not prohibited under the final 4(d) rule at 50 C.F.R. §17.40(o). Therefore, the PBO satisfies the subrecipient's responsibilities for this Action under ESA Section 7(a)(2) relative to the northern long-eared bat

This Proposed Action is not located within a National Wildlife Refuge or National Park; therefore, FEMA has no requirement to consult with the USFWS on potential project impacts to whooping cranes under section 7(a)(2).

The proposed project area overlaps the RPBB High Potential Zone (HPZ). Therefore, the RPBB can be assumed present in suitable habitat. FEMA does not anticipate any work to occur within RPBB nesting habitat as work will primarily be concentrated to streambanks, recreational trails, or maintained park areas. The Proposed Action would take place within bottomland and sloped upland forest, but areas proposed for repair are already disturbed recreational trails and creekbanks that have been previously bioengineered with the most recent work being completed in 2015 and 2018. During those previously completed projects, the creekbanks were cleared, grubbed, graded, and seeded. The goal of this project is to reduce overbank flooding and erosion to ensure long-term sustainability of the project area. USFWS has provided concurrence with FEMA's determination that the Proposed Action is not likely to adversely affect the RPBB (Appendix B). FEMA will require certain conservation measures as outlined in the Conservation Management Guidelines for the Rusty Patched Bumble Bee (Bombus affinis) document.

(https://www.fws.gov/midwest/endangered/insects/rpbb/pdf/ConservationGuidanceRPBBv1_2 7Feb2018.pdf).

These conservation measures include but are not limited to:

- Implement best management practices (BMPs), especially those that serve to minimize the spread of invasive species and to avoid or minimize soil compaction.
- Avoid or minimize soil disturbance and heavy equipment operation during overwintering (mid-October through mid-March).
- Avoid or minimize forest management that may destroy spring blooming flowers during their bloom periods.

- Consider thinning or single tree selection and dense invasive shrub removal that may improve overwintering and spring foraging habitat.
- Use native trees, shrubs, and flowering plants in landscaping.
- Provide plants that bloom from spring through fall (refer to the USFWS RPBB Midwest Plant Guide).
- Remove and control invasive plants in any habitat used for foraging, nesting, or overwintering.

Because the Proposed Action will occur along the Pheasant Branch Creek corridor on creekbanks or existing asphalt and gravel pedestrian trails, that work would be outside of suitable habitat of the EPFO, Mead's Milkweed and the prairie bush-clover. Furthermore, review of site conditions following the 2018 flooding event show eroded soil and disturbed vegetation, reducing the likelihood that intact plant communities would remain established in the action area; therefore, the Proposed Action will have no effect on the EPFO, Mead's milkweed, and prairie bush-clover.

3.3.4 Migratory Birds

A migratory bird is any species or family of birds that live, reproduce, or migrate within or across international borders at some point during their annual life cycle. The Migratory Bird Treaty Act (MBTA) of 1918, as amended, 16 U.S.C. §§ 703–712, prohibits unpermitted killing, capturing, selling, trading, and transport of migratory birds and their nests, eggs, and body parts. Almost all native birds, including common species such as American robin (*Turdus migratorius*) and American crow (*Corvus brachyrhynchos*) are protected by the MBTA. The proposed project area would support protected migratory birds.

The Bald and Golden Eagle Protection Act (BGEPA) of 1940, 16 U.S.C. §§ 668 et seq., prohibits the unpermitted take (defined as pursue, shoot, shoot at, poison, wound, kill, capture, trap, collect, molest, or disturb), possession, sale, purchase, barter, offer to sell, transport, export, or import any golden (Aquila chrysaetos) or bald eagle (Haliaeetus leucocephalus), alive or dead, including any part, nest, or egg (16 U.S.C. § 668(a)). As of 2019, 13 occupied eagle nests (observed as repaired, an incubating adult, eggs or young present) were observed throughout Dane County but no known occupied bald eagle nests occur within one mi. of the Proposed Action area. (WDNR 2019).

The Wisconsin Breeding Bird Atlas (2022) lists 131 bird species identified within Dane County. The proposed project is located in the Pheasant Branch Creek corridor and river corridors are important habitat for many birds. USFWS's IPaC review (2021, 2022d) of the proposed project area identified the following 20 USFWS Birds of Conservation Concern (BCC) or species that warrant attention for legal or susceptibility to development impacts that could occur in this portion of the Pheasant Branch Creek corridor (**Table 3-3**). In Wisconsin, the bald eagle would be potentially present or breeding/fledging young from December through August, while the other migratory birds will be potentially present and/or breeding approximately late April through October (see **Appendix B** for related USFWS correspondence and IPaC results).

Table 3-3: USFWS Birds of Conservation Concern or That Warrant Attention Identified by IPaC That May Utilize the Proposed Project Area. Source: USFWS IPaC, 2021.

Common Name	Scientific Name	Estimated Breeding Season
American Golden-plover	Pluvialis dominica	Breeds Elsewhere
Bald Eagle	Haliaeetus leucocephalus	• Dec. 1 – Aug. 31
Black Tern	Chlidonias niger	• May 15 – Aug. 20
Black-billed Cuckoo	Coccyus erythropthalmus	• May 15 – Oct. 10
Bobolink	Dolichonyx oryzivorus	• May 20 - Jul. 31
Canada Warbler	Cardellina canadensis	• May 20 – Aug. 10
Cerulean Warbler	Dendroica cerulea	• Apr. 22 – Jul. 20
Eastern Whip-poor-will	Antrostomus vociferus	• May 1 – Aug. 20
Golden Eagle	Aquila chrysaetos	Breeds Elsewhere
Golden-winged Warbler	Vermivora chrysoptera	• May 1 – Jul. 20
Henslow's Sparrow	Ammodramus henslowii	• May 1 – Aug. 31
• Le Conte's Sparrow	Ammodramus leconteii	• Jun. 1 – Aug. 15
Lesser Yellowlegs	Tringa flavipes	Breeds Elsewhere
Long-eared Owl	Asio otus	• Mar. 1 – Jul. 15
Marbled Godwit	Limosa fedoa	• May 1 – Jul. 31
Red-headed Woodpecker	Melanerpes erythrocephalus	• May 10 – Sep. 10
Ruddy Turnstone	Arenaria interpres morinella	Breeds Elsewhere
Rusty Blackbird	Euphagus carolinus	Breeds Elsewhere
Short-billed Dowitcher	Limnodromus griseus	Breeds Elsewhere
Wood Thrush	Hylocichla mustelina	• May 10 – Aug. 31

Alternative 1 - No Action

The No Action alternative would not directly impact migratory birds because there would be no construction. Continued erosion of the creekbank would potentially cause undermining of adjacent tree root systems that could cause increased tree fall throughout the Pheasant Branch Creek corridor, affecting migratory bird habitat.

Alternative 2 - Proposed Action

The Proposed Action would have minor permanent impacts on migratory bird species through the removal of trees within the proposed work areas needed for creekbank stabilization and creek realignment which could serve as habitat for migratory birds. The native species seeding of all disturbed and graded areas could result in some benefit of expanded migratory bird habitat and native seed production.

There would be minor short-term impacts from construction activities that disturb birds within the project area. A BMP to avoid and minimize impacts on migratory birds is provided in **Section 6.2.**

3.3.5 Invasive Species

Executive Order 13112, Invasive Species, requires federal agencies to prevent the introduction of invasive species and provide for their control to minimize the economic, ecological, and human health impacts caused by invasive species. The State of Wisconsin has also created a law authorizing the WDNR to establish a statewide program to control the spread of invasive species and promulgate rules to identify, classify, and control invasive species through a statewide management plan (Wisconsin Statutes § 23.22 (2) (a, b) (2022)). The Invasive Species Identification, Classification, and Control Rule (WAC, Chapter NR 40 2022) creates a comprehensive, science-based system with criteria to classify invasive species in Wisconsin into two categories: "prohibited" and "restricted." With certain exceptions, the transport, possession, transfer, and introduction of prohibited species is banned. Restricted species are also subject to a ban on transport, transfer, and introduction, but possession is allowed, except for fish and crayfish.

Per the WDNR and Dane County, many invasive plants and animals are present in Dane County, most notably Eurasian water-milfoil (Myriophyllum spicatum), curly-leaf pondweed (Potamogeton crispus), purple loosestrife (Lythrum salicaria), zebra mussel (Dreissena polymorpha), rusty crayfish (Orconectes rusticus), Cylindro (Cylindrospermopsis raciborski), common carp (Cyprinus carpio), Phragmites (Phragmites australis), Japanese knotweed (Polygonum cuspidatum), narrow-leaf cattail (Typha angustifolia), hybrid cattail (Typha x glauca), watercress (Nasturtium officinale), water lettuce (Pistia stratiotes), and reed canary grass (Phalaris arundinacea) (WDNR, 2022; Dane County, 2009). Other aquatic invasive species of special concern that may be already present in the Great Lakes and their tributaries, other parts of Wisconsin or neighboring states that could invade Dane County but are not yet confirmed to be present include Hydrilla (Hydrilla verticillate), water hyacinth (Eichornia crassipes), Quagga mussels (Dreissena bugensis), New Zealand mud snails (Potamopyrgus antipodarum), spiny water fleas (Bythotrephes cederstroemi), fishhook water fleas (Cercopagis pengoi), water flea (Daphnia lumholtzi), bloody red shrimp (Hemimysis anomala), Chinese mystery snail (Cipangopaludina chinensis), gizzard shad (Dorosoma cepedianum), round gobies (Neogobius melanostomus), ruffe (Gymnocephalus cernuus), northern snakehead (Channa argus), bighead

carp (*Hypophthalmichthys nobilis*), silver carp (*Hypophthalmichthys molitrix*), and viral hemorrhagic Septicemia (an infectious disease of fish).

Lake Mendota, into which Pheasant Branch Creek drains, has observations of curly-Leaf pondweed, Eurasian water-milfoil, spiny water flea, water lettuce, and zebra mussel (WDNR 2022d). Invasive species observed specifically in Pheasant Branch Creek are curly-leaf pondweed and narrow-leaf cattail (WDNR, 2022b). Curly-leaf pondweed is known to occur at various study sites within the proposed project area, but narrow-leaf cattail has only been observed just upstream of, but outside of the work area (WDNR 2022e).

Alternative 1 - No Action

The No Action alternative would have no project-related impacts because construction would not occur. However, adverse impacts on the proposed project area from invasive plant species, including known populations of curly-leaf pondweed, would continue to persist in Pheasant Branch Creek.

Action Alternative 2 - Proposed Action

Proposed in-channel work such as creek bottom excavation, installation of stone riffle structures, and creek realignment, would provide a minor short-term benefit through direct destruction of known populations of the invasive curly-leaf pondweed if it occurs at the specific locations of those types of proposed work. However, the Proposed Action could have minor short-term negative impacts from the potential spread of invasive species caused by construction activities. The transport of curly-leaf pondweed, known to be present in Pheasant Branch Creek within the proposed project area, to non-infested work areas or other off-site waterbodies may occur if that aquatic invasive species remains viable on vehicles or heavy equipment removed from inchannel work areas and not properly drained of all water and decontaminated. Construction activities on land could result in the transport of reed canary grass, purple loosestrife, or other terrestrial invasive plant species from outside of the project area if attached to vehicles or heavy equipment not properly decontaminated prior to entry into the work area. Disturbed soils associated with both creekbank stabilization and the repair of recreational trails and pedestrian bridges present invasive plant seeds with an opportunity to germinate and become established. Permanent or temporary soil stabilization must be applied to all exposed areas within five days after final grade is completed. Soil stabilization that could include native vegetative establishment and mulching will be applied to denuded areas which may not be at final grade but will remain dormant (undisturbed) for longer than seven days.

BMPs to avoid and minimize the spread of invasive species to or from the proposed project area are provided in **Section 6.2**.

3.4 Hazardous Materials

Hazardous materials are any items or agents (biological, chemical, radiological, or physical) that have the potential to cause harm to humans, animals, or the environment either by itself or through interaction with other factors. Sites within or adjacent to the project area, regulated by

federal hazardous materials laws such as the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), 42 U.S.C. §§ 9601 - 9675, and the Resource Conservation and Recovery Act (RCRA), 42 U.S.C. §§ 6901 *et seq.*, were identified using the USEPA Enviro facts and NEPA assist websites (USEPA 2022c, USEPA 2022d).

Envirofacts and NEPAassist did not identify any regulated hazardous material sites within 0.5 miles of the project area.

Alternative 1 - No Action

The No Action alternative would have no effect on hazardous materials because no construction activities would occur.

Action Alternative 2 - Proposed Action

The Proposed Action would involve the use of construction equipment and creating a potential risk for minor short-term impacts from leaks of oils, fuels, and lubricants. The use of equipment in good condition and construction site hygiene and best practices, in accordance with state and local ordinances, would reduce any potential effects to an insignificant level. Other than hazardous materials associated with construction equipment, the Proposed Action would not involve the addition of any hazardous facilities, operations, materials, or chemicals to the site, nor would it increase the overall risk of hazardous materials known to already exist in the environment. However, potential for exposure of previously unknown contaminated materials within the project area exists because of excavation and removal of soil and construction debris.

Hazardous materials are not known to be present at concentrations that pose a risk to human health or the environment. The possibility exists that unknown source material at the site could be encountered or released. Such encounters, for example, could pose moderate short-term impacts to onsite workers through direct, dermal contact and inhalation of VOCs emanating from any potential source material, or a potential minor impact to the public near the site through inhalation of VOCs. One potential area for such contacts might be a landfill uncovered by the flooding, sited across the creek from work proposed on the north bank (43.103281, -89.508123). In May of 2022, the DNR and City finalized an investigation that found no additional work near the landfill was required beyond the streambank stabilization occurring in the area. A permit exemption package will be sent from the City to the DNR in June of 2022.

Contingency plans, in the form of design specifications, would be prepared if source material is encountered in any part of the project area and submitted to WDNR for approval. These specifications would detail the procedures that would be implemented by the subrecipient to identify, manage, and dispose of source material in accordance with applicable local, state, and federal regulations. If source material is encountered and removed, its removal would positively impact the project area by removing a source of contaminant loading to surface water or groundwater.

3.5 Socioeconomics

3.5.1 Zoning and Land Use

The Project Area is in the incorporated city limits of Middleton, Dane County, Wisconsin and is subject to the City of Middleton Comprehensive Plan (Land Use chapter), Dane County Comprehensive Plan (Chapter 8: Land Use), City of Middleton Zoning Ordinance, and City of Middleton Zoning Map (Figure 11). The Middleton Zoning Ordinance and Map specify the




Figure 11: City of Middleton Zoning Map

permitted and conditional land uses within the project area, while the Land Use chapter of the Middleton Comprehensive Plan guides policy decisions about the physical development of the city. These documents were used to evaluate the project's consistency with local zoning and land use.

According to the Middleton Zoning Map, the parcels north of Century Avenue and west of U.S. Highway 12 are a mix of residential and planned development districts where work is being done to the trails to provide connectivity to the main stem of Pheasant Branch Creek. The majority of the proposed project is located within parcels zoned as Lowland Conservancy (CO-L). The Middleton Zoning Ordinance specifies that this district encompasses lowland wetlands,

combined with lands on the edge or fringe of wetlands, permitted to be public or private parks and recreation areas, open space areas, outdoor education areas, historic, natural, and scientific areas, game refuges, fish and wildlife habitat improvement projects, game farms and wildlife preserves and temporary water storage facilities (City of Middleton 1984).

The City of Middleton Comprehensive Plan (2021) describes the analysis, priorities, future projections, goals, and strategies that the City of Middleton developed to guide how decisions will be made over the next two decades. The Plan set objectives and strategies for land use, transportation, housing, economic development, character, "green city," governance and partnerships, and implementation. The Land Use chapter proposes the establishment of a land use pattern that promotes compact development, protection of natural resources, a range of housing options, mobility, and economic growth to maintain an exceptional quality of life.

The City of Middleton has developed a guidance document, the Conservancy Lands Plan 2018-2023, to direct land stewardship activities on its Conservancy-zoned lands. Conservancy lands are public lands managed for natural vegetation, habitat, water quality and passive recreation. Although conservancy lands vary in size, use, vegetative communities, landscape features, and management priorities, most conservancies share some or all the following characteristics:

- Unique plant communities, wildlife, and/or geology.
- Ecological function, such as protecting water quality or preserving wildlife habitat.
- Maintained as natural area and restored to the native plant community.
- Provide opportunities for passive recreation, education, and volunteering.

Alternative 1 - No Action

The No Action alternative would have a moderate long-term adverse effect on conformity with the city's Land Use chapter of the Comprehensive Plan and Conservation Lands Plan because recreational trails and pedestrian bridges would remain damaged and provide limited recreational and transportation services to the public. Achievement of the plans' goals for lands zoned as Lowland Conservancy to provide an area managed for water quality, restoration of the native plant community, and passive recreation would not occur. However, the proposed project area would remain managed to support existing natural vegetation, education, volunteering, and wildlife habitat in their current state. The parcels would remain zoned as they currently are.

Action Alternative 2 - Proposed Action

The Proposed Action would provide long-term conformity with the city's Land Use chapter of the Comprehensive Plan and Conservation Lands Plan because recreational trails and pedestrian bridges would be returned to safe public use, providing long-term recreational and transportation services to the public. The Proposed Action would restore the Pheasant Branch Creek corridor to its public recreational function, reduce creek sedimentation by improving flood-protection and erosion reduction, and re-vegetate exposed soils with a native seed mix. Therefore, the Proposed Action achieves the goals of the city's plans and zoning because it restores native plant communities and improves water quality, passive recreation opportunities and transportation services. The parcels would remain zoned as they currently are.

3.5.2 Noise

The Noise Control Act of 1972 (42 U.S.C. §§ 4901, et seq.) defines "noise" as an undesirable sound which is regulated at the federal level through that Act. Noise standards developed by USEPA (USEPA 1974) provide a basis for state and local government decision-making in setting local noise standards. Park, municipal, and residential areas are defined as noise-sensitive land uses using Federal Highway Administration (FHA) noise abatement criteria (23 C.F.R. § 772.5).

The Wisconsin Department of Transportation (WisDOT) determines noise impacts and evaluates possible mitigation measures, such as noise barriers in areas adjacent to principal highways. U.S. Highway 12 bisects the project area where it crosses Pheasant Branch Creek. Through municipal regulation, construction equipment may only operate "between the hours of 7:00 a.m. and 6:00 p.m. Monday through Saturday, except Federal and State holidays, unless such operation is not plainly audible at any time from within any occupied residential structure" (MCO 16.05(2)(e)).

Alternative 1 – No Action

The No Action alternative would not change ambient noise levels in the project area. No short-or long-term changes in noise levels would occur without construction activities.

Action Alternative 2 - Proposed Action

The Proposed Action would cause minor short-term increases in the ambient noise levels in the area associated with construction activities. Short-term impacts related to removal of damaged infrastructure and construction activities would include trucks hauling materials to and from the site, the operation of equipment such as excavators for creekbank grading and fill activities, and asphalt paving equipment when rebuilding recreational trails. Minor traffic noise would also be expected from construction vehicles and haul trucks arriving and departing from the project area. It is anticipated that damaged infrastructure demolition and construction activities will take place during the less noise-sensitive daylight hours. Because the project area is a mostly natural landscape located within an urban area currently used by the public, traffic is not anticipated to increase notably after project completion; therefore, no long-term change in noise levels will occur.

3.5.3 Public Services and Utilities

Municipal services provided by the City of Middleton include the Middleton Police Department, Middleton Fire Department, and Middleton-Cross Plains Area School District. There are three hospitals located together approximately 4 mi. southeast of the project area: University of Wisconsin's University Hospital, American Family Children's Hospital, and William S. Middleton Memorial VA Medical Center. The City of Middleton Police Department is approximately 0.6 mi. to the south of the proposed project area and another police station is located 0.2 mi. north. The closest fire station of the Middleton Fire Department is located approximately 0.5 mi. to the south. Public schools such as E.G. Kromrey Middle School, Middleton High School, and Clark Street Community School are located adjacent or in the vicinity of the project area (Dane County, 2022). The City of Madison Metro Transit (MMT) has two bus stops located adjacent to

the project area. The bus stops are #6146 Park & Pheasant Branch (Southbound) and the bus stop #6635 Park & Pheasant Branch (Northbound) (City of Madison 2022a).

The wastewater collection system of the Middleton Sewer Department is designed and built to collect and convey wastewater from homes, businesses, and industries to the Nine Springs Wastewater Treatment Plant in south Madison (City of Madison 2022b). The closest pumping stations to the project area are approximately 1 mi. each, pumping station #15 is to the southeast and #16 is to the south of the proposed project area.

The City of Middleton Parks and Recreation Department oversees management and maintenance of the proposed project area and bordering areas. Several public utilities including existing water, sewer, telecommunication, and electric utilities bisect the project area, typically where street-level bridges cross Pheasant Branch Creek.

Alternative 1 - No Action

The No Action alternative would have minor short-term and moderate long-term impacts on public services in the project area. Because the proposed project area serves the citizens of the City of Middleton as a recreation area, damages from flooding and erosion from Pheasant Branch Creek could cause closures of the area, eliminating public recreational use. Without repair of the recreational trails and pedestrian bridges, public recreational use will remain limited. Emergency vehicles or public utility vehicles would eventually not be able to serve public needs within the project area.

Action Alternative 2 - Proposed Action

The Proposed Action would have a minor short-term impact on public services during construction activities. Current water, sewer, telecommunication, and electric utilities are not expected to be shut down during construction; therefore, the Proposed Action would likely not cause any short- or long-term impacts on utility services in the area. If utilities do need to be temporarily shut off during construction, the subrecipient would follow local ordinances regarding shut down procedures and notification.

The Proposed Action would provide moderate long-term benefits to public services by returning the project area to a safe, useable public recreation area. Creekbank stabilization would increase the likelihood that the existing and repaired recreational infrastructure will not be damaged by flood events in the future. Furthermore, after project completion, more reliable access to public services (i.e.: adjacent public schools, public transportation, etc.) on foot or by bicycle through the project area will return, in addition to improved access for emergency and maintenance services.

3.5.4 Traffic and Circulation

The project area is located within the developed urban area of the City of Middleton and is surrounded and crossed by municipal roads and a U.S. highway. Roads crossing the proposed project area are Discovery Drive, Parmenter Street, Park Street, Century Avenue, and U.S.

Highway 12. To the north of the proposed project area is Donna Drive and to the south is U.S. Highway 14. The Pheasant Branch Creek corridor has snowmobile, bike, and pedestrian trails and municipal recreation areas and parks nearby such as Pheasant Branch Conservancy, Parisi Park, and Firemen's Park. The project area is a heavily utilized recreation area for pedestrians, cyclists, and other natural area recreation (birding, etc.).

Alternative 1 - No Action

The No Action alternative would have minor short-term and moderate long-term impacts on traffic and circulation in the area. Recreational trails and pedestrian bridges would remain only partially useable in a temporarily repaired condition and at risk of closure due to safety concerns. Non-motorized commuter use of the area would not be improved. The potential of erosion damage and closure of existing municipal road and highway crossings would continue without creekbank stabilization at those locations.

Action Alternative 2 - Proposed Action

The Proposed Action would result in minor short-term impacts resulting from construction detours, and the operation of construction vehicles and equipment to and from the site. The Proposed Action would have moderate long-term benefits to traffic and circulation in and around the project area would improve reliability of travel through the project area for bicyclists and pedestrians.

3.5.5 Environmental Justice (Executive Order 12898)

EO 12898, Federal Actions to Address Environmental Justice (EJ) in Minority and Low-income Populations, requires federal agencies to identify, address, and avoid disproportionately high and adverse human health or environmental effects on minority and low-income populations caused by their actions. Minorities are defined as anyone who identifies as black or African American, American Indian (Native American), or Alaska Native, Asian American, Native Hawaiian or Pacific Islander, Hispanic, or multiracial. Low-income populations are those with incomes at or below the annual statistical federal poverty thresholds determined by the U.S. Census Bureau.

The USEPA's Environmental Justice Screening and Mapping tool (EJScreen, USEPA 2022e) was used to investigate the presence of readily identifiable low income or minority populations within a 0.25-mi. buffer of the proposed project area. This 0.25-mi. buffer is considered the "affected area" for EJ analysis. Low-income or minority populations in an affected area can be analyzed through either one or both of the following criteria:

- The affected area (e.g., census block group) contains 50 percent or more minority persons or 25 percent or more low-income persons.
- The percentage of minority or low-income persons in an affected area (e.g., census block group) is more than 10 percent greater than the average of the surrounding Comparison Group (City of Middleton).

To evaluate impacts on vulnerable population groups of concern, information needs to be presented in relation to another group, a Comparison Group (USEPA 2016). The City of Middleton, as a whole, was defined as a Comparison Group to the affected area to determine if a disproportionate population of vulnerable socioeconomic characteristics of concern would be impacted. The project area is located within a very small portion of census block group ID# 550250109042, but is mostly within groups ID# 550250111011, ID# 550250111013, and ID# 550250111024. EJScreen provided data at the census block level and for the 0.25-mi.-buffer affected area. American Community Survey (ACS) 2015-2019 data were used by EJScreen to estimate population data relative to low-income composition (*Source:* EJScreen, USEPA 2022e) (**Table 3-4**). EJScreen used 2010 Census data to calculate racial composition for the affected area and the City of Middleton (*Source:* U.S. Census Bureau 2010) (**Table 3-5**).

Table 3-4: Low-Income Populations, 2022 Estimate

	Affected Area		City of Middleton	
	Population Percentage		Population	Percentage
Total Population	3,908		18,384	
Low Income	820	21	2,941	16

Table 3-5: Minority Populations, Census 2010

Race	Affected Area		City of N	liddleton
	Population	Percentage	Population	Percentage
Total Population	3,725		17,442	
White	3,042	82	13,884	79.6
Black or African American	153	4	889	5.1
Asian	121	3	977	5.6
American Indian and Alaska Native	7	0.2	34	0.2
Native Hawaiian and Other Pacific Islander	2	0.1	2	0
Some Other Race/Multiracial	109	2.9	714	4.1
Hispanic ²	291	8	942	5.4

² The terms Hispanic and Latino can apply to members of any race, including respondents who self-identified as "White." The total numbers of Hispanic and Latino residents for each geographic region are tabulated separately from the racial distribution by the U.S. Census Bureau.

Race A		Affected Area		liddleton
	Population Percentage		Population	Percentage
Total Minority Population ^{3,4}	683	18	3,558	20.4

Alternative 1 - No Action

The No Action alternative would not have any disproportionate high and adverse effect on EJ vulnerable populations. The affected area does not contain 50 percent or more minority persons or 25 percent or more low-income persons. The percentage of minority or low-income persons in the affected area is 2.4 percent less than the average of the surrounding Comparison Group (City of Middleton), so clearly does not meet the target of being 10 percent greater than the average of the surrounding Comparison Group, indicating disproportionately high effects.

Action Alternative 2 – Proposed Action

The Proposed Action would not have any disproportionately high and adverse effect on EJ vulnerable populations. The affected area does not contain 50 percent or more minority persons or 25 percent or more low-income persons. As noted above, the percentage of minority or low-income persons in the affected area does not meet the threshold for disproportionately high effects.

3.5.6 Safety and Security

The Occupational Safety and Health Act, 29 U.S.C. §§ 651 – 678, requires safe and healthful conditions for workers by setting and enforcing standards through training, outreach, and compliance assistance. The act created the Occupational Safety and Health Administration (OSHA) which established construction standards under 29 C.F.R. Part 1926. In addition, EO 13045, Protection of Children from Environmental Health Risks and Safety Risks, directs federal agencies to identify and assess environmental health and safety risks that may disproportionately affect children to ensure their policies, programs, activities, and standards address those risks. The EO broadly defines environmental health and safety risks as products or substances that a child is likely to encounter or ingest through the air, soil, water, or food. EJScreen was used to identify the percentage of children who live in the project area based on the 2015-2019 ACS. Approximately 509 (21%) of the population within a one mi. radius of the project area are ages 0 to 17 (USEPA 2022e). Public safety risks in the project area include flooding and erosion that damage infrastructure, temporary and partial repair of damaged pedestrian bridges and recreational trails, and tree fall.

Hispanic or Latino, essentially counting those individuals twice.

³ A minority is defined in CEQ's environmental justice guidance as a member of the following population groups: American Indian/Alaskan Native, Asian or Pacific Islander, Black (non-Hispanic), or Hispanic (CEQ 1997).
⁴ "Total Minority" includes all people who are not "White alone," plus Hispanics and Latinos who identify as white alone. This number may capture individuals who identify as both "not white" and those who identify as

Alternative 1 - No Action

Under the No Action alternative, continued erosion and flooding would perpetuate hazardous conditions which would have a moderate long-term impact on safety within the Pheasant Branch Creek corridor. Temporary minor repaired pedestrian bridges and recreational trails would remain public safety hazards and potential tree fall would increase because of continued erosion of soils from root systems. No public safety risks disproportionately affect children.

Action Alternative 2 - Proposed Action

Minor short-term impacts associated with standard construction-related safety risks would occur for construction workers at the project site. During construction, site safety of workers would be ensured by the contractors performing the work following standard industry safety practices.

Post-construction, the Proposed Action would provide moderate long-term safety benefits by reducing erosion and flooding in the project area. Public safety would be improved because of the reduction of risk of flooding and tree fall, in addition to removal of the hazards of damaged recreational trails and pedestrian bridges. No public safety risks disproportionately affect children.

3.6 Historic and Cultural Resources

Section 106 of the National Historic Preservation Act of 1966 (NHPA), as amended, 54 U.S.C. §§ 300101 - 307108, requires federal agencies to consider the potential effects on cultural resources of actions it proposes. Cultural resources are defined as prehistoric or historic archaeology sites, historic standing buildings and structures, historic districts, objects, artifacts, and cultural properties of historic or traditional significance—referred to as Traditional Cultural Properties—that may have religious or cultural significance to federally-recognized Native American Tribes (Tribes). Any other physical evidence of human activity considered important to a culture, subculture, or community for scientific, traditional, religious, or other reasons is also considered a cultural resource. The State Historic Preservation Office (SHPO) is the federal agency's primary Section 106 partner, as is the tribal Historic Preservation Officer (THPO) for projects affecting resources on tribal lands.

Cultural resources listed, eligible for listing, or potentially eligible for listing on the National Register of Historic Places (NRHP) are subject to protection from adverse impacts resulting from a federally funded undertaking. To be considered eligible for listing, a cultural resource must meet one or more of the criteria regarding the resource's significance, as well as demonstrate the integrity of physical features or other characteristics that are related to that significance. Eligibility criteria for listing a property in the NRHP are detailed in 36 C.F.R. § 60. Under the implementing regulations for conducting Section 106 consultation under the NHPA at 36 C.F.R. § 800, federal agencies are required to determine whether resources are eligible for listing and obtain concurrence on that finding from the SHPO or THPO as appropriate.

Under 36 C.F.R. § 800.4(a)(1), the Area of Potential Effects (APE) is defined as the geographic area(s) within which the undertaking may directly or indirectly affect cultural resources. Within

the APE, impacts on cultural resources are evaluated for both historic structures (above-ground cultural resources) and archaeology (below-ground cultural resources).

In addition to the NHPA, FEMA must also comply with the following federal laws that relate to historic and cultural resources:

- The Archaeological and Historic Preservation Act of 1974, 16 U.S.C. §§ 469 469c-2, provides for the survey, recovery, and preservation of significant scientific, prehistoric, archeological, or paleontological data when such data may be destroyed or irreparably lost due to a federal, federally licensed, federally funded (in part or whole) project.
- American Indian Religious Freedom Act of 1978 (AIRFA), 42 U.S.C. § 1996, which provides for the protection and preservation of Native American sites, possessions, and ceremonial and traditional rites.
- Archaeological Resources Protection Act of 1979, 16 U.S.C. §§ 470aa–470 mm, which
 provides for the protection of archaeological resources on public lands and Native
 American lands.
- Native American Graves Protection and Repatriation Act, 25 U.S.C. §§ 3001–3013, in cases where Native American cultural Items are found on federal and tribal lands.

To comply with the NHPA, an archaeological literature search and technical memorandum was undertaken by an SOI-qualified archaeologist with SERCO contracted by FEMA in February 2022. The investigation defined the APE as the construction limits for the project being evaluated in this EA. Work is not expected to have visual effects beyond the APE and the areas for equipment staging and access will conform to the existing paved trails adjacent to the stream. Following the February 2022 investigation, FEMA initiated consultation with the SHPO to confirm the finding that no historic properties would be affected if the project were implemented. The SHPO concurred with the finding of No Historic Properties Affected on April 11, 2022 (Appendix B).

3.6.1 Historic Structures

Historic properties are districts, sites, buildings, structures, and objects that are included in the NRHP or that meet the criteria for the NRHP; they also include records and human remains that are related to and located within such properties. Consideration of effects on historic properties is mandated both by NEPA and by Section 106 of the NHPA of 1966, as amended (16 U.S.C. § 470f). Section 106 requires Federal agencies to consider the effects of their undertakings on historic properties and to afford the SHPO and the Advisory Council on Historic Preservation an opportunity to comment on such undertakings.

No above-ground resources listed in or determined eligible for inclusion in the NRHP per occur within the APE. Therefore, no effects are anticipated for above-ground resources.

Alternative 1 - No Action

The No Action alternative would have no effect on historic properties listed or eligible for listing in the NRHP because none were identified in the APE.

Action Alternative 2 - Proposed Action

The Proposed Action would have no effect on historic structures listed or eligible for listing in the NRHP because none were identified in the APE. Consultation documentation is included in **Appendix B**.

3.6.2 Archaeological Resources

An archaeological literature search and technical memorandum was undertaken by an SOI-qualified archaeologist with SERCO contracted by FEMA in February 2022. Twenty archaeological sites within Sections 1, 2, 11, and 12 of Township 7 Range 8E (T7R8E) were identified. Most sites are pre-contact sites (e.g., Native American mounds and campsites/villages), although several sites also contain historic components. In addition, two historic cemeteries are present within T7R8E. Of the twenty sites, only one site, 47-DA-0815, crosses Pheasant Branch Creek and is within the APE. The site is a precontact campsite/village that has not been evaluated for eligibility for inclusion in the NRHP; however, a prior survey was conducted within the portion of the site within the APE and no archaeological resources were identified. Additionally, no further archaeological investigations are recommended (Settle 2016).

Alternative 1 - No Action

The No Action alternative would have no effect on known archaeological resources as no construction or ground disturbance activities would occur and such resources are not expected to be present.

Action Alternative 2 - Proposed Action

The Proposed Action would have no effect on any known archaeological sites or resources. Consultation documentation is included in **Appendix B**. The following project conditions, also included in **Section 6.2**, would provide additional protection to unknown archaeological sites:

- The subrecipient will monitor all ground disturbance during the construction phase. Should human skeletal remains or historic or archaeological materials be discovered during construction, all ground-disturbing activities on the project site shall cease and the City of Middleton will notify the coroner's office (in the case of human remains), the Wisconsin State Police, and FEMA. FEMA will notify the SHPO, the Miami Tribe of Oklahoma, and the Wisconsin Historical Society (WHS, State Archaeologist).
- All borrow or fill material must come from on-site, pre-existing stockpiles, material reclaimed from maintained roadside ditches (provided the designed width or depth of the ditch is not increased), or commercially procured material from a source existing prior to the event. For any FEMA-funded project requiring the use of a non-commercial source or a commercial source that was not permitted to operate prior to the event (e.g. a new pit, agricultural fields, road ROWs, etc.) in whole or in part, regardless of cost, the City of Middleton must notify FEMA prior to extracting material. FEMA must review the source for compliance with all applicable federal environmental planning and historic preservation laws and executive orders prior to a subrecipient or their contractor

commencing borrow extraction. Consultation and regulatory permitting may be required. Non-compliance with this requirement may jeopardize receipt of federal funding. Documentation of borrow sources utilized is required at closeout.

3.6.3 Tribal Coordination and Religious Sites

EO 13175, Consultation and Coordination with Indian Tribal Governments, directs federal agencies, "to establish regular and meaningful consultation and collaboration with tribal officials in the development of federal policies that have tribal implications, to strengthen the United States government-to-government relationships with Indian tribes, and to reduce the imposition of unfunded mandates upon Indian tribes...."

Requests for information on the presence or absence of known archaeological and Native American religious sites within the proposed project area were submitted to federally recognized tribal nations with potential interests in the project. On March 29, 2022, FEMA initiated consultation with the following tribal nations:

- Ho-Chunk Nation
- Osage Nation
- Miami Tribe of Oklahoma
- Menominee Indian Tribe of Wisconsin
- Winnebago Tribe of Nebraska

FEMA sent a letter to each tribe with details about the project location and proposed activity and requested comments from each tribal government within 30 days of the date of the letter. FEMA received a response from one tribal nation. The Miami Tribe of Oklahoma responded, asking to be informed of project progress and that "given the Miami Tribe's deep and enduring relationship to its historic lands and cultural property within present-day Wisconsin, if any human remains or Native American cultural items falling under the Native American Graves Protection and Repatriation Act (NAGPRA) or archaeological evidence is discovered during any phase of this project, the Miami Tribe requests immediate consultation with the entity of jurisdiction for the location of discovery." Correspondence with the tribal nations is provided in **Appendix C**.

Alternative 1 - No Action

The No Action alternative would have no effect on known Native American archaeological, historic, or religious sites as no construction or ground disturbance activities would occur.

Action Alternative 2 - Proposed Action

The Proposed Action would have no effect on known Native American archaeological, historic, or religious sites. Project conditions noted in Section 3.6.2 and Section 6.2 apply.

3.7 Comparison of Alternatives

Table 3-6: Comparison of Alternatives

No Action Impacts	Proposed Action	Mitigation
Geology, Soils, and Topography	·	
Moderate long-term adverse impacts to soils and topography from continued erosion.	 Minor short-term impacts to soil and topography from construction activities. Moderate long-term benefits from reduced soil erosion because of creekbank stabilization and in-channel structures. 	• See Section 6.2 , Condition 4.
	No short- or long-term impact to important farmland soil because none will be irreversibly converted.	
Water Resources and Water Qualit	y	
 Moderate long-term adverse impacts from sedimentation, soil erosion, and turbidity. No impact on surface water pollutants or groundwater and drinking water resources. 	 Moderate short-term impact on water quality during construction activities caused by excavators and other heavy equipment for fill and excavation. Moderate long-term benefits from reduced erosion and turbidity, but additional habitat diversity from stone vanes/riffle structures. No impact on surface water pollutants or groundwater and drinking water 	• See Section 6.2 , Condition 4.
	resources.	
Floodplain Management		T
 Moderate long-term adverse impacts from continued erosion, bank destabilization and collapse of additional cutbanks and trees. 	 Minor short-term adverse impacts from sediment disturbance by excavation and removal of vegetation and trees. Moderate long-term benefits from reduction of erosion and improved creek channel stability. 	• None
Air Quality		
 Minor short and long-term adverse impacts from decreased opportunities for the project area to be used for non- motorized commuting. 	 Minor, short-term adverse impacts from construction equipment emissions and exposed soils. Minor long-term benefit from repair of recreational infrastructure potentially increasing non-motorized commuting. 	• See Section 6.2 , Conditions 5 and 6.

No Action Impacts	Proposed Action	Mitigation			
Terrestrial and Aquatic Environmen	-	<u> </u>			
Moderate long-term adverse impacts from continued erosion of the creekbank, resulting in soil loss and reduced aquatic habitat quality from increased turbidity.	 Minor short-term impacts such as soil disturbance, removal of vegetation and potential sediment runoff from construction activities. Minor long-term impacts from the removal of trees. Moderate long-term benefit from all disturbed areas having native seeding 	• None			
	after construction activities.				
Wetlands					
No short- or long-term impacts.	Minor short-term adverse impacts to riverine and palustrine wetlands from in- channel and creekbank stabilization work.	• See Section 6.2, Condition 4.			
Threatened and Endangered Specie	es T				
No short- or long-term impacts.	Not likely to adversely affect the northern long eared bat or rusty patched bumble bee which potentially may be present in the vicinity.	• See Section 6.2 , Conditions 10 - 11			
	No impacts to the EPFO, Mead's milkweed, and the prairie bush-clover.				
Migratory Birds					
No short- or long-term impacts.	 Minor permanent impacts from trees and vegetation removal that may serve as migratory bird habitat. Minor long-term benefit from native 	• See Section 6.2 , Condition 12.			
	vegetative seeding.				
	 Minor short-term adverse impact from potential disturbance of nesting migratory birds if present during construction activity. 				
Invasive Species					
No short- or long-term impacts.	 Minor short-term benefit from destruction of known existing invasives if present at specific work areas Minor short-term adverse impact from the potential spread of invasives outside 	• See Section 6.2, Condition 13 - 17.			
	or into the project area as both cuttings and attached to construction equipment and vehicles.				

No Action Impacts	Proposed Action	Mitigation
Hazardous Materials		T
No short- or long-term impacts.	Minor short-term impact from potential risk of leaks from construction equipment.	• See Section 6.2, Conditions 8 and 9.
	The Proposed Action would not involve the exposure of any known hazardous materials or chemicals to the site, but would it increase the overall risk of hazardous materials not known to already exist in the environment being released because of excavation, resulting in moderate short-term impacts to onsite workers.	
Zoning and Land Use		
Moderate long-term adverse impact on zoning and land use due to non-conformity with land use plan goals.	Moderate long-term benefit on zoning and land use due to restored conformity with land use plan goals.	• None
Noise		
No short- or long-term impacts.	Minor short-term impacts associated with construction activity.	• See Section 6.2 , Condition 7.
	No long-term impact.	
Public Services and Utilities		
Minor short-term impacts to public services, resources and utilities.	Minor short-term impact on public services during the construction.	• None
 Moderate long-term impacts on utilities and public services if the erosion continues and recreational infrastructure not repaired. 	 Moderate long-term benefits from the removal of the threat of erosion that could damage public utilities and impact services and returning recreational infrastructure to safe public use. 	
Traffic and Circulation		
Minor short-term impacts from temporary repair conditions of recreational infrastructure	Minor short-term impact from the operation of construction vehicles and equipment to and from the site.	• None
Moderate long-term impacts on traffic and circulation as the risk of erosion damage to road crossings continue.	Moderate long-term benefits from improvement of pedestrian and cycling traffic conditions.	

No Action Impacts	Proposed Action	Mitigation			
Environmental Justice					
Negligible effect	Negligible effect, no disproportionate or adverse impacts.	• None			
Safety and Security					
Moderate long-term impact from hazardous conditions and damages to trails and bridges.	Minor short-term impact for construction workers.	• See Section 6.2 , Conditions 18 -			
damages to trails and bridges.	 Moderate long-term positive impact to the public from reduction of potential flooding and injury from damaged recreation infrastructure. 	21.			
Historic Structures					
• No short- or long-term impacts.	No short- or long-term impacts.	• None			
Archaeological Resources					
No short- or long-term impacts.	No short- or long-term impacts.	• See Section 6.2 , Conditions 22 and 23.			
Tribal and Religious Sites					
No short- or long-term impacts.	No short- or long-term impacts.	• See Section 6.2 , Conditions 22 and 23.			

4 **CUMULATIVE IMPACTS**

This section evaluates the potential cumulative impacts associated with the implementation of the Proposed Action. Cumulative impacts are defined in CEQ regulations for implementing NEPA (40 C.F.R. § 1508.7) as:

"The impacts of a proposed action when combined with impacts of past, present, or reasonably foreseeable future actions undertaken by any agency or person."

CEQ regulations require an assessment of cumulative effects during the decision-making process for federal projects. Cumulative impacts can result from individually minor but collectively significant actions.

The Proposed Action is an effort to repair and mitigate flooding and erosion damages within the Pheasant Branch Creek corridor. However, there are no known recently completed or proposed mitigation or natural restoration projects within one mi. of the project site. Additionally, there are no other known proposed projects within one mi. of the project area led by the City of Middleton, Dane County or WisDOT. There are no known projects that may cause cumulative impacts.

5 PUBLIC PARTICIPATION

This EA is available for agency and public review and comment for a period of 30 days. The public information process includes a public notice with information about the Proposed Action in the Middleton-Times Tribune (www.middletontimes.com). This EA will be available on FEMA's website at https://www.fema.gov/about/news-multimedia/events during the public comment period and the final EA will be archived at https://www.fema.gov/emergency-managers/practitioners/environmental-historic/nepa-repository. The EA is also available on the City of Middleton's Conservancy and Lands website at https://www.cityofmiddleton.us/171/Conservancy-Lands-Trails and the City's main website https://cityofmiddleton.us.

Those without internet access can review the EA on a computer available to the public during normal business hours at the Middleton Public Library or at Middleton City Hall.

Middleton Public Library 7425 Hubbard Avenue Middleton, WI 53562

Middleton City Hall 7436 Hubbard Avenue Middleton, WI 53562

This EA reflects the evaluation and assessment of the federal government, the decision-maker for the federal action; however, FEMA will take into consideration any substantive comments received during the public review period to inform the final decision regarding grant approval and project implementation. The public is invited to submit written comments by emailing fema-r5-environmental@fema.dhs.gov or via mail to:

Duane Castaldi, Regional Environmental Officer Attn: Pheasant Branch Creek Comments FEMA Region 5 536 South Clark Street, 6th Floor Chicago, IL 60605

The 30-day comment period ended with no comments from the public or agency reviewers, allowing the draft EA to be adopted as final. Consistent with the information presented here, FEMA has issued a Finding of No Significant Impact.

5.1 Subrecipient Outreach

The City of Middleton discussed the damages to the Pheasant Branch Creek corridor, including the path and bridges at several of their meetings in 2019 and 2022. All City meetings are open to the public. Documentation of these meetings is provided in **Appendix E**.

The Pheasant Branch Creek Corridor Restoration and Improvements Master Plan performed a public survey through POLCO, a software company in Middleton, Wisconsin. POLCO provides an online platform for communities' engagement polling with information tools to local government and other public sector leaders. On the online survey, there were 370 participants of which 337 were the city of Middleton residents. The survey consisted of 10 questions. **Table 5-1** summarizes the results of the survey.

Table 5-1: Public Survey Results

	Questions	Answers
1.	How often do you visit the Pheasant Branch Creek Corridor?	262 of 370 (71%) visit weekly or greater
2.	Why do you visit the Corridor?	The majority answered Nature, Exercise, and Relax/Bird Watch.
3.	How do you access the Creek Corridor?	309 of 370 (89%) arrive by foot.
4.	What activities would you like to occur within the Corridor that currently do not exist? (Please list below)	N/A None, No activities-keep natural, Stormwater/volunteering & seating options, Improved paths & wayfinding
5.	What do you feel makes the Corridor a special place in Middleton? (Please select one)	Pheasant Breach Creek (35%) Trail (44%)
6.	How important is Creek Corridor access during the winter season?	249 of 370 (67%) felt winter access is important
7.	Which benefit of the corridor is most important to you? (Please select one)	Transportation (21%), Access to nature/wellness (61%), Natural Systems (14%)
8.	What potential improvements do you consider priorities? (Please select up to your top three)	Natural Systems, Pedestrian Bridge Replacement, Physical Improvement, Trail Maintenance
9.	10. The City is always exploring grant opportunities to supplement city funds. If grants are not available or awarded, do you support the city borrowing funds to finance Corridor improvements?	Yes (87%) No (13%)

The first public input session was held on June 20, 2019, at 7:00 pm at Kromrey Middle School with the purpose of initial public input regarding uses, concerns, workshop evaluation, and desired improvements. The workshop evaluation indicated that the sessions were informative and provided opportunities for participation. There was interest in continuing discussion about the conservancy and the process.

The second public input session was held on September 10, 2019, at 7:00 pm in the Kromrey Middle School Cafetorium. A presentation of the Pheasant Branch Creek Corridor Restoration and Improvement Master Plan was given as a summary of the first session, objectives, tentative schedule, results, and input of the Draft Master Plan. The public input summary results of the first session were that the community and other users value the corridor, it should be kept as natural as possible, it should accommodate various users and that it is a key place where citizens and families interact. This main plan is an opportunity to replace what was lost and make improvements. Also, comments on trail alignment favored realigning trails and providing split use trails at the four bridges. Most of the participants did not approve of a wide gravel shoulder on the trail, but they supported the ecological restoration. The streambank stabilization and the birding areas were considered a priority.

On March 15, 2022, there was a follow-up meeting at the Middleton City Hall located at 7426 Hubbard Avenue, Middleton, WI 53562. The topics discussed were that Federal Emergency Management Agency (FEMA) was provided Geographic Information files to create necessary maps. Additionally, the period for comments was established, where the document would be located for public comment, and how the document would be finalized.

6 MITIGATION MEASURES AND PERMITS

6.1 Permits

The city must apply for and obtain coverage under the WPDES General Permit for Storm Water Associated with Land Disturbing Construction Activity (Permit No. WI-S067831-6) from the Wisconsin Department of Natural Resources (department). This general permit regulates the discharges of pollutants to waters of the state as provided in s. 283.33, Wis. Stats., and subch. III of ch. NR 216, Wis. Adm. Code. **Table 6-1** summarizes the necessary permits to implement the Proposed Action and their status.

Table 6-1: Permit Summary

Issuing Agency	Resource	Permit Title	Applicable Regulation/Law	Status
WDNR	Soils (Erosion), Water quality	General Permit for Storm Water Associated with Land Disturbing Construction Activity (Permit No. WI-S067831- 6)	283.33, Wis. Stats., and subch. III of ch. NR 216, Wis. Adm. Code.	Not Obtained Yet.
WDNR	Waters of the US including wetlands	General Permit to Place 6 Bridge Spans	30.206, Stats. and ch. NR 320, Wis. Adm. Code	Obtained by the City. WDNR GP-SC-2022- 13-02398, 2408-12. See Section 6.2 and Appendix G .
WDNR	Waters of the US including wetlands	Changing Stream Course and Bank Stabilization	ch. 30, Wis. Stats., and ch. NR 320, Wis. Adm. Code,	Obtained by the City. WDNR Permit IP-SC-2021-13-01703-04 includes general and project specific conditions for the project. See Section 6.2 and Appendix G.
Corps of Engineers (COE)	Waters of the US including wetlands	Nationwide Permit 13 – Bank Stabilization with Waiver	Section 404 of the Clean Water Act (CWA)	Initial permit obtained by the City. COE Regulatory File No. MVP-2021- 00484-SJW is pending revision and includes general and project specific conditions for the project. See Section 6.2 and Appendix G.
City of Middleton	Floodplain	Local Floodplain Development Permit / No Rise Certificate	EO 11988 Floodplain Management	Not Complete. Prior to commencing work, the full project should be approved by the Local Floodplain Administrator

Issuing Agency	Resource	Permit Title	Applicable Regulation/Law	Status
				accompanied by a no rise certificate.

6.2 Project Conditions

The subrecipient is responsible for compliance with federal, state, and local laws and regulations, including obtaining any necessary permits prior to beginning construction activities, and adhering to any conditions laid out in these permits. Any substantive change to the scope of work will require re-evaluation by FEMA for compliance with NEPA and any other laws or EOs. Failure to comply with FEMA grant conditions may jeopardize federal funding.

General Project Conditions

- 1. The subrecipient is responsible for obtaining and complying with all required local, state, and federal permits and approvals.
- 2. Develop and implement erosion control and post-construction storm water management plan to be submitted to WDNR.
- 3. If deviations from the proposed scope of work result in substantial design changes, the need for additional ground disturbance, additional removal of vegetation, or any other unanticipated changes to the physical environment, the subrecipient must contact FEMA so that the revised project scope can be evaluated for compliance with NEPA and other applicable environmental laws.

The following condition address mitigation of impacts to *Water Resources and Water Quality, Wetlands*, and *Soils*:

4. Prior to beginning work, the subrecipient will prepare for implementation an Erosion and Sediment Control Plan and a Storm Water Management Plan as required in the Wisconsin Pollutant Discharge Elimination System (WPDES) General Permit for Storm Water Associated with Land Disturbing Construction Activity, Permit No. WI-S067831-6.

Air Quality

- 5. To reduce the emission of criteria pollutants, construction equipment engine idling will be minimized to the extent practicable, and engines will be kept properly maintained.
- 6. Open construction areas will be minimized and watered as needed to minimize particulates such as fugitive dust.

Noise

7. Substantial use of construction equipment may occur only between the hours of 7:00 am and 6:00 pm Monday through Saturday.

Hazardous Materials

- 8. Contingency plans will be prepared that detail the procedures that the contractors will follow to identify, manage, and dispose of source materials, or other heavily contaminated materials, in accordance with all local, state, and federal regulations in the event hazardous source materials are encountered during creekbank excavation/resloping, creekbank infrastructure removal/replacement, bridge repair/relocation, pedestrian trail removal/replacement, or other construction activities. These specifications sections should include, but are not limited to, procedures that address Safety, Health, and Emergency Response Procedures; Environmental Protection Procedures; Contaminated Soil Excavation; Transportation and Disposal of Contaminated Material; and Contaminated Dewatering and Drainage.
- 9. WDNR will be notified if source material or other heavily contaminated material is encountered.

Threatened and Endangered Species

- 10. To minimize effects of the Rusty Patched Bumble Bee, the following (BMPs) should be followed: minimize the spread of invasive species, avoid or minimize soil compaction.; Avoid or minimize soil disturbance and heavy equipment operation during overwintering (mid-October through mid-March); avoid or minimize forest management that may destroy spring blooming flowers during their bloom periods; consider thinning or single tree selection and dense invasive shrub removal that may improve overwintering and spring foraging habitat; use native trees, shrubs and flowering plants in landscaping, provide plants that bloom from spring through fall; remove and control invasive plants in any habitat used for foraging, nesting, or overwintering
- 11. To minimize impacts to state listed species the City will provide the construction contractor a copy of the May 27, 2022, Wisconsin Department of Natural Resource Endangered Resource Review so that voluntary conservation measures may be incorporated into the project construction as appropriate.

Migratory Birds

12. Tree removal should be avoided during the migratory bird nesting season (approximately March 1 to October 10) to the extent practicable.

Invasive Species

- 13. Graded areas will be revegetated with native grasses and forbs, or native seed mixes.
- 14. All equipment should be inspected and cleaned (including but not limited to heavy equipment, vehicles, clothing, and gear) prior to entering the worksite. All soil, aggregate material, mulch, terrestrial or aquatic vegetation, seeds, animals, etc. must be removed using a hand tool, brush, compressed air, pressure washer, or otherwise.
- 15. If equipment is not disinfected prior to arriving at the project site, then equipment will be cleaned in the parking or staging area where equipment is loaded and unloaded, ensuring no material is deposited at the worksite or carried away to a new site. Material cleaned from equipment should be disposed of legally.

16. All equipment that enters the waters of Pheasant Branch Creek will be thoroughly drained of all water before moving to another site.

Safety and Security

- 17. To minimize risks to safety and human health, construction activities will be performed using qualified personnel trained to use the required equipment properly.
- 18. The construction site will be secured from public access.
- 19. All construction activities will be conducted in accordance with the standards specified in the Occupational Safety and Health Administration (OSHA) regulations.
- 20. All conditions of the project Health and Safety Plan will be adhered to.

Archaeological, Tribal, and Religious Sites

- 21. The subrecipient will monitor all ground disturbance during the construction phase. Should human skeletal remains or historic or archaeological materials be discovered during construction, all ground-disturbing activities on the project site shall cease and the City of Middleton will notify the coroner's office (in the case of human remains), the Wisconsin State Police, and FEMA. FEMA will notify the SHPO, the Miami Tribe of Oklahoma, and the Wisconsin Historical Society (WHS, State Archaeologist).
- 22. All borrow or fill material must come from on-site, pre-existing stockpiles, material reclaimed from maintained roadside ditches (provided the designed width or depth of the ditch is not increased), or commercially procured material from a source existing prior to the event. For any FEMA-funded project requiring the use of a non-commercial source or a commercial source that was not permitted to operate prior to the event (e.g. a new pit, agricultural fields, road ROWs, etc.) in whole or in part, regardless of cost, the City of Middleton must notify FEMA prior to extracting material. FEMA must review the source for compliance with all applicable federal environmental planning and historic preservation laws and executive orders prior to a subrecipient or their contractor commencing borrow extraction. Consultation and regulatory permitting may be required. Non-compliance with this requirement may jeopardize receipt of federal funding. Documentation of borrow sources utilized is required at closeout.

7 CONSULTATIONS AND REFERENCES

The following agencies were consulted during the preparation of this EA:

7.1 Federal, State, and Local Agencies

- Wisconsin Department of Natural Resources, Bureau of Natural Heritage Conservation
- Wisconsin State Historic Preservation Office
- U.S. Fish and Wildlife Service, Minnesota-Wisconsin Ecological Services Field Office
- U.S. Environmental Protection Agency Region V, NEPA Implementation Section
- Natural Resources Conservation Service
- U.S. Army Corps of Engineers, St. Paul District

7.2 Tribal Nations

- Ho-Chunk Nation
- Osage Nation
- Miami Tribe of Oklahoma
- Menominee Indian Tribe of Wisconsin
- Winnebago Tribe of Nebraska

7.3 References

- Bergeson S.M. 2012. Examining the suitability of the little brown bat (*Myotis lucifugus*) as a surrogate for the endangered Indiana bat (*Myotis sodalis*) (Master's thesis). Ball State University, Muncie, IN.
- Cheng, T.L., J.D. Reichard, J.T.H. Coleman, T.J. Weller, W.E. Thogmartin, B.E. Reichert, A.B. Bennett, H.G. Broders, J. Campbell, K. Etchison, D.J. Feller, R. Geboy, T. Hemberger, C. Herzog, A.C. Hicks, S. Houghton, J. Humber, J.A. Kath, R.A. King, S.C. Loeb, D. Massé, K.M. Morris, H. Niederriter, G. Nordquist, R.W. Perry, R.J. Reynolds, D.B. Sasse, M.R. Scafini, R.C. Stark, C.W. Stihler, S.C. Thomas, G.G. Turner, S. Webb, B.J. Westrich, and W.F. Frick. 2021. The scope and severity of white-nose syndrome on hibernating bats in North America. Conservation Biology Vol. 35, 5:1586-1597.
- Council on Environmental Quality. 1997. Environmental Justice: Guidance under NEPA. Executive Office of the President. Washington, DC.
- Colla, S.R. and L. Packer. 2008. Evidence for decline in eastern North America bumble bees (Hymenoptera: Apidae), with special focus on *Bombus affinis* (Cresson). Biodiversity Conservation 17:1379-1391.
- Colla S.R. and S. Dumesh. 2010. The bumble bees of southern Ontario: Notes on natural history and distribution. Journal of the Ecological Society of Southern Ontario 141:39-68.
- Crampton, L.H. and R. Barclay. 1998. Selection of roosting and foraging habitat by bats in different-aged aspen mixed-wood stands. Conservation Biology 12:1347-1358.
- Cryan, P.M., C.U. Meteyer, J.G. Boyles and D.S Blehert. 2010. Wing pathology of white-nose syndrome in bats suggests life-threatening disruption of physiology. BMC Biology 8:135-142.
- Dane County. 2009. Dane County Aquatic Invasive Species Prevention and Control Plan. Dane County Land & Water Resources Department, Office of Lakes and Watersheds.

 Madison, WI.
- Dane County. 2022. Land Information Office. Dane County's online interactive mapping application (DciMap). https://lio.countyofdane.com/ (accessed March 2, 2022).
- Day, E.A., G.P. Grzebieniak, K.M. Osterby, and C.L. Brynildson. 1985. Lake and Stream Classification Project; Surface Water Resources of Dane County. WDNR. Madison, WI.
- Federal Emergency Management Agency (FEMA). 2020. Flood Insurance Rate Map, Blue Earth County (Unincorporated Areas). Accessed May 2021. https://map1.msc.fema.gov/firm?id=2752310125D
- Fenton, M.B. and R.M. Barclay. 1980. Myotis lucifugus. Mammalian Species 142:1-8.
- Foster, R. W., A. Kurta. 1999. Roosting ecology of the northern bat (*Myotis septentrionalis*) and comparisons with the endangered Indiana bat (*Myotis sodalis*). Journal of Mammalogy 80: 659-672.

- Goulson, D., E. Nicholls, C. Bouias, E.L. Rotheray. 2015. Bee declines driven by combined stress from parasites, pesticides, and lack of flowers. Science 347: 1255957-1-1255957-9.
- Humphrey, S.R. and J.B. Cope. 1976. Population ecology of the little brown bat, *Myotis lucifugus*, in Indiana and north-central Kentucky. American Society of Mammalogists: Special Publication 4.
- Jackson, H. Mammals of Wisconsin. 1961. The University of Wisconsin Press. Madison, WI.
- Knight, M. E., A. P. Martin, S. Bishop, J. L. Osborne, R. J. Hale, R. A. Sanderson, and D. Goulson. 2005. An interspecific comparison of foraging range and nest density of four bumblebee (*Bombus*) species. Molecular Ecology 14: 1811-1820.
- Lorch, J.M., C.U. Meteyer, M.J. Behr, J.G. Boyles, P.M. Cryan, A.C. Hicks, A.E. Ballmann, J.T.H. Coleman, D.N. Redell, D.M. Reeder, and D.S. Blehert. 2011 Experimental infection of bats with *Geomyces destructans* causes white-nose syndrome. Nature 480:376-378.
- Madison, City of. 2022a. Metro Transit (MMT). https://cityofmadison.com/metro/stops (accessed March 2, 2022).
- Madison, City of. 2022b. Madison Metropolitan Sewerage District (MMSD). https://www.madsewer.org/who-we-are/service-area/ (accessed March 2, 2022)
- Middleton, City of. 1984. Middleton City Code of Ordinances Chapter 10, Zoning Ordinance. https://www.cityofmiddleton.us/DocumentCenter/View/20/Chapter-10---Zoning-PDF (accessed April 20, 2022).
- Minnis, A.M. and D.L. Lindner. 2013. Phylogenetic Evaluation of *Geomyces* and Allies Reveals No Close Relatives of *Pseudogymnoascus destructans*, comb. nov., in Bat Hibernacula of Eastern North America. USDA U.S. Forest Service, Center for Forest Mycology Research. Madison, WI.
- National Oceanic and Atmospheric Administration (NOAA). 2022. Essential Fish Habitat Mapper. https://www.fisheries.noaa.gov/resource/map/essential-fish-habitat-mapper (accessed April 10, 2022).
- National Park Service (NPS). 2022. Interactive Map of NPS Wild and Scenic Rivers. https://www.rivers.gov/wisconsin.php_(accessed April 1, 2022).
- National Resource Conservation Service (NRCS), U.S. Department of Agriculture. 2012. Farmland Protection Policy Act Manual. https://www.nrcs.usda.gov/Internet/FSE_DOCUMENTS/stelprdb1049240.pdf (accessed April 18, 2022).
- NRCS. 2021. Official Soil Series Descriptions and Series Classification. https://soilseries.sc.egov.usda.gov (accessed April 7, 2022).
- NRCS. 2022a. Web Soil Survey.

 https://websoilsurvey.sc.egov.usda.gov/App/WebSoilSurvey.aspx (accessed February 22, 2022).

- NRCS. 2022b. Farmland Protection Policy Act Guidance.
 https://www.nrcs.usda.gov/wps/portal/nrcs/main/national/landuse/fppa/ (accessed April 18, 2022).
- Olcott, P.G., 1972. Bedrock Topography of Dane County, Wisconsin. Wisconsin Geological and Natural History Survey Open-File Report, vol.1972-3.
- Potts, S.G., J.C. Biesmeijer, C. Kremen, P. Neumann, O. Schweiger, and W.E. Kunin. 2010. Global pollinator declines: trends, impacts and drivers. Trends in Ecological Evolution 25:345–353.
- Reeder, D., C.L. Frank, G.G. Turner, C.U. Meteyer, A. Kurta, E.R. Britzke, M.E. Vodzak, S.R. Darling, C.W. Stihler, A.C. Hicks, R. Jacob, L.E. Grieneisen, S.A. Brownlee, L.K. Muller, D.S. Blehert. 2012. Frequent arousal from hibernation linked to severity of infection and mortality in bats with white-nose syndrome. PLoS ONE 7: e38920. doi:10.1371/journal.pone.0038920.
- Settle, Kathleen. 2016. Phase I Archaeological Literature Review and Reconnaissance, Pheasant Branch Stream Restoration, Dane County, Wisconsin. Prepared by Cardno, on file with the City of Middleton and Wisconsin Historical Society.
- University of Wisconsin Madison (UW Madison). 2019. Reimagining the unimaginable the August 2018 Pheasant Branch flooding in Middleton, Wisconsin. Department of Planning and Landscape Architecture, Madison, WI. https://dpla.wisc.edu/wp-content/uploads/sites/1021/2021/09/Reimagining-the-Unimaginable-DPLA-2019.pdf (Accessed April 27, 2022).
- U.S. Census Bureau. 2020. 2020 Census of Population and Housing Middleton, WI.
- U.S. Environmental Protection Agency (USEPA). 1974. Information on Environmental Noise Requisite to Protect Public Health and Welfare with an Adequate Margin of Safety. https://nepis.epa.gov/Exe/ZyPDF.cgi/2000L3LN.PDF?Dockey=2000L3LN.PDF_(accessed April 2022).
- USEPA. 2016. Technical Guidance for Assessing Environmental Justice in Regulatory Analysis. https://epa.gov/sites/default/files/2016-06/documents/ejtg_5_6_16_v5.1.pdf (accessed April 15, 2022).
- USEPA. 2020. Sole Source Aquifer Mapper. https://www.epa.gov/dwssa/map-sole-source-aquifer-locations (accessed April 10, 2022).
- USEPA. 2022a. CADDIS Volume 2, Urbanization Stormwater Runoff and Impervious Surfaces. https://www.epa.gov/caddis-vol2/urbanization-stormwater-runoff (accessed April 12, 2022).
- USEPA. 2022b. Counties Designated "Nonattainment" for CAA's NAAQS. https://www3.epa.gov/airquality/greenbook/mapnpoll.html (accessed April 24, 2022).
- USEPA. 2022c. Envirofacts Website. https://enviro.epa.gov/ (accessed April 2, 2022).

- USEPA. 2022d. NEPAssist Website. https://www.epa.gov/nepa/nepassist (accessed April 2, 2022).
- USEPA. 2022e. Environmental Justice Screening and Mapping Tool (EJScreen ACS Report). https://www.epa.gov/enviroatlas/enviroatlas-interactive-map_(accessed February 28, 2022.
- U.S. Geological Survey (USGS). 1965. Water Supply Paper; Geology and Ground-Water Resources of Dane County, Wisconsin. https://pubs.usgs.gov/wsp/1779u/report.pdf (accessed February 22, 2022).
- U.S. Fish and Wildlife Service (USFWS). 1988. *Lespedeza leptostachya* Recovery Plan. USFWS, Twin Cities, MN.
- USFWS. 2003. Mead's Milkweed (*Asclepias meadii*) Recovery Plan. USFWS Great Lakes Big Rivers Region (Region 3), Fort Snelling, MN.
- USFWS. 2015. Endangered and Threatened Wildlife and Plants; Threatened Species Status for the Northern Long-Eared Bat With 4(d) Rule; Final Rule and Interim Rule. Federal Register 80(63): 17974–18033.
- USFWS. 2016. Rusty Patched Bumble Bee (*Bombus affinis*) Species Status Assessment, Final Report, Version 1.
- USFWS. 2019a. Coastal Barrier Resources System Mapper. https://fwsprimary.wim.usgs.gov/CBRSMapper-v2/ (accessed March 16, 2022).
- USFWS. 2019b. Rusty Patched Bumble Bee (*Bombus affinis*) Endangered Species Act Section 7(a)(2) Voluntary Implementation Guidance. Version 2.1. USFWS, Bloomington, MN.
- USFWS. 2021a. 5-Year Review: Summary and Evaluation, Eastern Prairie Fringed Orchid (*Platanthera leucophaea*). USFWS Chicago Ecological Services Field Office. Chicago, IL.
- USFWS. 2021b. 5-Year Review: Summary and Evaluation, Prairie Bush-clover (*Lespedeza leptostachya*) Minnesota-Wisconsin Ecological Services Field Office. Bloomington, MN.
- USFWS. 2022a. National Wetlands Inventory Wetlands Mapper. Department of the Interior. https://www.fws.gov/wetlands/data/mapper.html (accessed March 19, 2022).
- USFWS. 2022b. Range-wide Indiana Bat and Northern Long-eared Bat Survey Guidelines Appendix A: Phase 1 Habitat Assessments.
- USFWS. 2022c. Endangered and Threatened Wildlife and Plants; Endangered Species Status for Northern Long-Eared Bat; Proposed Rule. Federal Register 87(56): 16442–16452.
- USFWS. 2022d. Information for Planning and Consultation (IPaC). https://ipac.ecosphere.fws.gov/ (accessed May 19, 2021, April 15, 2022).
- U.S. Geological Survey (USGS). 2018a. Short-Term Seismicity Model. https://www.usgs.gov/media/images/short-term-seismicity-model-2018 (accessed April 2, 2022).

- USGS. 2018b. Long-Term National Seismic Hazard Map.

 https://www.usgs.gov/media/images/2018-long-term-national-seismic-hazard-map
 (accessed April 2, 2022).
- Watermolen, Dreux J., McDowell, Michael A., Trochlell. 2003. Patricia A. Birds of Pheasant Branch Conservancy. https://dnr.wi.gov/files/PDF/pubs/ss/SS0991.pdf (accessed April 29, 2022).
- Watermolen, Dreux J. & Reese, Mike. 2005. Butterflies of Pheasant Branch. https://pheasantbranch.org/wp-content/uploads/2019/02/Butterflies-of-PBC.pdf (accessed April 29, 2022).
- Watermolen, Dreux J. 2005. Mammals of Pheasant Branch. https://pheasantbranch.org/wp-content/uploads/2018/12/dnr_mammals_guide.pdf (accessed April 29, 2022).
- WDNR. 2015b. 2015-2025 Wisconsin Wildlife Action Plan. Madison, WI. PUB-NH-938.
- WDNR. 2017a. Wisconsin Northern Long-Eared Bat Species Guidance (updated from 2013). Bureau of Natural Heritage Conservation, Madison, WI. PUB-ER-700.
- WDNR. 2017b. (updated from 2013). Wisconsin Little Brown Bat Species Guidance. Bureau of Natural Heritage Conservation, Madison, WI. PUB-ER-705
- WDNR. 2019. Occupied Bald Eagle (*Haliaeetus leucocephalus*) Nests. https://dnr.wisconsin.gov/sites/default/files/topic/WildlifeHabitat/2019EagleNests.pdf (accessed April 11, 2022).
- WDNR. 2022a. Surface Water Data Viewer. https://dnrmaps.wi.gov/H5/?Viewer=SWDV (accessed on February 23, 2022).
- WDNR. 2022b. Water Detail Pheasant, Six Mile, and Pheasant Branch Creeks Watershed (LR10). https://dnr.wi.gov/water/waterDetail.aspx?WBIC=805900 (accessed on February 3, 2022).
- WDNR. 2022c. Wisconsin Natural Heritage Database. Accessed January 2022. Natural Heritage Inventory data access Wisconsin DNR
- WDNR. 2022d. Lakes and AIS Mapping Tool Lake Mendota https://dnrmaps.wi.gov/H5/?viewer=Lakes_AIS_Viewer (accessed March 29, 2022).
- WDNR. 2022e. Aquatic Invasive Species Dane County https://dnr.wi.gov/lakes/invasives/AISByWaterbody.aspx?location=13 (accessed March 29, 2022).
- Wisconsin Administrative Code (WAC), Chapter NR 40. 2022. Invasive Species Identification, Classification, and Control Rule.
- Wisconsin Department of Natural Resources (WDNR). 2015a. 2011 Water Quality Management Plan Six Mile and Pheasant Branch Creek Watersheds, Updated 2015. Lower Rock Basin, Wisconsin.

- Wisconsin Geological and Natural History Survey (WGNHS). 1999. HYDROGEOLOGY OF DANE COUNTY, WISCONSIN.
- Wisconsin Geological and Natural History Survey (WGNHS). 2013. Preliminary Bedrock Geology of Dane County, Wisconsin.

 https://wgnhs.wisc.edu/catalog/publication/000913/resource/wofr201301plate01 (accessed on February 22, 2022).
- Wisconsin Statutes § 23.22 (2) (a, b). 2022. 2019-2020 Wisconsin Statutes updated through 2021 Wisconsin Act 129.
- Young, H.L., 1992. Summary of Ground-Water Hydrology of the Cambrian-Ordovician Aquifer System in the Northern Midwest, United States. U.S. Geological Survey Professional Paper, vol. 1405-B

8 LIST OF PREPARERS

Table 8-1: Federal Emergency Management Agency Preparers

Reviewers	Experience and Expertise	Role in Preparation
Pamela Ruble	Public Assistance Task Force Lead	PA Program Monitor
Roger Ammons	Program Delivery Manager	PA Project Lead
Duane Castaldi	Regional Environmental Officer (REO)	Project Monitor
Karie Roach	Environmental Protection Specialist	Technical Monitor
Nicholas Dorochoff	Deputy REO	Technical Editor
Daniel Galan-Kercado	Senior Environmental Planner	NEPA Documentation Project Lead
Michael Sealy	Environmental Planner	NEPA Documentation
Varna Boyd, MA, RPA	Senior Archaeologist	Archaeological Research / Compliance
Eugene Fowler, Jr.	GIS Specialist	GIS/Graphics

APPENDICES

Appendix A: Projects Plans

Appendix B: Agency Consultation


Appendix C: Tribal Nation Consultation

Appendix D: Floodplain / Wetlands Management

Appendix E: City of Middleton Meeting Notes

Appendix F: Public Notice and Comments

Appendix G: Permits



PHEASANT BRANCH STREAMBANK STABILIZATION MAINSTEM POND TO CENTURY AVENUE

CITY PROJECT 18-125n

19

20

21

22-28

29-33

34-36

37-40

Sheet List Table Sheet Number Sheet Title TITLE SHEET AND SHEET INDEX PROJECT OVERVIEW MAINSTEM POND TO PARMENTER STREET PROJECT OVERVIEW TO PARMENTER TO PARK STREET PROJECT OVERVIEW PARK STREET TO CENTURY AVENUE PROPOSED PLAN 0+00 TO 6+50 PROPOSED PLAN 6+50 TO 12+00 PROPOSED PLAN 12+00 TO 15+50 PROPOSED PLAN 15+50 TO 23+50 PROPOSED PLAN 23+50 TO 29+00 PROPOSED PLAN 29+00 TO 36+50 11 PROPOSED PLAN 36+50 TO 41+50 12 PROPOSED PLAN 41+50 TO 47+50 13 14 15 16 PROPOSED PLAN 47+50 TO 51+50 PROPOSED PLAN 51+50 TO 59+50 PROPOSED PLAN 59+50 TO 67+50


PROPOSED PLAN 67+50 TO 73+00

CITY OF MIDDLETON PROPOSED PLAN 73+00 TO 80+00 PROPOSED PLAN 80+00 TO 86+00 PROPOSED PLAN 86+00 TO 92+50 PROPOSED PLAN 92+50 TO 98+50 PROPOSED PLAN 98+50 TO 105+00 EXISTING CROSS SECTIONS PROPOSED CROSS SECTIONS EROSION CONTROL / PLANTING PLAN DETAILS



Know what's below. Call before you dig.












PHEASANT BRANCH STREAMBANK STABILIZATION MAINSTEM POND TO CENTURY AVENUE


TITLE SHEET AND SHEET INDEX














































































































- PLACE ROOTWAD SO THAT ROOTFAN PROVIDES NEAR-BANK PROTECTION.


 Z. ANDE, ROOTWAD SHOD ECREES PREPENDICULARLY FROM PLOND DIRECTION TO PROVIDE ADEQUATE DEPLECTION.


 A. ADDITIONAL ROOTWAD SHOULD BE STEAKE REMOTH OF HE LOWEST FOR OF REVET MEMTE.

 A. PLACE SHOWE AT LEAST 2 FEET DIREP INTO BANK AT BASE TO STABILIZE AND ANCHOR LOGS REYED WITHIN ADDITIONAL PROVIDED TO STABILIZE AND ANCHOR LOGS REYED WITHIN CARDS AND ANCHOR LOGS.
- 4. IF ACC STORE AT LEAST 2 FEET DEEP INTO BANK AT BASE TO STABILUSE AND ANCHOR LOUIS REYED WITHIN STREAMMENT SHOULD BE KEYED INTO STREAMBARK APPROX. B-12 FEET BEADWILL OVER TOP OF ROTOTRAD REVETIMENT WITH EDISTING STREET F POOTER LOUIS TO BE BETED INTO BANK TO PROTECT AGAINST UNDERSOUTHING AND PROVIDE STABILITY FOR ROTOTRAD.

 8. KEY ROTOTRAD AND POOTER LOUIS INTO STREAMBARK THROUGH EXCAVATION AND/ON TRENCHING. D. RESEARCH OF BE LIBED FOR 8 THE CITIZENS THAT AND THE

ROOTWAD COMPOSITE INSTALLATION





Slope Stabilization Seed Mix

Scarntific Name	Common Name	Or/Acre	
Anarapagan perami	Hig fricantism grass	30,00	
Anarouseren krapawkis	Liffle bluesterrigrans	20.00	
Avenus sortiva	Common Oat	100.00	
Bautelous curtipending	Side-pats granta	15,00	
Carex multimbergs	Sano bracked seage	3.00	
Comer pensylvanica	Common nak tedga	5.00	
Figwitt cantidwith	Canada wild ryu	47.00	
Dynus eleginosa	Virgoiewidiye	15.00	
Gijiçema ohsata	Total marvingrass	3.00	
Lesitaro es si Affordiro	Annual Rye	100.00	
Paristain Wegative	SWitch grass	8.00	
Surphastrum succes	indian grass	12.00	
Sportivarpertinato	Prairie cord grass	42.00	
Forbs Total	al .	710.00	
Scientific Name	Common Name	Oz/Acre	
Asolenius symmu	Common milkweed	2,00	
Asplenius Innovivoro	Swamp milloweed	10.30	
Aster Interessionus	Side flowering aster	0.30	
bidens franciasa	Common bulliars Nos.	(1.50	
Chamaechvistir/Sissuulata	Rámica pos	4.00	
Cowloquiti Sercerolatio	S and consupris	6.00	
Dalest purpowest	Plente prince dover	1.00	

Scientific Name	Common Name	Ox/Acre	
Asalemias symmu	Common milkweed	2100	
Asplenius incomata	Swamp milloweed	11:30	
Aster Introfficeus	Side flowering aster	0.30	
biocos franciasa	Common bulliurs Non-	(1.50)	
Chamaechristir/asusukita	Ramicipia	14.00	
Cowlegas is receptable	Sand consupres	6.00	
Davint puvptivnesi	Plenie prince driver	7.00	
Гобилосея раурител	Purple moellineer	6300	
Eutrochilm maculatum	interprement	(0.30	
Herontius occidentals	Western swifftiwe	1.00	
Koelenis pyromidata	hunt-grass	1.00	
Louisio siphilikka	Great blue Inbella	0.25	
Lupinus parennis	Wild Appins	1,00	
Misonide filminal	Wild bengamed	5,00	
Dimovrhize skytrini	Heiry sweet (skel)	.0.20	
Padbeck on the	Black-cyted susan	7,00	
Solanga rigida	Soft golderrad	1.00	
Sofalago religaso	Rough galderrod	0.50	
Σρίσουν μυκ <i>ήσ</i> ου	Hm leaved golderwood	1.00	
Tot	61.A5		

12 SEED MIX

FINAL DESIGN

DETAILS 40

MAINSTEM POND TO CENTURY AVENUE
DETAILS
DANE COUNTY, WISCONSIN

Pheasant Branch Streambank Restoration and Habitat Enhancement Project

North of Century Avenue

PROPOSED CONDITIONS 0+00 - 5+00

City of Middleton, Dane County, Wisconsin City Project 18-125k

April 2021

SHEET INDEX

SHEET	DESCRIPTION	11	PROPOSED CONDITIONS 15+00 - 20+00
1	TITLE SHEET AND SHEET INDEX	12	DETAILS
2	EXISTING CONDITIONS 0+00 THROUGH 30+00		DETAILS
2	EXISTING CONDITIONS 0+00 THROUGH 5+00	13	DETAILS
3	EXISTING CONDITIONS 0-00 THROUGH 5-00	14	DETAILS
4	EXISTING CONDITIONS 5+00 THROUGH 10+00	45	
5	EXISTING CONDITIONS 10+00 THROUGH 15+00	15	DETAILS
		16	PLANTING AND EROSION CONTROL PLAN
6	EXISTING CONDITIONS 15+00 THROUGH 22+00		











LE SHEET AND SHEET INDEX
Pheasant Branch:
North of Century Avenue
Middleton, Dane County, Wisconsin


ESPANED BY: MTP/ACS
ATE: MARCH 2001
30 HC: J190357800


FINAL


DRAWING NO.


1

































- 2. All acaptment working in and around the stream channel shall be five of fluid leaks.
- Cere shall be taken to minimize equipment access to stream channel and fipellan areas to prevent unnecessary damage or impacts.
- 4. All materials shall be inspected prior to installation and free of eny damage or defects.
- Streambank eries shall be stabilized immediately following rootwed installation.
 Stope areas shall be installed effer stabilization of the streambank.
- Clear vegetation and grade existing steep upper edges of slope to a minimum 1.1 slope of flatter.
- 7. Seed slope area using Dry Sandy Slope Mix specified.
- 8. Install NAG C-1256N or equivalent (coli based, long-term) in all sandy areas requiring wrosion control brankeling.
- Due to the sandy nature of the soil on the site use 18 inch or longer wooden stakes to enchor blankets.



6 EROSION CONTROL BLANKET DETAIL

THE PROPERTY OF THE PROPERTY O

SEAMET COD

Š


WWOOD DRIVE W 53562 11-2855 Fax 6084


DESIGNED BY: WTRIACS
DATE: MARCH 202
LOS NO: LOSSSTOR

FINAL

DRAWING NO.

14





PHEASANT BRANCH CREEK TRAIL AND BRIDGES RECONSTRUCTION

CITY OF MIDDLETON DANE COUNTY, WISCONSIN CITY PROJECT 18-125N





LOCATION MAP

SHEET INDEX

O - GENERAL SHEETS

PP 17

TITLE SHEET TITLE SHEET PROJECT OVERVIEW AND CONTROL POINT TABLE TYPICAL SECTIONS SECSION CONTROL DETAILS PARLING DETAILS PROSION CONTROL PLANS TRAFFIC CONTROL PLANS TRAFFIC CONTROL PLANS

A - ALIGNMENT PLAN PHEASANT BRANCH CREEK TRAIL AUGMMENT PLAN PHEASANT BRANCH CREEK! NORTH FORK TRAIL ALIGNMENT PLAN

BRIDGE & TRAIL ALIGNMENT PLAN PP - PLAN & PROFILE SHEETS PHEASANT CREEK TRAIL PLAN & PROFILE SHEETS PP 1-15 NORTH FORK TRAIL PLAN & PROFILE SHEET DRIDGE A TRAIL PLAN & PROFILE SHEET

B - BRIDGE PLANS GENERAL NOTES DRIDGE 1 B-13404 GENERAL PLAN BRIDGE 2 B-13403 GENERAL PLAN BRIDGE 3 B-13402 GENERAL PLAN DRIDGE 4 B-13407 GENERAL PLAN BRIDGE 5 B-13-630 GENERAL PLAN DRIDGE 6 G-13-629 GENERAL PLAN

CS - CROSS SECTION SHEETS
CS 1-80 PHEADANT CREEK TRAIL CROSS SECTIONS
CS 61-65 NORTH FORK TRAIL CROSS SECTIONS
CS 56-61 ARDIGE A TRAIL CROSS SECTIONS







DOMESTIC WORTER MAIL DOSTING WATER MAIN WAIVE & HYCSRAY DON'THIS WATER SERVICE & CLERK STOP. PROPOSED WATER MAIN, VALVE, & HYDRING PROPOSED WATER SERVICE & CLIPS STOP EXBTING SANTARY SEWER & WANHOLE PROPOSED SANITARY SEWER & WANTED E EXISTING PORCEIVAN

DON'T NO STORM SOWER & MART PROPOSED STORM SEWER A MALET PROPOSED STORM REWER & SAMPLOSE SUPPLIES IN SUPPLIES

SURRED GAS & VALVE BURRIED CARLETTS EVISION SURRELITE CONTRACTOR BURNELFRER OFFICE CHERNICAD LITELTY

RELEGIST TRAINS SKRTNG CLESS & GUTTER PROPOSED CLIRA & GUTTER EXISTING SICERALY. PROPOSED SEEWALK EXECUTIVE CONTRACTORS

RECOGNED CLAVERT SIES FRACE LINE DRAFFADE ARROY

SUPPRINCE DOM: THE MEY BANG INC. opinopphy (mig

TREE LINE SEND-MARK BOVERS BON BOD PARKETON'S DOWN! INLINY POLE & GUY

SCHEROS LIGHT POLE PRINCIPAL STREET STON IN RO FLAGROLE

TREE-SECONOM TODG: (YWIGGON W TRUE TO BE REMOVED.

UTILITIES.

GAS MADISON GAS & ELECTRIC CONTACT: SHAUN ENORES P.O. BOX 1291 MADERON WIARRO (808) 253-7224 SENDRESEMBE COM WORKPLANSEMBE, DOM

ELECTRIC: MACISON BAS & ELECTRIC CONTACT: TONY SANFRATELLO P.O. BOX 1231 MADISON, WI 53T01 O. (608) 254-7379 ASAMPRATELLOGINGE.COM

FUELIC WORKS / CITY ENGINEERS CONTACT: SHAWN STAUSKE - PUBLIC WORKS DIRECTORICITY ENGINEER 7426 HUBBARD AVE. MEDDLETON, WE 53562 (908) 821-6381 SSTAUSKERGE MIDDLETON, MIJUS

SEWER & WATER: CITY OF MIDDLETON CONTACT: DAVE SARBACKER - UTILITY MANAGER 7428 HURBARD AVE. (908) 821-8275 DBARBACKER@CLMIDDLETON,MJUS

TELEPHONE & CATV. TOS & MID-PLAINS TELEPHONE MADISON, WI 53717 (808) 275-7104 JEFRY MYERS GTOSTELECOM COM

CHARTER COMMUNICATIONS MADESON, WI 53716 (808) 201-1321



or (800) 242-8511 www,DiggersHotline,com

NOTE
UPLIFF LOCATIONS SHOWN ON PLANS HIS APPROXIMATE AND CONTRACTOR
SHALL HAVE APPROPRIATE UTILITY MARK EXACT LOCATIONS PROPE TO
CONSTRUCTION


			900	696
THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAME	COMMITTED AND	\times		
	COMPANY OF SER			
	COMPANIES FT. SCHOOL			





PHEASANT BRANCH CREEK TRAIL & BRIDGES


TITLE PAGE

07











CONSTRUCTION SITE **EROSION CONTROL REQUIREMENTS**

- SECTION AROTE IN OF WISCOMEN STATE ADMINISTRATIVE CODE IDENTIFIES REQUIREMENTS. FOR CONSTRUCTION STE WID POST CONSTRUCTION SROSICN CONTROL. IT IS THE INTENT OF THESE PLANS TO SATISFY THESE USES, INCREMENTS. THE INSTRUCTOR AND STRUCTURES USES. TO CONTROL FROMON SHALL SETTHE RESPONSESLITY OF THE CONTRACTOR: CONTRACTOR SHALL SIPLEMENT AN APPROPRIATE MEANS OF CONTROLLING EROSON DURING SITE OPERATION. AND LIVITE, THE VESSETATION IS: RE-ESTABLISHED. ADJUST MIRVES TO THE CONTROL SYSTEM
- SHALL BE MADE AS REQUIRED ALL MORE SHALL BE IN ACCORDING WITH THE LATEST FOR CHILD THE WISCONDINGSING. CONSERVATION PRACTICS STANDARDS THESE STANDARDS ARE PERIODICALLY UPDATED AND IT IN THE CONTRACTOR'S RESPONSIBLITY TO ORTHAN AND REFERRINGS THE MOST RECENTLY RIELEASED STANDARD
- 1. THIS RECEMBTION IS ONLY ONE PART OF THE OVERALL EROSION CONTROL REQUISEMENTS. ADDITIONAL REQUIREMENTS MAY ALSO BE SHOWN ON THE CONTRACT DRAWNOR AND IN THE
- ACCOMPANYING SPECIFICATIONS.
 ADDITIONAL PROSENS CONTROL MEASURES, AS REQUESTED IN WAITING BY THE STATE OF LOCAL INSPECTORS, OR THE OWNER'S ENGINEER, SHALL BE INSTALLED WITHIN SAHOLIPS.
- THE AREA OF ERCOUNS LAND EXPONED TO THE REMENTS BY OPLINENCE EXCHIATION. TRENCHING RORROWAND FILL OPERATIONS AT ANY ONE THE SHALL BE WINNESSED TO THE MACHILIA EXTRAT PRACTICABLE, FOR MAY DISTURBED AREATHAT REMAINS MACTIVE FOR GREATER THAN TWORKING DAYS, OR WHERE GRADING WORK EXTENDS SEVEND THE PERMANENT ASSEMBLISHED THE SITE MEDIT OF TREATSD WITH TEMPORARY STABLE PATION MEASURES INCH AS SOIL TREATMENT, TEMPORARY SEEDING AND/OR MULCHING ALL DISTURBED AREAS SHALL BE TREATED WITH PERSONNING STARK STATION MEASURES WITHIN EMPRIME DAYS OF FINAL SEACHER
- ALL ERCRICH CONTROL MEASURES AND STRUCTURES SERVING THE SITE HUST BE IMPRICATED. AT LEAST WEEKLY OR WITHINGS HOURS OF THE TIME OF INCHES OF SAN HAS DOCUMEND. ALL NECESSARY REPAIR AND MAINTHUNGS WILL BE DONE AT THIS INSPECTION THIS.
- ALL ERCORON CONTROL DRIVERS AND/OR STRUCTURES SHALL HE PROPERLY INSTALLED PRICE TO CLEARING MID GRUSSING CHERKTICAS WITHIN THEIR RESPECTIVE DRAINAGE AREAS. THESE SHALL BE PROPERLY MAINTAINED FOR MAXIMUM EFFECT VENERAL LISTS. VEGETATION SERVICE SHEET
- ALL PROBLEM CONTROL DEVICES SHALL WE PROPERLY INSTALLED PRIOR TO ANY SOL DISTLIBRANCE. MY SLOPES STEEPER THAN 3HTV SHALL 66 STAKED WITH GROSION CONTROL FARRIC LINLEGS
- RESCATED ON THE PLAN. NO ALL WASTE AND LAURED BUILDING WATERIALS (INCLUDING SARRAGE OSIRIS, CLEANING WASTES).
- WASTEWATER TOXIC MATERIALS OR HAZARDOUS WATERIALS SHALL BE PROPERLY DISPOSED OF MICH NOT ALLOWED TO BE CARRIED OFF MITE BY RUNGET OR WIND.
- 11 WIND EFCISION SHALL SE KEPT TO A MINIMUM DURING CONSTRUCTION. WATERING, MULCH, OR A TACKING AGRIT MAY BE REQUIRED TO PROTECT NEAREN RESIDENCES AND WATER RESIDENCES.
- 12. CHAMPIELDED RUNDE ENTERING THE PROJECT SITE FROM ADJOINING LANDS SHALL BE DIVERTED THROUGH NUTURALLY OR ARTERCIALLY PROBLEM RESIDENCY CONFERENCES. IF CHANGE ZEO RUNCET CANNOT RE CARRETED, SITE NEW MANAGEMENT PRACTICES IN ST ACCOUNT FOR THE ADDITIONAL PLOWRATES AND EROSION POTENTIAL THAT SUCH RUNDER PRESENTS.
- 13. THE CONTRACTOR BHALL TAVE ALL POSSIBLE PRECALITIONS TO PREVENT BODD FROM BEING TRANSPORTED TO DESCRIPTION DE DESCRI SITE VEHICLE ACCESS SHALL BE SIMPT MOVICE SCRAPED (NOT ELISHED) PERIODICALLY TO REMOVE SOIL ORT, WOODS DUST
- 14 PROSION CONTROLS SHALL BE INSTALLED ON THE DOWNSTREAM SIDE OF TEMPORARY STOCKPLES. MAY SOL STOUGHTLE THAT REMAND FOR MORE THAN 30 DAYS SHALL BE CONFRED OR TREATED WITH STARL DATION PRACTICES SUCH AS TEMPOSARY OR PERSONNELT SEEDING AND MILL OF MILL. ALL STOCK PLES SHALL BE PLACED AT LEAST IS THEY FROM STREAMS OR WETLANDS.
- 15. ADDITIONAL FROMOS DON'TROL FOR LITELTY CONSTRUCTION (STORM SEWER, SWATTARY SEWER. WALES MYST ELCTOWNT MOTTOR THE KOTTOMBOS.
 - A PLACE EXCHINITIES TRENCH MATERIAL ON THE HIGH SIZE OF THE TRENCH.
 - IS GROWN IN COMPACT AND STADE OF THE TREME HARDINATE VIATED DIDE CONSTRUCTION. CONCHARGE OF THE NON WATER OR DEWATERING EFFICIENT MUST BE PROPERLY TREATED. TO REMOVE SEDMENT IN ACCORDANCE WITH THE WORK CONSERVATION PRACTICE. STWICKED 1011 - DEVINTERING OR A SURBEQUENT WONE DEVINTERING STANDARD PRIOR
- TO DISCHARGE INTO A STORM SEWER DITCH DRAINGEWAY, OR WETLAND OR LAVE 16. ALL DRAINGE CLAVIFITY, STORY DRAIN WAFTS, WANHARD, OR MY OTHER EXISTING STRUCTURES. THAT COULD BE DRIMAGED BY BEDIRENTATION SHALL, BE PROTECTED ACCORDING TO THE WARKOUS METUROS DECIMINATION IN THE PREVIOUS CONSERVATION PRACTICE STANDARDS.
- 17: MAY SOL EROSION THAT COCURS AFTER FINAL GRACING MICHOR STANLIZATION MUST BE REPARED WID THE STABILIZATION WORK REDOKE.
- 16. THE PIRKT BUT WEIGHT AFTER INITIAL STARLIZATION, ALL NEWLY SERDED AND MILITIAGO AREAS SHALL WATERED WHENEVER I DAYS ELAPSE WITHOUT A RAIN EVENT.
- 19 WHEN THE DOTURGED AREA HAS BEEN STABILIZED BY PERMANENT VEGETATION OR OTHER MEANS. TEMPORARY EMPS SUCH AS SUT FENCES, STRAW BALES, AND SECURENT TRAPS SHALL BE REMOVED. AND THESE AREAS STARK, \$250
- 20 ALL TEMPORIDO REST MANAGEMENT PRACTICES SHALL BE MANTANED UNTO THE SITE IS STADE OF IT.
- 21 ALL DISTURBED AREAS SHALL BE PERMANENTLY STABILIZED WITH SEED AND MULCHUM RISK OTHERWISE SPECIFIED. A MINIMUM OF FOUR FICHER OF TOPSOL SHALL BE APPLIED TO ALL ARREAS TO BE SEEDED OR SCHOOLS









worths INTERESTANCES THAN THOSE SHOWN REQUIRE A SPECIAL DISSION.

LIGHT RESIDENCE SHALL BE UNDERLAN WITH THE REPAIRED.
MEDIAN AND HOLVE SHALL BE UNDERLAN WITHIN HE PROFILE. (TOPOR NEW OPER TENTON OR SOLE), TO STILLSE UK.

ON THE POSITION OF BLANKET AND UNES BEED AND COMPACTED BOY. SHOWS A LANGET OVER COMPACTED BOY.

PREPARE SOIL REPORT HIS FALLING BLAVIETS, INCLIDING ANY NECESSARY APPLICATION OF LINE, FERTILIZER, INC. BEING AT THE USE OF THE BLOOK OF ANOTHER THE BLOOK THE BLOOK THAT THE OR DESIGN AT THE BLOOK THE BLOOK OF THE BLOOK THE BLOOK OF THE BLOOK THE BLO

- SOL THE SLANGETS IA DOWN US IN HORIZONTALLY ACROSS THE SLOPE. PLANGETS WILL UNDOLL WITH APPROPRIATE SIZE. ACADMST THE SIZE. SLANGES. ALL BLANGETS BOTT SE RECURSORY FASTERS TO DISC. BY PLANGE STAR SIGHT WAS IN APPROPRIATE LOCATIONS AS RESIZEN. IN THE STARP IS NOT THESE VIOLES.
- THE ROSES OF PARALLEL SEANNETS MUST BE STARLED WITH APPROXIMATELY 2"-0" (6 CM-12.5 CM) OVERLAP DEPENDING ON REASORT TYPE
- 5 CONSECTIVE ILLABORIS SPUCIO DOWN THE SLOPE MUST HE PLACED RID OVER SHO SHIRKLE STYLE) WITH AN APPROXIMATE 2 7 5 CB CONTRA STARLE THROUGH CHERLIPPED AREA APPROXIMATELY STYLE OR APART ACROSS RITHS HAMBELY WITH.

LODIE SOIL CONDITIONS. THE LISE OF STARLE OR STARE LENGTHS GREATER THANKS (IS CM) MAY BE SERVEY TO PROPERLY SECURE THE SLAWSTS.


EROSION CONTROL BLANKET DETAIL

GENERAL NOTES - INLET PROTECTION


PLET PROTECTION DEVICES SHALL SE MAINTAINED OR REPLACED AT THE DIRECTION. OF THE ENGINEER WHEN PERCOVING OR WANTAHING INLET PROTECTION, CARE SHALL BETWEEN SO THAT THE SECREDIT TRAPPED ON THE SECREDIT LE PARRICIDORS NOT FALL BITD THE RUET ANY MATERIAL FILLING BITD THE RUET SHALL BE REMOVED. INDEPENDENT Y

RIP RAP AT OUTLETS

SEFER TO THE CITY OF MIDDLETON STANDARD DETAIL FOR MUST PROTECT ON TYPE D. AND SPORCE WATTLES IN APPENDIX A



TYPICAL RIPRAP INSTALLATION.



EROSION CONTROL WATTEL DETAIL


			j	100	Allegan	- 11
ALC: U.S.	100405-017	-		100		7.7
	100,000,00	100				
	THE PROPERTY.	1000				





PHEASANT BRANCH CREEK TRAIL & BRIDGES CITY OF MEDILETON DANE COUNTY, WISCONSIN


EROSION CONTROL DETAILS


DARCHONA GS



































		-	19.16	MOMES .
MURIT WITE	· Market de			
	DEPOSITE OF COR	-		
	000000 PT 1000			


M8A THE


PHEASANT BRANCH CREEK TRAIL & BRIDGES GITY OF MIDDLETON DAME COUNTY, WISCONSIN


PHEASANT BRANCH CREEK TRAFFIC CONTROL PLAN


04925054














































































ADUTMENT BACKFILL DIAGRAM

I DITTOUT OF SUMMENT PRINCIPLE OF SUMMENT FOR FEBRUARY AND FEBRUARY OF SUMMENT OF SUMENT OF SUMMENT OF SUMENT OF SUMMENT OF SUMMENT OF SUMMENT OF SUMENT OF SUMMENT OF SUMMENT OF SUMMENT OF SUMMENT OF SUMMENT OF SUMMENT OF SUMENT OF



THE TANKED NATES

WEST SHELD NO SLOTE ASE VENTICAL.

THE SHENT SHELD SHALL SEE A SECTION.

THE SHENT SHELD SHALL SEE A SECTION SHELD SHALL SHALL

RODENT SHIELD

S - SMECONS WE APPROXIMATE THE COURT
IS SEED TO FIT WITO A 1995 CONTRACT.

DENERAL NOTES

HAR HTELL PERFORMENDAT WALL HE BARESTED WITLEAS TALESS SHOWN IN NOTE: OTHERWISE.

THE ATTECH PERFORMANCE MILLION IN THE HIS TIEM THE WORKETE WITHOUT HIS HELIOUL PILES.

THE U.S. IF THE BILL IN FRANCY OF THE ANDROPHING HE AS IN PROPERTY AND ADDRESS THE BIRDS THAT IN THE CONTROL THE BIRDS THE BIRDS THE BIRDS THAT IN THE CONTROL THE BIRDS THE BIR

THE EXISTING OPCOMENDES MALL BE THE OPPOSITIONED OF CHEAVATER FOR STRUCTURES FOR THE ABSTRACTS AND SHALL HE WILLIED IN THE NO TIBE "STRUCTURE EXCLUSION AND STRUCTURE INCOPPLE,"

S-MARIL STACT & THE ME HE HE HE HE HELD WITHOUT AND THAT WAS FOUND FOR HELD WHILE SHALL OF MALCOUNTY HE BE THE STRUCTURE BUT AREA AND STRUCTURAL SACRELY LAND OF BREATHER WHILE HE CETEMACH IN THE DESIGN OF THE THE CONTROL OF THE PERSON OF TH


ENTARTISM PEON THE AUTHORY WE MAINTAIN TO BE IN MATERIAL THE PEON PEON ANTWAL, EXPLORATE THE OF SHALL BE SET AT THE SOTTON OF DECEMBER AND EXTENDED 2-5-SOCK SOTTON OF MATERIAL SOTTEMBER THE BY WHALL TE WILLIES IN THE WITTEN THE DEPONDED AND ATTEMPT.


PROTECTIVE SCHALE THE TOPIC THALL SE AFFICE TO ALL EMPISE PARTS OF THE AUTHORITY AND ANGEL ANGEL AND AND ANGEL AND AND ANGEL AND ANGEL AND ANGEL AND ANGEL AND ANGEL AND ANGEL AND AND ANGEL AND ANGEL AND ANGEL AND ANGEL AND ANGEL AND ANGEL AND ANG


REMOVE SALVACE AND REMOTALL THE PERSONAL PROCESSIVE STRUCTURES ON STRUCTURES SHOWARD INCHESS. INCHEST AND ART, IN 19-400, THE-PART AS MOTER IN THE SPECIAL PROMISION.


SEASON IF ENGINE MEANING has THE BELLICED IN THE NO LITER "PERMISS NALVAKE AND SEASONAL SEPERTHAN SHOULD SHOULD SHOULD SHOULD SELECT SERVICES SHOULD SHOULD


Bevel envision baces of concrete the latest conclude hores.






















ELEVATION LOOMING AT FRONT FACE OF ABUTAENTS




NOTES: OISPLACE STIRRIUPS IN HACKWALL TO MISS PLING AS NEEDED SEE SHEET BE FOR HEAVING CONNECTION DETAIL



LEGEND

- CONSTRUCTION JOINT FORWED BY BEVELET 2NA, FLACE
- SEE GENERAL PLAN FOR ELEVATION
- Elmension determined by As-Built Plans, Actual Dimensions shall be field verified by the Contractor and Adjusted As necessary
- ●- +5 BART IN BACKWALL TO BE COATED
- A HORIZONTAL IS* WIDE RUSBERIZED WEMBRANE WATERPROPRING, PLACE ON R.F. OF CONST. JOINT AS SHOWN.
- O-PIPE UNDERDRAIN WRAPPED S-MCH, ENTEND THRU CEOTENTILE AT FAME OF RIPPAR HEAVY, SLOPE RUSH MK, OR SURAME DRAINAGE, PROVIDE RODERT PROTECTION AT ENDS OF MPE, SEE RODERT SHELD (ETAIL, SHEET IN).

F.F.-FRONT FACE D.F.-BACK FACE (L-SLEAN





PLAN


MSA MINING


PHEASANT BRANCH CREEK TRAIL & BRIDGES
CITY OF MIDDLETON
DANE COUNTY, WISCONSIN


ABUTMENT DETAILS 16-12-457 (BRIDGE 4) D4852204
















111	П		H									1				H		1				F			1									H		H	H	H		H	1							H	#	H		ļ
1	Ħ	H	#		Ħ	Ħ	H		ŧ	Ħ	H	#				Ħ	H	ŧ			Ħ	#			Ħ	H	Ħ			Ħ	Ħ	H		#	Ħ	Ħ	#	H	#	Ħ				Ħ	H			Ħ	Ħ	Ħ	#	#
Ш	H	Ш	Ħ		Ħ	Ħ		H			H	ŧ				Ħ		Ŧ	Ħ		Ħ	1		Ħ	Ħ		Ħ			Ħ	Ħ	Ħ	\pm	#	Ħ	\pm	Ħ	H		H					Œ			Ħ	#	H	İ	
į, į	Ħ		#		H	Ħ					Ħ			H		Ħ		÷			Ħ	+	Ħ	Ħ		Ħ	Ħ			H	Ħ	Ħ	#	#	Ħ	Ħ	#	H	#	Ħ				Ħ	H			Ħ	#	Ħ	+	
845	Е	Ш	H		H	H					H	I				H		Ε	E		Н	Ξ		H	H		H			H	H	Н	Η	H	Η	H	\blacksquare	П		H			H		Œ			H	\blacksquare		Ξ	
170	H		#		H					H	H		H	Ħ	H	Ħ			H		Ħ	+	H	Ħ	Ħ	H	Ħ			H	H	H	#	#	H	†	#	H	#	H			H	Ħ	Ħ	H		Ħ	#	H	#	
1111	H		Ħ		Н	П	П				H	I				H	П	Τ			Н	Ε		H			H			H	Н	П	H	H	H	П	H	Н	1	H			H		Œ	H		Н	H	П	Ξ	
HH:	H	##	#	H	Ħ	Ħ	+	-	ŧ	Ħ	Ħ	+	H	Ħ	H	Ħ	#	+	H	H	Ħ	#	H	Ħ	Ħ	H	Ħ		#	H	H	Ħ	#	#	Ħ	#	#	Ħ	#	H				Ħ	H	H	H	Ħ	#	Ħ	#	,
3	Н		H		H	Н		H		H	H				Н	H		-	E	Н	Н				H	H	H			H	H		\mathbb{H}		\exists	\blacksquare	\exists	H						Н	H	\pm	H	H	H	\blacksquare	1	
Ш	Ħ	#	10	H	Ħ	Ħ	Н	#	Ŧ	Ħ	Ħ	Ŧ	H	Ħ	H	Ħ	H	1	Ħ	H	Ħ	+	Ħ	Ħ	Ħ	H	Ħ		H	Ħ	Ħ	Ħ	Ħ	#	Ħ	#	#	Ħ	#	Ħ			H	Ħ	Ħ	+	Ħ	Ħ	#	Ħ	ŧ	,
Ш	Н		\blacksquare		H	H		\blacksquare	\pm	H	H				Н	H			E	Н	H	41			H	H	\exists			Н	H	\blacksquare	\mathbb{H}	1	H	Ħ	\exists	Н						Н	H			H	\blacksquare	\blacksquare	1	
Ш	Ħ	#	4		Ħ	Ħ	Ħ	#	#	Ħ	Ħ	+	H	Ħ		Ħ	Ħ	+		H	Ħ	1	1 1 1 1 1 1	m	1	100	#	-14	ń.	4	9	H	#	#	H	Ħ	#	H	#	Ħ				Ħ	Ħ		Ħ	Ħ	#	14	4	
Ш	Η	Ш	\pm		H	H		H	1	H	H	+		H		H		1		П	Ħ	-	E	Į,	H	Ħ	Ħ		E	世代	Н	10.25	4	\mathbb{H}	Ħ	H	\mathbb{H}	H	1	H			H		Œ	\pm	H	H	Ħ	H	+	
Ш	Ħ	#	1	1	Ħ	Ħ	Ħ		ŧ	Ħ	Ħ	+		Ħ	Ħ	Ħ	Ħ	1		Ħ	Ħ	ŧ	70	7	Ħ	Ħ	Ħ			7	Ħ	Ϊ	Ĭ	#	Ħ	Ħ	Ħ	H	#	Ħ			H	Ħ	Ħ	Ħ	Ħ	Ħ	#	14	4	,
1	H	Ш	\blacksquare		H	H		H	Ŧ	H	H	Ξ		Ш		H		Η	E		H	Ξ		H	Œ	H	H				H	H	\pm	\mathbb{H}	H	\blacksquare	\mathbb{H}	H	1	H			H	H	Œ	\pm	H	H	\mathbf{H}	H	+	
Ш	н	Ш	14		Н	Ħ		-	#	H	H	+		Ш	Н	Ħ			н	Н	Ħ	+	н		1			'n	90	Н	H	Н	#	#	Ħ	#	#	Н		Ħ	+		H	ш	H	H	Н	Ħ	#	14	ŧ	
Ш	Ħ	Ш	*		1	Ħ		٠			Ħ	+		1		1	4	1	4		Ħ	*	Ų,		Į.		Į	1100			Ц		*	#	Ħ	Ш	#	Ŧ	#	1	Ų.		*					1	#	H	٠	
Ш	Ħ	111	#		Ħ	Ħ		-	#		Ħ	-		#		Ħ			H		Ħ	-	П	H	18	*	Ŧ	rde:	da	П	Ħ	H	#	#	Ħ	Ħ	#	Ħ	#					н				Ħ	#	Ħ	#	
	H	\blacksquare	\blacksquare		H	H	H	H	İ	H		ŀ				Ħ	H	H	Ė		H	1		H	H		H			Ħ	H	H	\blacksquare	H		\mathbb{H}	H	Ħ		Ħ					H			H	\blacksquare	H	İ	
Ш	H	111	H		H	H		H	1	H	H	1			H	Ħ		H		H	H	1	H	H	H	H	H				H	H	Ħ	H	H	Ħ	Ħ		#	H				H	H			H	Ħ	H	1	
MSA	Ħ		#			Ħ				Ħ	H	İ			Ħ	Ħ	Ħ	İ	Ė	Ħ	Ħ	1			Ħ	Ħ	Ħ				Ħ	Ħ	\pm	Ħ	Ħ	Ħ	Ħ			Н					Ė		Ħ		Ħ	Ħ	1	
	Ħ	111	#		Ħ	Ħ	H	Ħ			Ħ	+				Ħ					Ħ	1		#	H	1	Ħ			H	H	#	#	#	Ħ	#	Ħ	Ħ	#	H				1	1	1		Ħ	#	Ħ	1	
=	Ħ	\blacksquare	\mathbb{H}		H	H					Ħ	I			Ħ	H				Ħ	H	-		H	Ħ	H	H				H		H	H	Ħ	H	\blacksquare			H			H		H			H	H		1	
200	H	111	1		H	H				H	H	1		H		Ħ			F		H	1	H		Ħ	Ħ	Ħ			H	H		#	#	H	#	#	H	#	Ħ					F		H	#			1	
5	H		#		Ħ	H	Ħ	Ħ		H	Ħ			Ш		H	#		Ė		H	1	to .	Ħ	Ħ	H	Ħ		Ħ	Ħ	H	Ħ	Ħ	H	Ħ	Ħ	Ħ	Ħ	1	H			E		Œ			Ħ	H	Ħ	1	
٠.	Ħ	##	4		Ħ	Ħ	+	#		Ħ	Ħ	+	H	#	H	Ħ	#	+	H	H	Ħ	1	2		1	52	Ц	14	1	18	M	H	#	Ħ	Ħ	#	#	Ħ	#	H				Ħ	Ħ	H	H	Ħ	#	14	¢	
IN	H	Н	H		H	Н	\mathbb{H}	H		H	H	÷			Н	Ħ		-	Ė	Н	H	Ŧ	現状	Į,	Ħ	Ħ	Ħ	Ŧ	\pm	100	H		1	#	Η	\pm	\pm	H	#					H	H	\pm		H	Η	\pm	Ξ	
低	Ħ	111	19	H										H		Ħ		1			Ħ	+	1	7	H	H	H		ď	75	H	90	7	#	H	Ħ	#	H	#	H	-	-						H	#	14	4	
讍	H				H		Н	H		H	H	Ŧ		H	H	H	\mathbb{H}	1	E	H	H			H	H	H	H				H	\blacksquare	\pm	#		\exists	\pm	H				-			H			H	Н	\pm	1	
HI.	Ħ	#	4				H							H		H		1			Ħ	+			1		披	+ 0	98		H	Ħ	Ħ	#	H	#	#	H	#	H	-							H	#	14	4	
115	Ħ		*		1	Ħ		*	ŧ	Ħ	H	İ		1		1	H		4		Ħ	*			ij.		Į.	1/80	100			U	٠	#	H	Ħ	Ħ	*	#	1	Ŧ		*	Ħ	H			1	Ħ	Ħ	ŧ	
	Ħ	Ш	H	П		Н	П		I		H	T	H			H		Ŧ			Н	Ŧ	П	F	H	*	+	de	dd	H	H	F	H	H	H	П	Н		П	П	1		E		H		П	П	H	П	Ξ	
	Ħ	#	Ħ		Ħ	Ħ	Ħ		ŧ		Ħ	Ŧ				Ħ	Ħ	İ			Ħ	ŧ	Ħ		Ħ	Ħ	Ħ		Ï		Ħ	Ħ	\pm	Ħ	Ħ	††	††	H		Ħ			H				Ħ	Ħ	Ħ	†	1	
2	Н	Ш	H			H		-				1				Ħ		+			Ħ	-		H		Н	H				Н	Н		1	H		Н		1	Н					H			H		Н	Ξ	
PHEASANT SPANCH OSESX TRALL & BRIDGES OFF CHARGOINT, AND CHAR	Ħ	##	#	H	Ħ	Ħ	H			Ħ	Ħ	ŧ	H	Ħ	H	Ħ	Ħ	Ŧ	Ħ	H	Ħ	+	Ħ	Ħ	Ħ	Ħ	Ħ			Ħ	Ħ	Ħ	#	#	Ħ	Ħ	Ħ	Ħ		Ħ			Ħ	Ħ	Ħ	Ħ	Ħ	Ħ	#	Ħ	ŧ	
8	Н	Ш	H		Н	H				H	H					Н			E	Н	H				H		Н				H	Н	Н	1	Н	\blacksquare	\blacksquare	Н	Н						H			Н	H	H	1	
2 9	Ħ	##	#	H	Ħ	Ħ	H		Ŧ	Ħ	Ħ	ŧ		Ħ	H	Ħ	Ħ	Ŧ	Ħ	H	Ħ	+	Ħ	Ħ	Ħ	Ħ	Ħ			Ħ	Ħ	Ħ	\pm	#	Ħ	Ħ	Ħ	Ħ		Ħ			Ħ	Ħ	Ħ	Ħ	Ħ	Ħ	#	H	ŧ	
98	H	\blacksquare	9		H	Н				Н	H				Н	H				Н	Н	I			H		H			H	H	Н	H	\blacksquare	H	H	H	Н		Н					H			H	H	14		
243	Ħ	#1	#	Ħ	Ħ	Ħ	Ħ	#	#		Ħ	+	H	Ħ	Ħ	#	Ħ	+	H	Ħ	Ħ	4	6	Ħ	Ħ	Ħ	Ħ	#			Ħ	#	#	#	Ħ	Ħ	#	Ħ		Ħ		Ħ	H	#	Ħ	#	Ħ	Ħ	#	Ħ	+	
100	Ħ	Ш	H		Ħ	Ħ			Ξ		Ħ			Ħ		Ħ					Ħ	1	1	ye.	-5	Min.		ú	è	Ç.	5	П	Ħ	Ħ		\exists	Ħ	Ħ	#	Ħ					Œ			Ħ	Ħ		ŧ	
25.5	Ħ	##	#	Ħ	Ħ	Ħ	Ħ	#	+	Ħ	Ħ	#		H	Ħ	Ħ	#	1		H	Ħ	†	ı	ŧ	Ħ	Ħ	Ħ	Ŧ	Ŧ	1	H	1	Ħ	#	Ħ	#	#	Ħ	#	Ħ		Ħ	H	Ħ	Ħ	#	Ħ	Ħ	#	Ħ	#	
. 2	Ħ	Ш	H		H	H	1	-11		H	H	Ŧ			H	Ħ	\blacksquare	+		Н	Ħ	+	¥	Ŗ.	Ħ	H	H		B	뿧	Ħ	E9.	1	\mathbb{H}	Ħ	\pm	\pm	H		H		1	H		H		H	H	Ħ		÷	
9	Ħ	#	#	1	Ħ	Ħ	#	#	#	Ħ	Ħ	#		#	H	#	#	+	H	H	Ħ	#	H	Ħ	#	H	Ħ			H	Ħ	#	#	#	Ħ	#	#	Ħ	#	Ħ			Ħ	Ħ	Ħ	#	#	Ħ	#	Ħ	#	
20	Ħ	#	H		Ħ	Ħ				\pm				Ħ		Ħ		1	E		$^{+}$	=		Ħ	1					Œ	Ħ			#	Ħ	\pm	\pm	\pm	#				E		Œ			Ħ	#		ŧ	
968	H	#	+		+	Ħ	#	+	+	#	H	+			H	1	#	+	4	H	#	#		#	1	1	Ħ		4		H	#	#	#	Ħ	#	#	ŧ.	#	1			+	#	1		1	1	#	Ħ	+	,
	H	Ш	H		H	H	H	H			H	F			H	H	H	F	I	H	H	F	П	H	Ĥ	4	Ð	4	46	H	H	F	H	H	H	H	H	H		Ħ					Œ			H	H	H	1	
_	Ħ	##	#		Ħ	Ħ	#	#	+	#	#	+		#	H	#	#	+			#	+	#		#	#	Ħ		H		Ħ	#	#	#	Ħ	#	#	Ħ	#	Ħ				#	#	1	1	Ħ	#	Ħ	1	
	Ħ	H	Ħ	Ħ	H	Ħ	Ħ	Ħ	1		Ħ	F		H	Ħ	Ħ	Ħ	Ŧ		Ħ	Ħ	F	Ħ		Ħ	Ħ	Ħ		Ŧ	Ħ	Ħ	Ħ	Ħ	Ħ	H	Ħ	Ħ	Ħ	#	Ħ			H		Ħ	Ħ		Ħ	#	Ħ	1	
2	Ħ	111	#		Ħ	Ħ	#	#	-	#	Ħ	+			Ħ	#	#	İ		Ħ	#	+			H	#	Ħ				Ħ	#	#	#	Ħ	#	#	Ħ	-	Ħ				1	#	1	1	Ħ	#	Ħ	1	
東	H	H	H			H	H	-	E		H	Ŧ				H	H	Ŧ	E		H	E	H	H			H				H	H	H	H	H	H	H	H	1	H	+			H	H		H	H	1	H	1	
E	Ħ	##	#			Ħ	H	#			Ħ	1				#	H	+			#	+		#	#		Ħ				Ħ	#	#	#	Ħ	#	#	Ħ	#	Ħ				#	#	#		Ħ	#	Ħ	#	
PHEASANT CREEK TRAIL CROSS SECTIONS	H	111	-		H	H			I	H	H	1		H	H	H	1	1	F	H	H	F	H	H		H	H			H	H	H	H	H	H	H	H	H	1	H	+	1	F	H	Œ		H	H	1		1	
62.5	H		#		Ħ			#		H	Ħ	1				#						1	400	H	Ħ		Ħ	1	Ħ		H	Ħ	#	#	Ħ	Ħ	#	Ħ		Ħ			#					Ħ	#		1	
Tie	H		4		H	H					H	F		Œ	H	H	H		E	H		F	E.	996	- (3	200	H	1	13	Ů.	8	H	H	H	H	H	H	H		П					H			H	H	4		
10	H		1		#	Ħ														H	Ħ	1	1	J	Ħ	Ħ	Ħ	f	Ŧ	₹	社	45	1	Ħ	Ħ		Ħ	Ħ		Ħ						Ħ		Ħ	#		1	
8	H		14		H	H				П	H	-		Œ	H	H	H		E	H	H	E	72	7	H	H	H		H		Ħ	TT.	7	1	H	H	H	H				-		H				H	H	4		
8	Ħ				#	Ħ	Ħ	-	ľ	1	Ħ	-		#	Ħ	#	Ħ			Ħ	#	-1-	11	11	10	Ħ	Ħ		+	н	H	#	#	#	Ħ	#	#	Ħ	#	Ħ					1	#	1	Ħ	#	Ħ	1	
EGT	Ħ	Ш	H		Ħ	H					H					H					H	-			3				99	H	H	H	Ħ	H	Ħ		H	Ħ		H	T					Ħ		H				
No.	H	Ш	+		1			+	F	H		F		+	H	1	#				H	+			H		I		-	1	H		+	#	1	#	H	ŧ	#	1	-		+	H	F			1	H	H	+	
	Ħ	Ш			H	H				H	Ħ	İ				H	Ħ			H	H	-1'	• 0	ΤŸ	1	F.	T	47	7	T	Ħ	1	Ħ	H	Ħ		H	Ħ	1	Н					H			H	H		1	
	H		H		H	H		#	-	H	H	-		#	H	H			F		H	1		H	H	H	H				H	H	#	#	H	\parallel	H		#	H					F	1		H	H		f	
-	Ħ	111	#		Ħ					H	Ħ	1				#		1		H		+	H	Ħ	Ħ		Ħ				H	#	#	#			H			Ħ	1							Ħ	#		1	
1404	H		H		H		H			H	H	F		F	H		H			F		-			H		H					H	H	Ħ	Ħ	Ħ	H	H	1												1	1
24,180						**		-14	+	++	++	-		•				-	-			-1-	4.15	- 4									-4-1		-1		4.15															































































































































1 211			
2 2 2			
100			
1 1 1 1 1			
8 1778			
11/1			
111			
f III la	-686688888		
<u> </u>			
		The second secon	
ill III			
		71 L	
		8.00 mg	
51.11.	10	746 75 11 222	1 149
		ENTRE - 1962	
ШШ		to the table to table to the table to table to the table to	
шш		St A. P. 1504-50	
Ш			
ш			
95			
3			
₩8A	-	\$ B	
8			
		TOTAL WALL TO THE PARTY OF THE	
-11		9 9	
323			
	100		
THE R			
1446	100	Design value	
		PROTECTION OF THE PROTECTION O	
-	100000000000		
20			
2	+3		
. 6	-525555555		
- 8			
豆 粥			
695			
200		TOP SET AND DRAW AND LINES LINES	
300	1999999999	TOP ORTANGED DAYS - LANK LANK LANK LANK LANK	
aee		<u> </u>	
693	00000000		
PHEASANT BRANCH CREEK TRAIL & BRIDGES OTH CHARGOUNTY, MICCORN	1		
8	100000		
8	0.000	Distriction (a) which is	
22.	1111111		
1 1		i shay jacydd	
PHEASIMIT CREEK TRAIL CROSS SECTIONS			
		Toward Aprilla Mark. 1998 Long. 1999 Long.	
		The second secon	
F			
30			est trans
08	1111	<u> </u>	
-			
ECTIONS	100	- Department of the control of the c	
		District Texts Service Continues Annual Contin	
		Section (Company Compa	
		MAP INFA	
-			
ğ1 åt			
. 1	000000000		0.0010.000000.0000000000000000000000000
100	HELETISE S		






















all the		.	
10 10	H		
	H		
	H		
ž III	ы		
Ш	ı		
A Green	E		
1	H		
9 2	Н		
	1		
	П		
Ш	П		
The section of the section of	Н	19 19 19 19 19 19 19 19 19 19 19 19 19 1	S S S S S S S S
	П	76	2008 3008 P
	П	jab	
	П		
	П		
	L		
i i i i i	Ì		
	П		
	П		* * * * * * * * * *
	П		SFA = 800×30
	П		
	H		
ΙЩ	Ц		
ЩЫ	Ц		
1	١I		
9	۱		
3	1		
₩8A	١	100	
	١		26
l	٠l	, in the second	
12	1		
1862	ш	35	B B B B B B B B B B B B B B B B B B B
3	ğ.		
H	9		
	Ē		DESCRIPE 427 10 10 10 10 10 10 10 1
133	i		
	_		87A+900+25
	1		
Ι.	₋		
L	ž		
1 8	Ë		
1	Ę		
9	ġ.		
1 9	Ĕ	arb.	
200	Ŷ		
311	8		
* B	ë		
90	d		200 Jan 300 32-4
2	ĔĮ		
	2		
PHEASANT BRANCH CREEK TRALL & BRIDGES GITY OF MIGLETON DAVIS COUNTY, WISCONSN	8		[240001494_+at170
	9		Kdethick - let 2
I '	"]		
ı	١		100 A-T 040FU4
_	٦		
	١		
	١		
	١		
26	١		
BRIDGE 4 TRAIL CROSS SECTIONS	1		is in the second
	١		
	١		
	١		
	١	*	
	١		
	١	S	
	١		Delegation
	١		December 1 - 2015 Sec December 2 - 2015 Sec December 2 - 2015 Sec December 2 - 2015 Sec December 2 - 2015
	١		Description and the second seco
	١		STA + StOred
	ı		
⊢	4		
COSE COSE	,l		
8: 8	,		















State of Wisconsin / DEPARTMENT OF NATURAL RESOURCES

Tony Evers, Governor Preston D. Cole, Secretary Telephone 608-266-2621 Toll Free 1-888-936-7463 TTY Access via relay - 711 101 S. Webster St. Box 7921 Madison, WI 53707-7921

May 27, 2022

Eric Learn Wisconsin Emergency Management PO Box 7865 Madison, WI 53707

SUBJECT: Endangered Resources Review (ERR Log # 22-369)

Proposed Pheasant Branch Creek Bridges, Trails and Stream Stabilization, Dane County, WI (T07N R08E S12, T07N R08E S01, T07N R08E S11, T07N R08E S02)

Dear Eric Learn,

The Bureau of Natural Heritage Conservation has reviewed the proposed project described in the Endangered Resources (ER) Review Request received May 6, 2022. The complete ER Review for this proposed project is attached and follow-up actions are summarized below:

Required Actions: 2 species

Recommended Actions: 7 species

No Follow-Up Actions: 8 species

Additional Recommendations Specified: Yes

This ER Review may contain Natural Heritage Inventory data (http://dnr.wi.gov/topic/NHI), including specific locations of endangered resources, which are considered sensitive and are not subject toWisconsin's Open Records Law. Information contained in this ER Review may be shared with individuals who need this information in order to carry out specific roles in the planning, permitting, and implementation of the proposed project. Specific locations of endangered resources may not be released or reproduced in any publicly disseminated documents.

The attached ER Review is for informational purposes and only addresses endangered resources issues. This ER Review does not constitute DNR authorization of the proposed project and does not exempt the project from securing necessary permits and approvals from the DNR and/or other permitting authorities. Please contact the ER Review Program whenever the project plans change, new details become available, or more than a year has passed to confirm if results of this ER Review are still valid.

Please contact me at 608-264-8968 or via email at anna.rossler@wi.gov if you have any questions about this ER Review.

Sincerely,

Anna Rossler

Endangered Resources Review Program

cc:

The information from this report is being shared with individuals who need this information in order to carry out specific roles in the planning, permitting, and implementation of the proposed project.



United States Department of the Interior



FISH AND WILDLIFE SERVICE

Minnesota-Wisconsin Ecological Services Field Office 4101 American Blvd E Bloomington, MN 55425-1665 Phone: (952) 252-0092 Fax: (952) 646-2873

In Reply Refer To: June 03, 2022

Project code: 2022-0035393

Project Name: DR-4402-WI City of Middleton, Pheasant Branch Creek

Subject: Verification letter for the 'DR-4402-WI City of Middleton, Pheasant Branch Creek'

project under the January 5, 2016, Programmatic Biological Opinion on Final 4(d)

Rule for the Northern Long-eared Bat and Activities Excepted from Take

Prohibitions.

Dear Karie Roach:

The U.S. Fish and Wildlife Service (Service) received on June 03, 2022 your effects determination for the 'DR-4402-WI City of Middleton, Pheasant Branch Creek' (the Action) using the northern long-eared bat (*Myotis septentrionalis*) key within the Information for Planning and Consultation (IPaC) system. This IPaC key assists users in determining whether a Federal action is consistent with the activities analyzed in the Service's January 5, 2016, Programmatic Biological Opinion (PBO). The PBO addresses activities excepted from "take" prohibitions applicable to the northern long-eared bat under the Endangered Species Act of 1973 (ESA) (87 Stat.884, as amended; 16 U.S.C. 1531 et seq.).

Based upon your IPaC submission, the Action is consistent with activities analyzed in the PBO. The Action may affect the northern long-eared bat; however, any take that may occur as a result of the Action is not prohibited under the ESA Section 4(d) rule adopted for this species at 50 CFR §17.40(o). Unless the Service advises you within 30 days of the date of this letter that your IPaC-assisted determination was incorrect, this letter verifies that the PBO satisfies and concludes your responsibilities for this Action under ESA Section 7(a)(2) with respect to the northern long-eared bat.

Please report to our office any changes to the information about the Action that you submitted in IPaC, the results of any bat surveys conducted in the Action area, and any dead, injured, or sick northern long-eared bats that are found during Action implementation. If the Action is not completed within one year of the date of this letter, you must update and resubmit the information required in the IPaC key.

This IPaC-assisted determination allows you to rely on the PBO for compliance with ESA Section 7(a)(2) <u>only</u> for the northern long-eared bat. It **does not** apply to the following ESA-protected species that also may occur in the Action area:

- Eastern Prairie Fringed Orchid Platanthera leucophaea Threatened
- Mead's Milkweed Asclepias meadii Threatened
- Monarch Butterfly Danaus plexippus Candidate
- Prairie Bush-clover Lespedeza leptostachya Threatened
- · Rusty Patched Bumble Bee Bombus affinis Endangered
- Whooping Crane Grus americana Experimental Population, Non-Essential

If the Action may affect other federally listed species besides the northern long-eared bat, a proposed species, and/or designated critical habitat, additional consultation between you and this Service office is required. If the Action may disturb bald or golden eagles, additional coordination with the Service under the Bald and Golden Eagle Protection Act is recommended.

[1] Take means to harass, harm, pursue, hunt, shoot, wound, kill, trap, capture, or collect, or to attempt to engage in any such conduct [ESA Section 3(19)].

Action Description

You provided to IPaC the following name and description for the subject Action.

1. Name

DR-4402-WI City of Middleton, Pheasant Branch Creek

2. Description

The following description was provided for the project 'DR-4402-WI City of Middleton, Pheasant Branch Creek':

Severe storms, tornadoes, straight-line winds, flooding, and landslides affected areas of the State of Wisconsin in the late summer and fall of 2018. President Trump signed the 4402-DR-WI Disaster Declaration on October 18, 2018. Under this declaration, Dane County, among others, was made eligible for FEMA's Public Assistance (PA) funding.

The disaster event caused severe damage to infrastructure along the Mainstem of Pheasant Branch Creek Corridor, that portion of the streambank east of the Mainstem Pond at Deming Way and continuing eastward past Park Street to Century Avenue in Middleton, Wisconsin (GPS Start: 43.10301, -89.51901 End: 43.10436, -89.49332); approximately two miles in total. The disaster event also damaged the "North of Century" portion of the streambank within the Pheasant Branch Conservancy (GPS Start: 43.104548, -89.493209 End: 43.108189, -89.491021), approximately 1,500 linear feet in total, beginning at the Century Avenue bridge over Pheasant Branch). The heavy rains, high flooding water levels, and overbank flow of the Pheasant Branch Creek caused slope failure and severe erosion to engineered and non-engineered creekbanks and damaged existing creekbank-stabilization infrastructure. Additionally, several existing maintenance-access trails, adjacent asphalt and gravel recreational trails, stormwater outfall structures, and pedestrian bridges over Pheasant Branch Creek were severely damaged from erosion caused by flooding.

The City is requesting PA funding for restoration of the Pheasant Branch Corridor by making (1) repairs and improvements to recreational trails and pedestrian bridges, (2) stream stabilization, and (3) channel work including stream realignment and associated bank stabilization. All work will be conducted in and adjacent to Pheasant Branch Creek, within the City of Middleton, between the Deming Way bridge and an area approximately 0.4 mi. downstream (north) of the Century Avenue bridge. Worksites and staging areas will be accessed using existing recreational trails and maintenance-access roads within developed rights-of-way.

The scope includes grading and reshaping of stream banks, replacement of rip rap and gabion baskets, installation of root wads, and redirecting portions of the creek to reduce erosion. Additionally, six pedestrian bridges and associated limestone, 06/03/2022 4

gravel, and asphalt recreational trails will be repaired. Each bridge will have the railing repaired and be elevated between 3 and 6 feet above its current location on new concrete abutments. Two of the bridges (43.104287, -89.505070 and 43.103350, -89.495906) will be relocated downstream from original locations 10 linear feet and 14 linear feet respectively.

Approximate location of the project can be viewed in Google Maps: https://www.google.com/maps/@43.10544204999999,-89.49309992279943,14z



Determination Key Result

This Federal Action may affect the northern long-eared bat in a manner consistent with the description of activities addressed by the Service's PBO dated January 5, 2016. Any taking that may occur incidental to this Action is not prohibited under the final 4(d) rule at 50 CFR §17.40(0). Therefore, the PBO satisfies your responsibilities for this Action under ESA Section 7(a)(2) relative to the northern long-eared bat.

Determination Key Description: Northern Long-eared Bat 4(d) Rule

This key was last updated in IPaC on May 15, 2017. Keys are subject to periodic revision.

This key is intended for actions that may affect the threatened northern long-eared bat.

The purpose of the key for Federal actions is to assist determinations as to whether proposed actions are consistent with those analyzed in the Service's PBO dated January 5, 2016.

Federal actions that may cause prohibited take of northern long-eared bats, affect ESA-listed species other than the northern long-eared bat, or affect any designated critical habitat, require ESA Section 7(a)(2) consultation in addition to the use of this key. Federal actions that may affect species proposed for listing or critical habitat proposed for designation may require a conference under ESA Section 7(a)(4).

Determination Key Result

This project may affect the threatened Northern long-eared bat; therefore, consultation with the Service pursuant to Section 7(a)(2) of the Endangered Species Act of 1973 (87 Stat.884, as amended; 16 U.S.C. 1531 et seq.) is required. However, based on the information you provided, this project may rely on the Service's January 5, 2016, *Programmatic Biological Opinion on Final 4(d) Rule for the Northern Long-Eared Bat and Activities Excepted from Take Prohibitions* to fulfill its Section 7(a)(2) consultation obligation.

Qualification Interview

Is the action authorized, funded, or being carried out by a Federal agency?

Yes

2. Have you determined that the proposed action will have "no effect" on the northern longeared bat? (If you are unsure select "No")

No

3. Will your activity purposefully Take northern long-eared bats?

No

4. [Semantic] Is the project action area located wholly outside the White-nose Syndrome Zone?

Automatically answered

No

5. Have you contacted the appropriate agency to determine if your project is near a known hibernaculum or maternity roost tree?

Location information for northern long-eared bat hibernacula is generally kept in state Natural Heritage Inventory databases — the availability of this data varies state-by-state. Many states provide online access to their data, either directly by providing maps or by providing the opportunity to make a data request. In some cases, to protect those resources, access to the information may be limited. A web page with links to state Natural Heritage Inventory databases and other sources of information on the locations of northern long-eared bat roost trees and hibernacula is available at www.fws.gov/media/nleb-roost-tree-and-hibernacula-state-specific-data-links-0.

Yes

6. Will the action affect a cave or mine where northern long-eared bats are known to hibernate (i.e., hibernaculum) or could it alter the entrance or the environment (physical or other alteration) of a hibernaculum?

No

7. Will the action involve Tree Removal?

Yes

- 8. Will the action only remove hazardous trees for the protection of human life or property? *No*
- 9. Will the action remove trees within 0.25 miles of a known northern long-eared bat hibernaculum at any time of year?

No

10. Will the action remove a known occupied northern long-eared bat maternity roost tree or any trees within 150 feet of a known occupied maternity roost tree from June 1 through July 31?

No

Project Questionnaire

If the project includes forest conversion, report the appropriate acreages below. Otherwise, type '0' in questions 1-3.

1. Estimated total acres of forest conversion:

0

2. If known, estimated acres of forest conversion from April 1 to October 31

n

3. If known, estimated acres of forest conversion from June 1 to July 31

0

If the project includes timber harvest, report the appropriate acreages below. Otherwise, type '0' in questions 4-6.

4. Estimated total acres of timber harvest

0

5. If known, estimated acres of timber harvest from April 1 to October 31

0

6. If known, estimated acres of timber harvest from June 1 to July 31

0

If the project includes prescribed fire, report the appropriate acreages below. Otherwise, type '0' in questions 7-9.

7. Estimated total acres of prescribed fire

0

8. If known, estimated acres of prescribed fire from April 1 to October 31 $\,$

0

9. If known, estimated acres of prescribed fire from June 1 to July 31 $\,$

0

If the project includes new wind turbines, report the megawatts of wind capacity below. Otherwise, type '0' in question 10.

10. What is the estimated wind capacity (in megawatts) of the new turbine(s)?

0

IPaC User Contact Information

Agency: Federal Emergency Management Agency

Name: Karie Roach

Address: 536 S Clark Street, 6th Floor

City: Chicago

State: IL

Zip: 60605

Email karie.roach@fema.dhs.gov

Phone: 3126188516



United States Department of the Interior



April 25, 2022

FISH AND WILDLIFE SERVICE

Minnesota-Wisconsin Ecological Services Field Office 4101 American Blvd E Bloomington, MN 55425-1665 Phone: (952) 252-0092 Fax: (952) 646-2873

http://www.fws.gov/midwest/Endangered/section7/s7process/step1.html

In Reply Refer To:

Project Code: 2022-0035393

Project Name: DR-4402-WI City of Middleton, Pheasant Branch Creek

Subject: List of threatened and endangered species that may occur in your proposed project

location or may be affected by your proposed project

To Whom It May Concern:

This response has been generated by the Information, Planning, and Conservation (IPaC) system to provide information on natural resources that could be affected by your project. The U.S. Fish and Wildlife Service (Service) provides this response under the authority of the Endangered Species Act of 1973 (16 U.S.C. 1531-1543), the Bald and Golden Eagle Protection Act (16 U.S.C. 668-668d), the Migratory Bird Treaty Act (16 U.S.C. 703-712), and the Fish and Wildlife Coordination Act (16 U.S.C. 661 et seq.).

Threatened and Endangered Species

The enclosed species list identifies threatened, endangered, proposed and candidate species, as well as proposed and final designated critical habitat, that may occur within the boundary of your proposed project and may be affected by your proposed project. The species list fulfills the requirement for obtaining a Technical Assistance Letter from the U.S. Fish and Wildlife Service under section 7(c) of the Endangered Species Act (Act) of 1973, as amended (16 U.S.C. 1531 et seq.).

New information based on updated surveys, changes in the abundance and distribution of species, changed habitat conditions, or other factors could change this list. Note that under 50 CFR 402.12(e) of the regulations implementing section 7 of the Act, the accuracy of this species list should be verified after 90 days. The Service recommends that verification be completed by visiting the ECOS IPaC website at regular intervals during project planning and implementation for updates to species lists and information. An updated list may be requested through the ECOS IPaC system by completing the same process used to receive the enclosed list.

Consultation Technical Assistance

Please refer to refer to our Section 7 website for guidance and technical assistance, including step-by-step instructions for making effects determinations for each species that might be present and for specific guidance on the following types of projects: projects in developed areas, HUD, CDBG, EDA, pipelines, buried utilities, telecommunications, and requests for a Conditional Letter of Map Revision (CLOMR) from FEMA.

Using the IPaC Official Species List to Make No Effect and May Affect Determinations for Listed Species

If IPaC returns a result of "There are no listed species found within the vicinity of the project," then
project proponents can conclude the proposed activities will have no effect on any federally listed
species under Service jurisdiction. Concurrence from the Service is not required for no
effect determinations. No further consultation or coordination is required. Attach this letter to the dated
IPaC species list report for your records.

- 2. If IPaC returns one or more federally listed, proposed, or candidate species as potentially present in the action area of the proposed project other than bats (see below) then project proponents must determine if proposed activities will have no effect on or may affect those species. For assistance in determining if suitable habitat for listed, candidate, or proposed species occurs within your project area or if species may be affected by project activities, you can obtain <u>Life History Information for Listed and Candidate Species</u> on our office website. If no impacts will occur to a species on the IPaC species list (e.g., there is no habitat present in the project area), the appropriate determination is no effect. No further consultation or coordination is required. Attach this letter to the dated IPaC species list report for your records.
- Should you determine that project activities may affect any federally listed, please contact our office for further coordination. Letters with requests for consultation or correspondence about your project should include the Consultation Tracking Number in the header. <u>Electronic submission is preferred</u>.

Northern Long-Eared Bats

Northern long-eared bats occur throughout Minnesota and Wisconsin and the information below may help in determining if your project may affect these species.

This species hibernates in caves or mines only during the winter. In Minnesota and Wisconsin, the hibernation season is considered to be November 1 to March 31. During the active season (April 1 to October 31) they roost in forest and woodland habitats. Suitable summer habitat for northern long-eared bats consists of a wide variety of forested/wooded habitats where they roost, forage, and travel and may also include some adjacent and interspersed non-forested habitats such as emergent wetlands and adjacent edges of agricultural fields, old fields and pastures. This includes forests and woodlots containing potential roosts (i.e., live trees and/or snags ≥3 inches dbh for northern long-eared bat that have exfoliating bark, cracks, crevices, and/or hollows), as well as linear features such as fencerows, riparian forests, and other wooded corridors. These wooded areas may be dense or loose aggregates of trees with variable amounts of canopy closure. Individual trees may be considered suitable habitat when they exhibit the characteristics of a potential roost tree and are located within 1,000 feet (305 meters) of forested/wooded habitat. Northern long-eared bats have also been observed roosting in human-made structures, such as buildings, barns, bridges, and bat houses; therefore, these structures should also be considered potential summer habitat and evaluated for use by bats. If your project will impact caves or mines or will involve clearing forest or woodland habitat containing suitable roosting habitat, northern long-eared bats could be affected.

Examples of unsuitable habitat include:

- Individual trees that are greater than 1,000 feet from forested or wooded areas,
- Trees found in highly developed urban areas (e.g., street trees, downtown areas),

- A pure stand of less than 3-inch dbh trees that are not mixed with larger trees, and
- A stand of eastern red cedar shrubby vegetation with no potential roost trees.

If IPaC returns a result that northern long-eared bats are potentially present in the action area of the proposed project, project proponents can conclude the proposed activities **may affect** this species **IF** one or more of the following activities are proposed:

- · Clearing or disturbing suitable roosting habitat, as defined above, at any time of year,
- Any activity in or near the entrance to a cave or mine,
- Mining, deep excavation, or underground work within 0.25 miles of a cave or mine,
- · Construction of one or more wind turbines, or
- Demolition or reconstruction of human-made structures that are known to be used by bats based on observations of roosting bats, bats emerging at dusk, or guano deposits or stains.

If none of the above activities are proposed, project proponents can conclude the proposed activities will have **no effect** on the northern long-eared bat. Concurrence from the Service is not required for **No Effect** determinations. No further consultation or coordination is required. Attach this letter to the dated IPaC species list report for your records.

If any of the above activities are proposed, please use the northern long-eared bat determination key in IPaC. This tool streamlines consultation under the 2016 rangewide programmatic biological opinion for the 4(d) rule. The key helps to determine if prohibited take might occur and, if not, will generate an automated verification letter. No further review by us is necessary.

Please note that on March 23, 2022, the Service published a proposal to reclassify the northern long-eared bat as endangered under the Endangered Species Act. The U.S. District Court for the District of Columbia has ordered the Service to complete a new final listing determination for the bat by November 2022 (Case 1:15-cv-00477, March 1, 2021). The bat, currently listed as threatened, faces extinction due to the range-wide impacts of white-nose syndrome (WNS), a deadly fungal disease affecting cave-dwelling bats across the continent. The proposed reclassification, if finalized, would remove the current 4(d) rule for the NLEB, as these rules may be applied only to threatened species. Depending on the type of effects a project has on NLEB, the change in the species' status may trigger the need to re-initiate consultation for any actions that are not completed and for which the Federal action agency retains discretion once the new listing determination becomes effective (anticipated to occur by December 30, 2022). If your project may result in incidental take of northern long-eared bats after the new listing goes into effect this will first need to addressed in an updated consultation that includes an Incidental Take Statement. If your project may require re-initiation of consultation, please contact our office for additional guidance.

Whooping Crane

Whooping crane is designated as a non-essential experimental population in Wisconsin and consultation under Section 7(a)(2) of the Endangered Species Act is only required if project activities will occur within a National Wildlife Refuge or National Park. If project activities are proposed on lands outside of a National Wildlife Refuge or National Park, then you are not required to consult. For additional information on this designation and consultation requirements, please review "Establishment of a Nonessential Experimental Population of

04/25/2022 4

Whooping Cranes in the Eastern United States."

Other Trust Resources and Activities

Bald and Golden Eagles - Although the bald eagle has been removed from the endangered species list, this species and the golden eagle are protected by the Bald and Golden Eagle Act and the Migratory Bird Treaty Act. Should bald or golden eagles occur within or near the project area please contact our office for further coordination. For communication and wind energy projects, please refer to additional guidelines below.

Migratory Birds - The Migratory Bird Treaty Act (MBTA) prohibits the taking, killing, possession, transportation, and importation of migratory birds, their eggs, parts, and nests, except when specifically authorized by the Service. The Service has the responsibility under the MBTA to proactively prevent the mortality of migratory birds whenever possible and we encourage implementation of recommendations that minimize potential impacts to migratory birds. Such measures include clearing forested habitat outside the nesting season (generally March 1 to August 31) or conducting nest surveys prior to clearing to avoid injury to eggs or nestlings.

Communication Towers - Construction of new communications towers (including radio, television, cellular, and microwave) creates a potentially significant impact on migratory birds, especially some 350 species of night-migrating birds. However, the Service has developed voluntary guidelines for minimizing impacts.

Transmission Lines - Migratory birds, especially large species with long wingspans, heavy bodies, and poor maneuverability can also collide with power lines. In addition, mortality can occur when birds, particularly hawks, eagles, kites, falcons, and owls, attempt to perch on uninsulated or unguarded power poles. To minimize these risks, please refer to guidelines developed by the Avian Power Line Interaction Committee and the Service. Implementation of these measures is especially important along sections of lines adjacent to wetlands or other areas that support large numbers of raptors and migratory birds.

Wind Energy - To minimize impacts to migratory birds and bats, wind energy projects should follow the Service's Wind Energy Guidelines. In addition, please refer to the Service's Eagle Conservation Plan Guidance, which provides guidance for conserving bald and golden eagles in the course of siting, constructing, and operating wind energy facilities.

State Department of Natural Resources Coordination

While it is not required for your Federal section 7 consultation, please note that additional state endangered or threatened species may also have the potential to be impacted. Please contact the Minnesota or Wisconsin Department of Natural Resources for information on state listed species that may be present in your proposed project area.

Minnesota

Minnesota Department of Natural Resources - Endangered Resources Review Homepage Email: Review.NHIS@state.mn.us

Wisconsin

Wisconsin Department of Natural Resources - Endangered Resources Review Homepage

Email: DNRERReview@wi.gov

We appreciate your concern for threatened and endangered species. Please feel free to contact our office with questions or for additional information.

Attachment(s):

- Official Species List
- USFWS National Wildlife Refuges and Fish Hatcheries
- Migratory Birds
 - Wetlands

Official Species List

This list is provided pursuant to Section 7 of the Endangered Species Act, and fulfills the requirement for Federal agencies to "request of the Secretary of the Interior information whether any species which is listed or proposed to be listed may be present in the area of a proposed action".

This species list is provided by:

Minnesota-Wisconsin Ecological Services Field Office 4101 American Blvd E Bloomington, MN 55425-1665 (952) 252-0092

Project Summary

Project Code: 2022-0035393

Event Code: None

Project Name: DR-4402-WI City of Middleton, Pheasant Branch Creek

Project Type: Stream Preservation

Project Description: Severe storms, tornadoes, straight-line winds, flooding, and landslides

affected areas of the State of Wisconsin in the late summer and fall of 2018. President Trump signed the 4402-DR-WI Disaster Declaration on October 18, 2018. Under this declaration, Dane County, among others,

was made eligible for FEMA's Public Assistance (PA) funding.

The disaster event caused severe damage to infrastructure along the Mainstem of Pheasant Branch Creek Corridor, that portion of the streambank east of the Mainstem Pond at Deming Way and continuing eastward past Park Street to Century Avenue in Middleton, Wisconsin (GPS Start: 43.10301, -89.51901 End: 43.10436, -89.49332); approximately two miles in total. The disaster event also damaged the "North of Century" portion of the streambank within the Pheasant Branch Conservancy (GPS Start: 43.104548, -89.493209 End: 43.108189, -89.491021), approximately 1,500 linear feet in total, beginning at the Century Avenue bridge over Pheasant Branch). The heavy rains, high flooding water levels, and overbank flow of the Pheasant Branch Creek caused slope failure and severe erosion to engineered and non-engineered creekbanks and damaged existing creekbank-stabilization infrastructure. Additionally, several existing maintenance-access trails, adjacent asphalt and gravel recreational trails, stormwater outfall structures, and pedestrian bridges over Pheasant Branch Creek were severely damaged from erosion caused by flooding.

The City is requesting PA funding for restoration of the Pheasant Branch Corridor by making (1) repairs and improvements to recreational trails and pedestrian bridges, (2) stream stabilization, and (3) channel work including stream realignment and associated bank stabilization. All work will be conducted in and adjacent to Pheasant Branch Creek, within the City of Middleton, between the Deming Way bridge and an area approximately 0.4 mi. downstream (north) of the Century Avenue bridge. Worksites and staging areas will be accessed using existing recreational trails and maintenance-access roads within developed rights-of-way.

The scope includes grading and reshaping of stream banks, replacement of rip rap and gabion baskets, installation of root wads, and redirecting portions of the creek to reduce erosion. Additionally, six pedestrian bridges and associated limestone, gravel, and asphalt recreational trails will be repaired. Each bridge will have the railing repaired and be

04/25/2022 3

elevated between 3 and 6 feet above its current location on new concrete abutments. Two of the bridges (43.104287, -89.505070 and 43.103350, -89.495906) will be relocated downstream from original locations 10 linear feet and 14 linear feet respectively.

Project Location:

Approximate location of the project can be viewed in Google Maps: https://www.google.com/maps/@43.105379549999995,-89.49311066792683,14z



Counties: Dane County, Wisconsin

Endangered Species Act Species

There is a total of 7 threatened, endangered, or candidate species on this species list.

Species on this list should be considered in an effects analysis for your project and could include species that exist in another geographic area. For example, certain fish may appear on the species list because a project could affect downstream species.

IPaC does not display listed species or critical habitats under the sole jurisdiction of NOAA Fisheries¹, as USFWS does not have the authority to speak on behalf of NOAA and the Department of Commerce.

See the "Critical habitats" section below for those critical habitats that lie wholly or partially within your project area under this office's jurisdiction. Please contact the designated FWS office if you have questions.

NOAA Fisheries, also known as the National Marine Fisheries Service (NMFS), is an
office of the National Oceanic and Atmospheric Administration within the Department of
Commerce.

Mammals

NAME	STATUS
Northern Long-eared Bat Myotis septentrionalis	Threatened
No critical habitat has been designated for this species.	
Species profile: https://ecos.fws.gov/ecp/species/9045	

Birds

NAME	STATUS
Whooping Crane Grus americana	Experimental
Population: U.S.A. (AL, AR, CO, FL, GA, ID, IL, IN, IA, KY, LA, MI, MN, MS, MO, NC,	Population,
NM, OH, SC, TN, UT, VA, WI, WV, western half of WY)	Non-
No critical habitat has been designated for this species.	Essential
Species profile: https://ecos.fws.gov/ecp/species/758	

Insects

NAME

Monarch Butterfly Danaus plexippus

Candidate

No critical habitat has been designated for this species. Species profile: https://ecos.fws.gov/ecp/species/9743

Rusty Patched Bumble Bee Bombus affinis

Endangered

Threatened

No critical habitat has been designated for this species. Species profile: https://ecos.fws.gov/ecp/species/9383

General project design guidelines:

https://ipac.ecosphere.fws.gov/project/YTADKGGEWNHIHPO4MRYN6PRJUM/

documents/generated/5967.pdf

Flowering Plants

NAME

Eastern Prairie Fringed Orchid Platanthera leucophaea

No critical habitat has been designated for this species. Species profile: https://ecos.fws.gov/ecp/species/601

Mead's Milkweed Asclepias meadii Threatened

No critical habitat has been designated for this species. Species profile: https://ecos.fws.gov/ecp/species/8204

Prairie Bush-clover Lespedeza leptostachya Threatened

No critical habitat has been designated for this species. Species profile: https://ecos.fws.gov/ecp/species/4458

Critical habitats

THERE ARE NO CRITICAL HABITATS WITHIN YOUR PROJECT AREA UNDER THIS OFFICE'S JURISDICTION.

USFWS National Wildlife Refuge Lands And Fish Hatcheries

Any activity proposed on lands managed by the <u>National Wildlife Refuge</u> system must undergo a 'Compatibility Determination' conducted by the Refuge. Please contact the individual Refuges to discuss any questions or concerns.

THERE ARE NO REFUGE LANDS OR FISH HATCHERIES WITHIN YOUR PROJECT AREA.

Migratory Birds

Certain birds are protected under the Migratory Bird Treaty Act¹ and the Bald and Golden Eagle Protection Act².

Any person or organization who plans or conducts activities that may result in impacts to migratory birds, eagles, and their habitats should follow appropriate regulations and consider implementing appropriate conservation measures, as described <u>below</u>.

- 1. The Migratory Birds Treaty Act of 1918.
- 2. The Bald and Golden Eagle Protection Act of 1940.
- 3. 50 C.F.R. Sec. 10.12 and 16 U.S.C. Sec. 668(a)

The birds listed below are birds of particular concern either because they occur on the USFWS
Birds of Conservation Concern (BCC) list or warrant special attention in your project location.

To learn more about the levels of concern for birds on your list and how this list is generated, see the FAQ below. This is not a list of every bird you may find in this location, nor a guarantee that every bird on this list will be found in your project area. To see exact locations of where birders and the general public have sighted birds in and around your project area, visit the E-bird data
mapping tool (Tip: enter your location, desired date range and a species on your list). For projects that occur off the Atlantic Coast, additional maps and models detailing the relative occurrence and abundance of bird species on your list are available. Links to additional information about Atlantic Coast birds, and other important information about your migratory bird list, including how to properly interpret and use your migratory bird report, can be found below.

For guidance on when to schedule activities or implement avoidance and minimization measures to reduce impacts to migratory birds on your list, click on the PROBABILITY OF PRESENCE SUMMARY at the top of your list to see when these birds are most likely to be present and breeding in your project area.

DDDDDDIAG

NAME	SEASON
American Golden-plover <i>Pluvialis dominica</i> This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska.	Breeds elsewhere
Bald Eagle Haliaeetus leucocephalus This is not a Bird of Conservation Concern (BCC) in this area, but warrants attention because of the Eagle Act or for potential susceptibilities in offshore areas from certain types of development or activities.	Breeds Dec 1 to Aug 31

2

NAME	BREEDING SEASON
Black Tern Chlidonias niger This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska. https://ecos.fws.gov/ecp/species/3093	Breeds May 15 to Aug 20
Black-billed Cuckoo Coccyzus erythropthalmus This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska. https://ecos.fws.gov/ecp/species/9399	Breeds May 15 to Oct 10
Bobolink <i>Dolichonyx oryzivorus</i> This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska.	Breeds May 20 to Jul 31
Canada Warbler Cardellina canadensis This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska.	Breeds May 20 to Aug 10
Cerulean Warbler Dendroica cerulea This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska. https://ecos.fws.gov/ecp/species/2974	Breeds Apr 22 to Jul 20
Eastern Whip-poor-will Antrostomus vociferus This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska.	Breeds May 1 to Aug 20
Golden Eagle Aquila chrysaetos This is not a Bird of Conservation Concern (BCC) in this area, but warrants attention because of the Eagle Act or for potential susceptibilities in offshore areas from certain types of development or activities. https://ecos.fws.gov/ecp/species/1680	Breeds elsewhere
Golden-winged Warbler Vermivora chrysoptera This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska. https://ecos.fws.gov/ecp/species/8745	Breeds May 1 to Jul 20
Henslow's Sparrow Ammodramus henslowii This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska. https://ecos.fws.gov/ecp/species/3941	Breeds May 1 to Aug 31
Le Conte's Sparrow Ammodramus leconteii This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska.	Breeds Jun 1 to Aug 15
Lesser Yellowlegs <i>Tringa flavipes</i> This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska. https://ecos.fws.gov/ecp/species/9679	Breeds elsewhere

NAME	BREEDING SEASON
Long-eared Owl asio otus This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska. https://ecos.fws.gov/ecp/species/3631	Breeds Mar 1 to Jul 15
Marbled Godwit Limosa fedoa This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska. https://ecos.fws.gov/ecp/species/9481	Breeds May 1 to Jul 31
Red-headed Woodpecker <i>Melanerpes erythrocephalus</i> This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska.	Breeds May 10 to Sep 10
Ruddy Turnstone Arenaria interpres morinella This is a Bird of Conservation Concern (BCC) only in particular Bird Conservation Regions (BCRs) in the continental USA	Breeds elsewhere
Rusty Blackbird <i>Euphagus carolinus</i> This is a Bird of Conservation Concern (BCC) only in particular Bird Conservation Regions (BCRs) in the continental USA	Breeds elsewhere
Short-billed Dowitcher Limnodromus griseus This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska. https://ecos.fws.gov/ecp/species/9480	Breeds elsewhere
Wood Thrush <i>Hylocichla mustelina</i> This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska.	Breeds May 10 to Aug 31

Probability Of Presence Summary

The graphs below provide our best understanding of when birds of concern are most likely to be present in your project area. This information can be used to tailor and schedule your project activities to avoid or minimize impacts to birds. Please make sure you read and understand the FAQ "Proper Interpretation and Use of Your Migratory Bird Report" before using or attempting to interpret this report.

Probability of Presence (■)

Each green bar represents the bird's relative probability of presence in the 10km grid cell(s) your project overlaps during a particular week of the year. (A year is represented as 12 4-week months.) A taller bar indicates a higher probability of species presence. The survey effort (see below) can be used to establish a level of confidence in the presence score. One can have higher confidence in the presence score if the corresponding survey effort is also high.

How is the probability of presence score calculated? The calculation is done in three steps:

 The probability of presence for each week is calculated as the number of survey events in the week where the species was detected divided by the total number of survey events for that week. For example, if in week 12 there were 20 survey events and the Spotted Towhee was found in 5 of them, the probability of presence of the Spotted Towhee in week 12 is 0.25.

- 2. To properly present the pattern of presence across the year, the relative probability of presence is calculated. This is the probability of presence divided by the maximum probability of presence across all weeks. For example, imagine the probability of presence in week 20 for the Spotted Towhee is 0.05, and that the probability of presence at week 12 (0.25) is the maximum of any week of the year. The relative probability of presence on week 12 is 0.25/0.25 = 1; at week 20 it is 0.05/0.25 = 0.2.
- The relative probability of presence calculated in the previous step undergoes a statistical conversion so that all possible values fall between 0 and 10, inclusive. This is the probability of presence score.

Breeding Season (*)

Yellow bars denote a very liberal estimate of the time-frame inside which the bird breeds across its entire range. If there are no yellow bars shown for a bird, it does not breed in your project area.

Survey Effort (1)


Vertical black lines superimposed on probability of presence bars indicate the number of surveys performed for that species in the 10km grid cell(s) your project area overlaps. The number of surveys is expressed as a range, for example, 33 to 64 surveys.


No Data (-)

A week is marked as having no data if there were no survey events for that week.


Survey Timeframe

Surveys from only the last 10 years are used in order to ensure delivery of currently relevant information. The exception to this is areas off the Atlantic coast, where bird returns are based on all years of available data, since data in these areas is currently much more sparse.





04/25/2022 6



Additional information can be found using the following links:

- Birds of Conservation Concern https://www.fws.gov/program/migratory-birds/species
- Measures for avoiding and minimizing impacts to birds https://www.fws.gov/library/collections/avoiding-and-minimizing-incidental-take-migratory-birds
- Nationwide conservation measures for birds https://www.fws.gov/sites/default/files/documents/nationwide-standard-conservation-measures.pdf

Migratory Birds FAQ

Tell me more about conservation measures I can implement to avoid or minimize impacts to migratory birds.

Nationwide Conservation Measures describes measures that can help avoid and minimize impacts to all birds at any location year round. Implementation of these measures is particularly important when birds are most likely to occur in the project area. When birds may be breeding in the area, identifying the locations of any active nests and avoiding their destruction is a very helpful impact minimization measure. To see when birds are most likely to occur and be breeding in your project area, view the Probability of Presence Summary. Additional measures or permits may be advisable depending on the type of activity you are conducting and the type of infrastructure or bird species present on your project site.

What does IPaC use to generate the migratory birds potentially occurring in my specified location?

The Migratory Bird Resource List is comprised of USFWS <u>Birds of Conservation Concern</u> (BCC) and other species that may warrant special attention in your project location.

The migratory bird list generated for your project is derived from data provided by the <u>Avian Knowledge Network (AKN)</u>. The AKN data is based on a growing collection of <u>survey</u>, <u>banding</u>, <u>and citizen science datasets</u> and is queried and filtered to return a list of those birds reported as occurring in the 10km grid cell(s) which your project intersects, and that have been identified as warranting special attention because they are a BCC species in that area, an eagle (<u>Eagle Act</u> requirements may apply), or a species that has a particular vulnerability to offshore activities or development.

Again, the Migratory Bird Resource list includes only a subset of birds that may occur in your project area. It is not representative of all birds that may occur in your project area. To get a list of all birds potentially present in your project area, please visit the AKN Phenology Tool.

What does IPaC use to generate the probability of presence graphs for the migratory birds potentially occurring in my specified location?

The probability of presence graphs associated with your migratory bird list are based on data provided by the <u>Avian Knowledge Network (AKN)</u>. This data is derived from a growing collection of <u>survey</u>, <u>banding</u>, <u>and citizen science datasets</u>.

Probability of presence data is continuously being updated as new and better information becomes available. To learn more about how the probability of presence graphs are produced and how to interpret them, go the Probability of Presence Summary and then click on the "Tell me about these graphs" link.

How do I know if a bird is breeding, wintering, migrating or present year-round in my project area?

To see what part of a particular bird's range your project area falls within (i.e. breeding, wintering, migrating or year-round), you may refer to the following resources: The Cornell Lab of Ornithology All About Birds Bird Guide, or (if you are unsuccessful in locating the bird of interest there), the Cornell Lab of Ornithology Neotropical Birds guide. If a bird on your migratory bird species list has a breeding season associated with it, if that bird does occur in your project area, there may be nests present at some point within the timeframe specified. If "Breeds elsewhere" is indicated, then the bird likely does not breed in your project area.

What are the levels of concern for migratory birds?

Migratory birds delivered through IPaC fall into the following distinct categories of concern:

- "BCC Rangewide" birds are <u>Birds of Conservation Concern</u> (BCC) that are of concern throughout their range anywhere within the USA (including Hawaii, the Pacific Islands, Puerto Rico, and the Virgin Islands);
- "BCC BCR" birds are BCCs that are of concern only in particular Bird Conservation Regions (BCRs) in the continental USA; and
- 3. "Non-BCC Vulnerable" birds are not BCC species in your project area, but appear on your list either because of the <u>Eagle Act</u> requirements (for eagles) or (for non-eagles) potential susceptibilities in offshore areas from certain types of development or activities (e.g. offshore energy development or longline fishing).

Although it is important to try to avoid and minimize impacts to all birds, efforts should be made, in particular, to avoid and minimize impacts to the birds on this list, especially eagles and BCC species of rangewide concern. For more information on conservation measures you can implement to help avoid and minimize migratory bird impacts and requirements for eagles, please see the FAQs for these topics.

Details about birds that are potentially affected by offshore projects

For additional details about the relative occurrence and abundance of both individual bird species and groups of bird species within your project area off the Atlantic Coast, please visit the Northeast Ocean Data Portal. The Portal also offers data and information about other taxa besides

birds that may be helpful to you in your project review. Alternately, you may download the bird model results files underlying the portal maps through the <u>NOAA NCCOS Integrative Statistical Modeling and Predictive Mapping of Marine Bird Distributions and Abundance on the Atlantic Outer Continental Shelf project webpage.</u>

Bird tracking data can also provide additional details about occurrence and habitat use throughout the year, including migration. Models relying on survey data may not include this information. For additional information on marine bird tracking data, see the <u>Diving Bird Study</u> and the <u>nanotag studies</u> or contact <u>Caleb Spiegel</u> or <u>Pam Loring</u>.

What if I have eagles on my list?

If your project has the potential to disturb or kill eagles, you may need to obtain a permit to avoid violating the Eagle Act should such impacts occur.

Proper Interpretation and Use of Your Migratory Bird Report

The migratory bird list generated is not a list of all birds in your project area, only a subset of birds of priority concern. To learn more about how your list is generated, and see options for identifying what other birds may be in your project area, please see the FAQ "What does IPaC use to generate the migratory birds potentially occurring in my specified location". Please be aware this report provides the "probability of presence" of birds within the 10 km grid cell(s) that overlap your project; not your exact project footprint. On the graphs provided, please also look carefully at the survey effort (indicated by the black vertical bar) and for the existence of the "no data" indicator (a red horizontal bar). A high survey effort is the key component. If the survey effort is high, then the probability of presence score can be viewed as more dependable. In contrast, a low survey effort bar or no data bar means a lack of data and, therefore, a lack of certainty about presence of the species. This list is not perfect; it is simply a starting point for identifying what birds of concern have the potential to be in your project area, when they might be there, and if they might be breeding (which means nests might be present). The list helps you know what to look for to confirm presence, and helps guide you in knowing when to implement conservation measures to avoid or minimize potential impacts from your project activities, should presence be confirmed. To learn more about conservation measures, visit the FAQ "Tell me about conservation measures I can implement to avoid or minimize impacts to migratory birds" at the bottom of your migratory bird trust resources page.

Wetlands

Impacts to <u>NWI wetlands</u> and other aquatic habitats may be subject to regulation under Section 404 of the Clean Water Act, or other State/Federal statutes.

For more information please contact the Regulatory Program of the local <u>U.S. Army Corps of Engineers District</u>.

Please note that the NWI data being shown may be out of date. We are currently working to update our NWI data set. We recommend you verify these results with a site visit to determine the actual extent of wetlands on site.

WETLAND INFORMATION WAS NOT AVAILABLE WHEN THIS SPECIES LIST WAS GENERATED. PLEASE VISIT <u>HTTPS://WWW.FWS.GOV/WETLANDS/DATA/MAPPER.HTML</u> OR CONTACT THE FIELD OFFICE FOR FURTHER INFORMATION.

IPaC User Contact Information

Agency: Federal Emergency Management Agency

Name: Karie Roach

Address: 536 S Clark Street, 6th Floor

City: Chicago

State: IL

Zip: 60605

Email karie.roach@fema.dhs.gov

Phone: 3126188516

From: <u>Utrup, Nick J</u>

To: <u>FEMA-R5-Environmental</u>

Subject: Re: [EXTERNAL] FEMA - Section 7 Informal Consultation - Pheasant Branch Conservancy - All Remaining Sites,

Middleton, WI

Date: Thursday, May 20, 2021 10:23:23 AM

Attachments: <u>image001.png</u>

This email is in response to your request for our concurrence with your determination that the Pheasant Branch Corridor project may affect, but is not likely to adversely affect the rusty patched bumble bee.

We concur with your determination that the permitted activities may affect, but are not likely to adversely affect rusty patched bumble bee in the action area indicated in the materials provided by you.

This email response concludes your consultation requirements with our office. Please let me know if you have any further questions.

Thanks,

Nick

Nick Utrup U.S. Fish and Wildlife Service 4101 American Boulevard East Bloomington, MN 55425

Mobile: (612) 600-6122 (preferred)
Office: (952) 252-0092 ext. 204
Email: Nick Utrup@fws.gov

From: FEMA-R5-Environmental <fema-r5-environmental@fema.dhs.gov>

Sent: Thursday, May 20, 2021 9:52 AM **To:** Utrup, Nick J <nick_utrup@fws.gov> **Cc:** Dapo, Jack <jack.dapo@fema.dhs.gov>

Subject: [EXTERNAL] FEMA - Section 7 Informal Consultation - Pheasant Branch Conservancy - All

Remaining Sites, Middleton, WI

This email has been received from outside of DOI - Use caution before clicking on links, opening attachments, or responding.

Hi Nick,

Please find attached consultation documentation for the captioned project. FEMA had previously sent your office an informal consultation for the Pheasant Branch Conversancy South Fork. This informal consultation covers the remaining sites in the RPBB High Potential Zone. Please let me know if any issues opening documents and please don't hesitate to reach out with any questions.

Thanks,

Region V Environmental and Historic Preservation Team
Office: 312.408.5549 | fema-r5-environmental@fema.dhs.gov
536 South Clark Street, 6th Floor, Chicago, IL 60605

Federal Emergency Management Agency

fema.gov





May 20, 2021

Nick Utrup Minnesota/Wisconsin Ecological Services Field Office U.S Fish and Wildlife Service 4101 American Boulevard East Bloomington, MN 55425

Re: Pheasant Branch Conservancy, Continued City of Middleton, Dane County, Wisconsin DR-4402-WI, Projects 79137, 79139, and 88229 Various Locations

Dear Mr. Utrup:

Pursuant to Section 7 of the Endangered Species Act (ESA), I am writing this letter is to initiate and conclude informal consultation between the Federal Emergency Management Agency (FEMA) and your office regarding the captioned project under FEMA's Public Assistance Grant Program.

FEMA recently sent your office an informal consultation for Pheasant Branch Conservancy South Fork. Your office concurred with our determination of "may affect, not likely to adversely affect" the rusty patched bumble bee. FEMA is sending this informal consultation to cover the remaining work in the Conservancy following flooding damage and erosion to the Pheasant Branch Stream Corridor and other surrounding areas. FEMA concludes that the proposed work on the remaining sites is not likely to adversely affect the rusty patched bumble bee with implementation of recommended conservation measures. FEMA is determining "no effect" for the eastern prairie fringed orchid, Mead's milkweed, northern long-eared bat, and prairie bush clover. Additionally, the whooping crane is listed as a nonessential experimental population and is not being considered under Section 7 of the ESA. The official species list is attached, along with documentation supporting FEMA's conclusions. FEMA requests concurrence with this determination and any additional input from your office. Please send your response to Duane Castaldi, FEMA Region V Environmental Officer, 536 S. Clark St., Suite 600, Chicago IL 60605 or fema-r5-environmental@fema.dhs.gov. Any questions can be directed to 312-408-5549.

Sincerely,

Duane Castaldi Regional Environmental Officer FEMA Region V

Enclosures



Pheasant Branch Conservancy and Pheasant Branch Corridor, All Remaining Sites
City of Middleton, Dane County, Wisconsin
DR-4402-WI, Projects 79137, 79139, and 88229
Various Locations

PROJECT DESCRIPTION:

Background:

The Pheasant Branch Conservancy and Pheasant Branch Corridor covers approximately 550 acres of diverse topography on the northern edge of the City of Middleton in Dane County, Wisconsin. The Conservancy contains open-water marsh areas, springs, prairies, meadows, lowland forest, and wooded areas as well as the Pheasant Branch Creek that runs through its center. The Corridor includes the stream with steep banks and meanders before reaching its outlet into Lake Mendota.

Historically, the City of Middleton performed work within the Conservancy and Corridor to reduce erosion and ensure long-term sustainability of the area. They performed streambed relocation and streambank stabilization projects (most recently in 2007, 2008, 2009, 2010, 2012, 2015 and 2018), incorporating a variety of construction methods including sheet pile retaining walls, gabion baskets, toe wood and root wad, and rip-rap toe protection. The City cleared, grubbed, graded and seeded the banks as part of these efforts.

Streambank Repair and Stabilization - Pheasant Branch Conservancy and Corridor:

Severe storms, tornadoes, straight-line winds, flooding, and landslides affected areas of the State of Wisconsin in the late summer and fall of 2018. President Trump signed the 4402-DR-WI Disaster Declaration on October 18, 2018. Under this declaration, Dane County, among others, was made eligible for FEMA's Public Assistance (PA) funding.

The disaster event caused severe damage to infrastructure along the Mainstem of the Pheasant Branch Creek Corridor, that portion of the streambank east of the Mainstem Pond at Deming Way and continuing eastward past Park Street to Century Avenue in Middleton, Wisconsin (GPS Start: 43.10301, -89.51901 End: 43.10436, -89.49332); approximately two miles in total. The disaster event also damaged the "North of Century" portion of the streambank within the Pheasant Branch Conservancy (GPS Start: 43.104548, -89.493209 End: 43.108189, -89.491021), approximately 1,500 linear feet in total, beginning at the Century Avenue bridge over Pheasant Branch).

The flooding event washed away both engineered and non-engineered portions of the streambanks. The City is requesting PA funding for restoration of the Pheasant Branch Corridor by grading and reshaping of stream banks, replacement of rip rap and gabion baskets, installation of root wads, and redirecting portions of the creek to reduce erosion. However, FEMA is only proposing to fund restoration of areas where previously engineered stream stabilization structures washed out as a result of the disaster event.

Work will be performed in a manner to minimize siltation into the stream. Erosion control blankets will be installed prior to initiating repairs and will be maintained until native vegetation is established. All areas will be revegetated with native seed mix. Where bio-engineered toe protection and streambank stabilization is planned, footer logs provided by the contractor will be placed on the steam bed and used as an anchor point. Root wads will be placed on top of footer logs. Root wads will protrude up to four feet into the creek channel and will provide aquatic habitat to fish and other species as well as stabilize the streambank and prevent erosion. Above root wads there will be placement of bio-mat and one foot of fill

and seed mixed with rip rap. Native seed mix will be spread and monitored until native vegetation is established. In other locations, gabion baskets, sheet pile walls, or rip-rap toe protection will be replaced where they washed out at eroded streambanks. This work is expected to commence in 2021.

Park Street:

Damage at Park Street (GPS Start: 43.103024, -89.502220 End: 43.102802, -89.501125) was severe. The floodwaters were constricted by the Park Street culverts and the resulting higher velocity caused washout of the existing gabion baskets and erosion of over 8,000 cubic yards of the streambank, resulting in a new 90-foot-high slope 75 feet north of the former streambank. Trees downed by the slope failure and flooding, were removed directly after the event. At the crest of the slope, leaning trees were removed in a 15-foot-wide and 100-foot-long area; the stumps were not removed. Some of the trees were 3 inches diameter at breast height or greater. Those trees were in threat of falling due to the displaced slope and exposed roots. Because of the proximity to the Park Street culverts, sidewalk, and roadway, and the instability of the sheer slope, the City prioritized repairs at Park Street to address public safety. Work completed to stabilize the slope and streambank included installation of gabion baskets, grading of the slope, removal of downed trees and a section of leaning trees at the crest of the slope, root wad installation, extension of the culvert apron, and re-vegetation of the area. Work at Park Street was completed between July and October 2019.

Recreational Trails and Pedestrian Bridges:

Portions of a recreational trail and its supporting slopes adjacent to the stream were also damaged, as well as several timber and wood pedestrian bridges. Several existing storm sewer inlets and outlets associated within nearby parks also experienced erosion damage. City forces repaired the adjacent trail and pedestrian bridges in late April 2019, and also repaired storm sewer inlets. These areas were repaired to pre-disaster condition using previously established trails for access with all work occurring within the previous facility footprint. No impacts to species were anticipated at these locations.

Rusty Patched Bumble Bee (RPBB) High Potential Zone (HPZ):

This consultation covers sites that occur within the RPBB HPZ. This portion of the HPZ covers a large area of the City of Middleton and extends to the surrounding cities. Portions of this HPZ contain

developed areas where the RPBB is not likely to be present such as lawns, open water, cultivated croplands, or unvegetated areas.

Some project areas within the Corridor may include wintering habitat. However, due to previous engineered streambank stabilization and frequent flooding of the Pheasant Branch Creek, it is unlikely these areas would contain undisturbed soils suitable for RPBB wintering.

Project Locations within the RPBB HPZ:

South Fork:

Site 1 South Fork Trail Site 11 (Bridge south of Market St) (43.09109, -89.53173)	Project #79139 - reset pedestrian bridge on new abutment and center support adjacent to previous bridge location. Work was completed in July 2020.
Site 2 South Park Fork Trail Site 10 (at Market Street underpass) (43.09257, -89.53106)	 Project #79139 - resurface asphalt trail under Market Street bridge. Work was completed in July 2020. Rip-rap was replaced on the bridge abutment.

Corridor - Mainstem to Century:

Site 3 Station 0+00 to 6+50 (43.10268, -89.51803)	 Project #88229 – stone toe projection and slope grading for 91 LF on south bank (Site 5) and 229 LF on north bank (Site 4) east of Deming Way.
Sites 4&5 Station 23+50 to 29+00 (43.10340, -89.51008)	 Project #88229 – root wad composite installation and slope grading for 160 LF on south bank. Project #79137 DI 253310 – restore rip-rap at the Clark Street stormwater outfall to pre-disaster condition.
Sites 6, 7, & 8 Station 29+00 to 36+50 (43.10264, -89.50896)	 Project #79139 DI#253354 – replace fill and rip-rap around bridge abutment and replace pedestrian bridge structure including railing, support and deck to pre-disaster condition. Project #79139 DI# 264565 – asphalt trail will be resurfaced to pre-disaster condition for length of 250 LF. Project #88229 – proposed streambank grading for 217 LF intermittently on south bank.

Sites 9 & 10	 Project #88229 – proposed stone toe protection and slope grading for 366 LF
Station 36+50 to 41+50 (43.10432, - 89.50780)	 intermittently on east bank. Project #79139 DI# 264565 – asphalt trail will be resurfaced to pre-disaster condition for length of 189 LF.
Sites 11 & 12 Station 41+50 to 47+50 (43.10476, -89.50767) to (43.10517, -89.50693)	 Project #88229 – proposed stone toe protection and slope grading for 50 LF on east bank. Project #88229 – proposed rootwad composite and slope grading for 209 LF intermittently on west bank.
Site 13 Station 47+50 to 51+50 (43.10446, -89.50564)	 Project #88229 – proposed stone toe protection and slope grading for 80 LF on south bank.
Site 14 Station 51+50 to 59+50 (43.10437, -89.50533)	 Project #79139 DI #253354 – resurface 15 LF of trail to pre-disaster condition.
Site 15 Station 59+50 to 67+50 (43.10401, -89.50334)	 Project #88229 – repair 80 LF of sheet pile damage to pre-disaster condition on north bank.
Site 16 - Park Street 67+50 to 73+00 (43.103024, -89.502220 to (43.102802, -89.501125)	Project #79137 – The floodwaters washed out the existing gabion baskets and eroded over 8,000 cubic yards of the streambank, resulting in a new 90-foot-high slope 75 feet north of the former streambank. Trees downed by the slope failure and flooding, were removed directly after the event. At the crest of the slope, leaning trees were removed in a 15-foot-wide and 100-foot-long area; the stumps were not removed. Some of the trees were 3 inches diameter at breast height or greater. Those trees were in threat of falling due to the displaced slope and exposed roots. Work to stabilize the slope and streambank included installation of gabion baskets, grading of the slope, root wad installation, extension of the culvert apron, and revegetation of the area. Work was

	completed between July and October 2019.
Sites 17, 18, & 19 73+00 to 80+00 (43.10190, -89.50077 to 43.10266, -89.49984)	 Project #79139 DI #253354 – resurface trail to pre-disaster condition and repair bridge abutment. Project #79139 DI #264565 – resurface 235 LF of trail to pre-disaster condition. Project #88229 – proposed toewood and slope grading on east bank for 150 LF.
Sites 20, 21, 22, & 23 80+00 to 86+00 (43.10269, -89.49855)	 Project #79139 DI #264565 – resurface trail to pre-disaster condition for 279 LF. Project #79139 DI#253354 – resurfacing of trail to pre-disaster condition and bridge repair. Project #79137 DI #253310 – restore rip-rap at the outfall of the storm sewer coming from Nina Court for 123 LF on south bank. Project #88229 – repair 40 LF gabion wall to pre-disaster condition.
Site 24 86+00 to 92+50 (43.10377, -89.49780)	Project #88229 DI #253597 - proposed rootwad installation and slope grading for 100 LF on west bank and stone toe protection and grading on south bank.
Sites 25 & 26 92+50 to 98+50 (43.10334, -89.49593 to 43.10350, -89.49511)	 Project #79139 – trail repair to predisaster condition for 250 LF on both sides of bridge (DI #264565 Site 5) and bridge repair (DI #253354 Site 6) Project #79137 DI 253310 – restore rip-rap at the outfall of the storm sewer on Santa Maria Court for 32 LF on south bank.

North of Century:

Site 27 (W. of Parmenter and N. of Clark St. School) (43.104548, -89.49321 to 43.10819, -89.49102)	Project #88229 - replacement of erosion mat, fill, and root wad intermittently on east bank and west bank for approximately 0.40 miles.
Site 28 (43.10826, -89.49010)	Project #79139 – Resurface approximately 374 LF of trail to pre- disaster condition.
Site 29 (43.10872, -89.48625 to 43.10915 to - 89.48510)	Project # 79139 - replace 961 LF of elevated treated wood walking surface boards and edge boards to pre-disaster condition.

South Pond:

Site 30	Project #79137 DI 253310 - replacement
(43.09473, -89.53109)	of rip-rap surrounding draining outlets on South Pond. Work completed in spring of 2019.

Tiedeman Pond:

Site 31 (43.08993, -89.50695)	Project 79139 DI 253354 – removed concrete steps, walkway and handrail and replaced with a switchback ADA compliant concrete walkway and replaced existing asphalt walkway with a steeply sloping one along with resurfacing 700 LF of granular trail surface. Work began around November 2019 and was completed in August 2020.
Site 32 (43.09125, -89.50216)	Project 79139 DI 264562 - replaced damaged boardwalk deck boards to pre- disaster condition. Work is completed.

Lakeview Drive:

Site 33	Project 79137 DI 253310 - replaced
(43.09464, -89.48773)	scour holes with 7 CY of fill. Work was completed in spring of 2019.

Baskerville Harbor:

Site 34 (43.10537, -89.48267)	 Project 79137 DI 253310 - remove and replace 200 LF of steel piling and replace rip-rap shoreline protection in Baskerville Harbor with addition of underwater rip-rap for scour protection at base of bulkhead. Work was completed in the spring of 2020.
-------------------------------	--

Graber Pond:

Site 35	Project 79139 DI 264563 - pumped
(43.12049, -89.50520)	water level as emergency action directly following flooding event. Work is completed.

Donna Pond:

Site 36 (43.10524, -89.50864)	Project 79137 DI 253310 - mitigation efforts to prevent future flooding damage to Donna Pond by expanding pond 10 feet east and increasing depth by one foot. Restored 8,500 cy of fill, extended clay liner to top of berm, added concrete to access walkways to maintain ADA accessibility. Work was completed October 2019.
----------------------------------	--

Airport Road Underpass and Penni Klein Park:

Site 37 (Airport Road Underpass) (43.11126, -89.53614)	Project 79139 – replacement of damaged asphalt underpass under Airport Road with a concrete underpass and cheek wall, and heavy rip-rap bank stabilization, with replacement of fence posts.
Site 38 (Penni Klein Park) (43.11237, -89.53926)	Project 79139 DI 253354 – replace crushed trail and asphalt surface to pre- disaster condition.

MAY AFFECT, NOT LIKELY TO ADVERSELY AFFECT (MANLAA) DETERMINATION:

Rusty Patched Bumble Bee (E)

Species Characteristics:

The sites listed above all overlap the rusty patched bumble bee (RPBB) High Potential Zone (HPZ). Therefore, the RPBB can be assumed present in suitable habitat.

RPBB suitable habitat can be divided into nesting and wintering based on the species life cycle and availability of nectar and pollen resources. The former corresponds to the RPBB active season and the latter to RPBB winter hibernation period. The USFWS assumes that the RPBB is present in nesting habitat between March 16 and October 14 and in wintering habitat from October 15 to March 15 (USFWS 2019).

Nesting habitat can include upland grasslands and shrublands with presence of forage and as far as 30 meters into the edges of adjacent forest and woodland (USFWS, 2019). Typically, bumble bees forage within a few hundred meters of their nest with maximum forage distance of about one kilometer (Knight et al, 2005). FEMA does not anticipate any work to occur within nesting habitat as work will primarily be concentrated to streambanks, recreational trails, or maintained park areas.

Wintering habitat can include upland forest and woodland with undisturbed soil. The federal actions covered by this consultation will take place within upland forest, but areas proposed for repair have been previously bioengineered with the most recent work being completed in 2015 and 2018. The goal of this project is to reduce erosion and ensure long-term sustainability of the Conservancy.

Potential Impacts:

Due to previous engineering and grading of areas, along with frequent flooding, it is likely that soils in the area have already been disturbed. With planting of native vegetation and bioengineering techniques designed to reduce erosion, long-term restoration of the Corridor is expected.

Replacement of shot rock and gabion baskets may result in disturbance of soil supporting and adjacent to structures but work will largely conform to the existing footprint.

The existing trail system will be used for equipment access to and from project areas to reduce ground disturbance. Minor clearing and grubbing of vegetation within wintering habitat and around facilities to be repaired, may affect the RPBB. FEMA will implement a conservation measure to revegetate disturbed areas with a native seed mix. This would provide a long-term benefit to the RPBB in the area.

Determination:

FEMA finds that with implementation of conservation measures to revegetate disturbed areas, this project may affect but is not likely to adversely affect the rusty patched bumble bee.

NO EFFECT DETERMINATIONS:

Eastern Prairie Fringed Orchid (T)

Support for No Effect Determination

This species occurs in a wide variety of habitats, from mesic prairie to wetlands such as sedge meadows, marsh edges, and bogs. It requires full sun for optimum growth and flowering along with a grassy habitat with little or no woody encroachment.

Work is expected to occur along the Pheasant Branch Creek Corridor on streambanks and outside of eastern prairie fringed orchid suitable habitat. Furthermore, review of site conditions following the 2018 flooding event show eroded soil and disturbed vegetation, reducing the likelihood that intact plant communities would remain established in the action area; therefore, FEMA determines that actions detailed in this project will have no effect to the eastern prairie fringed orchid.

Mead's Milkweed (T)

Support for No Effect Determination

Mead's milkweed requires a moderately wet (mesic) to moderately dry (dry mesic) upland tallgrass prairie or glad/barren habitat characterized by vegetation adapted for drought and fire, and the plant will persist in stable late-successional prairie (USFWS, 2005). As of 2003, the species had been extirpated from Wisconsin, with restoration and reintroduction efforts being underway (USFWS, 2003).

Work is expected to occur within Pheasant Branch Creek corridor on streambanks and outside of Mead's milkweed suitable habitat. Furthermore, review of site conditions following the 2018 flooding event show eroded soil and disturbed vegetation, reducing the likelihood that intact plant communities would remain established in the action area;

therefore, FEMA determines that actions detailed in this project will have no effect to the Mead's milkweed.

Northern Long-Eared Bat (T)

Species Characteristics:

The northern long-eared bat (NLEB) roosts during summer months underneath bark, cavities, or in crevices of both live and dead trees. Suitable summer habitat for this species may be defined as patches of forest of half an acre in size or greater with potential roost trees that are 3-inches in diameter at breast height (dbh) or greater and containing cavities, loose bark, hollows, or split limbs; or single and small patches of trees of those same characteristics and within 1,000 feet of forested areas. Outside of summer months, this species hibernates in caves and mines or other suitable types of hibernacula.

Potential Impacts:

Minor clearing and grubbing of shrubs, grasses, and plants is expected. As part of the project at Park Street, a 15-foot-wide and 100-foot-long area of trees of which some are 3 inches dbh or greater were removed as they were at the crest of an unstable slope. The center of this area is approximately (GPS:43.103145, -89.501382). Work was completed between July and October 2019.

Determination:

FEMA understands that fallen or leaning trees are not considered suitable habitat; therefore, FEMA determines that this project will have no effect to the northern long-eared bat.

Prairie Bush Clover (E)

Support for No Effect Determination:

In Wisconsin, the prairie bush clover can be found in gravelly or sandy hillside prairies and has a significant association with Dry Prairie and Drymesic Prairie natural communities, and a moderate association with Mesic Prairie natural communities (WINDR, 2020). The blooming phenology is from late July through late August with fruiting phenology beginning early August and lasting through early September.

Work is expected to occur within Pheasant Branch Creek corridor on streambanks and outside of prairie bush clover suitable habitat. Furthermore, review of site conditions following the 2018 flooding event show eroded soil and vegetation reducing the likelihood that intact plant communities would remain established in the action area; therefore, FEMA determines that actions detailed in this project will have no effect to the prairie bush clover.

Whooping Crane (Experimental)

For the purposes of the Endangered Species Act Section 7, if any nonessential experimental population (NEP) designated cranes are

located outside of a National Wildlife Refuge or National Park, they are treated as a species proposed for listing, and the agency is not required to consult with the USFWS.

References

- Anderson, D. S., & Smith, W. R. 2020. Lespedeza leptostachya: Prairie Bush clover | Rare Species Guide. Minnesota Department of Natural Resources.

 https://www.dnr.state.mn.us/rsg/profile.html?action=elementDetail&selectedElement=PDFAB27090
- Bowles, M., & T. (Eds.). 2003. Mead's Milkweed (Asclepias meadii) Recovery Plan. Retrieved December 09, 2020, from https://www.fws.gov/midwest/endangered/plants/pdf/meads-fnl-rp.pdf
- Knight, M. E., A. P. Martin, S. Bishop, J. L. Osborne, R. J. Hale, R. A. Sanderson, and D. Goulson. 2005. An interspecific comparison of foraging range and nest density of four bumblebee (Bombus) species. Molecular Ecology 14: 1811-1820.
- Michigan Natural Features Inventory. 1999. Special Plant Abstract for *Platanthera Leucophaea* (Eastern prairie fringed-orchid). Retrieved December 09, 2020, from https://www.researchgate.net/publication/269995147_The_Pollinators_of_Ohio_and_Michigan_populations_of_Eastern_prairie_fringed_orchid_Plantanthera_leucophaea
- U.S. Fish and Wildlife Service (USFWS). 2005. Eastern Prairie Fringed Orchid (*Platanthera leucophaea*). Retrieved December 09, 2020, from https://www.fws.gov/midwest/endangered/plants/epfo/epfo.html
- U.S. Fish and Wildlife Service (USFWS). 2015. Northern Long-Eared Bat (*Myotis septentrionalis*). Retrieved December 16, 2020, from <u>USFWS: Northern Long-Eared Bat Fact Sheet</u>
- U.S. Fish and Wildlife Service (USFWS). 2005. Mead's Milkweed (Asclepias meadii). Retrieved December 09, 2020, from https://www.fws.gov/midwest/endangered/plants/meads/meadsmil.html
- U.S. Fish and Wildlife Service (USFWS). 2019. Rusty Patched Bumble Bee (Bombus affinis) Endangered Species Act Section 7(a)(2) Voluntary Implementation Guidance. Version 2.1. USFWS, Bloomington, MN. 24 p.
- U.S. Fish and Wildlife Service (USFWS). 2019. Rusty Patched Bumble Bee (*Bombus affinis*). Retrieved December 16, 2020, from <u>USFWS: Rusty patched bumble bee Fact Sheet</u>
- Wisconsin Department of Natural Resources (WDNR). 2020. Prairie Bush Clover (*Lespedeza leptostachya*). Retrieved December 09, 2020, from https://dnr.wi.gov/topic/EndangeredResources/Plants.asp?mode=detail&SpecCode=PDFAB27090


Pheasant Branch Conservancy and Pheasant Branch Corridor
Middleton, Dane County
DR-4402-WI, Projects 79137, 79139, and 88229
Various Locations
Page 1 of 25

Figure 1: Sites marked in blue with general areas labeled in red. USGS Maps "Middleton" and "Middleton West," 1:24,000.



Pheasant Branch Conservancy and Pheasant Branch Corridor Middleton, Dane County DR-4402-WI, Projects 79137, 79139, and 88229 Various Locations Page 2 of 25

Figure 2: Sites marked in blue. RPBB HPZ polygon displayed in red. HPZ shapefile downloaded from https://www.fws.gov/midwest/endangered/insects/rpbb/rpbbmap.html. Shapefile updated March 17, 2021. Uploaded in Esri ArcGIS Pro.




Pheasant Branch Conservancy and Pheasant Branch Corridor Middleton, Dane County DR-4402-WI, Projects 79137, 79139, and 88229 Various Locations Page 3 of 25

Figure 3: South Fork (Sites 1 & 2). USGS Maps "Middleton" and "Middleton West," 1:24,000. Enlarged for detail.



Pheasant Branch Conservancy and Pheasant Branch Corridor Middleton, Dane County DR-4402-WI, Projects 79137, 79139, and 88229 Various Locations Page 4 of 25

Figure 4: Site 1, (43.09109, -89.53173), action area marked in red. Reset pedestrian bridge on new abutment with stone toe protection. Work completed in summer 2020. Google Earth Aerial, 2018 (directly after flooding event) and 2020 (after repairs completed).





Pheasant Branch Conservancy and Pheasant Branch Corridor Middleton, Dane County DR-4402-WI, Projects 79137, 79139, and 88229 Various Locations Page 5 of 25

Figure 5: Site 2, (43.09257, -89.53106), action area marked in red. Rip-rap replaced under Market Street bridge. Section of asphalt recreation trail was resurfaced. Work completed in summer 2020. Google Earth Aerial, 2018 (directly after flooding event) and 2020 (after repairs completed).






Pheasant Branch Conservancy and Pheasant Branch Corridor
Middleton, Dane County
DR-4402-WI, Projects 79137, 79139, and 88229
Various Locations
Page 6 of 25

Figure 6: Main Stem. USGS Maps "Middleton" and "Middleton West," 1:24,000. Enlarged for detail.



Pheasant Branch Conservancy and Pheasant Branch Corridor Middleton, Dane County DR-4402-WI, Projects 79137, 79139, and 88229 Various Locations Page 7 of 25

Figure 7: Site 3, Station 0+00 to 6+50 (43.10268, -89.51803), action area marked in red. Stone toe protection and slope grading on north and south banks. Google Earth Aerial, 2020 data.



Pheasant Branch Conservancy and Pheasant Branch Corridor Middleton, Dane County DR-4402-WI, Projects 79137, 79139, and 88229 Various Locations Page 8 of 25

Figure 3: Sites 4&5, Station 23+50 to 29+00 (43.10340, -89.51008) and Sites 6, 7, and 8, Station 29+00 to 36+50 (43.10264, -89.50896), action area marked in red. Stone toe protection and slope grading on south banks. Replacement of pedestrian bridge and asphalt trail. Google Earth Aerial, 2018 data (directly after flooding event).




Pheasant Branch Conservancy and Pheasant Branch Corridor Middleton, Dane County DR-4402-WI, Projects 79137, 79139, and 88229 Various Locations Page 9 of 25

Figure 9: Sites 9&10, 36+50 to 41+50 (43.10432, -89.50780), Sites 11&12, 41+50 to 47+50 (43.10476, -89.50767) to (43.10517, -89.50693). Action area marked in red. Stone toe protection and slope grading on east bank and proposed root wad composite on west bank. Replacement of asphalt pedestrian trail. Google Earth Aerial, 2020 data.



Pheasant Branch Conservancy and Pheasant Branch Corridor Middleton, Dane County DR-4402-WI, Projects 79137, 79139, and 88229 Various Locations Page 10 of 25

Figure 10: Site 13, 47+50 to 51+50 (43.10446, -89.50564), Site 14, 51+50 to 59+50 (43.10437, -89.50533), and Site 15 59+50 to 67+50 (43.10401, -89.50334). Action area marked in red. Stone toe protection and slope grading on south bank, replacement of sheet pile on north bank, and replacement of asphalt pedestrian trail. Google Earth Aerial, 2018 data.



Pheasant Branch Conservancy and Pheasant Branch Corridor
Middleton, Dane County
DR-4402-WI, Projects 79137, 79139, and 88229
Various Locations
Page 11 of 25

Figure 11: Site 16, 67+50 to 73+00 (43.103024, -89.502220 to (43.102802, -89.501125). Action area marked in red. Proposed streambank grading. Google Earth Aerial, 2018 data.



Pheasant Branch Conservancy and Pheasant Branch Corridor Middleton, Dane County DR-4402-WI, Projects 79137, 79139, and 88229 Various Locations Page 12 of 25

Figure 12: Site 17, 18, & 19, 73+00 to 80+00 (43.10190, -89.50077 to 43.10266, -89.49984). Action area marked in red. Stone toe protection and slope grading on south bank, replacement of sheet pile on north bank, and replacement of asphalt pedestrian trail. Google Earth Aerial, 2014 data.




Pheasant Branch Conservancy and Pheasant Branch Corridor
Middleton, Dane County
DR-4402-WI, Projects 79137, 79139, and 88229
Various Locations
Page 13 of 25

Figure 13: Site 20, 21, 22, & 23, 80+00 to 86+00 (43.10269, -89.49855) and Site 24 86+00 to 92+50 (43.10377, -89.49780). Action area marked in red. Stone toe protection and slope grading on south bank, replacement of sheet pile on north bank, proposed root wad installation on the west bank, and replacement of asphalt pedestrian trail. Google Earth Aerial, 2018 data.



Pheasant Branch Conservancy and Pheasant Branch Corridor Middleton, Dane County DR-4402-WI, Projects 79137, 79139, and 88229 Various Locations Page 14 of 25

Figure 14: Sites 25 & 26, 92+50 to 98+50 (43.10334, -89.49593 to 43.10350, -89.49511). Action area marked in red. Replacement of trail to pre-disaster condition and replacement of rip-rap at storm sewer outfall. Google Earth Aerial, 2014 data.



Pheasant Branch Conservancy and Pheasant Branch Corridor Middleton, Dane County DR-4402-WI, Projects 79137, 79139, and 88229 Various Locations Page 15 of 25

Figure 15: North of Century (Sites 27, 28, and 29). USGS Maps "Middleton" and "Middleton West," 1:24,000. Enlarged for detail.



Pheasant Branch Conservancy and Pheasant Branch Corridor Middleton, Dane County DR-4402-WI, Projects 79137, 79139, and 88229 Various Locations Page 16 of 25

Figure 16: Sites 27 and 28 (43.104548, -89.49321 to 43.10819, -89.49102). Action area marked in red. Replacement of erosion mat, fill, and root wad intermittently on east and west bank. Replacement of trail surface and pedestrian bridge. Google Earth Aerial, 2018 data.



Pheasant Branch Conservancy and Pheasant Branch Corridor Middleton, Dane County DR-4402-WI, Projects 79137, 79139, and 88229 Various Locations Page 17 of 25

Figure 17: Site 29 (43.10872, -89.48625 to 43.10915, -89.48410). Action area marked in red. Replacement of erosion mat, fill, and root wad intermittently on east and west bank. Replacement of trail surface and pedestrian bridge. Google Earth Aerial, 2020 data.




Pheasant Branch Conservancy and Pheasant Branch Corridor
Middleton, Dane County
DR-4402-WI, Projects 79137, 79139, and 88229
Various Locations
Page 18 of 25

Figure 18: Site 30 (43.09473, -89.53109). Action area marked in red. Replacement of rip-rap surrounding drainage outlet on South Pond. Google Earth Aerial, 2020 data.




Pheasant Branch Conservancy and Pheasant Branch Corridor Middleton, Dane County DR-4402-WI, Projects 79137, 79139, and 88229 Various Locations Page 19 of 25

Figure 19: Sites 31 and 32 (43.08993, -89.50695). Action area marked in red. Replacement of concrete steps and handrails and boardwalk near Tiedeman Pond. Google Earth Aerial, 2020 data.




Pheasant Branch Conservancy and Pheasant Branch Corridor
Middleton, Dane County
DR-4402-WI, Projects 79137, 79139, and 88229
Various Locations
Page 20 of 25

Figure 20: Site 33 (43.09464, -89.48773). Action area marked in red. Replacement of fill in scour holes near Lakeview Drive. Work was completed in spring of 2019. Google Earth Aerial, 2020 data.




Pheasant Branch Conservancy and Pheasant Branch Corridor
Middleton, Dane County
DR-4402-WI, Projects 79137, 79139, and 88229
Various Locations
Page 21 of 25

Figure 21: Site 34 (43.10537, -89.48267). Action area marked in red. Remove and replace 200 LF of steel piling in Baskerville Harbor along with addition of rip-rap shoreline protection. Work was completed in the spring of 2020. Google Earth Aerial, 2020 data.




Pheasant Branch Conservancy and Pheasant Branch Corridor
Middleton, Dane County
DR-4402-WI, Projects 79137, 79139, and 88229
Various Locations
Page 22 of 25

Figure 22: Site 35 (43.12049, -89.5052). Action area marked in red. Pump water level as emergency action directly following flooding event. Work is completed. Google Earth Aerial, 2020 data.



Pheasant Branch Conservancy and Pheasant Branch Corridor
Middleton, Dane County
DR-4402-WI, Projects 79137, 79139, and 88229
Various Locations
Page 23 of 25

Figure 23: Site 36 (43.10524, -89.50864). Action area marked in red. Mitigation efforts to prevent future flooding damage to Donna Pond by expanding pond 10 feet east and increasing depth by one foot. Work was completed October 2019. Google Earth Aerial, 2018 data.



Pheasant Branch Conservancy and Pheasant Branch Corridor
Middleton, Dane County
DR-4402-WI, Projects 79137, 79139, and 88229
Various Locations
Page 24 of 25

Figure 24: Airport Road Underpass and Penni Klein Park (Sites 37 and 38). USGS Maps "Middleton" and "Middleton West," 1:24,000. Enlarged for detail.



Pheasant Branch Conservancy and Pheasant Branch Corridor
Middleton, Dane County
DR-4402-WI, Projects 79137, 79139, and 88229
Various Locations
Page 25 of 25

Figure 25: Sites 37 (43.11126, -89.53614) & 38 (43.11237, -89.53926). Action area marked in red. Google Earth Aerial, 2020 data.





Photo 1: Site 1 (March 2019) taken at 43.091090, -89.531726. View of eroded pedestrian bridge abutment.



Photo 2: Site 2 (March 2019) taken at 43.092573, -89.531055. View of eroded under pass of Market Street bridge.



Photo 3: Site 3 (June 2019) taken at 43.102573, -89.517960. View of debris on eroded streambank facing South towards Deming Way.



Photo 4: Site 3 (June 2019) taken at 43.102596, -89.517990. View of debris on eroded streambank facing east.




Photo 5: Site 4 (May 2019) taken at 43.10333, -89.50996. View of eroded south streambank facing Parmenter Street.




Photo 6: Site 4 (May 2019) taken at 43.103191, -89.510483. View of eroded south streambank facing east.




Photo 7: Site 4 (May 2019) taken at 43.103390, -89.510002. View of eroded south streambank facing southwest.



Photo 8: Site 5 (February 2019) taken at 43.103252, -89.509789. View of minor washout of rip-rap surrounding Clark Street stormwater outfall.



Photo 9: Sites 6 & 7 (March 2019) taken at 43.103016, -89.509429. View of damaged pedestrian bridge and eroded rip-rap on abutment. Asphalt path to be resurfaced.



Photo 10: Site 6 (March 2019) taken at 43.103016, -89.509429. View of eroded rip-rap on abutment of damaged pedestrian bridge.



Photo II: Site 8 (May 2019) taken at 43.102867, -89.509087. View of eroded south streambank facing east.



Photo 12: Site 8 (May 2019) taken at 43.102783, -89.509079. View of eroded south streambank facing west.




Photo 13: Site 8 (May 2019) taken at 43.102787, -89.509117. View of eroded south streambank facing west.




Photo 14: Site 9 (May 2019) taken at 43.104397, -89.507538. View of eroded south streambank facing southeast.




Photo 15: Site 9 (May 2019) taken at 43.104225, -89.507309. View of eroded south streambank facing south.




Photo 16: Site 9 (May 2019) taken at 43.103996, -89.507568. View of eroded south streambank facing east.



Photo 17: Site 10 (March 2019) taken at 43.104170, -89.507500. View of damaged asphalt path before and after pedestrian bridge.




Photo 18: Site 11 (May 2019) taken at 43.104877, -89.507683. View of eroded east streambank.




Photo 19: Site 13 (May 2019) taken at 43.104538, -89.507736. View of eroded west streambank.




Photo 20: Site 12 (May 2019) taken at 43.104527, -89.507896. View of eroded west streambank.




Photo 21: Site 13 (May 2019) taken at 43.104126, -89.505188. View of eroded west streambank.



Photo 22: Site 13 (provided March 2021) taken at 43.10441, -89.50561. View of eroded west streambank.



Photo 23: Site 14 (March 2019) taken at 43.104287, -89.505070. No damage to pedestrian bridge. Recreation path will be resurfaced.




Photo 24: Site 15 (May 2019) taken at 43.103909, -89.503334. View of damaged sheetpile wall on north streambank.



Photo 25: Site 15 (May 2019) taken at 43.103809, -89.503159. View of damaged sheetpile wall on north streambank.



Photo 26: Site 16 (September 2018). Screen capture taken from drone footage. View of damaged north streambank at Park Street.



Photo 27: Site 16 (September 2018) taken at Park Street. View of eroded north streambank after storm.



Photo 28: Site 16 (September 2018). View of culverts under Park Street. Facing west.



Photo 29: Site 16 (December 2019). View of work to extend culvert aprons. Facing west towards Park Street.



Photo 30: Site 16 (December 2019). Photo taken at Park Street facing east. View of repairs to eroded north streambank. Work completed in 2019.



Photo 31: Site 16 (December 2019). Park Street. View of installation of footer logs and root wads to eroded north streambank. Work completed in 2019.



Photo 32: Sites 17 & 18 (March 2019). Photo taken at 43.101879, -89.501156. View of washout of bridge abutment and trail surface.





Photo 33: Site 19 (provided March 2021) taken at 43.10244, -89.49998. View of eroded east streambank.



Photo 34: Site 19 (provided March 2021) taken at 43.10252, -89.49995. View of eroded east streambank.



Photo 35: Sites 20 & 21 (March 2019) taken at 43.103065, -89.498190. View of displaced rip-rap surrounding pedestrian bridge abutment. Trail will be resurfaced to pre-disaster condition.




Photo 36: Site 22 (February 2019) taken at 43.102962, -89.498253. View of displaced rip-rap surrounding Nina Court outfall.




Photo 37: Site 23 (May 2019) taken at 43.103050, -89.498055. View of damaged gabion wall.



Photo 38: Site 24 (provided March 2021) taken at 43.10366, -89.49771. View of eroded west streambank.



Photo 39: Site 25 (Marc 2019) taken at 43.103350, -89.495906. View of washout around bridge. Recreation trail to be resurfaced.




Photo 40: Site 26 (February 2019) taken at 43.103512, -89.495293. View of washout around culvert at Santa Maria Court.



Photo 41: Site 27 (May 2019) taken at 43.10569, -89.49296. View of eroded streambank.



Photo 42: Site 27 (May 2019) taken at 43.10566, -89.49291. View of eroded streambank.



Photo 43: Site 27 (May 2019) taken at 43.10564, -89.49279. View of eroded west streambank.




Photo 43: Site 28 (March 2019) taken at 43.10864, -89.49090. View of damaged pedestrian bridge and trail. Bridge repairs are not eligible for FEMA funding. Trail will be resurfaced to pre-disaster condition.



Photo 43: Site 29 (March 2019) taken at 43.10872, -89.48625. View of boardwalk.




Photo 44: Site 31 (date unknown) taken at 43.089930, -89.506948. Damaged stairs.



Photo 44: Site 32 (March 2019) taken at 43.091254, -89.502157. Damaged recreational trail.



Photo 45: Site 33 (February 2019) taken at 43.094688, -89.48758. Lakeview Drive.



Photo 46: Site 34 (May 2019) taken at 43.10543, -89.48278. Baskerville Harbor. View of eroded southwest bank.



Photo 47: Site 35 (May 2019) taken at 43.11905, -89.50619. Graber Pond. View of damaged boardwalk.




Photo 48: Site 36 (August 2018), provided by the applicant. Taken at 43.10524, -89.50864. Donna Pond. View of collapsed embankment.



Photo 49: Site 37. Taken at 43.11126, -89.53614. Airport Road underpass. View of damaged asphalt trail and displaced rip-rap.



Photo 51: Site 37. Taken at 43.11126, -89.53614. Airport Road underpass. View of damaged asphalt trail and displaced rip-rap.



Photo 52: Site 38. Taken at 43.11229, -89.54029. Klein Park. View of damaged asphalt trail.



United States Department of the Interior



FISH AND WILDLIFE SERVICE

Green Bay Ecological Services Field Office 2661 Scott Tower Drive New Franken, WI 54229-9565 Phone: (920) 866-1717 Fax: (920) 866-1710

In Reply Refer To: May 19, 2021

Consultation Code: 03E17000-2021-SLI-1300

Event Code: 03E17000-2021-E-04376

Project Name: DR-4402-WI City of Middleton, Pheasant Branch Conservancy, All Remaining

Sites

Subject: List of threatened and endangered species that may occur in your proposed project

location or may be affected by your proposed project

To Whom It May Concern:

This response has been generated by the Information, Planning, and Conservation (IPaC) system to provide information on natural resources that could be affected by your project. The U.S. Fish and Wildlife Service (Service) provides this response under the authority of the Endangered Species Act of 1973 (16 U.S.C. 1531-1543), the Bald and Golden Eagle Protection Act (16 U.S.C. 668-668d), the Migratory Bird Treaty Act (16 U.S.C. 703-712), and the Fish and Wildlife Coordination Act (16 U.S.C. 661 *et seq.*).

Threatened and Endangered Species

The enclosed species list identifies threatened, endangered, proposed and candidate species, as well as proposed and final designated critical habitat, that may occur within the boundary of your proposed project and may be affected by your proposed project. The species list fulfills the requirement for obtaining a Technical Assistance Letter from the U.S. Fish and Wildlife Service under section 7(c) of the Endangered Species Act (Act) of 1973, as amended (16 U.S.C. 1531 *et seq.*).

New information based on updated surveys, changes in the abundance and distribution of species, changed habitat conditions, or other factors could change this list. Note that under 50 CFR 402.12(e) of the regulations implementing section 7 of the Act, the accuracy of this species list should be verified after 90 days. The Service recommends that verification be completed by visiting the ECOS IPaC website at regular intervals during project planning and implementation

for updates to species lists and information. An updated list may be requested through the ECOS IPaC system by completing the same process used to receive the enclosed list.

Consultation Technical Assistance

Please refer to the Midwest Region <u>S7 Technical Assistance</u> website for step-by-step instructions for making species determinations and for specific guidance on the following types of projects: projects in developed areas, HUD, CDBG, EDA, pipelines, buried utilities, telecommunications, and requests for a Conditional Letter of Map Revision (CLOMR) from FEMA.

Using the IPaC Official Species List to Make No Effect and May Affect Determinations for Listed Species

- 1. If IPaC returns a result of "There are no listed species found within the vicinity of the project," then project proponents can conclude the proposed activities will have no effect on any federally listed species under Service jurisdiction. Concurrence from the Service is not required for No Effect determinations. No further consultation or coordination is required. Attach this letter to the dated IPaC species list report for your records. An example "No Effect" document also can be found on the S7 Technical Assistance website.
- 2. If IPaC returns one or more federally listed, proposed, or candidate species as potentially present in the action area of the proposed project other than bats (see below) then project proponents must determine if proposed activities will have no effect on or may affect those species. For assistance in determining if suitable habitat for listed, candidate, or proposed species occurs within your project area or if species may be affected by project activities, you can obtain Life History Information for Listed and Candidate Species through the S7 Technical Assistance website. If no impacts will occur to a species on the IPaC species list (e.g., there is no habitat present in the project area), the appropriate determination is No Effect. No further consultation or coordination is required. Attach this letter to the dated IPaC species list report for your records. An example "No Effect" document also can be found on the S7 Technical Assistance website.
- 3. Should you determine that project activities **may affect** any federally listed, please contact our office for further coordination. Letters with requests for consultation or correspondence about your project should include the Consultation Tracking Number in the header. <u>Electronic submission is preferred</u>.

Northern Long-Eared Bats

05/19/2021

Northern long-eared bats occur throughout Minnesota and Wisconsin and the information below may help in determining if your project may affect these species.

This species hibernates in caves or mines only during the winter. In Minnesota and Wisconsin, the hibernation season is considered to be November 1 to March 31. During the active season (April 1 to October 31) they roost in forest and woodland habitats. Suitable summer habitat for northern long-eared bats consists of a wide variety of forested/wooded habitats where they roost, forage, and travel and may also include some adjacent and interspersed non-forested habitats such as emergent wetlands and adjacent edges of agricultural fields, old fields and pastures. This includes forests and woodlots containing potential roosts (i.e., live trees and/or snags ≥3 inches dbh for northern long-eared bat that have exfoliating bark, cracks, crevices, and/or hollows), as well as linear features such as fencerows, riparian forests, and other wooded corridors. These wooded areas may be dense or loose aggregates of trees with variable amounts of canopy closure. Individual trees may be considered suitable habitat when they exhibit the characteristics of a potential roost tree and are located within 1,000 feet (305 meters) of forested/wooded habitat. Northern long-eared bats have also been observed roosting in human-made structures, such as buildings, barns, bridges, and bat houses; therefore, these structures should also be considered potential summer habitat and evaluated for use by bats. If your project will impact caves or mines or will involve clearing forest or woodland habitat containing suitable roosting habitat, northern long-eared bats could be affected.

Examples of unsuitable habitat include:

- · Individual trees that are greater than 1,000 feet from forested or wooded areas,
- Trees found in highly developed urban areas (e.g., street trees, downtown areas),
- · A pure stand of less than 3-inch dbh trees that are not mixed with larger trees, and
- · A stand of eastern red cedar shrubby vegetation with no potential roost trees.

If IPaC returns a result that northern long-eared bats are potentially present in the action area of the proposed project, project proponents can conclude the proposed activities **may affect** this species **IF** one or more of the following activities are proposed:

- · Clearing or disturbing suitable roosting habitat, as defined above, at any time of year,
- · Any activity in or near the entrance to a cave or mine,
- · Mining, deep excavation, or underground work within 0.25 miles of a cave or mine,
- Construction of one or more wind turbines, or

• Demolition or reconstruction of human-made structures that are known to be used by bats based on observations of roosting bats, bats emerging at dusk, or guano deposits or stains.

If none of the above activities are proposed, project proponents can conclude the proposed activities will have **no effect** on the northern long-eared bat. Concurrence from the Service is not required for **No Effect** determinations. No further consultation or coordination is required. Attach this letter to the dated IPaC species list report for your records. An example "No Effect" document also can be found on the S7 Technical Assistance website.

If any of the above activities are proposed, please use the northern long-eared bat determination key in IPaC. This tool streamlines consultation under the 2016 rangewide programmatic biological opinion for the 4(d) rule. The key helps to determine if prohibited take might occur and, if not, will generate an automated verification letter. No further review by us is necessary. Please visit the links below for additional information about "may affect" determinations for the northern long-eared bat.

NLEB Section 7 consultation

Key to the NLEB 4(d) rule for federal actions that may affect

Instructions for the NLEB 4(d) assisted d-key

Maternity tree and hibernaculum locations by state

Other Trust Resources and Activities

Bald and Golden Eagles - Although the bald eagle has been removed from the endangered species list, this species and the golden eagle are protected by the Bald and Golden Eagle Act and the Migratory Bird Treaty Act. Should bald or golden eagles occur within or near the project area please contact our office for further coordination. For communication and wind energy projects, please refer to additional guidelines below.

Migratory Birds - The Migratory Bird Treaty Act (MBTA) prohibits the taking, killing, possession, transportation, and importation of migratory birds, their eggs, parts, and nests, except when specifically authorized by the Service. The Service has the responsibility under the MBTA to proactively prevent the mortality of migratory birds whenever possible and we encourage implementation of recommendations that minimize potential impacts to migratory birds. Such measures include clearing forested habitat outside the nesting season (generally March 1 to August 31) or conducting nest surveys prior to clearing to avoid injury to eggs or nestlings.

Communication Towers - Construction of new communications towers (including radio, television, cellular, and microwave) creates a potentially significant impact on migratory birds, especially some 350 species of night-migrating birds. However, the Service has developed voluntary guidelines for minimizing impacts.

Transmission Lines - Migratory birds, especially large species with long wingspans, heavy bodies, and poor maneuverability can also collide with power lines. In addition, mortality can occur when birds, particularly hawks, eagles, kites, falcons, and owls, attempt to perch on uninsulated or unguarded power poles. To minimize these risks, please refer to guidelines developed by the Avian Power Line Interaction Committee and the Service. Implementation of these measures is especially important along sections of lines adjacent to wetlands or other areas that support large numbers of raptors and migratory birds.

Wind Energy - To minimize impacts to migratory birds and bats, wind energy projects should follow the Service's Wind Energy Guidelines. In addition, please refer to the Service's Eagle Conservation Plan Guidance, which provides guidance for conserving bald and golden eagles in the course of siting, constructing, and operating wind energy facilities.

State Department of Natural Resources Coordination

While it is not required for your Federal section 7 consultation, please note that additional state endangered or threatened species may also have the potential to be impacted. Please contact the Minnesota or Wisconsin Department of Natural Resources for information on state listed species that may be present in your proposed project area.

Minnesota

Minnesota Department of Natural Resources - Endangered Resources Review Homepage

Email: Review.NHIS@state.mn.us

Wisconsin

Wisconsin Department of Natural Resources - Endangered Resources Review Homepage

Email: <u>DNRERReview@wi.gov</u>

We appreciate your concern for threatened and endangered species. Please feel free to contact our office with questions or for additional information.

Attachment(s):

Official Species List

Official Species List

This list is provided pursuant to Section 7 of the Endangered Species Act, and fulfills the requirement for Federal agencies to "request of the Secretary of the Interior information whether any species which is listed or proposed to be listed may be present in the area of a proposed action".

This species list is provided by:

Green Bay Ecological Services Field Office 2661 Scott Tower Drive New Franken, WI 54229-9565 (920) 866-1717

Project Summary

Consultation Code: 03E17000-2021-SLI-1300 Event Code: 03E17000-2021-E-04376

Project Name: DR-4402-WI City of Middleton, Pheasant Branch Conservancy, All

Remaining Sites

Project Type: STREAM / WATERBODY / CANALS / LEVEES / DIKES

Project Description: Severe storms, tornadoes, straight-line winds, flooding, and landslides

affected areas of the State of Wisconsin in the late summer and fall of 2018. President Trump signed the 4402-DR-WI Disaster Declaration on October 18, 2018. Under this declaration, Dane County, among others,

was made eligible for FEMA's Public Assistance (PA) funding.

The disaster event caused severe damage to infrastructure along the Mainstem of Pheasant Branch Creek Corridor, that portion of the streambank east of the Mainstem Pond at Deming Way and continuing eastward past Park Street to Century Avenue in Middleton, Wisconsin (GPS Start: 43.10301, -89.51901 End: 43.10436, -89.49332); approximately two miles in total. The disaster event also damaged the "North of Century" portion of the streambank within the Pheasant Branch Conservancy (GPS Start: 43.104548, -89.493209 End: 43.108189, -89.491021), approximately 1,500 linear feet in total, beginning at the Century Avenue bridge over Pheasant Branch).

The flooding event washed away both engineered and non-engineered portions of the streambanks. The City is requesting PA funding for restoration of the Pheasant Branch Corridor by grading and reshaping of stream banks, replacement of rip rap and gabion baskets, installation of root wads, and redirecting portions of the creek to reduce erosion. However, FEMA is only proposing to fund restoration of areas where previously engineered stream stabilization structures washed out as a result of the disaster event.

Portions of a recreational trail and its supporting slopes adjacent to the stream were also damaged, as well as several timber and wood pedestrian bridges. Several existing storm sewer inlets and outlets associated within nearby parks also experienced erosion damage. City forces repaired the adjacent trail and pedestrian bridges in late April 2019, and also repaired storm sewer inlets. These areas were repaired to pre-disaster condition using previously established trails for access with all work occurring within the previous facility footprint. No impacts to species were anticipated at these trail and bridge locations.

Project Location:

Approximate location of the project can be viewed in Google Maps: https://www.google.com/maps/@43.104213200000004,-89.51327386736948,14z



Counties: Dane County, Wisconsin

CTATIC

CTATIC

Endangered

Endangered Species Act Species

There is a total of 6 threatened, endangered, or candidate species on this species list.

Species on this list should be considered in an effects analysis for your project and could include species that exist in another geographic area. For example, certain fish may appear on the species list because a project could affect downstream species.

IPaC does not display listed species or critical habitats under the sole jurisdiction of NOAA Fisheries¹, as USFWS does not have the authority to speak on behalf of NOAA and the Department of Commerce.

See the "Critical habitats" section below for those critical habitats that lie wholly or partially within your project area under this office's jurisdiction. Please contact the designated FWS office if you have questions.

1. <u>NOAA Fisheries</u>, also known as the National Marine Fisheries Service (NMFS), is an office of the National Oceanic and Atmospheric Administration within the Department of Commerce.

Mammals

NAME	STATUS
Northern Long-eared Bat <i>Myotis septentrionalis</i> No critical habitat has been designated for this species. Species profile: https://ecos.fws.gov/ecp/species/9045	Threatened

Birds

NAME	STATUS
Whooping Crane <i>Grus americana</i>	Experimental
Population: U.S.A. (AL, AR, CO, FL, GA, ID, IL, IN, IA, KY, LA, MI, MN, MS, MO, NC,	Population,
NM, OH, SC, TN, UT, VA, WI, WV, western half of WY)	Non-
No critical habitat has been designated for this species.	Essential
Species profile: https://ecos.fws.gov/ecp/species/758	Lissciitiai

Insects

NAME	SIAIUS

Rusty Patched Bumble Bee Bombus affinis

No critical habitat has been designated for this species. Species profile: https://ecos.fws.gov/ecp/species/9383

05/19/2021 Event Code: 03E17000-2021-E-04376

5

Flowering Plants

NAME

Eastern Prairie Fringed Orchid Platanthera leucophaea
No critical habitat has been designated for this species.
Species profile: https://ecos.fws.gov/ecp/species/601

Mead's Milkweed Asclepias meadii
No critical habitat has been designated for this species.
Species profile: https://ecos.fws.gov/ecp/species/8204

Prairie Bush-clover Lespedeza leptostachya

Threatened

Prairie Bush-clover *Lespedeza leptostachya*No critical habitat has been designated for this species.

Species profile: https://ecos.fws.gov/ecp/species/4458

Critical habitats

THERE ARE NO CRITICAL HABITATS WITHIN YOUR PROJECT AREA UNDER THIS OFFICE'S JURISDICTION.



State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Tony Evers, Governor Preston D. Cole, Secretary

101 S. Webster St. Box 7921 Madison, Wisconsin 53707-7921 Telephone 608-266-2621 FAX 608-267-3579 TTY 608-267-6897

November 6, 2019

Jacob Webb Ayres Associates 5201 E. Terrace Drive, Suite 200 Madison, WI 53718

SUBJECT: Endangered Resources Review (ERR Log # 19-768)

Proposed Middleton Trails Flood Damage Repair

Dear Mr. Webb,

The Bureau of Natural Heritage Conservation has reviewed the proposed project described in the Endangered Resources (ER) Review Request received November 1, 2019. The complete ER Review for this proposed project is attached and follow-up actions are summarized below:

Required Actions: 1 species Recommended Actions: 3 species No Follow-Up Actions: 4 species

Additional Recommendations Specified: No

This ER Review may contain Natural Heritage Inventory data (http://dnr.wi.gov/topic/NHI), including specific locations of endangered resources, which are considered sensitive and are not subject to Wisconsin's Open Records Law. Information contained in this ER Review may be shared with individuals who need this information in order to carry out specific roles in the planning, permitting, and implementation of the proposed project. Specific locations of endangered resources may not be released or reproduced in any publicly disseminated documents.

The attached ER Review is for informational purposes and only addresses endangered resources issues. This ER Review does not constitute DNR authorization of the proposed project and does not exempt the project from securing necessary permits and approvals from the DNR and/or other permitting authorities.

Please contact me at (608) 266-5241 or via email at angelal.white@wisconsin.gov if you have any questions about this ER Review.

Sincerely,

Angela White

angela white

Endangered Resources Review Program



From: <u>Castaldi, Duane</u>
To: <u>Roach, Karie</u>

Subject: FW: SHPO Review: 22-0500/DA - Pheasant Branch Creek Streambank and Trail Restoration

Date: Monday, April 11, 2022 2:06:54 PM

Duane Castaldi

Regional Environmental Officer | FEMA Region V | Department of Homeland Security

Office: 312.408.5549 | Mobile: 312.576.0067

duane.castaldi@fema.dhs.gov

Federal Emergency Management Agency

fema.gov

From: tyler.howe@wisconsinhistory.org <tyler.howe@wisconsinhistory.org>

Sent: Monday, April 11, 2022 1:52 PM

To: Castaldi, Duane < Duane. Castaldi@fema.dhs.gov>

Subject: SHPO Review: 22-0500/DA - Pheasant Branch Creek Streambank and Trail Restoration

CAUTION: This email originated from outside of DHS. DO NOT click links or open attachments unless you recognize and/or trust the sender. Please select the Phish Alert Report button on the top right of your screen to report this email if it is unsolicited or suspicious in nature.

Good afternoon Duane:

We have completed our review of WHS #22-0500, Pheasant Branch Creek Streambank and Trail Restoration project and concur with your findings that no cultural or historic resources eligible for, or included on, the National Register of Historic Places (NRHP) were encountered within the proposed Area of Potential Effect (APE). We also concur with your determination the proposed federal undertaking will have No Effect to historic properties.

As such, it is the opinion of the WI SHPO the proposed federal undertaking may proceed as planned. If your plans change or cultural materials/human remains are found during the project, please halt all work and contact our office.

Please use this email as your official SHPO concurrence for the project. If you require a hard copy signed form, please contact me and I will provide you a signed copy as soon as possible.

All the best,

Tyler

Tyler B. Howe, PhD
Compliance Section Manager
State Historic Preservation Office

Wisconsin Historical Society 816 State Street, Madison, WI 53706

tyler.howe@wisconsinhistory.org

Wisconsin Historical Society

Collecting, Preserving, and Sharing Stories Since 1846



March 29, 2022

Tyler B. Howe, PhD, Compliance Section Manager State Historic Preservation Office Wisconsin Historical Society 816 State Street Madison, WI 53706

Re: Pheasant Branch Creek Stabilization
Middleton, Dane County, Wisconsin
FEMA Project #88229; PW 593
43.103301, -89.513886 to 43.109433, -89.491877
S1, 2, 11, and 12 T7N R8E

Dear Mr. Howe:

Pursuant to the Section 106 of the National Historic Preservation Act, I am writing this letter to initiate and conclude consultation regarding the captioned Public Assistance Grant Program project.

In accordance with 36 CFR §800.11, I am enclosing documentation regarding this undertaking and its effect on historic properties. This documentation provides the justification for FEMA's finding of no historic properties affected; the purpose of this communication is to seek concurrence in that finding.

Due to workplace restrictions in response to COVID-19, we are using email to deliver this Section 106 consultation. Pursuant to 36 CFR 800.4(d)(1), if we receive no response from your office within thirty (30) days, we will consider FEMA's responsibilities under Section 106 fulfilled and will move forward with this undertaking. Because our reliance on digital communications must continue until our offices reopen, we would appreciate a response by email from your office. For your convenience, we have included a response area below. If you have questions, do not hesitate to contact Karie Roach of my staff at 312-408-5549 or at fema-r5-environmental@fema.dhs.gov.

Sincerely,

Duane Castaldi

Regional Environmental Officer

Castell

FEMA Region 5

enclosures

Pheasant Branch Creek Stabilization Middleton, Dane County, WI Project #88229, PW 593 March 29, 2022 Page 2 of 2

	++++++You may email this page to <u>fema-r5-environmental@fema.dhs.gov</u> +++++++	
Re:	Pheasant Branch Creek Stabilization Middleton, Dane County, Wisconsin FEMA Project #88229; PW 593 43.103301, -89.513886 to 43.109433, -89.491877 S1, 2, 11, and 12 T7N R8E	
	Under the authority of the National Historic Preservation Act of 1966, as amended, the Wisconsin State Historic Preservation Office <i>concurs</i> with FEMA's finding that the captioned undertaking will result in <i>no historic properties affected.</i>	
	Under the authority of the National Historic Preservation Act of 1966, as amended, the Wisconsin State Historic Preservation Office <i>objects</i> to FEMA's finding that the captioned undertaking will result in <i>no historic properties affected</i> for the reasons noted below:	
	Wisconsin State Historic Preservation Office Date	

Comments:

REQUEST FOR SHPO COMMENT AND CONSULTATION ON A FEDERAL UNDERTAKING

Submit one copy with each undertaking for which our comment is requested. Please print or type. Return to: Wisconsin Historical Society, State Historic Preservation Office, 816 State Street, Madison, WI 53706

Please Check All Boxes and Include All of the Following Information, as Applicable.

L	GENERAL INFORMATION		
✓	This is a new submittal. This is supplemental information relating to Case #:, and title: This project is being undertaken pursuant to the terms and conditions of a progreement. The title of the agreement is		r other interagency
a	Federal Agency Jurisdiction (Agency providing funds, assistance, license, permit):	FEMA	
ь.	Federal Agency Contact Person: Duane Castaldi	Phone:	312-408-5549
c.	Project Contact Person:	Phone	
d.	Return Address: 536 South Clark Street, 6th Floor City. Chicago, IL.		Zip Code: 60605
e.	Email Address: duane.castaldi@fema.dhs.gov		4.00
£	Project Name: Pheasant Branch Creek Streambank and Trail Restoration		
g.	Project Street Address. see continuation sheet		
h	County. Dane City: Middleton	Zin Co	de: 53562
i	Project Location: Township ^{7N} , Range ⁸ , East ■ or West □, Se		
j.	Project Narrative Description—Attach Information as Necessary.		
k.	Area of Potential Effect (APE). Attach Copy of U.S.G.S. 7.5 Minute Topographic	Ouadrangle sh	owing APE.
п	IDENTIFICATION OF HISTORIC PROPERTIES		
V	Historic Properties are located within the project APE per 36 CFR 800.4. Attach so Historic Properties are not located within the project APE per 36 CFR 800.4. Attach		
ш.	FINDINGS		
	No historic properties will be affected (i.e., none is present or there are historic properfiect upon them). Attach necessary documentation, as described at 36 CFR 800.1 The proposed undertaking will have no adverse effect on one or more historic prop 36 CFR 800.5. Attach necessary documentation, as described at 36 CFR 800.11. The proposed undertaking will result in an adverse effect to one or more historic proposed undertaking will result in an adverse effect to one or more historic proposed representative, will consult with the SHPO and other consulting parties 800.6. Attach supporting documentation as described at 36 CFR 800.11. DUANE D CASTALDI Digitally signed by DUANE D CASTALDI Date: 2022.03.29 10.45:30-05007	I. erties located to reperties and the resolve the action of the second control of the	within the project APE under ne applicant, or other federally
	Duane Castaldi	Date:	
100	or print name:		-
IV.	STATE HISTORIC PRESERVATION OFFICE COMMENTS		
	Agree with the finding in section III above. Object to the finding for reasons indicated in attached letter. Cannot review until information is sent as follows:		
Autho	orized Signature:	Date:	
			HP-05-07 (9-28-18)



March 29, 2022

Documentation Initiating and Concluding Section 106 Consultation for a FEMA-Funded Undertaking

Project Information:

Project ID: #88229; PW 593

Title: Pheasant Branch Creek Stabilization

Address: Pheasant Branch Creek from crossing at Deming Way, eastward to

Century Avenue, then northward, parallel to Conservancy Lane

Location: Middleton, Dane County, WI

GPS: 43.102620, -89.51821 to 43.10945, -89.49057

PLSS: S1, 2, 11, and 12 T7N R8E

Description of Undertaking and APE:

As a result of severe storms, tornadoes, straight-line winds, flooding, and landslides affecting areas of the State of Wisconsin, President Trump signed the 4402-DR-WI Disaster Declaration on October 18, 2018. Under this declaration, Dane County, among others, was made eligible for FEMA's Public Assistance (PA) Program funding. The disaster event resulted in damage to infrastructure along the Pheasant Branch Creek Corridor from crossing at Deming Way and continuing eastward to north of Century Avenue in Middleton, Wisconsin (43.10262, -89.51821 to 43.10945, -89.49057).

The City of Middleton performed streambed relocation and streambank stabilization projects (most recently in 2007, 2008, 2009, 2010, 2012, and 2015) intermittently along this stretch of Pheasant Branch Creek, incorporating a variety of construction methods including sheet pile retaining walls, gabion baskets, toewood and rootwad, and rip rap toe protection. The City cleared, grubbed, graded and seeded the banks as part of these efforts. The flooding event washed away both engineered and non-engineered portions of the streambanks. However, only the areas with engineered stream stabilization will be funded by the FEMA PA grant program. Portions of a recreational trail and its supporting slopes adjacent to the stream were also damaged, as well as six timber and wood pedestrian bridges. Several existing storm sewer inlets and outlets associated with the parks and creek corridor experienced erosion damage.

The Applicant, the City of Middleton, proposes to use contract services to repair the engineered streambanks in-kind to their pre-disaster design, save for the substitution of rip-rap toe protection and fill instead of rootwad and fill in several locations. Some locations along the bank that were damaged in the event will not be repaired but will be allowed to naturalize. All work is intermittent throughout the proposed construction project bounds.

The six timber and wood pedestrian bridges will be replaced and the recreational trail will be repaired and modified. The streambed will be lowered in a few locations to

accommodate the new bridges and trail modifications. Additionally, the stream itself will be shifted in two locations (43.104399, -89.504811 and 43.104008, -89.503381).

The Pheasant Branch and Pheasant Branch Conservancy

Although assessment of the entire Pheasant Branch waterway and Middleton's parks is beyond the scope of this review, an overview of the larger resource will help describe the APE and provide context for the review and recommendations of this consultation. The Friends of Pheasant Branch compiled a booklet (*Friends of Pheasant Branch, Geology, Cultural History and Ecology of the Pheasant Branch Conservancy and Watershed in Middleton, Wisconsin,* 2005) providing an overview of the area; this document provided the basis for the short history below.

The Ho-Chunk Nation occupied the area where the marshes and Pheasant Branch drain into Lake Mendota. Mounds located approximately one and one-half miles north and also approximately one-half mile east of the eastern edge of the proposed undertaking are associated with Native American occupation.

After an 1832 treaty with the Ho-Chunk Nation involving most of Dane County, European settlement began. The area was platted in 1836 and began to be developed. Beginning in the 1850's, portions of the Pheasant Branch creek west of present-day Park Street and the marshes to the west and north were channelized and drained to facilitate a peat harvesting industry and farming. The Pheasant Branch Creek channels now called North Fork and South Fork were created in the settlement period and increased the original creek watershed and stormwater flows considerably.

A village called Pheasant Branch was established in 1853 and was centered around the current Century Avenue Bridge over Pheasant Branch, near the current Branch Street. The village lost its importance in 1856 when the Milwaukee and Mississippi Railroad routed through Peatville, a village located to the southwest. Peatville eventually became Middleton.

After WWII, the area became a residential suburb of Madison and additional roads, utilities and buildings were built. The City of Middletown built nine storm sewers to drain the developed areas; these emptied into Pheasant Branch. A landfill (roughly between GPS Start: 43.10264, -89.50947 to 43.10329, -89.50777) along the southern edge of the creek east of Clark Street School was abandoned and capped after several creek flows and rain events caused erosion and sedimentation flow into Lake Mendota. In 1965, Middleton residents formed the Middleton Conservation Committee to address erosion and sedimentation issues with Pheasant Branch and Lake Mendota. The committee's efforts resulted in the 1970 rerouting of the main creek channel to flow northward into the marsh to reduce sedimentation flow into the lake. The Conservation Committee also spearheaded the purchase of approximately 340 acres of land by the City of to create the Pheasant Branch Conservancy (PBC) in the 1970s and 1980s. Dane County and the Wisconsin DNR also own lands contiguous to the City's parcels that comprise the total 550-acre conservancy.

The section of the Pheasant Branch stream, known as the Mainstem, flows easterly from the Mainstem Pond near Deming Way, under Parmenter Street to Park Street, then from Park to Century Avenue. The area from Parmenter to Park is called Firemen's Park and the area from Park to Century is called Parisi Park.

Firemen's Park is generally bordered by municipal, multi-and single-family residences, and school buildings; the Middleton Police Station, a multi-family complex, several large

residences and the Kromrey Middle School front onto Donna Drive with Firemen's Park and the Pheasant Branch at their rear. Part of Pheasant Branch was relocated to enable the middle school construction. Middleton High School's athletic campus borders Firemen's Park at the south side.

East of Park Street, Parisi Park is generally bordered by one and two-story single-family residences with a cluster of commercial buildings near Century Avenue and Branch Street that back onto the Conservancy property.

A large portion of the stream (approximately 2,800 linear feet beginning 450 feet north of Century Avenue) flows north-northeast from Century Avenue through a wooded area with post-1992 residential neighborhoods to the west, some commercial and multifamily buildings to the south, and at a distance of over one-quarter mile, a residential neighborhood to the east. To the north, the waterway flows into the Pheasant Branch Marsh, where the flow then passes southward again to Lake Mendota.

The streambank was realigned and straightened in 1970. A review of Historic Aerials' historic maps (http://www.historicaerials.com) shows the earlier stream route looping eastward in the late 1800's then looping further northward starting in the early 1900's until the 1970 realignment and straightening. The maps also indicate the current stream route was occasionally identified as an artificial ditch (1975, 1979).

Various other engineering and bank stabilization efforts along the stream banks occurred after this project, including the installation of a stream gage station and a rank of gabion baskets on the west bank immediately north of Century Avenue. The most recent streambank stabilization effort occurred in early 2018 when the Conservancy acted to improve the stream quality and reduce sediment outflow by adding cross vanes, toewood/rootwads, rip rap toes, erosion blankets, fabric, and mats, grading and seeding of banks, and removing log jams. The 2018 project began 100 feet north of Century and continued north for 4,000 linear feet. The disaster event, occurring between August 17 and September 14, 2018, severely damaged the stabilization project.

Construction drawings for the project and maps illustrating the APE are included in this submission. The Area of Potential Effect (APE) is defined as the construction limits as the work is not expected to have visual effects beyond the APE. Areas for equipment staging and access will conform to the existing paved trails adjacent to the stream. The APE is noted on Figure 3.

Steps Taken to Identify Historic Properties and the Description of Historic Properties:

Archaeology

An archaeological literature search and technical memorandum of recommendations was undertaken by an SOI-Qualified archaeologist with SERCO contracted by FEMA (Attachment 4).¹ The literature search and technical memorandum indicates that the APE for the corridor, except for two segments, has been previously surveyed (Figure 32). These two segments were heavily modified during a Pheasant Branch Creek Relocation project (City Project #69-108), which was permitted in 1969 and constructed in 1970. A new channel was excavated to flow in a north-northeast direction. In total, 22,050 cubic yards were excavated, and the new channel banks were covered with 16,078 square

¹ Technical Memorandum Final, Project 88229 Event #4402DR-WI Water Control Facilities PBC Streambank Restoration Archaeological Desktop Assessment, City of Middleton, Dane County, Wisconsin. February 3, 2022.

yards of topsoil and seed. Given the APE, scope of work, and the significant extent and nature of the ground disturbing activities for previous stream relocation, the work within these two segments is not likely to encounter archaeological artifacts or features within their original depositional contexts that yield information important to history or prehistory.

SERCO identified only one archaeological site, 47-DA-0815 as partially within the APE. This site was originally identified in 1936 and partially surveyed in a 2016 archaeological survey conducted for a Phase I Archaeological Literature Review and Reconnaissance Pheasant Branch Stream Restoration, Dane County, Wisconsin by Cardno.² The partial survey encompasses the APE for this undertaking. The portions of the site that overlap the boundaries of the APE were not recommended for further investigations (Figure 33). FEMA notes that the prior archaeological investigations extended partially beyond the current APE although the entire boundaries of the site were not investigated. It is noted that the limestone walking path was the eastern most limit of the archaeological investigation and is not within this undertaking's APE.

Photos taken post-disaster within the boundaries of 47-DA-0815 (Figures 24-29) illustrate that the velocity of water within Pheasant Creek eroded, destabilized and washed out the nature-based solutions, soils, root wads as well as rip rap, geotechnical fabric and gabion baskets that were installed as part of the implemented Pheasant Branch Stream restoration project.

Although an evaluation of eligibility of 47-DA-0185 outside of the boundaries of the APE is beyond the scope of this review, within the APE, given the velocity of water, significant disturbance from prior installation of streambank stabilization, and prior archaeological investigations that extended beyond the banks which did not encounter archaeological artifacts or features, it is unlikely that intact soils with archaeological artifacts or features within their original depositional contexts exist.

The two stream relocations, (43.104399, -89.504811 and 43.104008, -89.503381) were within the CARDNO previous archaeological survey and outside of the recorded DA-47-0185 (Figures 15, 16, 17).

Based on the absence of archaeological features or artifacts within the APE, FEMA has determined that there are no below ground properties eligible for listing on the National Register of Historic Places within the APE for this undertaking.

Standing Structures

The nearest NRHP-listed properties and one NRHP historic district are located over three-quarters of a mile from the APE for this undertaking. The Dr. Newman C. Rowley House and the Middletown Depot are both over one mile southwest of the Century Avenue bridge over Pheasant Branch. The eastern end of the East End Historic District is three-quarters of a mile southwest of the Century Avenue bridge.

The closest surveyed property found in the Wisconsin SHPO database is the 1847 Old Stamm House, surveyed in 1977. The two-story fieldstone gabled ell building was constructed as a store and was used as a hotel, tavern, dance hall, supper club and restaurant. The building is on the south side of Century Avenue, approximately 325 feet

² Vernonica Parsell, Principal Investigator. Cardno, Phase I Archaeological Reconnaissance Pheasant Branch Stream Restoration, City of Middleton, Dane County, Wisconsin. 2016.

from Pheasant Branch; views into and from the Pheasant Branch are limited by heavy vegetation.

The pedestrian bridges crossing Pheasant Branch within the proposed construction project APE are simple utilitarian timber and wood structures supported on earthen embankments and are not of historic age. No other standing structures exist within the APE for this undertaking.

Preliminary Determination of Eligibility:

Based on the information provided above, FEMA has determined that *no resources* within the APE are eligible for listing on the National Register of Historic Places.

Finding:

FEMA finds that this undertaking will result in *no historic properties affected*.

Summary of Views of Consulting Parties or Public:

On March 29, 2022, the following Tribes were provided information regarding this project:

Ho-Chunk Nation

Menominee Indian Tribe of Wisconsin

Miami Tribe of Oklahoma

Osage Nation

Winnebago Tribe of Nebraska

Figures:

Figure 1: Approximate undertaking site marked in blue, not to scale. GoogleEarth image




Figure 2: Approximate undertaking sitemarked in blue, not to scale.

USGS Map "Middleton, WI" and "Madison West, WI," 1:24000, enlarged to show detail.



Figure 3: APE in black. Work locations are in blue and orange (stone toe), red (bank grading), purple (rootwad), pink (boulder clusters) and brown (toewood).

USGS Map "Middleton, WI" and "Madison West, WI," with WISAHRD overlay.




Figure 4: Photo Log. Work locations are in blue and orange (stone toe), red (bank grading), purple (rootwad), pink (boulder clusters) and brown (toewood).

GoogleEarth image.



Figure 5: Photo facing east Project files



Figure 7: Photo facing northeast *Project files*




Figure 6: Facing east *Project files*



Figure 8: Photo facing east *Project files*



Figure 9: Facing west Project files



Figure 11: Facing north *Project files*



Figure 10: Facing south *Project files*




Figure 12: Facing south *Project files*



Area of scouring and wash away of soil

Figure 13: Facing southeast *Project files*



Figure 15: Facing southeast, stream relocation *Project files*



Figure 14: Facing north *Project files*



Figure 16: Facing south, stream relocation *Project files*



Figure 17 Facing south, stream relocation *Project files*



Figure 19: Facing south *Project files*



Figure 18: Facing southwest *Project files*



Figure 20: Facing southwest *Project files*



Figure 21: Facing southwest *Project files*



Figure 23: Facing north *Project files*




Figure 22: Facing west *Project files*



Figure 24: Facing south, 47-DA-0815, FEMA APE previously surveyed.




Figure 25: Facing south, 47-DR-0185, FEMA APE previously surveyed.

Project files

Figure 26: Facing north, 47-DA-0185, FEMA APE previously surveyed.

Project files



Figure 27: Facing west, 47-DA-0185, FEMA APE previously surveyed.

*Project files**

Figure 28: Facing southwest, 47-DA-0185, FEMA APE previously surveyed. Project files

Figure 29: Facing north, 47-DA-0185, FEMA APE previously surveyed.




Figure 31: Facing north *Project files*



Figure 30: Facing north *Project files*







Figure 33: CARDNO 47-DA-0185 Archaeology Shovel Tests, APE previously surveyed. Note buffer extending beyond bank grading areas which extend beyond APE. The eastern limit of the site was only investigated up to and not beyond the existing limestone path. *Cardno aerial.*



TECHNICAL MEMORANDUM FINAL

PROJECT # 88229 EVENT #4402DR-WI WATER CONTROL FACILITIES PBC STREAMBANK RESTORATION ARCHAEOLOGICAL DESKTOP ASSESSMENT CITY OF MIDDLETON, DANE COUNTY, WISCONSIN

SENIOR ARCHAEOLOGIST: Varna Boyd, MA, RPA, Principal Investigator

SUBJECT: Archaeological Desktop Assessment

DATE: February 3, 2022

This technical memorandum details the results of an archaeological desktop assessment in support of the Federal Emergency Management Agency's (FEMA) Public Assistance Grant, 4402DR-WI, for Water Control Facilities PBC Streambank Restoration in the City of Middleton, Wisconsin (Figure 1). The streambank restoration project is a result of Disaster #4402DR-WI (a severe storm with heavy rains) that occurred between August 17 and September 14, 2018. The severe storms and rains caused surface water flooding and high-velocity run-off to the Pheasant Branch drainage channel, which resulted in damage to water control facilities and stream embankments along portions of Pheasant Branch Creek.

The archaeological desktop assessment was conducted in anticipation of consultation with the Wisconsin Historical Society (WHS), which serves as the State Historic Preservation Office (SHPO), and Tribal Historic Preservation Officers (THPO) in compliance with Section 106 of the National Historic Preservation Act (NHPA) and the National Environmental Policy Act (NEPA). The assessment was performed by a professional archaeologist who exceeds the Secretary of the Interior's *Professional Qualifications Standards* (48 FR 44716, September 29, 1983) and who has worked in Wisconsin previously. Portions of this assessment contain sensitive archaeological information (i.e., site location data).

ASSESSMENT GOALS AND METHODS

The goals of the assessment were to determine if previously identified archaeological resources were adjacent to or within the Area of Potential Effect (APE), which has been defined as the proposed limits of ground disturbance; determine what areas, if any, had been previously surveyed within the APE; determine the potential for archaeological resources within any previously unsurveyed areas; and make recommendations for further study, as warranted.



Figure 1: Project Location (Source: City of Middleton, WI).

To accomplish these goals, site file and previous survey research was conducted in the WHS's Wisconsin Historic Preservation Database (WHPD) for Township 7, Region 8E (T7R8E), Sections 1, 2, 11, and 12, which was considered the study area. Environmental data (e.g., soils) that could affect the potential for archaeological resources were reviewed for the APE.

Based on the known presence of archaeological sites in the vicinity, the potential for archaeological sites to be present within the project APE was initially considered to be high. However, it was also known that portions of the APE had been previously disturbed (e.g., graded) and that portions had been previously surveyed (see following section). As a result, the assessment also included a comparison of previous survey areas and project plans to determine if there were unsurveyed areas within the APE and if so, evaluate their potential for archaeological resources. Recommendations were made based on the combined data analysis. No archival research or review of architectural resources or properties was included in this archaeological desktop assessment.

ARCHAEOLOGICAL SITE FILE RESEARCH

Numerous surveys have been conducted in the vicinity, including studies by Archaeological Consulting and Services (Figure 2; Salkin 1992, 1993, and 2008), the WHS-Museum Archaeology Program (Figure 2; Hamilton 2010), and Cardno (Figure 3; Settle 2016) within the project APE. Only two small areas in the North of Century section of the APE have not been surveyed (Figure 4).




Figure 2: Surveys Prior to 2016 in the Project Vicinity (Source: Settle 2016:15).

Twenty archaeological sites were identified within the four T7R8E sections comprising the study area (Attachment 1). The majority (n=15) are precontact (i.e., Native American) mounds, campsites/villages, lithic workshops (i.e., stone tool manufacture), or lithic scatters (i.e., byproducts of stone tool production). There were also three multicomponent sites, including two precontact and historic Native American sites and one precontact and historic site. Two historic cemeteries, St. Luke's Cemetery and St. Bernard's Cemetery, are also present within the study area.
One site, 47-DA-0989 (Pheasant Branch Nature Preserve #1), has been determined not eligible for the NRHP; the remaining sites have not been evaluated for eligibility to the NRHP based on the WHPD site files.
The only site identified within the project APE was 47-DA-0815 (Site B), The site was originally identified in 1936 by Charles Brown of the WHS.
An archaeological survey of the western third of the site near Pheasant Branch was conducted by Cardno as part of a City of Middleton stream restoration project (Figure 3; Settle 2016). Ten shovel tests were excavated in that study, but none contained artifacts or cultural features. Portions of the east Pheasant Branch streambank and the entire west bank were not tested due to 15 percent or greater slopes (Settle 2016). Ground disturbance related to a limestone walking path was also noted in the eastern portion of Pheasant Branch within the Cardno project area (Settle 2016). Cardno recommended no further archaeological studies in what is now part of the current project APE (Settle 2016). FEMA will provide this technical memorandum as part of the SHPO consultation for this FEMA undertaking.

Two cemeteries are located within the study area. St. Luke's Cemetery is approximately 0.5 miles north and west of the project APE at 7515 Century Place in Middleton. St. Luke's Cemetery dates from approximately 1851 to the present. St. Bernard's Cemetery is approximately 0.4 miles south and southeast of the project APE at 1925 Branch Street in Middleton. It dates from 1897 to the present, but most headstones are from the 1960s to the present.

As the Sauk Mound, Heim Mound, the Murphy site, and the two cemeteries all have human burials, they are protected under the 1985 Wisconsin Act 316 (Wis. Stats. 157.70). While not expected as part of the current project, any effects to these sites require consultation with the WHS.

RESULTS AND RECOMMENDATIONS

The archaeological desktop assessment resulted in the identification of numerous prior surveys in the project APE as well as 20 archaeological sites within the study area. The proposed APE has been previously surveyed except for two small areas in the North of Century portion of the project. According to the City of Middleton, these two areas were part of the Pheasant Branch Creek Relocation project (City Project #69-108), which was permitted in 1969 and constructed in 1970 (personal communication between Mr. Roger Ammons, FEMA Program Delivery Manager, and Shawn Stauske, City of Middleton's Director of Public Works June 9, 2020). A new channel was excavated to flow in a north-northeast direction. In total, 22,050 cubic yards were excavated, and the new channel banks were covered with 16,078 square yards of topsoil and seed. These activities have significantly disturbed the unsurveyed areas of the APE. As a result, no further archaeological survey is recommended within these two areas.

Only one of the 20 archaeological sites, 47-DA-0815 (Site B), is present within the project APE. Prior survey by Cardno was conducted in the portions of the site that overlap the project APE and no artifacts or cultural features were identified. As a result, it is unlikely that further survey would identify other cultural resources. As a result, no further work is recommended within the portion of the site within the proposed APE. However, if plans change and the APE is expanded, additional analysis should be conducted to ensure no unsurveyed areas of the site will be impacted by the proposed project.

Due to the location of the project APE, no effects are anticipated for any of the other archaeological sites or cemeteries, including the Sauk Mound, Heim Mound, and the Murphy site. As a result of the desktop archaeological assessment, it is anticipated that the proposed project will have no effect to known archaeological resources.

REFERENCES CITED

Hamilton, Kelley

2010 CTH Q (Allen Boulevard) Archaeological Monitor, Dane County. Prepared by the Wisconsin Historical Society-Museum Archaeology Program.

Salkin, Philip H.

- 1992 An Archaeological Survey of the Proposed Pheasant Branch Interceptor Tributary Route in Middleton, Wisconsin. Prepared by Archaeological Consulting and Services.
- 1993 A Program of Archaeological testing at Two Sites (47DA987 and 47DA989) in Middleton, Dane County, Wisconsin. Prepared by Archaeological Consulting and Services.
- 2008 WDOT Archaeological Survey Field Report: Pheasant Branch Creek Trail in Dane County, Wisconsin. Prepared by Archaeological Consulting and Services.

Settle, Kathleen

2016 Phase I Archaeological Literature Review and Reconnaissance Pheasant Branch Stream Restoration, Dane County, Wisconsin. Prepared by Cardno.

ATTACHMENT 1

Attachment 1: Archaeological Sites within T7R8E Sections 1, 2, 11, and 12.

T7R8E Section Number	Site Number and Name	Site Type	Within APE	WHS Project Number	Recommendation	Notes
1	47-DA-0815, Site B		Yes	16-0992	Consultation with SHPO, but no anticipated effect	The site overlaps Pheasant Branch and the APE. A Cardno survey (Settle 2016) in the western third of the site found no artifacts or other cultural resources. The current status of the site is unknown, and the site inventory notes a request for consultation.
1	47-DA-0209, Baskerville Campsite	Precontact Campsite/Village/Workshop	No	N/A	No effect	
1	47-DA-0989, Pheasant Branch Nature Preserve #1	Precontact Campsite/Village	No	92-0421	No effect	Not eligible.
1	47-DA-1249, Middleton Hills	Precontact (Late Paleoindian – Late Woodland) Campsite/Village	No	N/A	No effect	
2	St. Luke's Cemetery	Historic Cemetery	No	N/A	No effect	
2	47-DA-0737, Freeman	Precontact (Middle Archaic and Early Woodland) Lithic Scatter and Historic Periods	No	10-0283 and 89- 0646	No effect	
2	47-DA-0966, S. Ziegler III	Precontact Workshop	No	89-0646	No effect	

T7R8E Section Number	Site Number and Name	Site Type	Within APE	WHS Project Number	Recommendation	Notes
2	47-DA-1422, Murphy Site II	Precontact (Middle and Late Archaic, Late Woodland) Campsite/Village/Burial	No	10-0283	No effect	
11	47-DA-0441, Woodside Heights Park	Precontact (Archaic) Campsite/Village	No	78-1104	No effect	
11	47-DA-0447, Park Shores	Precontact (Late Paleoindian and Archaic) Campsite/Village	No	78-1104	No effect	Most of site was destroyed by development, but a wooded area may still have intact deposits.
12	St. Bernard's Cemetery	Historic Cemetery	No	N/A	No effect	Any work in the park requires monitoring by an archaeologist.
12	47-DA-0381, Miller	Precontact and Historic Native American Campsite/Village	No	N/A	No effect	
12	47-DA-0389, Pheasant Branch	Precontact and Historic Native American Campsite/Village	No	11-9007, 10-7712	No effect	Portions of the site have been heavily disturbed. Site boundaries were amended in 2010.
12	47-DA-0423, Lemcke	Precontact (Late Archaic) Campsite/Village	No	N/A	No effect	
12	47-DA-0433, Sauk Trail School	Precontact (Late Woodland) Isolated Finds	No	11-9012	No effect	
12	47-DA-0495, Iltis Beach	Precontact (Late Woodland) Campsite/Village/Workshop	No	N/A	No effect	
12	47-DA-0816, Heim Farm	Precontact (Late Paleoindian, Late Archaic – Middle Woodland) Campsite/Village	No	11-9012	No effect	
Total Sites	20		1			

60 to 90% complete plans were provided as part of this consultation.

See Appendix A for the most recent project plans.





March 29, 2022

William Quackenbush, Tribal Historic Preservation Officer Ho-Chunk Nation W 9814 Airport Rd P.O. Box 667 Black River Falls, Wisconsin 54615

Re: Pheasant Branch Creek Stabilization Middleton, Dane County, Wisconsin FEMA Project #88229; PW 593 43.103301, -89.513886 to 43.109433, -89.491877 S1, 2, 11, and 12 T7N R8E

Dear Mr. Quackenbush:

Pursuant to the Section 106 of the National Historic Preservation Act, I am writing this letter to initiate and conclude consultation regarding the captioned Public Assistance Grant Program project. In accord with 36 CFR §800.11, I am enclosing documentation regarding this undertaking and its effect on historic properties, which is being sent concurrently to the Wisconsin State Historic Preservation Office for their review. This documentation provides the justification for FEMA's finding of no historic properties affected.

FEMA is providing these materials to the following federally recognized Indian tribes (Tribes) thought to have interests in the area:

- Ho-Chunk Nation
- Menominee Indian Tribe of Wisconsin
- Miami Tribe of Oklahoma

Osage Nation

Castole

Winnebago Tribe of Nebraska

In accord with 36 CFR 800.2(c)(2)(ii), FEMA is providing this opportunity for the Ho-Chunk Nation to join the consultation by identifying concerns and providing comments about historic properties that may be affected by this undertaking. FEMA would also appreciate notice of Tribes other than those listed above that may have an interest in this undertaking.

SWe would appreciate a response from your office within 30 days. If you have questions, do not hesitate to contact me at 312-408-5549 or at fema-r5-environmental@fema.dhs.gov. If we do not receive a response within 30 days, FEMA will move forward with this undertaking without comment from the Ho–Chunk Nation.

Sincerely,

Duane Castaldi

Regional Environmental Officer

FEMA Region 5



March 29, 2022

Documentation Initiating and Concluding Section 106 Consultation for a FEMA-Funded Undertaking

Project Information:

Project ID: #88229; PW 593

Title: Pheasant Branch Creek Stabilization

Address: Pheasant Branch Creek from crossing at Deming Way, eastward to

Century Avenue, then northward, parallel to Conservancy Lane

Location: Middleton, Dane County, WI

GPS: 43.102620, -89.51821 to 43.10945, -89.49057

PLSS: S1, 2, 11, and 12 T7N R8E

Description of Undertaking and APE:

As a result of severe storms, tornadoes, straight-line winds, flooding, and landslides affecting areas of the State of Wisconsin, President Trump signed the 4402-DR-WI Disaster Declaration on October 18, 2018. Under this declaration, Dane County, among others, was made eligible for FEMA's Public Assistance (PA) Program funding. The disaster event resulted in damage to infrastructure along the Pheasant Branch Creek Corridor from crossing at Deming Way and continuing eastward to north of Century Avenue in Middleton, Wisconsin (43.10262, -89.51821 to 43.10945, -89.49057).

The City of Middleton performed streambed relocation and streambank stabilization projects (most recently in 2007, 2008, 2009, 2010, 2012, and 2015) intermittently along this stretch of Pheasant Branch Creek, incorporating a variety of construction methods including sheet pile retaining walls, gabion baskets, toewood and rootwad, and rip rap toe protection. The City cleared, grubbed, graded and seeded the banks as part of these efforts. The flooding event washed away both engineered and non-engineered portions of the streambanks. However, only the areas with engineered stream stabilization will be funded by the FEMA PA grant program. Portions of a recreational trail and its supporting slopes adjacent to the stream were also damaged, as well as six timber and wood pedestrian bridges. Several existing storm sewer inlets and outlets associated with the parks and creek corridor experienced erosion damage.

The Applicant, the City of Middleton, proposes to use contract services to repair the engineered streambanks in-kind to their pre-disaster design, save for the substitution of rip-rap toe protection and fill instead of rootwad and fill in several locations. Some locations along the bank that were damaged in the event will not be repaired but will be allowed to naturalize. All work is intermittent throughout the proposed construction project bounds.

The six timber and wood pedestrian bridges will be replaced and the recreational trail will be repaired and modified. The streambed will be lowered in a few locations to

accommodate the new bridges and trail modifications. Additionally, the stream itself will be shifted in two locations (43.104399, -89.504811 and 43.104008, -89.503381).

The Pheasant Branch and Pheasant Branch Conservancy

Although assessment of the entire Pheasant Branch waterway and Middleton's parks is beyond the scope of this review, an overview of the larger resource will help describe the APE and provide context for the review and recommendations of this consultation. The Friends of Pheasant Branch compiled a booklet (*Friends of Pheasant Branch, Geology, Cultural History and Ecology of the Pheasant Branch Conservancy and Watershed in Middleton, Wisconsin,* 2005) providing an overview of the area; this document provided the basis for the short history below.

The Ho-Chunk Nation occupied the area where the marshes and Pheasant Branch drain into Lake Mendota. Mounds located approximately one and one-half miles north and also approximately one-half mile east of the eastern edge of the proposed undertaking are associated with Native American occupation.

After an 1832 treaty with the Ho-Chunk Nation involving most of Dane County, European settlement began. The area was platted in 1836 and began to be developed. Beginning in the 1850's, portions of the Pheasant Branch creek west of present-day Park Street and the marshes to the west and north were channelized and drained to facilitate a peat harvesting industry and farming. The Pheasant Branch Creek channels now called North Fork and South Fork were created in the settlement period and increased the original creek watershed and stormwater flows considerably.

A village called Pheasant Branch was established in 1853 and was centered around the current Century Avenue Bridge over Pheasant Branch, near the current Branch Street. The village lost its importance in 1856 when the Milwaukee and Mississippi Railroad routed through Peatville, a village located to the southwest. Peatville eventually became Middleton.

After WWII, the area became a residential suburb of Madison and additional roads, utilities and buildings were built. The City of Middletown built nine storm sewers to drain the developed areas; these emptied into Pheasant Branch. A landfill (roughly between GPS Start: 43.10264, -89.50947 to 43.10329, -89.50777) along the southern edge of the creek east of Clark Street School was abandoned and capped after several creek flows and rain events caused erosion and sedimentation flow into Lake Mendota. In 1965, Middleton residents formed the Middleton Conservation Committee to address erosion and sedimentation issues with Pheasant Branch and Lake Mendota. The committee's efforts resulted in the 1970 rerouting of the main creek channel to flow northward into the marsh to reduce sedimentation flow into the lake. The Conservation Committee also spearheaded the purchase of approximately 340 acres of land by the City of to create the Pheasant Branch Conservancy (PBC) in the 1970s and 1980s. Dane County and the Wisconsin DNR also own lands contiguous to the City's parcels that comprise the total 550-acre conservancy.

The section of the Pheasant Branch stream, known as the Mainstem, flows easterly from the Mainstem Pond near Deming Way, under Parmenter Street to Park Street, then from Park to Century Avenue. The area from Parmenter to Park is called Firemen's Park and the area from Park to Century is called Parisi Park.

Firemen's Park is generally bordered by municipal, multi-and single-family residences, and school buildings; the Middleton Police Station, a multi-family complex, several large

residences and the Kromrey Middle School front onto Donna Drive with Firemen's Park and the Pheasant Branch at their rear. Part of Pheasant Branch was relocated to enable the middle school construction. Middleton High School's athletic campus borders Firemen's Park at the south side.

East of Park Street, Parisi Park is generally bordered by one and two-story single-family residences with a cluster of commercial buildings near Century Avenue and Branch Street that back onto the Conservancy property.

A large portion of the stream (approximately 2,800 linear feet beginning 450 feet north of Century Avenue) flows north-northeast from Century Avenue through a wooded area with post-1992 residential neighborhoods to the west, some commercial and multifamily buildings to the south, and at a distance of over one-quarter mile, a residential neighborhood to the east. To the north, the waterway flows into the Pheasant Branch Marsh, where the flow then passes southward again to Lake Mendota.

The streambank was realigned and straightened in 1970. A review of Historic Aerials' historic maps (http://www.historicaerials.com) shows the earlier stream route looping eastward in the late 1800's then looping further northward starting in the early 1900's until the 1970 realignment and straightening. The maps also indicate the current stream route was occasionally identified as an artificial ditch (1975, 1979).

Various other engineering and bank stabilization efforts along the stream banks occurred after this project, including the installation of a stream gage station and a rank of gabion baskets on the west bank immediately north of Century Avenue. The most recent streambank stabilization effort occurred in early 2018 when the Conservancy acted to improve the stream quality and reduce sediment outflow by adding cross vanes, toewood/rootwads, rip rap toes, erosion blankets, fabric, and mats, grading and seeding of banks, and removing log jams. The 2018 project began 100 feet north of Century and continued north for 4,000 linear feet. The disaster event, occurring between August 17 and September 14, 2018, severely damaged the stabilization project.

Construction drawings for the project and maps illustrating the APE are included in this submission. The Area of Potential Effect (APE) is defined as the construction limits as the work is not expected to have visual effects beyond the APE. Areas for equipment staging and access will conform to the existing paved trails adjacent to the stream. The APE is noted on Figure 3.

Steps Taken to Identify Historic Properties and the Description of Historic Properties:

Archaeology

An archaeological literature search and technical memorandum of recommendations was undertaken by an SOI-Qualified archaeologist with SERCO contracted by FEMA (Attachment 4).¹ The literature search and technical memorandum indicates that the APE for the corridor, except for two segments, has been previously surveyed (Figure 32). These two segments were heavily modified during a Pheasant Branch Creek Relocation project (City Project #69-108), which was permitted in 1969 and constructed in 1970. A new channel was excavated to flow in a north-northeast direction. In total, 22,050 cubic yards were excavated, and the new channel banks were covered with 16,078 square

¹ Technical Memorandum Final, Project 88229 Event #4402DR-WI Water Control Facilities PBC Streambank Restoration Archaeological Desktop Assessment, City of Middleton, Dane County, Wisconsin. February 3, 2022.

yards of topsoil and seed. Given the APE, scope of work, and the significant extent and nature of the ground disturbing activities for previous stream relocation, the work within these two segments is not likely to encounter archaeological artifacts or features within their original depositional contexts that yield information important to history or prehistory.

SERCO identified only one archaeological site, 47-DA-0815 as partially within the APE. This site was originally identified in 1936 and partially surveyed in a 2016 archaeological survey conducted for a Phase I Archaeological Literature Review and Reconnaissance Pheasant Branch Stream Restoration, Dane County, Wisconsin by Cardno.² The partial survey encompasses the APE for this undertaking. The portions of the site that overlap the boundaries of the APE were not recommended for further investigations (Figure 33). FEMA notes that the prior archaeological investigations extended partially beyond the current APE although the entire boundaries of the site were not investigated. It is noted that the limestone walking path was the eastern most limit of the archaeological investigation and is not within this undertaking's APE.

Photos taken post-disaster within the boundaries of 47-DA-0815 (Figures 24-29) illustrate that the velocity of water within Pheasant Creek eroded, destabilized and washed out the nature-based solutions, soils, root wads as well as rip rap, geotechnical fabric and gabion baskets that were installed as part of the implemented Pheasant Branch Stream restoration project.

Although an evaluation of eligibility of 47-DA-0185 outside of the boundaries of the APE is beyond the scope of this review, within the APE, given the velocity of water, significant disturbance from prior installation of streambank stabilization, and prior archaeological investigations that extended beyond the banks which did not encounter archaeological artifacts or features, it is unlikely that intact soils with archaeological artifacts or features within their original depositional contexts exist.

The two stream relocations, (43.104399, -89.504811 and 43.104008, -89.503381) were within the CARDNO previous archaeological survey and outside of the recorded DA-47-0185 (Figures 15, 16, 17).

Based on the absence of archaeological features or artifacts within the APE, FEMA has determined that there are no below ground properties eligible for listing on the National Register of Historic Places within the APE for this undertaking.

Standing Structures

The nearest NRHP-listed properties and one NRHP historic district are located over three-quarters of a mile from the APE for this undertaking. The Dr. Newman C. Rowley House and the Middletown Depot are both over one mile southwest of the Century Avenue bridge over Pheasant Branch. The eastern end of the East End Historic District is three-quarters of a mile southwest of the Century Avenue bridge.

The closest surveyed property found in the Wisconsin SHPO database is the 1847 Old Stamm House, surveyed in 1977. The two-story fieldstone gabled ell building was constructed as a store and was used as a hotel, tavern, dance hall, supper club and restaurant. The building is on the south side of Century Avenue, approximately 325 feet

² Vernonica Parsell, Principal Investigator. Cardno, Phase I Archaeological Reconnaissance Pheasant Branch Stream Restoration, City of Middleton, Dane County, Wisconsin. 2016.

from Pheasant Branch; views into and from the Pheasant Branch are limited by heavy vegetation.

The pedestrian bridges crossing Pheasant Branch within the proposed construction project APE are simple utilitarian timber and wood structures supported on earthen embankments and are not of historic age. No other standing structures exist within the APE for this undertaking.

Preliminary Determination of Eligibility:

Based on the information provided above, FEMA has determined that *no resources* within the APE are eligible for listing on the National Register of Historic Places.

Finding:

FEMA finds that this undertaking will result in *no historic properties affected*.

Summary of Views of Consulting Parties or Public:

On March 29, 2022, the following Tribes were provided information regarding this project:

Ho-Chunk Nation

Menominee Indian Tribe of Wisconsin

Miami Tribe of Oklahoma

Osage Nation

Winnebago Tribe of Nebraska

Figures:

Figure 1: Approximate undertaking site marked in blue, not to scale. GoogleEarth image




Figure 2: Approximate undertaking sitemarked in blue, not to scale.

USGS Map "Middleton, WI" and "Madison West, WI," 1:24000, enlarged to show detail.



Figure 3: APE in black. Work locations are in blue and orange (stone toe), red (bank grading), purple (rootwad), pink (boulder clusters) and brown (toewood).

USGS Map "Middleton, WI" and "Madison West, WI," with WISAHRD overlay.




Figure 4: Photo Log. Work locations are in blue and orange (stone toe), red (bank grading), purple (rootwad), pink (boulder clusters) and brown (toewood).

GoogleEarth image.



Figure 5: Photo facing east Project files



Figure 7: Photo facing northeast *Project files*




Figure 6: Facing east *Project files*



Figure 8: Photo facing east *Project files*



Figure 9: Facing west *Project files*



Figure 11: Facing north *Project files*



Figure 10: Facing south *Project files*




Figure 12: Facing south *Project files*



Area of scouring and wash away of soil

Figure 13: Facing southeast *Project files*



Figure 15: Facing southeast, stream relocation *Project files*



Figure 14: Facing north *Project files*



Figure 16: Facing south, stream relocation *Project files*



Figure 17 Facing south, stream relocation *Project files*



Figure 19: Facing south *Project files*



Figure 18: Facing southwest *Project files*



Figure 20: Facing southwest *Project files*



Figure 21: Facing southwest *Project files*



Figure 23: Facing north *Project files*




Figure 22: Facing west *Project files*



Figure 24: Facing south, 47-DA-0815, FEMA APE previously surveyed.




Figure 25: Facing south, 47-DR-0185, FEMA APE previously surveyed.

Project files

Figure 26: Facing north, 47-DA-0185, FEMA APE previously surveyed.

Project files



Figure 27: Facing west, 47-DA-0185, FEMA APE previously surveyed.

*Project files**

Figure 28: Facing southwest, 47-DA-0185, FEMA APE previously surveyed. Project files

Figure 29: Facing north, 47-DA-0185, FEMA APE previously surveyed.




Figure 31: Facing north *Project files*



Figure 30: Facing north *Project files*







Figure 33: CARDNO 47-DA-0185 Archaeology Shovel Tests, APE previously surveyed. Note buffer extending beyond bank grading areas which extend beyond APE. The eastern limit of the site was only investigated up to and not beyond the existing limestone path. *Cardno aerial.*



TECHNICAL MEMORANDUM FINAL

PROJECT # 88229 EVENT #4402DR-WI WATER CONTROL FACILITIES PBC STREAMBANK RESTORATION ARCHAEOLOGICAL DESKTOP ASSESSMENT CITY OF MIDDLETON, DANE COUNTY, WISCONSIN

SENIOR ARCHAEOLOGIST: Varna Boyd, MA, RPA, Principal Investigator

SUBJECT: Archaeological Desktop Assessment

DATE: February 3, 2022

This technical memorandum details the results of an archaeological desktop assessment in support of the Federal Emergency Management Agency's (FEMA) Public Assistance Grant, 4402DR-WI, for Water Control Facilities PBC Streambank Restoration in the City of Middleton, Wisconsin (Figure 1). The streambank restoration project is a result of Disaster #4402DR-WI (a severe storm with heavy rains) that occurred between August 17 and September 14, 2018. The severe storms and rains caused surface water flooding and high-velocity run-off to the Pheasant Branch drainage channel, which resulted in damage to water control facilities and stream embankments along portions of Pheasant Branch Creek.

The archaeological desktop assessment was conducted in anticipation of consultation with the Wisconsin Historical Society (WHS), which serves as the State Historic Preservation Office (SHPO), and Tribal Historic Preservation Officers (THPO) in compliance with Section 106 of the National Historic Preservation Act (NHPA) and the National Environmental Policy Act (NEPA). The assessment was performed by a professional archaeologist who exceeds the Secretary of the Interior's *Professional Qualifications Standards* (48 FR 44716, September 29, 1983) and who has worked in Wisconsin previously. Portions of this assessment contain sensitive archaeological information (i.e., site location data).

ASSESSMENT GOALS AND METHODS

The goals of the assessment were to determine if previously identified archaeological resources were adjacent to or within the Area of Potential Effect (APE), which has been defined as the proposed limits of ground disturbance; determine what areas, if any, had been previously surveyed within the APE; determine the potential for archaeological resources within any previously unsurveyed areas; and make recommendations for further study, as warranted.



Figure 1: Project Location (Source: City of Middleton, WI).

To accomplish these goals, site file and previous survey research was conducted in the WHS's Wisconsin Historic Preservation Database (WHPD) for Township 7, Region 8E (T7R8E), Sections 1, 2, 11, and 12, which was considered the study area. Environmental data (e.g., soils) that could affect the potential for archaeological resources were reviewed for the APE.

Based on the known presence of archaeological sites in the vicinity, the potential for archaeological sites to be present within the project APE was initially considered to be high. However, it was also known that portions of the APE had been previously disturbed (e.g., graded) and that portions had been previously surveyed (see following section). As a result, the assessment also included a comparison of previous survey areas and project plans to determine if there were unsurveyed areas within the APE and if so, evaluate their potential for archaeological resources. Recommendations were made based on the combined data analysis. No archival research or review of architectural resources or properties was included in this archaeological desktop assessment.

ARCHAEOLOGICAL SITE FILE RESEARCH

Numerous surveys have been conducted in the vicinity, including studies by Archaeological Consulting and Services (Figure 2; Salkin 1992, 1993, and 2008), the WHS-Museum Archaeology Program (Figure 2; Hamilton 2010), and Cardno (Figure 3; Settle 2016) within the project APE. Only two small areas in the North of Century section of the APE have not been surveyed (Figure 4).




Figure 2: Surveys Prior to 2016 in the Project Vicinity (Source: Settle 2016:15).

Twenty archaeological sites were identified within the four T7R8E sections comprising the study area (Attachment 1). The majority (n=15) are precontact (i.e., Native American) mounds, campsites/villages, lithic workshops (i.e., stone tool manufacture), or lithic scatters (i.e., byproducts of stone tool production). There were also three multicomponent sites, including two precontact and historic Native American sites and one precontact and historic site. Two historic cemeteries, St. Luke's Cemetery and St. Bernard's Cemetery, are also present within the study area.
One site, 47-DA-0989 (Pheasant Branch Nature Preserve #1), has been determined not eligible for the NRHP; the remaining sites have not been evaluated for eligibility to the NRHP based on the WHPD site files.
The only site identified within the project APE was 47-DA-0815 (Site B), The site was originally identified in 1936 by Charles Brown of the WHS.
An archaeological survey of the western third of the site near Pheasant Branch was conducted by Cardno as part of a City of Middleton stream restoration project (Figure 3; Settle 2016). Ten shovel tests were excavated in that study, but none contained artifacts or cultural features. Portions of the east Pheasant Branch streambank and the entire west bank were not tested due to 15 percent or greater slopes (Settle 2016). Ground disturbance related to a limestone walking path was also noted in the eastern portion of Pheasant Branch within the Cardno project area (Settle 2016). Cardno recommended no further archaeological studies in what is now part of the current project APE (Settle 2016). FEMA will provide this technical memorandum as part of the SHPO consultation for this FEMA undertaking.

Two cemeteries are located within the study area. St. Luke's Cemetery is approximately 0.5 miles north and west of the project APE at 7515 Century Place in Middleton. St. Luke's Cemetery dates from approximately 1851 to the present. St. Bernard's Cemetery is approximately 0.4 miles south and southeast of the project APE at 1925 Branch Street in Middleton. It dates from 1897 to the present, but most headstones are from the 1960s to the present.

As the Sauk Mound, Heim Mound, the Murphy site, and the two cemeteries all have human burials, they are protected under the 1985 Wisconsin Act 316 (Wis. Stats. 157.70). While not expected as part of the current project, any effects to these sites require consultation with the WHS.

RESULTS AND RECOMMENDATIONS

The archaeological desktop assessment resulted in the identification of numerous prior surveys in the project APE as well as 20 archaeological sites within the study area. The proposed APE has been previously surveyed except for two small areas in the North of Century portion of the project. According to the City of Middleton, these two areas were part of the Pheasant Branch Creek Relocation project (City Project #69-108), which was permitted in 1969 and constructed in 1970 (personal communication between Mr. Roger Ammons, FEMA Program Delivery Manager, and Shawn Stauske, City of Middleton's Director of Public Works June 9, 2020). A new channel was excavated to flow in a north-northeast direction. In total, 22,050 cubic yards were excavated, and the new channel banks were covered with 16,078 square yards of topsoil and seed. These activities have significantly disturbed the unsurveyed areas of the APE. As a result, no further archaeological survey is recommended within these two areas.

Only one of the 20 archaeological sites, 47-DA-0815 (Site B), is present within the project APE. Prior survey by Cardno was conducted in the portions of the site that overlap the project APE and no artifacts or cultural features were identified. As a result, it is unlikely that further survey would identify other cultural resources. As a result, no further work is recommended within the portion of the site within the proposed APE. However, if plans change and the APE is expanded, additional analysis should be conducted to ensure no unsurveyed areas of the site will be impacted by the proposed project.

Due to the location of the project APE, no effects are anticipated for any of the other archaeological sites or cemeteries, including the Sauk Mound, Heim Mound, and the Murphy site. As a result of the desktop archaeological assessment, it is anticipated that the proposed project will have no effect to known archaeological resources.

REFERENCES CITED

Hamilton, Kelley

2010 CTH Q (Allen Boulevard) Archaeological Monitor, Dane County. Prepared by the Wisconsin Historical Society-Museum Archaeology Program.

Salkin, Philip H.

- 1992 An Archaeological Survey of the Proposed Pheasant Branch Interceptor Tributary Route in Middleton, Wisconsin. Prepared by Archaeological Consulting and Services.
- 1993 A Program of Archaeological testing at Two Sites (47DA987 and 47DA989) in Middleton, Dane County, Wisconsin. Prepared by Archaeological Consulting and Services.
- 2008 WDOT Archaeological Survey Field Report: Pheasant Branch Creek Trail in Dane County, Wisconsin. Prepared by Archaeological Consulting and Services.

Settle, Kathleen

2016 Phase I Archaeological Literature Review and Reconnaissance Pheasant Branch Stream Restoration, Dane County, Wisconsin. Prepared by Cardno.

ATTACHMENT 1

Attachment 1: Archaeological Sites within T7R8E Sections 1, 2, 11, and 12.

T7R8E Section Number	Site Number and Name	Site Type	Within APE	WHS Project Number	Recommendation	Notes
1	47-DA-0815, Site B		Yes	16-0992	Consultation with SHPO, but no anticipated effect	The site overlaps Pheasant Branch and the APE. A Cardno survey (Settle 2016) in the western third of the site found no artifacts or other cultural resources. The current status of the site is unknown, and the site inventory notes a request for consultation.
1	47-DA-0209, Baskerville Campsite	Precontact Campsite/Village/Workshop	No	N/A	No effect	
1	47-DA-0989, Pheasant Branch Nature Preserve #1	Precontact Campsite/Village	No	92-0421	No effect	Not eligible.
1	47-DA-1249, Middleton Hills	Precontact (Late Paleoindian – Late Woodland) Campsite/Village	No	N/A	No effect	
2	St. Luke's Cemetery	Historic Cemetery	No	N/A	No effect	
2	47-DA-0737, Freeman	Precontact (Middle Archaic and Early Woodland) Lithic Scatter and Historic Periods	No	10-0283 and 89- 0646	No effect	
2	47-DA-0966, S. Ziegler III	Precontact Workshop	No	89-0646	No effect	

T7R8E Section Number	Site Number and Name	Site Type	Within APE	WHS Project Number	Recommendation	Notes
2	47-DA-1422, Murphy Site II	Precontact (Middle and Late Archaic, Late Woodland) Campsite/Village/Burial	No	10-0283	No effect	
11	47-DA-0441, Woodside Heights Park	Precontact (Archaic) Campsite/Village	No	78-1104	No effect	
11	47-DA-0447, Park Shores	Precontact (Late Paleoindian and Archaic) Campsite/Village	No	78-1104	No effect	Most of site was destroyed by development, but a wooded area may still have intact deposits.
12	St. Bernard's Cemetery	Historic Cemetery	No	N/A	No effect	Any work in the park requires monitoring by an archaeologist.
12	47-DA-0381, Miller	Precontact and Historic Native American Campsite/Village	No	N/A	No effect	
12	47-DA-0389, Pheasant Branch	Precontact and Historic Native American Campsite/Village	No	11-9007, 10-7712	No effect	Portions of the site have been heavily disturbed. Site boundaries were amended in 2010.
12	47-DA-0423, Lemcke	Precontact (Late Archaic) Campsite/Village	No	N/A	No effect	
12	47-DA-0433, Sauk Trail School	Precontact (Late Woodland) Isolated Finds	No	11-9012	No effect	
12	47-DA-0495, Iltis Beach	Precontact (Late Woodland) Campsite/Village/Workshop	No	N/A	No effect	
12	47-DA-0816, Heim Farm	Precontact (Late Paleoindian, Late Archaic – Middle Woodland) Campsite/Village	No	11-9012	No effect	
Total Sites	20		1			

60 to 90% complete plans were provided as part of this consultation.

See Appendix A for the most recent project plans.



March 29, 2022

David Grignon, Tribal Historic Preservation Officer Menominee Indian Tribe of Wisconsin W3426 Cty VV West P.O. Box 910 Keshena, Wisconsin 54135-0910

Re: Pheasant Branch Creek Stabilization Middleton, Dane County, Wisconsin FEMA Project #88229; PW 593 43.103301, -89.513886 to 43.109433, -89.491877 S1, 2, 11, and 12 T7N R8E

Dear Mr. Grignon:

Pursuant to the Section 106 of the National Historic Preservation Act, I am writing this letter to initiate and conclude consultation regarding the captioned Public Assistance Grant Program project. In accord with 36 CFR §800.11, I am enclosing documentation regarding this undertaking and its effect on historic properties, which is being sent concurrently to the Wisconsin State Historic Preservation Office for their review. This documentation provides the justification for FEMA's finding of no historic properties affected.

FEMA is providing these materials to the following federally recognized Indian tribes (Tribes) thought to have interests in the area:

- Ho-Chunk Nation
- Menominee Indian Tribe of Wisconsin
- Miami Tribe of Oklahoma

- Osage Nation
- Winnebago Tribe of Nebraska

In accord with 36 CFR 800.2(c)(2)(ii), FEMA is providing this opportunity for the Menominee Indian Tribe of Wisconsin to join the consultation by identifying concerns and providing comments about historic properties that may be affected by this undertaking. FEMA would also appreciate notice of Tribes other than those listed above that may have an interest in this undertaking.

SWe would appreciate a response from your office within 30 days. If you have questions, do not hesitate to contact me at 312-408-5549 or at fema-r5-environmental@fema.dhs.gov. If we do not receive a response within 30 days, FEMA will move forward with this undertaking without comment from the Menominee Indian Tribe of Wisconsin.

Sincerely,

Duane Castaldi

Regional Environmental Officer

FEMA Region 5



March 29, 2022

Documentation Initiating and Concluding Section 106 Consultation for a FEMA-Funded Undertaking

Project Information:

Project ID: #88229; PW 593

Title: Pheasant Branch Creek Stabilization

Address: Pheasant Branch Creek from crossing at Deming Way, eastward to

Century Avenue, then northward, parallel to Conservancy Lane

Location: Middleton, Dane County, WI

GPS: 43.102620, -89.51821 to 43.10945, -89.49057

PLSS: S1, 2, 11, and 12 T7N R8E

Description of Undertaking and APE:

As a result of severe storms, tornadoes, straight-line winds, flooding, and landslides affecting areas of the State of Wisconsin, President Trump signed the 4402-DR-WI Disaster Declaration on October 18, 2018. Under this declaration, Dane County, among others, was made eligible for FEMA's Public Assistance (PA) Program funding. The disaster event resulted in damage to infrastructure along the Pheasant Branch Creek Corridor from crossing at Deming Way and continuing eastward to north of Century Avenue in Middleton, Wisconsin (43.10262, -89.51821 to 43.10945, -89.49057).

The City of Middleton performed streambed relocation and streambank stabilization projects (most recently in 2007, 2008, 2009, 2010, 2012, and 2015) intermittently along this stretch of Pheasant Branch Creek, incorporating a variety of construction methods including sheet pile retaining walls, gabion baskets, toewood and rootwad, and rip rap toe protection. The City cleared, grubbed, graded and seeded the banks as part of these efforts. The flooding event washed away both engineered and non-engineered portions of the streambanks. However, only the areas with engineered stream stabilization will be funded by the FEMA PA grant program. Portions of a recreational trail and its supporting slopes adjacent to the stream were also damaged, as well as six timber and wood pedestrian bridges. Several existing storm sewer inlets and outlets associated with the parks and creek corridor experienced erosion damage.

The Applicant, the City of Middleton, proposes to use contract services to repair the engineered streambanks in-kind to their pre-disaster design, save for the substitution of rip-rap toe protection and fill instead of rootwad and fill in several locations. Some locations along the bank that were damaged in the event will not be repaired but will be allowed to naturalize. All work is intermittent throughout the proposed construction project bounds.

The six timber and wood pedestrian bridges will be replaced and the recreational trail will be repaired and modified. The streambed will be lowered in a few locations to

accommodate the new bridges and trail modifications. Additionally, the stream itself will be shifted in two locations (43.104399, -89.504811 and 43.104008, -89.503381).

The Pheasant Branch and Pheasant Branch Conservancy

Although assessment of the entire Pheasant Branch waterway and Middleton's parks is beyond the scope of this review, an overview of the larger resource will help describe the APE and provide context for the review and recommendations of this consultation. The Friends of Pheasant Branch compiled a booklet (*Friends of Pheasant Branch, Geology, Cultural History and Ecology of the Pheasant Branch Conservancy and Watershed in Middleton, Wisconsin,* 2005) providing an overview of the area; this document provided the basis for the short history below.

The Ho-Chunk Nation occupied the area where the marshes and Pheasant Branch drain into Lake Mendota. Mounds located approximately one and one-half miles north and also approximately one-half mile east of the eastern edge of the proposed undertaking are associated with Native American occupation.

After an 1832 treaty with the Ho-Chunk Nation involving most of Dane County, European settlement began. The area was platted in 1836 and began to be developed. Beginning in the 1850's, portions of the Pheasant Branch creek west of present-day Park Street and the marshes to the west and north were channelized and drained to facilitate a peat harvesting industry and farming. The Pheasant Branch Creek channels now called North Fork and South Fork were created in the settlement period and increased the original creek watershed and stormwater flows considerably.

A village called Pheasant Branch was established in 1853 and was centered around the current Century Avenue Bridge over Pheasant Branch, near the current Branch Street. The village lost its importance in 1856 when the Milwaukee and Mississippi Railroad routed through Peatville, a village located to the southwest. Peatville eventually became Middleton.

After WWII, the area became a residential suburb of Madison and additional roads, utilities and buildings were built. The City of Middletown built nine storm sewers to drain the developed areas; these emptied into Pheasant Branch. A landfill (roughly between GPS Start: 43.10264, -89.50947 to 43.10329, -89.50777) along the southern edge of the creek east of Clark Street School was abandoned and capped after several creek flows and rain events caused erosion and sedimentation flow into Lake Mendota. In 1965, Middleton residents formed the Middleton Conservation Committee to address erosion and sedimentation issues with Pheasant Branch and Lake Mendota. The committee's efforts resulted in the 1970 rerouting of the main creek channel to flow northward into the marsh to reduce sedimentation flow into the lake. The Conservation Committee also spearheaded the purchase of approximately 340 acres of land by the City of to create the Pheasant Branch Conservancy (PBC) in the 1970s and 1980s. Dane County and the Wisconsin DNR also own lands contiguous to the City's parcels that comprise the total 550-acre conservancy.

The section of the Pheasant Branch stream, known as the Mainstem, flows easterly from the Mainstem Pond near Deming Way, under Parmenter Street to Park Street, then from Park to Century Avenue. The area from Parmenter to Park is called Firemen's Park and the area from Park to Century is called Parisi Park.

Firemen's Park is generally bordered by municipal, multi-and single-family residences, and school buildings; the Middleton Police Station, a multi-family complex, several large

residences and the Kromrey Middle School front onto Donna Drive with Firemen's Park and the Pheasant Branch at their rear. Part of Pheasant Branch was relocated to enable the middle school construction. Middleton High School's athletic campus borders Firemen's Park at the south side.

East of Park Street, Parisi Park is generally bordered by one and two-story single-family residences with a cluster of commercial buildings near Century Avenue and Branch Street that back onto the Conservancy property.

A large portion of the stream (approximately 2,800 linear feet beginning 450 feet north of Century Avenue) flows north-northeast from Century Avenue through a wooded area with post-1992 residential neighborhoods to the west, some commercial and multifamily buildings to the south, and at a distance of over one-quarter mile, a residential neighborhood to the east. To the north, the waterway flows into the Pheasant Branch Marsh, where the flow then passes southward again to Lake Mendota.

The streambank was realigned and straightened in 1970. A review of Historic Aerials' historic maps (http://www.historicaerials.com) shows the earlier stream route looping eastward in the late 1800's then looping further northward starting in the early 1900's until the 1970 realignment and straightening. The maps also indicate the current stream route was occasionally identified as an artificial ditch (1975, 1979).

Various other engineering and bank stabilization efforts along the stream banks occurred after this project, including the installation of a stream gage station and a rank of gabion baskets on the west bank immediately north of Century Avenue. The most recent streambank stabilization effort occurred in early 2018 when the Conservancy acted to improve the stream quality and reduce sediment outflow by adding cross vanes, toewood/rootwads, rip rap toes, erosion blankets, fabric, and mats, grading and seeding of banks, and removing log jams. The 2018 project began 100 feet north of Century and continued north for 4,000 linear feet. The disaster event, occurring between August 17 and September 14, 2018, severely damaged the stabilization project.

Construction drawings for the project and maps illustrating the APE are included in this submission. The Area of Potential Effect (APE) is defined as the construction limits as the work is not expected to have visual effects beyond the APE. Areas for equipment staging and access will conform to the existing paved trails adjacent to the stream. The APE is noted on Figure 3.

Steps Taken to Identify Historic Properties and the Description of Historic Properties:

Archaeology

An archaeological literature search and technical memorandum of recommendations was undertaken by an SOI-Qualified archaeologist with SERCO contracted by FEMA (Attachment 4).¹ The literature search and technical memorandum indicates that the APE for the corridor, except for two segments, has been previously surveyed (Figure 32). These two segments were heavily modified during a Pheasant Branch Creek Relocation project (City Project #69-108), which was permitted in 1969 and constructed in 1970. A new channel was excavated to flow in a north-northeast direction. In total, 22,050 cubic yards were excavated, and the new channel banks were covered with 16,078 square

¹ Technical Memorandum Final, Project 88229 Event #4402DR-WI Water Control Facilities PBC Streambank Restoration Archaeological Desktop Assessment, City of Middleton, Dane County, Wisconsin. February 3, 2022.

yards of topsoil and seed. Given the APE, scope of work, and the significant extent and nature of the ground disturbing activities for previous stream relocation, the work within these two segments is not likely to encounter archaeological artifacts or features within their original depositional contexts that yield information important to history or prehistory.

SERCO identified only one archaeological site, 47-DA-0815 as partially within the APE. This site was originally identified in 1936 and partially surveyed in a 2016 archaeological survey conducted for a Phase I Archaeological Literature Review and Reconnaissance Pheasant Branch Stream Restoration, Dane County, Wisconsin by Cardno.² The partial survey encompasses the APE for this undertaking. The portions of the site that overlap the boundaries of the APE were not recommended for further investigations (Figure 33). FEMA notes that the prior archaeological investigations extended partially beyond the current APE although the entire boundaries of the site were not investigated. It is noted that the limestone walking path was the eastern most limit of the archaeological investigation and is not within this undertaking's APE.

Photos taken post-disaster within the boundaries of 47-DA-0815 (Figures 24-29) illustrate that the velocity of water within Pheasant Creek eroded, destabilized and washed out the nature-based solutions, soils, root wads as well as rip rap, geotechnical fabric and gabion baskets that were installed as part of the implemented Pheasant Branch Stream restoration project.

Although an evaluation of eligibility of 47-DA-0185 outside of the boundaries of the APE is beyond the scope of this review, within the APE, given the velocity of water, significant disturbance from prior installation of streambank stabilization, and prior archaeological investigations that extended beyond the banks which did not encounter archaeological artifacts or features, it is unlikely that intact soils with archaeological artifacts or features within their original depositional contexts exist.

The two stream relocations, (43.104399, -89.504811 and 43.104008, -89.503381) were within the CARDNO previous archaeological survey and outside of the recorded DA-47-0185 (Figures 15, 16, 17).

Based on the absence of archaeological features or artifacts within the APE, FEMA has determined that there are no below ground properties eligible for listing on the National Register of Historic Places within the APE for this undertaking.

Standing Structures

The nearest NRHP-listed properties and one NRHP historic district are located over three-quarters of a mile from the APE for this undertaking. The Dr. Newman C. Rowley House and the Middletown Depot are both over one mile southwest of the Century Avenue bridge over Pheasant Branch. The eastern end of the East End Historic District is three-quarters of a mile southwest of the Century Avenue bridge.

The closest surveyed property found in the Wisconsin SHPO database is the 1847 Old Stamm House, surveyed in 1977. The two-story fieldstone gabled ell building was constructed as a store and was used as a hotel, tavern, dance hall, supper club and restaurant. The building is on the south side of Century Avenue, approximately 325 feet

² Vernonica Parsell, Principal Investigator. Cardno, Phase I Archaeological Reconnaissance Pheasant Branch Stream Restoration, City of Middleton, Dane County, Wisconsin. 2016.

from Pheasant Branch; views into and from the Pheasant Branch are limited by heavy vegetation.

The pedestrian bridges crossing Pheasant Branch within the proposed construction project APE are simple utilitarian timber and wood structures supported on earthen embankments and are not of historic age. No other standing structures exist within the APE for this undertaking.

Preliminary Determination of Eligibility:

Based on the information provided above, FEMA has determined that *no resources* within the APE are eligible for listing on the National Register of Historic Places.

Finding:

FEMA finds that this undertaking will result in *no historic properties affected*.

Summary of Views of Consulting Parties or Public:

On March 29, 2022, the following Tribes were provided information regarding this project:

Ho-Chunk Nation

Menominee Indian Tribe of Wisconsin

Miami Tribe of Oklahoma

Osage Nation

Winnebago Tribe of Nebraska

Figures:

Figure 1: Approximate undertaking site marked in blue, not to scale. GoogleEarth image




Figure 2: Approximate undertaking sitemarked in blue, not to scale.

USGS Map "Middleton, WI" and "Madison West, WI," 1:24000, enlarged to show detail.



Figure 3: APE in black. Work locations are in blue and orange (stone toe), red (bank grading), purple (rootwad), pink (boulder clusters) and brown (toewood).

USGS Map "Middleton, WI" and "Madison West, WI," with WISAHRD overlay.




Figure 4: Photo Log. Work locations are in blue and orange (stone toe), red (bank grading), purple (rootwad), pink (boulder clusters) and brown (toewood).

GoogleEarth image.



Figure 5: Photo facing east Project files



Figure 7: Photo facing northeast *Project files*




Figure 6: Facing east *Project files*



Figure 8: Photo facing east Project files



loss of soil, rip-rap from upstream

Figure 9: Facing west *Project files*



Figure 11: Facing north *Project files*



Figure 10: Facing south *Project files*




Figure 12: Facing south *Project files*



Area of scouring and wash away of soil

Figure 13: Facing southeast *Project files*



Figure 15: Facing southeast, stream relocation *Project files*



Figure 14: Facing north *Project files*



Figure 16: Facing south, stream relocation *Project files*



Figure 17 Facing south, stream relocation *Project files*



Figure 19: Facing south *Project files*



Figure 18: Facing southwest *Project files*



Figure 20: Facing southwest *Project files*



Figure 21: Facing southwest *Project files*



Figure 23: Facing north *Project files*




Figure 22: Facing west *Project files*



Figure 24: Facing south, 47-DA-0815, FEMA APE previously surveyed.




Figure 25: Facing south, 47-DR-0185, FEMA APE previously surveyed.

Project files

Figure 26: Facing north, 47-DA-0185, FEMA APE previously surveyed.

Project files



Figure 27: Facing west, 47-DA-0185, FEMA APE previously surveyed.

*Project files**

Figure 28: Facing southwest, 47-DA-0185, FEMA APE previously surveyed. Project files

Figure 29: Facing north, 47-DA-0185, FEMA APE previously surveyed.




Figure 31: Facing north *Project files*



Figure 30: Facing north *Project files*







Figure 33: CARDNO 47-DA-0185 Archaeology Shovel Tests, APE previously surveyed. Note buffer extending beyond bank grading areas which extend beyond APE. The eastern limit of the site was only investigated up to and not beyond the existing limestone path. *Cardno aerial.*



TECHNICAL MEMORANDUM FINAL

PROJECT # 88229 EVENT #4402DR-WI WATER CONTROL FACILITIES PBC STREAMBANK RESTORATION ARCHAEOLOGICAL DESKTOP ASSESSMENT CITY OF MIDDLETON, DANE COUNTY, WISCONSIN

SENIOR ARCHAEOLOGIST: Varna Boyd, MA, RPA, Principal Investigator

SUBJECT: Archaeological Desktop Assessment

DATE: February 3, 2022

This technical memorandum details the results of an archaeological desktop assessment in support of the Federal Emergency Management Agency's (FEMA) Public Assistance Grant, 4402DR-WI, for Water Control Facilities PBC Streambank Restoration in the City of Middleton, Wisconsin (Figure 1). The streambank restoration project is a result of Disaster #4402DR-WI (a severe storm with heavy rains) that occurred between August 17 and September 14, 2018. The severe storms and rains caused surface water flooding and high-velocity run-off to the Pheasant Branch drainage channel, which resulted in damage to water control facilities and stream embankments along portions of Pheasant Branch Creek.

The archaeological desktop assessment was conducted in anticipation of consultation with the Wisconsin Historical Society (WHS), which serves as the State Historic Preservation Office (SHPO), and Tribal Historic Preservation Officers (THPO) in compliance with Section 106 of the National Historic Preservation Act (NHPA) and the National Environmental Policy Act (NEPA). The assessment was performed by a professional archaeologist who exceeds the Secretary of the Interior's *Professional Qualifications Standards* (48 FR 44716, September 29, 1983) and who has worked in Wisconsin previously. Portions of this assessment contain sensitive archaeological information (i.e., site location data).

ASSESSMENT GOALS AND METHODS

The goals of the assessment were to determine if previously identified archaeological resources were adjacent to or within the Area of Potential Effect (APE), which has been defined as the proposed limits of ground disturbance; determine what areas, if any, had been previously surveyed within the APE; determine the potential for archaeological resources within any previously unsurveyed areas; and make recommendations for further study, as warranted.



Figure 1: Project Location (Source: City of Middleton, WI).

To accomplish these goals, site file and previous survey research was conducted in the WHS's Wisconsin Historic Preservation Database (WHPD) for Township 7, Region 8E (T7R8E), Sections 1, 2, 11, and 12, which was considered the study area. Environmental data (e.g., soils) that could affect the potential for archaeological resources were reviewed for the APE.

Based on the known presence of archaeological sites in the vicinity, the potential for archaeological sites to be present within the project APE was initially considered to be high. However, it was also known that portions of the APE had been previously disturbed (e.g., graded) and that portions had been previously surveyed (see following section). As a result, the assessment also included a comparison of previous survey areas and project plans to determine if there were unsurveyed areas within the APE and if so, evaluate their potential for archaeological resources. Recommendations were made based on the combined data analysis. No archival research or review of architectural resources or properties was included in this archaeological desktop assessment.

ARCHAEOLOGICAL SITE FILE RESEARCH

Numerous surveys have been conducted in the vicinity, including studies by Archaeological Consulting and Services (Figure 2; Salkin 1992, 1993, and 2008), the WHS-Museum Archaeology Program (Figure 2; Hamilton 2010), and Cardno (Figure 3; Settle 2016) within the project APE. Only two small areas in the North of Century section of the APE have not been surveyed (Figure 4).




Figure 2: Surveys Prior to 2016 in the Project Vicinity (Source: Settle 2016:15).

Twenty archaeological sites were identified within the four T7R8E sections comprising the study area (Attachment 1). The majority (n=15) are precontact (i.e., Native American) mounds, campsites/villages, lithic workshops (i.e., stone tool manufacture), or lithic scatters (i.e., byproducts of stone tool production). There were also three multicomponent sites, including two precontact and historic Native American sites and one precontact and historic site. Two historic cemeteries, St. Luke's Cemetery and St. Bernard's Cemetery, are also present within the study area.
One site, 47-DA-0989 (Pheasant Branch Nature Preserve #1), has been determined not eligible for the NRHP; the remaining sites have not been evaluated for eligibility to the NRHP based on the WHPD site files.
The only site identified within the project APE was 47-DA-0815 (Site B), The site was originally identified in 1936 by Charles Brown of the WHS.
An archaeological survey of the western third of the site near Pheasant Branch was conducted by Cardno as part of a City of Middleton stream restoration project (Figure 3; Settle 2016). Ten shovel tests were excavated in that study, but none contained artifacts or cultural features. Portions of the east Pheasant Branch streambank and the entire west bank were not tested due to 15 percent or greater slopes (Settle 2016). Ground disturbance related to a limestone walking path was also noted in the eastern portion of Pheasant Branch within the Cardno project area (Settle 2016). Cardno recommended no further archaeological studies in what is now part of the current project APE (Settle 2016). FEMA will provide this technical memorandum as part of the SHPO consultation for this FEMA undertaking.

Two cemeteries are located within the study area. St. Luke's Cemetery is approximately 0.5 miles north and west of the project APE at 7515 Century Place in Middleton. St. Luke's Cemetery dates from approximately 1851 to the present. St. Bernard's Cemetery is approximately 0.4 miles south and southeast of the project APE at 1925 Branch Street in Middleton. It dates from 1897 to the present, but most headstones are from the 1960s to the present.

As the Sauk Mound, Heim Mound, the Murphy site, and the two cemeteries all have human burials, they are protected under the 1985 Wisconsin Act 316 (Wis. Stats. 157.70). While not expected as part of the current project, any effects to these sites require consultation with the WHS.

RESULTS AND RECOMMENDATIONS

The archaeological desktop assessment resulted in the identification of numerous prior surveys in the project APE as well as 20 archaeological sites within the study area. The proposed APE has been previously surveyed except for two small areas in the North of Century portion of the project. According to the City of Middleton, these two areas were part of the Pheasant Branch Creek Relocation project (City Project #69-108), which was permitted in 1969 and constructed in 1970 (personal communication between Mr. Roger Ammons, FEMA Program Delivery Manager, and Shawn Stauske, City of Middleton's Director of Public Works June 9, 2020). A new channel was excavated to flow in a north-northeast direction. In total, 22,050 cubic yards were excavated, and the new channel banks were covered with 16,078 square yards of topsoil and seed. These activities have significantly disturbed the unsurveyed areas of the APE. As a result, no further archaeological survey is recommended within these two areas.

Only one of the 20 archaeological sites, 47-DA-0815 (Site B), is present within the project APE. Prior survey by Cardno was conducted in the portions of the site that overlap the project APE and no artifacts or cultural features were identified. As a result, it is unlikely that further survey would identify other cultural resources. As a result, no further work is recommended within the portion of the site within the proposed APE. However, if plans change and the APE is expanded, additional analysis should be conducted to ensure no unsurveyed areas of the site will be impacted by the proposed project.

Due to the location of the project APE, no effects are anticipated for any of the other archaeological sites or cemeteries, including the Sauk Mound, Heim Mound, and the Murphy site. As a result of the desktop archaeological assessment, it is anticipated that the proposed project will have no effect to known archaeological resources.

REFERENCES CITED

Hamilton, Kelley

2010 CTH Q (Allen Boulevard) Archaeological Monitor, Dane County. Prepared by the Wisconsin Historical Society-Museum Archaeology Program.

Salkin, Philip H.

- 1992 An Archaeological Survey of the Proposed Pheasant Branch Interceptor Tributary Route in Middleton, Wisconsin. Prepared by Archaeological Consulting and Services.
- 1993 A Program of Archaeological testing at Two Sites (47DA987 and 47DA989) in Middleton, Dane County, Wisconsin. Prepared by Archaeological Consulting and Services.
- 2008 WDOT Archaeological Survey Field Report: Pheasant Branch Creek Trail in Dane County, Wisconsin. Prepared by Archaeological Consulting and Services.

Settle, Kathleen

2016 Phase I Archaeological Literature Review and Reconnaissance Pheasant Branch Stream Restoration, Dane County, Wisconsin. Prepared by Cardno.

ATTACHMENT 1

Attachment 1: Archaeological Sites within T7R8E Sections 1, 2, 11, and 12.

T7R8E Section Number	Site Number and Name	Site Type	Within APE	WHS Project Number	Recommendation	Notes
1	47-DA-0815, Site B		Yes	16-0992	Consultation with SHPO, but no anticipated effect	The site overlaps Pheasant Branch and the APE. A Cardno survey (Settle 2016) in the western third of the site found no artifacts or other cultural resources. The current status of the site is unknown, and the site inventory notes a request for consultation.
1	47-DA-0209, Baskerville Campsite	Precontact Campsite/Village/Workshop	No	N/A	No effect	
1	47-DA-0989, Pheasant Branch Nature Preserve #1	Precontact Campsite/Village	No	92-0421	No effect	Not eligible.
1	47-DA-1249, Middleton Hills	Precontact (Late Paleoindian – Late Woodland) Campsite/Village	No	N/A	No effect	
2	St. Luke's Cemetery	Historic Cemetery	No	N/A	No effect	
2	47-DA-0737, Freeman	Precontact (Middle Archaic and Early Woodland) Lithic Scatter and Historic Periods	No	10-0283 and 89- 0646	No effect	
2	47-DA-0966, S. Ziegler III	Precontact Workshop	No	89-0646	No effect	

T7R8E Section Number	Site Number and Name	Site Type	Within APE	WHS Project Number	Recommendation	Notes
2	47-DA-1422, Murphy Site II	Precontact (Middle and Late Archaic, Late Woodland) Campsite/Village/Burial	No	10-0283	No effect	
11	47-DA-0441, Woodside Heights Park	Precontact (Archaic) Campsite/Village	No	78-1104	No effect	
11	47-DA-0447, Park Shores	Precontact (Late Paleoindian and Archaic) Campsite/Village	No	78-1104	No effect	Most of site was destroyed by development, but a wooded area may still have intact deposits.
12	St. Bernard's Cemetery	Historic Cemetery	No	N/A	No effect	Any work in the park requires monitoring by an archaeologist.
12	47-DA-0381, Miller	Precontact and Historic Native American Campsite/Village	No	N/A	No effect	
12	47-DA-0389, Pheasant Branch	Precontact and Historic Native American Campsite/Village	No	11-9007, 10-7712	No effect	Portions of the site have been heavily disturbed. Site boundaries were amended in 2010.
12	47-DA-0423, Lemcke	Precontact (Late Archaic) Campsite/Village	No	N/A	No effect	
12	47-DA-0433, Sauk Trail School	Precontact (Late Woodland) Isolated Finds	No	11-9012	No effect	
12	47-DA-0495, Iltis Beach	Precontact (Late Woodland) Campsite/Village/Workshop	No	N/A	No effect	
12	47-DA-0816, Heim Farm	Precontact (Late Paleoindian, Late Archaic – Middle Woodland) Campsite/Village	No	11-9012	No effect	
Total Sites	20		1			

60 to 90% complete plans were provided as part of this consultation.

See Appendix A for the most recent project plans.



March 29, 2022

Diane Hunter, Tribal Historic Preservation Officer Miami Tribe of Oklahoma PO Box 1326 Miami, Oklahoma 74355

Re: Pheasant Branch Creek Stabilization Middleton, Dane County, Wisconsin FEMA Project #88229; PW 593 43.103301, -89.513886 to 43.109433, -89.491877 S1, 2, 11, and 12 T7N R8E

Dear Ms. Hunter:

Pursuant to the Section 106 of the National Historic Preservation Act, I am writing this letter to initiate and conclude consultation regarding the captioned Public Assistance Grant Program project. In accord with 36 CFR §800.11, I am enclosing documentation regarding this undertaking and its effect on historic properties, which is being sent concurrently to the Wisconsin State Historic Preservation Office for their review. This documentation provides the justification for FEMA's finding of no historic properties affected.

FEMA is providing these materials to the following federally recognized Indian tribes (Tribes) thought to have interests in the area:

- Ho-Chunk Nation
- Menominee Indian Tribe of Wisconsin
- Miami Tribe of Oklahoma

Osage Nation

Castoll

Winnebago Tribe of Nebraska

In accord with 36 CFR 800.2(c)(2)(ii), FEMA is providing this opportunity for the Miami Tribe of Oklahoma to join the consultation by identifying concerns and providing comments about historic properties that may be affected by this undertaking. FEMA would also appreciate notice of Tribes other than those listed above that may have an interest in this undertaking.

SWe would appreciate a response from your office within 30 days. If you have questions, do not hesitate to contact me at 312-408-5549 or at fema-r5-environmental@fema.dhs.gov. If we do not receive a response within 30 days, FEMA will move forward with this undertaking without comment from the Miami Tribe of Oklahoma.

Sincerely,

Duane Castaldi

Regional Environmental Officer

FEMA Region 5

Sent by email to dhunter@miamination.com



March 29, 2022

Documentation Initiating and Concluding Section 106 Consultation for a FEMA-Funded Undertaking

Project Information:

Project ID: #88229; PW 593

Title: Pheasant Branch Creek Stabilization

Address: Pheasant Branch Creek from crossing at Deming Way, eastward to

Century Avenue, then northward, parallel to Conservancy Lane

Location: Middleton, Dane County, WI

GPS: 43.102620, -89.51821 to 43.10945, -89.49057

PLSS: S1, 2, 11, and 12 T7N R8E

Description of Undertaking and APE:

As a result of severe storms, tornadoes, straight-line winds, flooding, and landslides affecting areas of the State of Wisconsin, President Trump signed the 4402-DR-WI Disaster Declaration on October 18, 2018. Under this declaration, Dane County, among others, was made eligible for FEMA's Public Assistance (PA) Program funding. The disaster event resulted in damage to infrastructure along the Pheasant Branch Creek Corridor from crossing at Deming Way and continuing eastward to north of Century Avenue in Middleton, Wisconsin (43.10262, -89.51821 to 43.10945, -89.49057).

The City of Middleton performed streambed relocation and streambank stabilization projects (most recently in 2007, 2008, 2009, 2010, 2012, and 2015) intermittently along this stretch of Pheasant Branch Creek, incorporating a variety of construction methods including sheet pile retaining walls, gabion baskets, toewood and rootwad, and rip rap toe protection. The City cleared, grubbed, graded and seeded the banks as part of these efforts. The flooding event washed away both engineered and non-engineered portions of the streambanks. However, only the areas with engineered stream stabilization will be funded by the FEMA PA grant program. Portions of a recreational trail and its supporting slopes adjacent to the stream were also damaged, as well as six timber and wood pedestrian bridges. Several existing storm sewer inlets and outlets associated with the parks and creek corridor experienced erosion damage.

The Applicant, the City of Middleton, proposes to use contract services to repair the engineered streambanks in-kind to their pre-disaster design, save for the substitution of rip-rap toe protection and fill instead of rootwad and fill in several locations. Some locations along the bank that were damaged in the event will not be repaired but will be allowed to naturalize. All work is intermittent throughout the proposed construction project bounds.

The six timber and wood pedestrian bridges will be replaced and the recreational trail will be repaired and modified. The streambed will be lowered in a few locations to

accommodate the new bridges and trail modifications. Additionally, the stream itself will be shifted in two locations (43.104399, -89.504811 and 43.104008, -89.503381).

The Pheasant Branch and Pheasant Branch Conservancy

Although assessment of the entire Pheasant Branch waterway and Middleton's parks is beyond the scope of this review, an overview of the larger resource will help describe the APE and provide context for the review and recommendations of this consultation. The Friends of Pheasant Branch compiled a booklet (*Friends of Pheasant Branch, Geology, Cultural History and Ecology of the Pheasant Branch Conservancy and Watershed in Middleton, Wisconsin,* 2005) providing an overview of the area; this document provided the basis for the short history below.

The Ho-Chunk Nation occupied the area where the marshes and Pheasant Branch drain into Lake Mendota. Mounds located approximately one and one-half miles north and also approximately one-half mile east of the eastern edge of the proposed undertaking are associated with Native American occupation.

After an 1832 treaty with the Ho-Chunk Nation involving most of Dane County, European settlement began. The area was platted in 1836 and began to be developed. Beginning in the 1850's, portions of the Pheasant Branch creek west of present-day Park Street and the marshes to the west and north were channelized and drained to facilitate a peat harvesting industry and farming. The Pheasant Branch Creek channels now called North Fork and South Fork were created in the settlement period and increased the original creek watershed and stormwater flows considerably.

A village called Pheasant Branch was established in 1853 and was centered around the current Century Avenue Bridge over Pheasant Branch, near the current Branch Street. The village lost its importance in 1856 when the Milwaukee and Mississippi Railroad routed through Peatville, a village located to the southwest. Peatville eventually became Middleton.

After WWII, the area became a residential suburb of Madison and additional roads, utilities and buildings were built. The City of Middletown built nine storm sewers to drain the developed areas; these emptied into Pheasant Branch. A landfill (roughly between GPS Start: 43.10264, -89.50947 to 43.10329, -89.50777) along the southern edge of the creek east of Clark Street School was abandoned and capped after several creek flows and rain events caused erosion and sedimentation flow into Lake Mendota. In 1965, Middleton residents formed the Middleton Conservation Committee to address erosion and sedimentation issues with Pheasant Branch and Lake Mendota. The committee's efforts resulted in the 1970 rerouting of the main creek channel to flow northward into the marsh to reduce sedimentation flow into the lake. The Conservation Committee also spearheaded the purchase of approximately 340 acres of land by the City of to create the Pheasant Branch Conservancy (PBC) in the 1970s and 1980s. Dane County and the Wisconsin DNR also own lands contiguous to the City's parcels that comprise the total 550-acre conservancy.

The section of the Pheasant Branch stream, known as the Mainstem, flows easterly from the Mainstem Pond near Deming Way, under Parmenter Street to Park Street, then from Park to Century Avenue. The area from Parmenter to Park is called Firemen's Park and the area from Park to Century is called Parisi Park.

Firemen's Park is generally bordered by municipal, multi-and single-family residences, and school buildings; the Middleton Police Station, a multi-family complex, several large

residences and the Kromrey Middle School front onto Donna Drive with Firemen's Park and the Pheasant Branch at their rear. Part of Pheasant Branch was relocated to enable the middle school construction. Middleton High School's athletic campus borders Firemen's Park at the south side.

East of Park Street, Parisi Park is generally bordered by one and two-story single-family residences with a cluster of commercial buildings near Century Avenue and Branch Street that back onto the Conservancy property.

A large portion of the stream (approximately 2,800 linear feet beginning 450 feet north of Century Avenue) flows north-northeast from Century Avenue through a wooded area with post-1992 residential neighborhoods to the west, some commercial and multifamily buildings to the south, and at a distance of over one-quarter mile, a residential neighborhood to the east. To the north, the waterway flows into the Pheasant Branch Marsh, where the flow then passes southward again to Lake Mendota.

The streambank was realigned and straightened in 1970. A review of Historic Aerials' historic maps (http://www.historicaerials.com) shows the earlier stream route looping eastward in the late 1800's then looping further northward starting in the early 1900's until the 1970 realignment and straightening. The maps also indicate the current stream route was occasionally identified as an artificial ditch (1975, 1979).

Various other engineering and bank stabilization efforts along the stream banks occurred after this project, including the installation of a stream gage station and a rank of gabion baskets on the west bank immediately north of Century Avenue. The most recent streambank stabilization effort occurred in early 2018 when the Conservancy acted to improve the stream quality and reduce sediment outflow by adding cross vanes, toewood/rootwads, rip rap toes, erosion blankets, fabric, and mats, grading and seeding of banks, and removing log jams. The 2018 project began 100 feet north of Century and continued north for 4,000 linear feet. The disaster event, occurring between August 17 and September 14, 2018, severely damaged the stabilization project.

Construction drawings for the project and maps illustrating the APE are included in this submission. The Area of Potential Effect (APE) is defined as the construction limits as the work is not expected to have visual effects beyond the APE. Areas for equipment staging and access will conform to the existing paved trails adjacent to the stream. The APE is noted on Figure 3.

Steps Taken to Identify Historic Properties and the Description of Historic Properties:

Archaeology

An archaeological literature search and technical memorandum of recommendations was undertaken by an SOI-Qualified archaeologist with SERCO contracted by FEMA (Attachment 4).¹ The literature search and technical memorandum indicates that the APE for the corridor, except for two segments, has been previously surveyed (Figure 32). These two segments were heavily modified during a Pheasant Branch Creek Relocation project (City Project #69-108), which was permitted in 1969 and constructed in 1970. A new channel was excavated to flow in a north-northeast direction. In total, 22,050 cubic yards were excavated, and the new channel banks were covered with 16,078 square

¹ Technical Memorandum Final, Project 88229 Event #4402DR-WI Water Control Facilities PBC Streambank Restoration Archaeological Desktop Assessment, City of Middleton, Dane County, Wisconsin. February 3, 2022.

yards of topsoil and seed. Given the APE, scope of work, and the significant extent and nature of the ground disturbing activities for previous stream relocation, the work within these two segments is not likely to encounter archaeological artifacts or features within their original depositional contexts that yield information important to history or prehistory.

SERCO identified only one archaeological site, 47-DA-0815 as partially within the APE. This site was originally identified in 1936 and partially surveyed in a 2016 archaeological survey conducted for a Phase I Archaeological Literature Review and Reconnaissance Pheasant Branch Stream Restoration, Dane County, Wisconsin by Cardno.² The partial survey encompasses the APE for this undertaking. The portions of the site that overlap the boundaries of the APE were not recommended for further investigations (Figure 33). FEMA notes that the prior archaeological investigations extended partially beyond the current APE although the entire boundaries of the site were not investigated. It is noted that the limestone walking path was the eastern most limit of the archaeological investigation and is not within this undertaking's APE.

Photos taken post-disaster within the boundaries of 47-DA-0815 (Figures 24-29) illustrate that the velocity of water within Pheasant Creek eroded, destabilized and washed out the nature-based solutions, soils, root wads as well as rip rap, geotechnical fabric and gabion baskets that were installed as part of the implemented Pheasant Branch Stream restoration project.

Although an evaluation of eligibility of 47-DA-0185 outside of the boundaries of the APE is beyond the scope of this review, within the APE, given the velocity of water, significant disturbance from prior installation of streambank stabilization, and prior archaeological investigations that extended beyond the banks which did not encounter archaeological artifacts or features, it is unlikely that intact soils with archaeological artifacts or features within their original depositional contexts exist.

The two stream relocations, (43.104399, -89.504811 and 43.104008, -89.503381) were within the CARDNO previous archaeological survey and outside of the recorded DA-47-0185 (Figures 15, 16, 17).

Based on the absence of archaeological features or artifacts within the APE, FEMA has determined that there are no below ground properties eligible for listing on the National Register of Historic Places within the APE for this undertaking.

Standing Structures

The nearest NRHP-listed properties and one NRHP historic district are located over three-quarters of a mile from the APE for this undertaking. The Dr. Newman C. Rowley House and the Middletown Depot are both over one mile southwest of the Century Avenue bridge over Pheasant Branch. The eastern end of the East End Historic District is three-quarters of a mile southwest of the Century Avenue bridge.

The closest surveyed property found in the Wisconsin SHPO database is the 1847 Old Stamm House, surveyed in 1977. The two-story fieldstone gabled ell building was constructed as a store and was used as a hotel, tavern, dance hall, supper club and restaurant. The building is on the south side of Century Avenue, approximately 325 feet

² Vernonica Parsell, Principal Investigator. Cardno, Phase I Archaeological Reconnaissance Pheasant Branch Stream Restoration, City of Middleton, Dane County, Wisconsin. 2016.

from Pheasant Branch; views into and from the Pheasant Branch are limited by heavy vegetation.

The pedestrian bridges crossing Pheasant Branch within the proposed construction project APE are simple utilitarian timber and wood structures supported on earthen embankments and are not of historic age. No other standing structures exist within the APE for this undertaking.

Preliminary Determination of Eligibility:

Based on the information provided above, FEMA has determined that *no resources* within the APE are eligible for listing on the National Register of Historic Places.

Finding:

FEMA finds that this undertaking will result in *no historic properties affected*.

Summary of Views of Consulting Parties or Public:

On March 29, 2022, the following Tribes were provided information regarding this project:

Ho-Chunk Nation

Menominee Indian Tribe of Wisconsin

Miami Tribe of Oklahoma

Osage Nation

Winnebago Tribe of Nebraska

Figures:

Figure 1: Approximate undertaking site marked in blue, not to scale. GoogleEarth image




Figure 2: Approximate undertaking sitemarked in blue, not to scale.

USGS Map "Middleton, WI" and "Madison West, WI," 1:24000, enlarged to show detail.



Figure 3: APE in black. Work locations are in blue and orange (stone toe), red (bank grading), purple (rootwad), pink (boulder clusters) and brown (toewood).

USGS Map "Middleton, WI" and "Madison West, WI," with WISAHRD overlay.




Figure 4: Photo Log. Work locations are in blue and orange (stone toe), red (bank grading), purple (rootwad), pink (boulder clusters) and brown (toewood).

GoogleEarth image.



Figure 5: Photo facing east Project files



Figure 7: Photo facing northeast *Project files*




Figure 6: Facing east *Project files*



Figure 8: Photo facing east *Project files*



loss of soil, rip-rap from upstream

Figure 9: Facing west Project files



Figure 11: Facing north *Project files*



Figure 10: Facing south *Project files*




Figure 12: Facing south *Project files*



Area of scouring and wash away of soil

Figure 13: Facing southeast *Project files*



Figure 15: Facing southeast, stream relocation *Project files*



Figure 14: Facing north *Project files*



Figure 16: Facing south, stream relocation *Project files*



Figure 17 Facing south, stream relocation *Project files*



Figure 19: Facing south *Project files*



Figure 18: Facing southwest *Project files*



Figure 20: Facing southwest *Project files*



Figure 21: Facing southwest *Project files*



Figure 23: Facing north *Project files*




Figure 22: Facing west *Project files*



Figure 24: Facing south, 47-DA-0815, FEMA APE previously surveyed.




Figure 25: Facing south, 47-DR-0185, FEMA APE previously surveyed.

Project files

Figure 26: Facing north, 47-DA-0185, FEMA APE previously surveyed.

Project files



Figure 27: Facing west, 47-DA-0185, FEMA APE previously surveyed.

Project files

Figure 28: Facing southwest, 47-DA-0185, FEMA APE previously surveyed. Project files

Figure 29: Facing north, 47-DA-0185, FEMA APE previously surveyed.




Figure 31: Facing north *Project files*



Figure 30: Facing north *Project files*







Figure 33: CARDNO 47-DA-0185 Archaeology Shovel Tests, APE previously surveyed. Note buffer extending beyond bank grading areas which extend beyond APE. The eastern limit of the site was only investigated up to and not beyond the existing limestone path. *Cardno aerial.*



TECHNICAL MEMORANDUM FINAL

PROJECT # 88229 EVENT #4402DR-WI WATER CONTROL FACILITIES PBC STREAMBANK RESTORATION ARCHAEOLOGICAL DESKTOP ASSESSMENT CITY OF MIDDLETON, DANE COUNTY, WISCONSIN

SENIOR ARCHAEOLOGIST: Varna Boyd, MA, RPA, Principal Investigator

SUBJECT: Archaeological Desktop Assessment

DATE: February 3, 2022

This technical memorandum details the results of an archaeological desktop assessment in support of the Federal Emergency Management Agency's (FEMA) Public Assistance Grant, 4402DR-WI, for Water Control Facilities PBC Streambank Restoration in the City of Middleton, Wisconsin (Figure 1). The streambank restoration project is a result of Disaster #4402DR-WI (a severe storm with heavy rains) that occurred between August 17 and September 14, 2018. The severe storms and rains caused surface water flooding and high-velocity run-off to the Pheasant Branch drainage channel, which resulted in damage to water control facilities and stream embankments along portions of Pheasant Branch Creek.

The archaeological desktop assessment was conducted in anticipation of consultation with the Wisconsin Historical Society (WHS), which serves as the State Historic Preservation Office (SHPO), and Tribal Historic Preservation Officers (THPO) in compliance with Section 106 of the National Historic Preservation Act (NHPA) and the National Environmental Policy Act (NEPA). The assessment was performed by a professional archaeologist who exceeds the Secretary of the Interior's *Professional Qualifications Standards* (48 FR 44716, September 29, 1983) and who has worked in Wisconsin previously. Portions of this assessment contain sensitive archaeological information (i.e., site location data).

ASSESSMENT GOALS AND METHODS

The goals of the assessment were to determine if previously identified archaeological resources were adjacent to or within the Area of Potential Effect (APE), which has been defined as the proposed limits of ground disturbance; determine what areas, if any, had been previously surveyed within the APE; determine the potential for archaeological resources within any previously unsurveyed areas; and make recommendations for further study, as warranted.



Figure 1: Project Location (Source: City of Middleton, WI).

To accomplish these goals, site file and previous survey research was conducted in the WHS's Wisconsin Historic Preservation Database (WHPD) for Township 7, Region 8E (T7R8E), Sections 1, 2, 11, and 12, which was considered the study area. Environmental data (e.g., soils) that could affect the potential for archaeological resources were reviewed for the APE.

Based on the known presence of archaeological sites in the vicinity, the potential for archaeological sites to be present within the project APE was initially considered to be high. However, it was also known that portions of the APE had been previously disturbed (e.g., graded) and that portions had been previously surveyed (see following section). As a result, the assessment also included a comparison of previous survey areas and project plans to determine if there were unsurveyed areas within the APE and if so, evaluate their potential for archaeological resources. Recommendations were made based on the combined data analysis. No archival research or review of architectural resources or properties was included in this archaeological desktop assessment.

ARCHAEOLOGICAL SITE FILE RESEARCH

Numerous surveys have been conducted in the vicinity, including studies by Archaeological Consulting and Services (Figure 2; Salkin 1992, 1993, and 2008), the WHS-Museum Archaeology Program (Figure 2; Hamilton 2010), and Cardno (Figure 3; Settle 2016) within the project APE. Only two small areas in the North of Century section of the APE have not been surveyed (Figure 4).




Figure 2: Surveys Prior to 2016 in the Project Vicinity (Source: Settle 2016:15).

Twenty archaeological sites were identified within the four T7R8E sections comprising the study area (Attachment 1). The majority (n=15) are precontact (i.e., Native American) mounds, campsites/villages, lithic workshops (i.e., stone tool manufacture), or lithic scatters (i.e., byproducts of stone tool production). There were also three multicomponent sites, including two precontact and historic Native American sites and one precontact and historic site. Two historic cemeteries, St. Luke's Cemetery and St. Bernard's Cemetery, are also present within the study area.
One site, 47-DA-0989 (Pheasant Branch Nature Preserve #1), has been determined not eligible for the NRHP; the remaining sites have not been evaluated for eligibility to the NRHP based on the WHPD site files.
The only site identified within the project APE was 47-DA-0815 (Site B), The site was originally identified in 1936 by Charles Brown of the WHS.
An archaeological survey of the western third of the site near Pheasant Branch was conducted by Cardno as part of a City of Middleton stream restoration project (Figure 3; Settle 2016). Ten shovel tests were excavated in that study, but none contained artifacts or cultural features. Portions of the east Pheasant Branch streambank and the entire west bank were not tested due to 15 percent or greater slopes (Settle 2016). Ground disturbance related to a limestone walking path was also noted in the eastern portion of Pheasant Branch within the Cardno project area (Settle 2016). Cardno recommended no further archaeological studies in what is now part of the current project APE (Settle 2016). FEMA will provide this technical memorandum as part of the SHPO consultation for this FEMA undertaking.

Two cemeteries are located within the study area. St. Luke's Cemetery is approximately 0.5 miles north and west of the project APE at 7515 Century Place in Middleton. St. Luke's Cemetery dates from approximately 1851 to the present. St. Bernard's Cemetery is approximately 0.4 miles south and southeast of the project APE at 1925 Branch Street in Middleton. It dates from 1897 to the present, but most headstones are from the 1960s to the present.

As the Sauk Mound, Heim Mound, the Murphy site, and the two cemeteries all have human burials, they are protected under the 1985 Wisconsin Act 316 (Wis. Stats. 157.70). While not expected as part of the current project, any effects to these sites require consultation with the WHS.

RESULTS AND RECOMMENDATIONS

The archaeological desktop assessment resulted in the identification of numerous prior surveys in the project APE as well as 20 archaeological sites within the study area. The proposed APE has been previously surveyed except for two small areas in the North of Century portion of the project. According to the City of Middleton, these two areas were part of the Pheasant Branch Creek Relocation project (City Project #69-108), which was permitted in 1969 and constructed in 1970 (personal communication between Mr. Roger Ammons, FEMA Program Delivery Manager, and Shawn Stauske, City of Middleton's Director of Public Works June 9, 2020). A new channel was excavated to flow in a north-northeast direction. In total, 22,050 cubic yards were excavated, and the new channel banks were covered with 16,078 square yards of topsoil and seed. These activities have significantly disturbed the unsurveyed areas of the APE. As a result, no further archaeological survey is recommended within these two areas.

Only one of the 20 archaeological sites, 47-DA-0815 (Site B), is present within the project APE. Prior survey by Cardno was conducted in the portions of the site that overlap the project APE and no artifacts or cultural features were identified. As a result, it is unlikely that further survey would identify other cultural resources. As a result, no further work is recommended within the portion of the site within the proposed APE. However, if plans change and the APE is expanded, additional analysis should be conducted to ensure no unsurveyed areas of the site will be impacted by the proposed project.

Due to the location of the project APE, no effects are anticipated for any of the other archaeological sites or cemeteries, including the Sauk Mound, Heim Mound, and the Murphy site. As a result of the desktop archaeological assessment, it is anticipated that the proposed project will have no effect to known archaeological resources.

REFERENCES CITED

Hamilton, Kelley

2010 CTH Q (Allen Boulevard) Archaeological Monitor, Dane County. Prepared by the Wisconsin Historical Society-Museum Archaeology Program.

Salkin, Philip H.

- 1992 An Archaeological Survey of the Proposed Pheasant Branch Interceptor Tributary Route in Middleton, Wisconsin. Prepared by Archaeological Consulting and Services.
- 1993 A Program of Archaeological testing at Two Sites (47DA987 and 47DA989) in Middleton, Dane County, Wisconsin. Prepared by Archaeological Consulting and Services.
- 2008 WDOT Archaeological Survey Field Report: Pheasant Branch Creek Trail in Dane County, Wisconsin. Prepared by Archaeological Consulting and Services.

Settle, Kathleen

2016 Phase I Archaeological Literature Review and Reconnaissance Pheasant Branch Stream Restoration, Dane County, Wisconsin. Prepared by Cardno.

ATTACHMENT 1

Attachment 1: Archaeological Sites within T7R8E Sections 1, 2, 11, and 12.

T7R8E Section Number	Site Number and Name	Site Type	Within APE	WHS Project Number	Recommendation	Notes
1	47-DA-0815, Site B		Yes	16-0992	Consultation with SHPO, but no anticipated effect	The site overlaps Pheasant Branch and the APE. A Cardno survey (Settle 2016) in the western third of the site found no artifacts or other cultural resources. The current status of the site is unknown, and the site inventory notes a request for consultation.
1	47-DA-0209, Baskerville Campsite	Precontact Campsite/Village/Workshop	No	N/A	No effect	
1	47-DA-0989, Pheasant Branch Nature Preserve #1	Precontact Campsite/Village	No	92-0421	No effect	Not eligible.
1	47-DA-1249, Middleton Hills	Precontact (Late Paleoindian – Late Woodland) Campsite/Village	No	N/A	No effect	
2	St. Luke's Cemetery	Historic Cemetery	No	N/A	No effect	
2	47-DA-0737, Freeman	Precontact (Middle Archaic and Early Woodland) Lithic Scatter and Historic Periods	No	10-0283 and 89- 0646	No effect	
2	47-DA-0966, S. Ziegler III	Precontact Workshop	No	89-0646	No effect	

T7R8E Section Number	Site Number and Name	Site Type	Within APE	WHS Project Number	Recommendation	Notes
2	47-DA-1422, Murphy Site II	Precontact (Middle and Late Archaic, Late Woodland) Campsite/Village/Burial	No	10-0283	No effect	
11	47-DA-0441, Woodside Heights Park	Precontact (Archaic) Campsite/Village	No	78-1104	No effect	
11	47-DA-0447, Park Shores	Precontact (Late Paleoindian and Archaic) Campsite/Village	No	78-1104	No effect	Most of site was destroyed by development, but a wooded area may still have intact deposits.
12	St. Bernard's Cemetery	Historic Cemetery	No	N/A	No effect	Any work in the park requires monitoring by an archaeologist.
12	47-DA-0381, Miller	Precontact and Historic Native American Campsite/Village	No	N/A	No effect	
12	47-DA-0389, Pheasant Branch	Precontact and Historic Native American Campsite/Village	No	11-9007, 10-7712	No effect	Portions of the site have been heavily disturbed. Site boundaries were amended in 2010.
12	47-DA-0423, Lemcke	Precontact (Late Archaic) Campsite/Village	No	N/A	No effect	
12	47-DA-0433, Sauk Trail School	Precontact (Late Woodland) Isolated Finds	No	11-9012	No effect	
12	47-DA-0495, Iltis Beach	Precontact (Late Woodland) Campsite/Village/Workshop	No	N/A	No effect	
12	47-DA-0816, Heim Farm	Precontact (Late Paleoindian, Late Archaic – Middle Woodland) Campsite/Village	No	11-9012	No effect	
Total Sites	20		1			

60 to 90% complete plans were provided as part of this consultation.

See Appendix A for the most recent project plans.



Miami Tribe of Oklahoma

3410 P St. NW, Miami, OK 74354 ◆ P.O. Box 1326, Miami, OK 74355 Ph: (918) 541-1300 ◆ Fax: (918) 542-7260 www.miamination.com



Via email: fema-r5-environmental@fema.dhs.gov

April 1, 2022

Duane D. Castaldi Regional Environmental Officer U.S. Department of Homeland Security FEMA Region V 536 South Clark Street, 6th Floor Chicago, IL 60605

Re: Project #88229; PW 593, Pheasant Branch Creek Stabilization, Dane County, Wisconsin – Comments of the Miami Tribe of Oklahoma

Dear Mr. Castaldi:

Aya, kikwehsitoole – I show you respect. The Miami Tribe of Oklahoma, a federally recognized Indian tribe with a Constitution ratified in 1939 under the Oklahoma Indian Welfare Act of 1936, respectfully submits the following comments regarding Project #88229; PW 593, Pheasant Branch Creek Stabilization in Dane County, Wisconsin.

The Miami Tribe offers no objection to the above-referenced project at this time, as we are not currently aware of existing documentation directly linking a specific Miami cultural or historic site to the project site. However, given the Miami Tribe's deep and enduring relationship to its historic lands and cultural property within present-day Wisconsin, if any human remains or Native American cultural items falling under the Native American Graves Protection and Repatriation Act (NAGPRA) or archaeological evidence is discovered during any phase of this project, the Miami Tribe requests immediate consultation with the entity of jurisdiction for the location of discovery. In such a case, please contact me at 918-541-8966 or by email at dhunter@miamination.com to initiate consultation.

The Miami Tribe accepts the invitation to serve as a consulting party to the proposed project. In my capacity as Tribal Historic Preservation Officer I am the point of contact for consultation.

Respectfully,

Diane Hunter

Diane Hunter

Tribal Historic Preservation Officer



March 29, 2022

Andrea Hunter, Director & Tribal Historic Preservation Officer Osage Nation 627 Grandview Avenue Pawhuska, Oklahoma 74056

Re: Pheasant Branch Creek Stabilization Middleton, Dane County, Wisconsin FEMA Project #88229; PW 593 43.103301, -89.513886 to 43.109433, -89.491877 S1, 2, 11, and 12 T7N R8E

Dear Dr. Hunter:

Pursuant to the Section 106 of the National Historic Preservation Act, I am writing this letter to initiate and conclude consultation regarding the captioned Public Assistance Grant Program project. In accord with 36 CFR §800.11, I am enclosing documentation regarding this undertaking and its effect on historic properties, which is being sent concurrently to the Wisconsin State Historic Preservation Office for their review. This documentation provides the justification for FEMA's finding of no historic properties affected.

FEMA is providing these materials to the following federally recognized Indian tribes (Tribes) thought to have interests in the area:

- Ho-Chunk Nation
- Menominee Indian Tribe of Wisconsin
- Miami Tribe of Oklahoma

Osage Nation

Castole

Winnebago Tribe of Nebraska

In accord with 36 CFR 800.2(c)(2)(ii), FEMA is providing this opportunity for the Osage Nation to join the consultation by identifying concerns and providing comments about historic properties that may be affected by this undertaking. FEMA would also appreciate notice of Tribes other than those listed above that may have an interest in this undertaking.

SWe would appreciate a response from your office within 30 days. If you have questions, do not hesitate to contact me at 312-408-5549 or at fema-r5-environmental@fema.dhs.gov. If we do not receive a response within 30 days, FEMA will move forward with this undertaking without comment from the Osage Nation.

Sincerely,

Duane Castaldi

Regional Environmental Officer

FEMA Region 5



March 29, 2022

Documentation Initiating and Concluding Section 106 Consultation for a FEMA-Funded Undertaking

Project Information:

Project ID: #88229; PW 593

Title: Pheasant Branch Creek Stabilization

Address: Pheasant Branch Creek from crossing at Deming Way, eastward to

Century Avenue, then northward, parallel to Conservancy Lane

Location: Middleton, Dane County, WI

GPS: 43.102620, -89.51821 to 43.10945, -89.49057

PLSS: S1, 2, 11, and 12 T7N R8E

Description of Undertaking and APE:

As a result of severe storms, tornadoes, straight-line winds, flooding, and landslides affecting areas of the State of Wisconsin, President Trump signed the 4402-DR-WI Disaster Declaration on October 18, 2018. Under this declaration, Dane County, among others, was made eligible for FEMA's Public Assistance (PA) Program funding. The disaster event resulted in damage to infrastructure along the Pheasant Branch Creek Corridor from crossing at Deming Way and continuing eastward to north of Century Avenue in Middleton, Wisconsin (43.10262, -89.51821 to 43.10945, -89.49057).

The City of Middleton performed streambed relocation and streambank stabilization projects (most recently in 2007, 2008, 2009, 2010, 2012, and 2015) intermittently along this stretch of Pheasant Branch Creek, incorporating a variety of construction methods including sheet pile retaining walls, gabion baskets, toewood and rootwad, and rip rap toe protection. The City cleared, grubbed, graded and seeded the banks as part of these efforts. The flooding event washed away both engineered and non-engineered portions of the streambanks. However, only the areas with engineered stream stabilization will be funded by the FEMA PA grant program. Portions of a recreational trail and its supporting slopes adjacent to the stream were also damaged, as well as six timber and wood pedestrian bridges. Several existing storm sewer inlets and outlets associated with the parks and creek corridor experienced erosion damage.

The Applicant, the City of Middleton, proposes to use contract services to repair the engineered streambanks in-kind to their pre-disaster design, save for the substitution of rip-rap toe protection and fill instead of rootwad and fill in several locations. Some locations along the bank that were damaged in the event will not be repaired but will be allowed to naturalize. All work is intermittent throughout the proposed construction project bounds.

The six timber and wood pedestrian bridges will be replaced and the recreational trail will be repaired and modified. The streambed will be lowered in a few locations to

accommodate the new bridges and trail modifications. Additionally, the stream itself will be shifted in two locations (43.104399, -89.504811 and 43.104008, -89.503381).

The Pheasant Branch and Pheasant Branch Conservancy

Although assessment of the entire Pheasant Branch waterway and Middleton's parks is beyond the scope of this review, an overview of the larger resource will help describe the APE and provide context for the review and recommendations of this consultation. The Friends of Pheasant Branch compiled a booklet (*Friends of Pheasant Branch, Geology, Cultural History and Ecology of the Pheasant Branch Conservancy and Watershed in Middleton, Wisconsin,* 2005) providing an overview of the area; this document provided the basis for the short history below.

The Ho-Chunk Nation occupied the area where the marshes and Pheasant Branch drain into Lake Mendota. Mounds located approximately one and one-half miles north and also approximately one-half mile east of the eastern edge of the proposed undertaking are associated with Native American occupation.

After an 1832 treaty with the Ho-Chunk Nation involving most of Dane County, European settlement began. The area was platted in 1836 and began to be developed. Beginning in the 1850's, portions of the Pheasant Branch creek west of present-day Park Street and the marshes to the west and north were channelized and drained to facilitate a peat harvesting industry and farming. The Pheasant Branch Creek channels now called North Fork and South Fork were created in the settlement period and increased the original creek watershed and stormwater flows considerably.

A village called Pheasant Branch was established in 1853 and was centered around the current Century Avenue Bridge over Pheasant Branch, near the current Branch Street. The village lost its importance in 1856 when the Milwaukee and Mississippi Railroad routed through Peatville, a village located to the southwest. Peatville eventually became Middleton.

After WWII, the area became a residential suburb of Madison and additional roads, utilities and buildings were built. The City of Middletown built nine storm sewers to drain the developed areas; these emptied into Pheasant Branch. A landfill (roughly between GPS Start: 43.10264, -89.50947 to 43.10329, -89.50777) along the southern edge of the creek east of Clark Street School was abandoned and capped after several creek flows and rain events caused erosion and sedimentation flow into Lake Mendota. In 1965, Middleton residents formed the Middleton Conservation Committee to address erosion and sedimentation issues with Pheasant Branch and Lake Mendota. The committee's efforts resulted in the 1970 rerouting of the main creek channel to flow northward into the marsh to reduce sedimentation flow into the lake. The Conservation Committee also spearheaded the purchase of approximately 340 acres of land by the City of to create the Pheasant Branch Conservancy (PBC) in the 1970s and 1980s. Dane County and the Wisconsin DNR also own lands contiguous to the City's parcels that comprise the total 550-acre conservancy.

The section of the Pheasant Branch stream, known as the Mainstem, flows easterly from the Mainstem Pond near Deming Way, under Parmenter Street to Park Street, then from Park to Century Avenue. The area from Parmenter to Park is called Firemen's Park and the area from Park to Century is called Parisi Park.

Firemen's Park is generally bordered by municipal, multi-and single-family residences, and school buildings; the Middleton Police Station, a multi-family complex, several large

residences and the Kromrey Middle School front onto Donna Drive with Firemen's Park and the Pheasant Branch at their rear. Part of Pheasant Branch was relocated to enable the middle school construction. Middleton High School's athletic campus borders Firemen's Park at the south side.

East of Park Street, Parisi Park is generally bordered by one and two-story single-family residences with a cluster of commercial buildings near Century Avenue and Branch Street that back onto the Conservancy property.

A large portion of the stream (approximately 2,800 linear feet beginning 450 feet north of Century Avenue) flows north-northeast from Century Avenue through a wooded area with post-1992 residential neighborhoods to the west, some commercial and multifamily buildings to the south, and at a distance of over one-quarter mile, a residential neighborhood to the east. To the north, the waterway flows into the Pheasant Branch Marsh, where the flow then passes southward again to Lake Mendota.

The streambank was realigned and straightened in 1970. A review of Historic Aerials' historic maps (http://www.historicaerials.com) shows the earlier stream route looping eastward in the late 1800's then looping further northward starting in the early 1900's until the 1970 realignment and straightening. The maps also indicate the current stream route was occasionally identified as an artificial ditch (1975, 1979).

Various other engineering and bank stabilization efforts along the stream banks occurred after this project, including the installation of a stream gage station and a rank of gabion baskets on the west bank immediately north of Century Avenue. The most recent streambank stabilization effort occurred in early 2018 when the Conservancy acted to improve the stream quality and reduce sediment outflow by adding cross vanes, toewood/rootwads, rip rap toes, erosion blankets, fabric, and mats, grading and seeding of banks, and removing log jams. The 2018 project began 100 feet north of Century and continued north for 4,000 linear feet. The disaster event, occurring between August 17 and September 14, 2018, severely damaged the stabilization project.

Construction drawings for the project and maps illustrating the APE are included in this submission. The Area of Potential Effect (APE) is defined as the construction limits as the work is not expected to have visual effects beyond the APE. Areas for equipment staging and access will conform to the existing paved trails adjacent to the stream. The APE is noted on Figure 3.

Steps Taken to Identify Historic Properties and the Description of Historic Properties:

Archaeology

An archaeological literature search and technical memorandum of recommendations was undertaken by an SOI-Qualified archaeologist with SERCO contracted by FEMA (Attachment 4).¹ The literature search and technical memorandum indicates that the APE for the corridor, except for two segments, has been previously surveyed (Figure 32). These two segments were heavily modified during a Pheasant Branch Creek Relocation project (City Project #69-108), which was permitted in 1969 and constructed in 1970. A new channel was excavated to flow in a north-northeast direction. In total, 22,050 cubic yards were excavated, and the new channel banks were covered with 16,078 square

¹ Technical Memorandum Final, Project 88229 Event #4402DR-WI Water Control Facilities PBC Streambank Restoration Archaeological Desktop Assessment, City of Middleton, Dane County, Wisconsin. February 3, 2022.

yards of topsoil and seed. Given the APE, scope of work, and the significant extent and nature of the ground disturbing activities for previous stream relocation, the work within these two segments is not likely to encounter archaeological artifacts or features within their original depositional contexts that yield information important to history or prehistory.

SERCO identified only one archaeological site, 47-DA-0815 as partially within the APE. This site was originally identified in 1936 and partially surveyed in a 2016 archaeological survey conducted for a Phase I Archaeological Literature Review and Reconnaissance Pheasant Branch Stream Restoration, Dane County, Wisconsin by Cardno.² The partial survey encompasses the APE for this undertaking. The portions of the site that overlap the boundaries of the APE were not recommended for further investigations (Figure 33). FEMA notes that the prior archaeological investigations extended partially beyond the current APE although the entire boundaries of the site were not investigated. It is noted that the limestone walking path was the eastern most limit of the archaeological investigation and is not within this undertaking's APE.

Photos taken post-disaster within the boundaries of 47-DA-0815 (Figures 24-29) illustrate that the velocity of water within Pheasant Creek eroded, destabilized and washed out the nature-based solutions, soils, root wads as well as rip rap, geotechnical fabric and gabion baskets that were installed as part of the implemented Pheasant Branch Stream restoration project.

Although an evaluation of eligibility of 47-DA-0185 outside of the boundaries of the APE is beyond the scope of this review, within the APE, given the velocity of water, significant disturbance from prior installation of streambank stabilization, and prior archaeological investigations that extended beyond the banks which did not encounter archaeological artifacts or features, it is unlikely that intact soils with archaeological artifacts or features within their original depositional contexts exist.

The two stream relocations, (43.104399, -89.504811 and 43.104008, -89.503381) were within the CARDNO previous archaeological survey and outside of the recorded DA-47-0185 (Figures 15, 16, 17).

Based on the absence of archaeological features or artifacts within the APE, FEMA has determined that there are no below ground properties eligible for listing on the National Register of Historic Places within the APE for this undertaking.

Standing Structures

The nearest NRHP-listed properties and one NRHP historic district are located over three-quarters of a mile from the APE for this undertaking. The Dr. Newman C. Rowley House and the Middletown Depot are both over one mile southwest of the Century Avenue bridge over Pheasant Branch. The eastern end of the East End Historic District is three-quarters of a mile southwest of the Century Avenue bridge.

The closest surveyed property found in the Wisconsin SHPO database is the 1847 Old Stamm House, surveyed in 1977. The two-story fieldstone gabled ell building was constructed as a store and was used as a hotel, tavern, dance hall, supper club and restaurant. The building is on the south side of Century Avenue, approximately 325 feet

² Vernonica Parsell, Principal Investigator. Cardno, Phase I Archaeological Reconnaissance Pheasant Branch Stream Restoration, City of Middleton, Dane County, Wisconsin. 2016.

from Pheasant Branch; views into and from the Pheasant Branch are limited by heavy vegetation.

The pedestrian bridges crossing Pheasant Branch within the proposed construction project APE are simple utilitarian timber and wood structures supported on earthen embankments and are not of historic age. No other standing structures exist within the APE for this undertaking.

Preliminary Determination of Eligibility:

Based on the information provided above, FEMA has determined that *no resources* within the APE are eligible for listing on the National Register of Historic Places.

Finding:

FEMA finds that this undertaking will result in *no historic properties affected*.

Summary of Views of Consulting Parties or Public:

On March 29, 2022, the following Tribes were provided information regarding this project:

Ho-Chunk Nation

Menominee Indian Tribe of Wisconsin

Miami Tribe of Oklahoma

Osage Nation

Winnebago Tribe of Nebraska

Figures:

Figure 1: Approximate undertaking site marked in blue, not to scale. GoogleEarth image




Figure 2: Approximate undertaking sitemarked in blue, not to scale.

USGS Map "Middleton, WI" and "Madison West, WI," 1:24000, enlarged to show detail.



Figure 3: APE in black. Work locations are in blue and orange (stone toe), red (bank grading), purple (rootwad), pink (boulder clusters) and brown (toewood).

USGS Map "Middleton, WI" and "Madison West, WI," with WISAHRD overlay.




Figure 4: Photo Log. Work locations are in blue and orange (stone toe), red (bank grading), purple (rootwad), pink (boulder clusters) and brown (toewood).

GoogleEarth image.



Figure 5: Photo facing east Project files



Figure 7: Photo facing northeast *Project files*




Figure 6: Facing east *Project files*



Figure 8: Photo facing east *Project files*



loss of soil, rip-rap from upstream

Figure 9: Facing west *Project files*



Figure 11: Facing north *Project files*



Figure 10: Facing south *Project files*




Figure 12: Facing south *Project files*



Area of scouring and wash away of soil

Figure 13: Facing southeast *Project files*



Figure 15: Facing southeast, stream relocation *Project files*



Figure 14: Facing north *Project files*



Figure 16: Facing south, stream relocation *Project files*



Figure 17 Facing south, stream relocation *Project files*



Figure 19: Facing south *Project files*



Figure 18: Facing southwest *Project files*



Figure 20: Facing southwest *Project files*



Figure 21: Facing southwest *Project files*



Figure 23: Facing north *Project files*




Figure 22: Facing west *Project files*



Figure 24: Facing south, 47-DA-0815, FEMA APE previously surveyed.




Figure 25: Facing south, 47-DR-0185, FEMA APE previously surveyed.

Project files

Figure 26: Facing north, 47-DA-0185, FEMA APE previously surveyed.

Project files



Figure 27: Facing west, 47-DA-0185, FEMA APE previously surveyed.

*Project files**

Figure 28: Facing southwest, 47-DA-0185, FEMA APE previously surveyed. Project files

Figure 29: Facing north, 47-DA-0185, FEMA APE previously surveyed.




Figure 31: Facing north *Project files*



Figure 30: Facing north *Project files*







Figure 33: CARDNO 47-DA-0185 Archaeology Shovel Tests, APE previously surveyed. Note buffer extending beyond bank grading areas which extend beyond APE. The eastern limit of the site was only investigated up to and not beyond the existing limestone path. *Cardno aerial.*



TECHNICAL MEMORANDUM FINAL

PROJECT # 88229 EVENT #4402DR-WI WATER CONTROL FACILITIES PBC STREAMBANK RESTORATION ARCHAEOLOGICAL DESKTOP ASSESSMENT CITY OF MIDDLETON, DANE COUNTY, WISCONSIN

SENIOR ARCHAEOLOGIST: Varna Boyd, MA, RPA, Principal Investigator

SUBJECT: Archaeological Desktop Assessment

DATE: February 3, 2022

This technical memorandum details the results of an archaeological desktop assessment in support of the Federal Emergency Management Agency's (FEMA) Public Assistance Grant, 4402DR-WI, for Water Control Facilities PBC Streambank Restoration in the City of Middleton, Wisconsin (Figure 1). The streambank restoration project is a result of Disaster #4402DR-WI (a severe storm with heavy rains) that occurred between August 17 and September 14, 2018. The severe storms and rains caused surface water flooding and high-velocity run-off to the Pheasant Branch drainage channel, which resulted in damage to water control facilities and stream embankments along portions of Pheasant Branch Creek.

The archaeological desktop assessment was conducted in anticipation of consultation with the Wisconsin Historical Society (WHS), which serves as the State Historic Preservation Office (SHPO), and Tribal Historic Preservation Officers (THPO) in compliance with Section 106 of the National Historic Preservation Act (NHPA) and the National Environmental Policy Act (NEPA). The assessment was performed by a professional archaeologist who exceeds the Secretary of the Interior's *Professional Qualifications Standards* (48 FR 44716, September 29, 1983) and who has worked in Wisconsin previously. Portions of this assessment contain sensitive archaeological information (i.e., site location data).

ASSESSMENT GOALS AND METHODS

The goals of the assessment were to determine if previously identified archaeological resources were adjacent to or within the Area of Potential Effect (APE), which has been defined as the proposed limits of ground disturbance; determine what areas, if any, had been previously surveyed within the APE; determine the potential for archaeological resources within any previously unsurveyed areas; and make recommendations for further study, as warranted.



Figure 1: Project Location (Source: City of Middleton, WI).

To accomplish these goals, site file and previous survey research was conducted in the WHS's Wisconsin Historic Preservation Database (WHPD) for Township 7, Region 8E (T7R8E), Sections 1, 2, 11, and 12, which was considered the study area. Environmental data (e.g., soils) that could affect the potential for archaeological resources were reviewed for the APE.

Based on the known presence of archaeological sites in the vicinity, the potential for archaeological sites to be present within the project APE was initially considered to be high. However, it was also known that portions of the APE had been previously disturbed (e.g., graded) and that portions had been previously surveyed (see following section). As a result, the assessment also included a comparison of previous survey areas and project plans to determine if there were unsurveyed areas within the APE and if so, evaluate their potential for archaeological resources. Recommendations were made based on the combined data analysis. No archival research or review of architectural resources or properties was included in this archaeological desktop assessment.

ARCHAEOLOGICAL SITE FILE RESEARCH

Numerous surveys have been conducted in the vicinity, including studies by Archaeological Consulting and Services (Figure 2; Salkin 1992, 1993, and 2008), the WHS-Museum Archaeology Program (Figure 2; Hamilton 2010), and Cardno (Figure 3; Settle 2016) within the project APE. Only two small areas in the North of Century section of the APE have not been surveyed (Figure 4).




Figure 2: Surveys Prior to 2016 in the Project Vicinity (Source: Settle 2016:15).

Twenty archaeological sites were identified within the four T7R8E sections comprising the study area (Attachment 1). The majority (n=15) are precontact (i.e., Native American) mounds, campsites/villages, lithic workshops (i.e., stone tool manufacture), or lithic scatters (i.e., byproducts of stone tool production). There were also three multicomponent sites, including two precontact and historic Native American sites and one precontact and historic site. Two historic cemeteries, St. Luke's Cemetery and St. Bernard's Cemetery, are also present within the study area.
One site, 47-DA-0989 (Pheasant Branch Nature Preserve #1), has been determined not eligible for the NRHP; the remaining sites have not been evaluated for eligibility to the NRHP based on the WHPD site files.
The only site identified within the project APE was 47-DA-0815 (Site B), The site was originally identified in 1936 by Charles Brown of the WHS.
An archaeological survey of the western third of the site near Pheasant Branch was conducted by Cardno as part of a City of Middleton stream restoration project (Figure 3; Settle 2016). Ten shovel tests were excavated in that study, but none contained artifacts or cultural features. Portions of the east Pheasant Branch streambank and the entire west bank were not tested due to 15 percent or greater slopes (Settle 2016). Ground disturbance related to a limestone walking path was also noted in the eastern portion of Pheasant Branch within the Cardno project area (Settle 2016). Cardno recommended no further archaeological studies in what is now part of the current project APE (Settle 2016). FEMA will provide this technical memorandum as part of the SHPO consultation for this FEMA undertaking.

Two cemeteries are located within the study area. St. Luke's Cemetery is approximately 0.5 miles north and west of the project APE at 7515 Century Place in Middleton. St. Luke's Cemetery dates from approximately 1851 to the present. St. Bernard's Cemetery is approximately 0.4 miles south and southeast of the project APE at 1925 Branch Street in Middleton. It dates from 1897 to the present, but most headstones are from the 1960s to the present.

As the Sauk Mound, Heim Mound, the Murphy site, and the two cemeteries all have human burials, they are protected under the 1985 Wisconsin Act 316 (Wis. Stats. 157.70). While not expected as part of the current project, any effects to these sites require consultation with the WHS.

RESULTS AND RECOMMENDATIONS

The archaeological desktop assessment resulted in the identification of numerous prior surveys in the project APE as well as 20 archaeological sites within the study area. The proposed APE has been previously surveyed except for two small areas in the North of Century portion of the project. According to the City of Middleton, these two areas were part of the Pheasant Branch Creek Relocation project (City Project #69-108), which was permitted in 1969 and constructed in 1970 (personal communication between Mr. Roger Ammons, FEMA Program Delivery Manager, and Shawn Stauske, City of Middleton's Director of Public Works June 9, 2020). A new channel was excavated to flow in a north-northeast direction. In total, 22,050 cubic yards were excavated, and the new channel banks were covered with 16,078 square yards of topsoil and seed. These activities have significantly disturbed the unsurveyed areas of the APE. As a result, no further archaeological survey is recommended within these two areas.

Only one of the 20 archaeological sites, 47-DA-0815 (Site B), is present within the project APE. Prior survey by Cardno was conducted in the portions of the site that overlap the project APE and no artifacts or cultural features were identified. As a result, it is unlikely that further survey would identify other cultural resources. As a result, no further work is recommended within the portion of the site within the proposed APE. However, if plans change and the APE is expanded, additional analysis should be conducted to ensure no unsurveyed areas of the site will be impacted by the proposed project.

Due to the location of the project APE, no effects are anticipated for any of the other archaeological sites or cemeteries, including the Sauk Mound, Heim Mound, and the Murphy site. As a result of the desktop archaeological assessment, it is anticipated that the proposed project will have no effect to known archaeological resources.

REFERENCES CITED

Hamilton, Kelley

2010 CTH Q (Allen Boulevard) Archaeological Monitor, Dane County. Prepared by the Wisconsin Historical Society-Museum Archaeology Program.

Salkin, Philip H.

- 1992 An Archaeological Survey of the Proposed Pheasant Branch Interceptor Tributary Route in Middleton, Wisconsin. Prepared by Archaeological Consulting and Services.
- 1993 A Program of Archaeological testing at Two Sites (47DA987 and 47DA989) in Middleton, Dane County, Wisconsin. Prepared by Archaeological Consulting and Services.
- 2008 WDOT Archaeological Survey Field Report: Pheasant Branch Creek Trail in Dane County, Wisconsin. Prepared by Archaeological Consulting and Services.

Settle, Kathleen

2016 Phase I Archaeological Literature Review and Reconnaissance Pheasant Branch Stream Restoration, Dane County, Wisconsin. Prepared by Cardno.

ATTACHMENT 1

Attachment 1: Archaeological Sites within T7R8E Sections 1, 2, 11, and 12.

T7R8E Section Number	Site Number and Name	Site Type	Within APE	WHS Project Number	Recommendation	Notes
1	47-DA-0815, Site B		Yes	16-0992	Consultation with SHPO, but no anticipated effect	The site overlaps Pheasant Branch and the APE. A Cardno survey (Settle 2016) in the western third of the site found no artifacts or other cultural resources. The current status of the site is unknown, and the site inventory notes a request for consultation.
1	47-DA-0209, Baskerville Campsite	Precontact Campsite/Village/Workshop	No	N/A	No effect	
1	47-DA-0989, Pheasant Branch Nature Preserve #1	Precontact Campsite/Village	No	92-0421	No effect	Not eligible.
1	47-DA-1249, Middleton Hills	Precontact (Late Paleoindian – Late Woodland) Campsite/Village	No	N/A	No effect	
2	St. Luke's Cemetery	Historic Cemetery	No	N/A	No effect	
2	47-DA-0737, Freeman	Precontact (Middle Archaic and Early Woodland) Lithic Scatter and Historic Periods	No	10-0283 and 89- 0646	No effect	
2	47-DA-0966, S. Ziegler III	Precontact Workshop	No	89-0646	No effect	

T7R8E Section Number	Site Number and Name	Site Type	Within APE	WHS Project Number	Recommendation	Notes
2	47-DA-1422, Murphy Site II	Precontact (Middle and Late Archaic, Late Woodland) Campsite/Village/Burial	No	10-0283	No effect	
11	47-DA-0441, Woodside Heights Park	Precontact (Archaic) Campsite/Village	No	78-1104	No effect	
11	47-DA-0447, Park Shores	Precontact (Late Paleoindian and Archaic) Campsite/Village	No	78-1104	No effect	Most of site was destroyed by development, but a wooded area may still have intact deposits.
12	St. Bernard's Cemetery	Historic Cemetery	No	N/A	No effect	Any work in the park requires monitoring by an archaeologist.
12	47-DA-0381, Miller	Precontact and Historic Native American Campsite/Village	No	N/A	No effect	
12	47-DA-0389, Pheasant Branch	Precontact and Historic Native American Campsite/Village	No	11-9007, 10-7712	No effect	Portions of the site have been heavily disturbed. Site boundaries were amended in 2010.
12	47-DA-0423, Lemcke	Precontact (Late Archaic) Campsite/Village	No	N/A	No effect	
12	47-DA-0433, Sauk Trail School	Precontact (Late Woodland) Isolated Finds	No	11-9012	No effect	
12	47-DA-0495, Iltis Beach	Precontact (Late Woodland) Campsite/Village/Workshop	No	N/A	No effect	
12	47-DA-0816, Heim Farm	Precontact (Late Paleoindian, Late Archaic — Middle Woodland) Campsite/Village	No	11-9012	No effect	
Total Sites	20		1			

60 to 90% complete plans were provided as part of this consultation.

See Appendix A for the most recent project plans.



March 29, 2022

Sunshine Thomas-Bear, Tribal Historic Preservation Officer Winnebago Tribe of Nebraska 415 East Little Priest Dr Winnebago, Nebraska 68071

Re: Pheasant Branch Creek Stabilization Middleton, Dane County, Wisconsin FEMA Project #88229; PW 593 43.103301, -89.513886 to 43.109433, -89.491877 S1, 2, 11, and 12 T7N R8E

Dear Ms. Thomas-Bear

Pursuant to the Section 106 of the National Historic Preservation Act, I am writing this letter to initiate and conclude consultation regarding the captioned Public Assistance Grant Program project. In accord with 36 CFR §800.11, I am enclosing documentation regarding this undertaking and its effect on historic properties, which is being sent concurrently to the Wisconsin State Historic Preservation Office for their review. This documentation provides the justification for FEMA's finding of no historic properties affected.

FEMA is providing these materials to the following federally recognized Indian tribes (Tribes) thought to have interests in the area:

- Ho-Chunk Nation
- Menominee Indian Tribe of Wisconsin
- Miami Tribe of Oklahoma

Osage Nation

Castole

Winnebago Tribe of Nebraska

In accord with 36 CFR 800.2(c)(2)(ii), FEMA is providing this opportunity for the Winnebago Tribe of Nebraska to join the consultation by identifying concerns and providing comments about historic properties that may be affected by this undertaking. FEMA would also appreciate notice of Tribes other than those listed above that may have an interest in this undertaking.

SWe would appreciate a response from your office within 30 days. If you have questions, do not hesitate to contact me at 312-408-5549 or at fema-r5-environmental@fema.dhs.gov. If we do not receive a response within 30 days, FEMA will move forward with this undertaking without comment from the Winnebago Tribe of Nebraska.

Sincerely,

Duane Castaldi

Regional Environmental Officer

FEMA Region 5

Sent by email to sunshine.bear@winnebagotribe.com



March 29, 2022

Documentation Initiating and Concluding Section 106 Consultation for a FEMA-Funded Undertaking

Project Information:

Project ID: #88229; PW 593

Title: Pheasant Branch Creek Stabilization

Address: Pheasant Branch Creek from crossing at Deming Way, eastward to

Century Avenue, then northward, parallel to Conservancy Lane

Location: Middleton, Dane County, WI

GPS: 43.102620, -89.51821 to 43.10945, -89.49057

PLSS: S1, 2, 11, and 12 T7N R8E

Description of Undertaking and APE:

As a result of severe storms, tornadoes, straight-line winds, flooding, and landslides affecting areas of the State of Wisconsin, President Trump signed the 4402-DR-WI Disaster Declaration on October 18, 2018. Under this declaration, Dane County, among others, was made eligible for FEMA's Public Assistance (PA) Program funding. The disaster event resulted in damage to infrastructure along the Pheasant Branch Creek Corridor from crossing at Deming Way and continuing eastward to north of Century Avenue in Middleton, Wisconsin (43.10262, -89.51821 to 43.10945, -89.49057).

The City of Middleton performed streambed relocation and streambank stabilization projects (most recently in 2007, 2008, 2009, 2010, 2012, and 2015) intermittently along this stretch of Pheasant Branch Creek, incorporating a variety of construction methods including sheet pile retaining walls, gabion baskets, toewood and rootwad, and rip rap toe protection. The City cleared, grubbed, graded and seeded the banks as part of these efforts. The flooding event washed away both engineered and non-engineered portions of the streambanks. However, only the areas with engineered stream stabilization will be funded by the FEMA PA grant program. Portions of a recreational trail and its supporting slopes adjacent to the stream were also damaged, as well as six timber and wood pedestrian bridges. Several existing storm sewer inlets and outlets associated with the parks and creek corridor experienced erosion damage.

The Applicant, the City of Middleton, proposes to use contract services to repair the engineered streambanks in-kind to their pre-disaster design, save for the substitution of rip-rap toe protection and fill instead of rootwad and fill in several locations. Some locations along the bank that were damaged in the event will not be repaired but will be allowed to naturalize. All work is intermittent throughout the proposed construction project bounds.

The six timber and wood pedestrian bridges will be replaced and the recreational trail will be repaired and modified. The streambed will be lowered in a few locations to

accommodate the new bridges and trail modifications. Additionally, the stream itself will be shifted in two locations (43.104399, -89.504811 and 43.104008, -89.503381).

The Pheasant Branch and Pheasant Branch Conservancy

Although assessment of the entire Pheasant Branch waterway and Middleton's parks is beyond the scope of this review, an overview of the larger resource will help describe the APE and provide context for the review and recommendations of this consultation. The Friends of Pheasant Branch compiled a booklet (*Friends of Pheasant Branch, Geology, Cultural History and Ecology of the Pheasant Branch Conservancy and Watershed in Middleton, Wisconsin,* 2005) providing an overview of the area; this document provided the basis for the short history below.

The Ho-Chunk Nation occupied the area where the marshes and Pheasant Branch drain into Lake Mendota. Mounds located approximately one and one-half miles north and also approximately one-half mile east of the eastern edge of the proposed undertaking are associated with Native American occupation.

After an 1832 treaty with the Ho-Chunk Nation involving most of Dane County, European settlement began. The area was platted in 1836 and began to be developed. Beginning in the 1850's, portions of the Pheasant Branch creek west of present-day Park Street and the marshes to the west and north were channelized and drained to facilitate a peat harvesting industry and farming. The Pheasant Branch Creek channels now called North Fork and South Fork were created in the settlement period and increased the original creek watershed and stormwater flows considerably.

A village called Pheasant Branch was established in 1853 and was centered around the current Century Avenue Bridge over Pheasant Branch, near the current Branch Street. The village lost its importance in 1856 when the Milwaukee and Mississippi Railroad routed through Peatville, a village located to the southwest. Peatville eventually became Middleton.

After WWII, the area became a residential suburb of Madison and additional roads, utilities and buildings were built. The City of Middletown built nine storm sewers to drain the developed areas; these emptied into Pheasant Branch. A landfill (roughly between GPS Start: 43.10264, -89.50947 to 43.10329, -89.50777) along the southern edge of the creek east of Clark Street School was abandoned and capped after several creek flows and rain events caused erosion and sedimentation flow into Lake Mendota. In 1965, Middleton residents formed the Middleton Conservation Committee to address erosion and sedimentation issues with Pheasant Branch and Lake Mendota. The committee's efforts resulted in the 1970 rerouting of the main creek channel to flow northward into the marsh to reduce sedimentation flow into the lake. The Conservation Committee also spearheaded the purchase of approximately 340 acres of land by the City of to create the Pheasant Branch Conservancy (PBC) in the 1970s and 1980s. Dane County and the Wisconsin DNR also own lands contiguous to the City's parcels that comprise the total 550-acre conservancy.

The section of the Pheasant Branch stream, known as the Mainstem, flows easterly from the Mainstem Pond near Deming Way, under Parmenter Street to Park Street, then from Park to Century Avenue. The area from Parmenter to Park is called Firemen's Park and the area from Park to Century is called Parisi Park.

Firemen's Park is generally bordered by municipal, multi-and single-family residences, and school buildings; the Middleton Police Station, a multi-family complex, several large

residences and the Kromrey Middle School front onto Donna Drive with Firemen's Park and the Pheasant Branch at their rear. Part of Pheasant Branch was relocated to enable the middle school construction. Middleton High School's athletic campus borders Firemen's Park at the south side.

East of Park Street, Parisi Park is generally bordered by one and two-story single-family residences with a cluster of commercial buildings near Century Avenue and Branch Street that back onto the Conservancy property.

A large portion of the stream (approximately 2,800 linear feet beginning 450 feet north of Century Avenue) flows north-northeast from Century Avenue through a wooded area with post-1992 residential neighborhoods to the west, some commercial and multifamily buildings to the south, and at a distance of over one-quarter mile, a residential neighborhood to the east. To the north, the waterway flows into the Pheasant Branch Marsh, where the flow then passes southward again to Lake Mendota.

The streambank was realigned and straightened in 1970. A review of Historic Aerials' historic maps (http://www.historicaerials.com) shows the earlier stream route looping eastward in the late 1800's then looping further northward starting in the early 1900's until the 1970 realignment and straightening. The maps also indicate the current stream route was occasionally identified as an artificial ditch (1975, 1979).

Various other engineering and bank stabilization efforts along the stream banks occurred after this project, including the installation of a stream gage station and a rank of gabion baskets on the west bank immediately north of Century Avenue. The most recent streambank stabilization effort occurred in early 2018 when the Conservancy acted to improve the stream quality and reduce sediment outflow by adding cross vanes, toewood/rootwads, rip rap toes, erosion blankets, fabric, and mats, grading and seeding of banks, and removing log jams. The 2018 project began 100 feet north of Century and continued north for 4,000 linear feet. The disaster event, occurring between August 17 and September 14, 2018, severely damaged the stabilization project.

Construction drawings for the project and maps illustrating the APE are included in this submission. The Area of Potential Effect (APE) is defined as the construction limits as the work is not expected to have visual effects beyond the APE. Areas for equipment staging and access will conform to the existing paved trails adjacent to the stream. The APE is noted on Figure 3.

Steps Taken to Identify Historic Properties and the Description of Historic Properties:

Archaeology

An archaeological literature search and technical memorandum of recommendations was undertaken by an SOI-Qualified archaeologist with SERCO contracted by FEMA (Attachment 4).¹ The literature search and technical memorandum indicates that the APE for the corridor, except for two segments, has been previously surveyed (Figure 32). These two segments were heavily modified during a Pheasant Branch Creek Relocation project (City Project #69-108), which was permitted in 1969 and constructed in 1970. A new channel was excavated to flow in a north-northeast direction. In total, 22,050 cubic yards were excavated, and the new channel banks were covered with 16,078 square

¹ Technical Memorandum Final, Project 88229 Event #4402DR-WI Water Control Facilities PBC Streambank Restoration Archaeological Desktop Assessment, City of Middleton, Dane County, Wisconsin. February 3, 2022.

yards of topsoil and seed. Given the APE, scope of work, and the significant extent and nature of the ground disturbing activities for previous stream relocation, the work within these two segments is not likely to encounter archaeological artifacts or features within their original depositional contexts that yield information important to history or prehistory.

SERCO identified only one archaeological site, 47-DA-0815 as partially within the APE. This site was originally identified in 1936 and partially surveyed in a 2016 archaeological survey conducted for a Phase I Archaeological Literature Review and Reconnaissance Pheasant Branch Stream Restoration, Dane County, Wisconsin by Cardno.² The partial survey encompasses the APE for this undertaking. The portions of the site that overlap the boundaries of the APE were not recommended for further investigations (Figure 33). FEMA notes that the prior archaeological investigations extended partially beyond the current APE although the entire boundaries of the site were not investigated. It is noted that the limestone walking path was the eastern most limit of the archaeological investigation and is not within this undertaking's APE.

Photos taken post-disaster within the boundaries of 47-DA-0815 (Figures 24-29) illustrate that the velocity of water within Pheasant Creek eroded, destabilized and washed out the nature-based solutions, soils, root wads as well as rip rap, geotechnical fabric and gabion baskets that were installed as part of the implemented Pheasant Branch Stream restoration project.

Although an evaluation of eligibility of 47-DA-0185 outside of the boundaries of the APE is beyond the scope of this review, within the APE, given the velocity of water, significant disturbance from prior installation of streambank stabilization, and prior archaeological investigations that extended beyond the banks which did not encounter archaeological artifacts or features, it is unlikely that intact soils with archaeological artifacts or features within their original depositional contexts exist.

The two stream relocations, (43.104399, -89.504811 and 43.104008, -89.503381) were within the CARDNO previous archaeological survey and outside of the recorded DA-47-0185 (Figures 15, 16, 17).

Based on the absence of archaeological features or artifacts within the APE, FEMA has determined that there are no below ground properties eligible for listing on the National Register of Historic Places within the APE for this undertaking.

Standing Structures

The nearest NRHP-listed properties and one NRHP historic district are located over three-quarters of a mile from the APE for this undertaking. The Dr. Newman C. Rowley House and the Middletown Depot are both over one mile southwest of the Century Avenue bridge over Pheasant Branch. The eastern end of the East End Historic District is three-quarters of a mile southwest of the Century Avenue bridge.

The closest surveyed property found in the Wisconsin SHPO database is the 1847 Old Stamm House, surveyed in 1977. The two-story fieldstone gabled ell building was constructed as a store and was used as a hotel, tavern, dance hall, supper club and restaurant. The building is on the south side of Century Avenue, approximately 325 feet

² Vernonica Parsell, Principal Investigator. Cardno, Phase I Archaeological Reconnaissance Pheasant Branch Stream Restoration, City of Middleton, Dane County, Wisconsin. 2016.

from Pheasant Branch; views into and from the Pheasant Branch are limited by heavy vegetation.

The pedestrian bridges crossing Pheasant Branch within the proposed construction project APE are simple utilitarian timber and wood structures supported on earthen embankments and are not of historic age. No other standing structures exist within the APE for this undertaking.

Preliminary Determination of Eligibility:

Based on the information provided above, FEMA has determined that *no resources* within the APE are eligible for listing on the National Register of Historic Places.

Finding:

FEMA finds that this undertaking will result in *no historic properties affected*.

Summary of Views of Consulting Parties or Public:

On March 29, 2022, the following Tribes were provided information regarding this project:

Ho-Chunk Nation

Menominee Indian Tribe of Wisconsin

Miami Tribe of Oklahoma

Osage Nation

Winnebago Tribe of Nebraska

Figures:

Figure 1: Approximate undertaking site marked in blue, not to scale. GoogleEarth image




Figure 2: Approximate undertaking sitemarked in blue, not to scale.

USGS Map "Middleton, WI" and "Madison West, WI," 1:24000, enlarged to show detail.



Figure 3: APE in black. Work locations are in blue and orange (stone toe), red (bank grading), purple (rootwad), pink (boulder clusters) and brown (toewood).

USGS Map "Middleton, WI" and "Madison West, WI," with WISAHRD overlay.




Figure 4: Photo Log. Work locations are in blue and orange (stone toe), red (bank grading), purple (rootwad), pink (boulder clusters) and brown (toewood).

GoogleEarth image.



Figure 5: Photo facing east Project files



Figure 7: Photo facing northeast *Project files*




Figure 6: Facing east *Project files*



Figure 8: Photo facing east *Project files*



loss of soil, rip-rap from upstream

Figure 9: Facing west *Project files*



Figure 11: Facing north *Project files*



Figure 10: Facing south *Project files*




Figure 12: Facing south *Project files*



Area of scouring and wash away of soil

Figure 13: Facing southeast *Project files*



Figure 15: Facing southeast, stream relocation *Project files*



Figure 14: Facing north *Project files*



Figure 16: Facing south, stream relocation *Project files*



Figure 17 Facing south, stream relocation *Project files*



Figure 19: Facing south *Project files*



Figure 18: Facing southwest *Project files*



Figure 20: Facing southwest *Project files*



Figure 21: Facing southwest *Project files*



Figure 23: Facing north *Project files*




Figure 22: Facing west *Project files*



Figure 24: Facing south, 47-DA-0815, FEMA APE previously surveyed.




Figure 25: Facing south, 47-DR-0185, FEMA APE previously surveyed.

Project files

Figure 26: Facing north, 47-DA-0185, FEMA APE previously surveyed.

Project files



Figure 27: Facing west, 47-DA-0185, FEMA APE previously surveyed.

*Project files**

Figure 28: Facing southwest, 47-DA-0185, FEMA APE previously surveyed. Project files

Figure 29: Facing north, 47-DA-0185, FEMA APE previously surveyed.




Figure 31: Facing north *Project files*



Figure 30: Facing north *Project files*







Figure 33: CARDNO 47-DA-0185 Archaeology Shovel Tests, APE previously surveyed. Note buffer extending beyond bank grading areas which extend beyond APE. The eastern limit of the site was only investigated up to and not beyond the existing limestone path. *Cardno aerial.*



TECHNICAL MEMORANDUM FINAL

PROJECT # 88229 EVENT #4402DR-WI WATER CONTROL FACILITIES PBC STREAMBANK RESTORATION ARCHAEOLOGICAL DESKTOP ASSESSMENT CITY OF MIDDLETON, DANE COUNTY, WISCONSIN

SENIOR ARCHAEOLOGIST: Varna Boyd, MA, RPA, Principal Investigator

SUBJECT: Archaeological Desktop Assessment

DATE: February 3, 2022

This technical memorandum details the results of an archaeological desktop assessment in support of the Federal Emergency Management Agency's (FEMA) Public Assistance Grant, 4402DR-WI, for Water Control Facilities PBC Streambank Restoration in the City of Middleton, Wisconsin (Figure 1). The streambank restoration project is a result of Disaster #4402DR-WI (a severe storm with heavy rains) that occurred between August 17 and September 14, 2018. The severe storms and rains caused surface water flooding and high-velocity run-off to the Pheasant Branch drainage channel, which resulted in damage to water control facilities and stream embankments along portions of Pheasant Branch Creek.

The archaeological desktop assessment was conducted in anticipation of consultation with the Wisconsin Historical Society (WHS), which serves as the State Historic Preservation Office (SHPO), and Tribal Historic Preservation Officers (THPO) in compliance with Section 106 of the National Historic Preservation Act (NHPA) and the National Environmental Policy Act (NEPA). The assessment was performed by a professional archaeologist who exceeds the Secretary of the Interior's *Professional Qualifications Standards* (48 FR 44716, September 29, 1983) and who has worked in Wisconsin previously. Portions of this assessment contain sensitive archaeological information (i.e., site location data).

ASSESSMENT GOALS AND METHODS

The goals of the assessment were to determine if previously identified archaeological resources were adjacent to or within the Area of Potential Effect (APE), which has been defined as the proposed limits of ground disturbance; determine what areas, if any, had been previously surveyed within the APE; determine the potential for archaeological resources within any previously unsurveyed areas; and make recommendations for further study, as warranted.



Figure 1: Project Location (Source: City of Middleton, WI).

To accomplish these goals, site file and previous survey research was conducted in the WHS's Wisconsin Historic Preservation Database (WHPD) for Township 7, Region 8E (T7R8E), Sections 1, 2, 11, and 12, which was considered the study area. Environmental data (e.g., soils) that could affect the potential for archaeological resources were reviewed for the APE.

Based on the known presence of archaeological sites in the vicinity, the potential for archaeological sites to be present within the project APE was initially considered to be high. However, it was also known that portions of the APE had been previously disturbed (e.g., graded) and that portions had been previously surveyed (see following section). As a result, the assessment also included a comparison of previous survey areas and project plans to determine if there were unsurveyed areas within the APE and if so, evaluate their potential for archaeological resources. Recommendations were made based on the combined data analysis. No archival research or review of architectural resources or properties was included in this archaeological desktop assessment.

ARCHAEOLOGICAL SITE FILE RESEARCH

Numerous surveys have been conducted in the vicinity, including studies by Archaeological Consulting and Services (Figure 2; Salkin 1992, 1993, and 2008), the WHS-Museum Archaeology Program (Figure 2; Hamilton 2010), and Cardno (Figure 3; Settle 2016) within the project APE. Only two small areas in the North of Century section of the APE have not been surveyed (Figure 4).




Figure 2: Surveys Prior to 2016 in the Project Vicinity (Source: Settle 2016:15).

Twenty archaeological sites were identified within the four T7R8E sections comprising the study area (Attachment 1). The majority (n=15) are precontact (i.e., Native American) mounds, campsites/villages, lithic workshops (i.e., stone tool manufacture), or lithic scatters (i.e., byproducts of stone tool production). There were also three multicomponent sites, including two precontact and historic Native American sites and one precontact and historic site. Two historic cemeteries, St. Luke's Cemetery and St. Bernard's Cemetery, are also present within the study area.
One site, 47-DA-0989 (Pheasant Branch Nature Preserve #1), has been determined not eligible for the NRHP; the remaining sites have not been evaluated for eligibility to the NRHP based on the WHPD site files.
The only site identified within the project APE was 47-DA-0815 (Site B), The site was originally identified in 1936 by Charles Brown of the WHS.
An archaeological survey of the western third of the site near Pheasant Branch was conducted by Cardno as part of a City of Middleton stream restoration project (Figure 3; Settle 2016). Ten shovel tests were excavated in that study, but none contained artifacts or cultural features. Portions of the east Pheasant Branch streambank and the entire west bank were not tested due to 15 percent or greater slopes (Settle 2016). Ground disturbance related to a limestone walking path was also noted in the eastern portion of Pheasant Branch within the Cardno project area (Settle 2016). Cardno recommended no further archaeological studies in what is now part of the current project APE (Settle 2016). FEMA will provide this technical memorandum as part of the SHPO consultation for this FEMA undertaking.

Two cemeteries are located within the study area. St. Luke's Cemetery is approximately 0.5 miles north and west of the project APE at 7515 Century Place in Middleton. St. Luke's Cemetery dates from approximately 1851 to the present. St. Bernard's Cemetery is approximately 0.4 miles south and southeast of the project APE at 1925 Branch Street in Middleton. It dates from 1897 to the present, but most headstones are from the 1960s to the present.

As the Sauk Mound, Heim Mound, the Murphy site, and the two cemeteries all have human burials, they are protected under the 1985 Wisconsin Act 316 (Wis. Stats. 157.70). While not expected as part of the current project, any effects to these sites require consultation with the WHS.

RESULTS AND RECOMMENDATIONS

The archaeological desktop assessment resulted in the identification of numerous prior surveys in the project APE as well as 20 archaeological sites within the study area. The proposed APE has been previously surveyed except for two small areas in the North of Century portion of the project. According to the City of Middleton, these two areas were part of the Pheasant Branch Creek Relocation project (City Project #69-108), which was permitted in 1969 and constructed in 1970 (personal communication between Mr. Roger Ammons, FEMA Program Delivery Manager, and Shawn Stauske, City of Middleton's Director of Public Works June 9, 2020). A new channel was excavated to flow in a north-northeast direction. In total, 22,050 cubic yards were excavated, and the new channel banks were covered with 16,078 square yards of topsoil and seed. These activities have significantly disturbed the unsurveyed areas of the APE. As a result, no further archaeological survey is recommended within these two areas.

Only one of the 20 archaeological sites, 47-DA-0815 (Site B), is present within the project APE. Prior survey by Cardno was conducted in the portions of the site that overlap the project APE and no artifacts or cultural features were identified. As a result, it is unlikely that further survey would identify other cultural resources. As a result, no further work is recommended within the portion of the site within the proposed APE. However, if plans change and the APE is expanded, additional analysis should be conducted to ensure no unsurveyed areas of the site will be impacted by the proposed project.

Due to the location of the project APE, no effects are anticipated for any of the other archaeological sites or cemeteries, including the Sauk Mound, Heim Mound, and the Murphy site. As a result of the desktop archaeological assessment, it is anticipated that the proposed project will have no effect to known archaeological resources.

REFERENCES CITED

Hamilton, Kelley

2010 CTH Q (Allen Boulevard) Archaeological Monitor, Dane County. Prepared by the Wisconsin Historical Society-Museum Archaeology Program.

Salkin, Philip H.

- 1992 An Archaeological Survey of the Proposed Pheasant Branch Interceptor Tributary Route in Middleton, Wisconsin. Prepared by Archaeological Consulting and Services.
- 1993 A Program of Archaeological testing at Two Sites (47DA987 and 47DA989) in Middleton, Dane County, Wisconsin. Prepared by Archaeological Consulting and Services.
- 2008 WDOT Archaeological Survey Field Report: Pheasant Branch Creek Trail in Dane County, Wisconsin. Prepared by Archaeological Consulting and Services.

Settle, Kathleen

2016 Phase I Archaeological Literature Review and Reconnaissance Pheasant Branch Stream Restoration, Dane County, Wisconsin. Prepared by Cardno.

ATTACHMENT 1

Attachment 1: Archaeological Sites within T7R8E Sections 1, 2, 11, and 12.

T7R8E Section Number	Site Number and Name	Site Type	Within APE	WHS Project Number	Recommendation	Notes
1	47-DA-0815, Site B		Yes	16-0992	Consultation with SHPO, but no anticipated effect	The site overlaps Pheasant Branch and the APE. A Cardno survey (Settle 2016) in the western third of the site found no artifacts or other cultural resources. The current status of the site is unknown, and the site inventory notes a request for consultation.
1	47-DA-0209, Baskerville Campsite	Precontact Campsite/Village/Workshop	No	N/A	No effect	
1	47-DA-0989, Pheasant Branch Nature Preserve #1	Precontact Campsite/Village	No	92-0421	No effect	Not eligible.
1	47-DA-1249, Middleton Hills	Precontact (Late Paleoindian – Late Woodland) Campsite/Village	No	N/A	No effect	
2	St. Luke's Cemetery	Historic Cemetery	No	N/A	No effect	
2	47-DA-0737, Freeman	Precontact (Middle Archaic and Early Woodland) Lithic Scatter and Historic Periods	No	10-0283 and 89- 0646	No effect	
2	47-DA-0966, S. Ziegler III	Precontact Workshop	No	89-0646	No effect	

T7R8E Section Number	Site Number and Name	Site Type	Within APE	WHS Project Number	Recommendation	Notes
2	47-DA-1422, Murphy Site II	Precontact (Middle and Late Archaic, Late Woodland) Campsite/Village/Burial	No	10-0283	No effect	
11	47-DA-0441, Woodside Heights Park	Precontact (Archaic) Campsite/Village	No	78-1104	No effect	
11	47-DA-0447, Park Shores	Precontact (Late Paleoindian and Archaic) Campsite/Village	No	78-1104	No effect	Most of site was destroyed by development, but a wooded area may still have intact deposits.
12	St. Bernard's Cemetery	Historic Cemetery	No	N/A	No effect	Any work in the park requires monitoring by an archaeologist.
12	47-DA-0381, Miller	Precontact and Historic Native American Campsite/Village	No	N/A	No effect	
12	47-DA-0389, Pheasant Branch	Precontact and Historic Native American Campsite/Village	No	11-9007, 10-7712	No effect	Portions of the site have been heavily disturbed. Site boundaries were amended in 2010.
12	47-DA-0423, Lemcke	Precontact (Late Archaic) Campsite/Village	No	N/A	No effect	
12	47-DA-0433, Sauk Trail School	Precontact (Late Woodland) Isolated Finds	No	11-9012	No effect	
12	47-DA-0495, Iltis Beach	Precontact (Late Woodland) Campsite/Village/Workshop	No	N/A	No effect	
12	47-DA-0816, Heim Farm	Precontact (Late Paleoindian, Late Archaic — Middle Woodland) Campsite/Village	No	11-9012	No effect	
Total Sites	20		1			

60 to 90% complete plans were provided as part of this consultation.

See Appendix A for the most recent project plans.



Disaster/Program: DR-4402-WI / Public Assistance Project No.: 88229 PW 593

Reviewer: Duane Castaldi Date: June 8, 2022

EXECUTIVE ORDER 11988Floodplain Management Checklist (44 CFR Part 9)

TITLE: Pheasant Branch Creek Trail, Bridges, and Streambank Restoration Project –

Deming Way to North of Century PROPOSED ACTION: For full details refer to the Environmental Assessment Section 2.2. The Proposed Action consists of three components: (1) repairs and improvements to recreational trails and pedestrian bridges, (2) stream stabilization, and (3) channel work including stream realignment and associated bank stabilization. APPLICABILITY: Actions which have the potential to affect floodplains or their occupants, or which are subject to potential harm by location in floodplains. The proposed action could potentially adversely affect the ☑ YES □ NO floodplain. The proposed action could potentially be adversely affected by the floodplain. **REMARKS:** Actions taken in this project could adversely affect the floodplain such as improvements occurring within the floodplain including the placement of fill. The floodplain could also adversely impact both the nature based solutions proposed and the trails and pedestrian bridges improved by this project. IF BOTH ANSWERS ARE NO, REVIEW IS COMPLETE; OTHERWISE CONTINUE WITH REVIEW. Mark the review steps required per applicability: \square All 8 / \square 1, 4, 5, 8 / \square 1-6, 8 CRITICAL ACTION: ☐ **YES** Review against 500 Year floodplain.

STEP 1: Determine whether the proposed action is in the 100-year floodplain, or, for critical actions, in the 500-year floodplain.

associated bank stabilization.

Review against 100 Year floodplain

For full details refer to the Environmental Assessment Section 2.2. The Proposed Action consists of three components: (1) repairs and improvements to recreational trails and pedestrian bridges, (2) stream stabilization, and (3) channel work including stream realignment and

FLOOD HAZARD DATA:

SCOPE OF WORK:

 \boxtimes NO

The current effective Flood Insurance Rate Map (FIRM) panels 55025C0382G and 55025C0401G, effective on 01/02/2009 (**Figures 6-9 of the Environmental Assessment**) show the location of the proposed work in relation to and within the floodplain. The proposed project is completely located within

Disaster/Program: DR-4402-WI / Public Assistance Project No.: 88229 PW 593

Reviewer: Duane Castaldi Date: June 8, 2022

> the Zone AE, which is the designated Special Flood Hazard Area (SFHA) subject to inundation by the 100-year flood. In addition, all of the proposed channel work is located within the FEMA Regulatory Floodway.

WETLAND DATA:

The project is located in a wetland as mapped by the U.S. Fish and Wildlife
Service's National Wetlands Inventory. NWI classifies the Pheasant Branch
Creek as Riverine habitat with applicable codes PEM1A, PEM1C, PFO1A,
PFO1B, PFO1Bd, PFO1C, PSS1/EM1Bd, PUBG, PUBKr, and R2UB2H
(for NWI Code definitions, see Appendix D of the Environmental
Assessment). Figure 10 of the Environmental Assessment depicts the
NWI wetlands within the project area. Dated: June 2022.
The proposed action may be in a wetland based on evaluation from soil surveys, aerial photographs, site visit or other data.
The project is outside of a designated wetland but has potential to affect the wetland, including support or encouragement of wetland development.

IF THE ANSWERS IS YES, CONTINUE WITH THE FOLLOWING STEPS; OTHERWISE REVIEW IS COMPLETE.

STEP 2: Notify the public at the earliest possible time of the intent to carry out an action in a floodplain and involve the affected and interested public in the decision-making process.

> Notice was provided as part of a disaster cumulative notice. \boxtimes

Publication: Wisconsin State Journal

Date: November 16, 2018

Project-specific notice provided.

Publication: Click or tap here to enter text.

Date: Click or tap here to enter text.

Per allowances noted at 44 CFR Part 9.12(d)6, this notice is understood to meet the

requirements of both Steps 2 and 7.

STEP 3: Identify and evaluate practicable alternatives to locating the proposed action in a floodplain (including alternatives sites, actions and the "no action" option). If a practicable alternative exists outside the floodplain, FEMA must locate the action at the alternative site..

> ☐ YES ☒ NO Is there a practicable alternative site location outside of the floodplain / wetland?

REMARKS: While the Environmental Assessment analyzes both the proposed action and the no action alternative, FEMA and the applicant did consider other alternatives. These other alternatives were all dismissed because they didn't meet the community needs or didn't address the flood hazard in full. All alternatives take place in the floodplain and there is no possibibility of avoiding the floodplain due to the location of the trail system, park, and amenities.

Disaster/Program: DR-4402-WI / Publi Reviewer: Duane Castaldi	c Assistance	Project No.: 88229 PW 593 Date: June 8, 2022
□ YES ⋈ NO	•	le alternative action outside of the floodplain ot affect the floodplain / wetland?
REMARKS: No	o. all alternatives do	have effects on the wetlands and

floodplains.

☐ **YES** ☒ **NO** Is the No Action Alternative the most practicable alternative?

REMARKS: The no action alternative does not address project purpose and needs and therefore is not an appropriate solution.

IF ANY ANSWER IS YES, THEN FEMA SHALL TAKE THAT ACTION AND THE REVIEW IS CONCLUDED.

STEP 4:	Identify the potential direct and indirect impacts associated with the occupancy or modification of floodplains and the potential direct and indirect support of floodplain development that could result from the proposed action. 44CFR Part 9.10.					
	☐ YES ⊠ NO	Is the Proposed Action based on incomplete information?				
⊠ YES □ NO		Is the proposed action in compliance with the NFIP?				
	☐ YES ⊠ NO	Does the proposed action increase the risk of flood loss?				
	□ YES ⊠ NO	Will the proposed action result in an increased base discharge or increase the flood hazard potential to other properties or structures?				
	⊠ YES □ NO	Does the proposed action minimize the impact of floods on human health, safety and welfare?				
	□ YES ⊠ NO	Will the proposed action induce future growth and development, which will potentially adversely affect the floodplain?				
	⊠ YES □ NO	Does the proposed action involve dredging and/or filling of a floodplain?				
	☐ YES ⋈ NO	Will the proposed action result in the discharge of pollutants into the floodplain?				
	□ YES ⊠ NO	Does the proposed action avoid long- and short-term adverse impacts associated with the occupancy and modification of floodplains?				
	□ YES ⊠ NO	Will the proposed action result in any indirect impacts that will affect the natural values and functions of floodplains or wetlands?				
	☐ YES ☒ NO	Will the proposed action forego an opportunity to restore the natural and beneficial values served by floodplains?				
	⊠ YES □ NO	Does the proposed action restore and/or preserve the natural and beneficial values served by floodplains?				

Disaster/Program: DR-4402-WI / Public Assistance
Reviewer: Duane Castaldi

YES
NO Will the proposed action result in an increase to the useful life of a structure or facility?

REMARKS: The repairs and improvements to existing trails, bridges, and park amenities funded by this Public Assistance project include

amenities funded by this Public Assistance project include mitigation measures, such as raising the bridges above the floodplain, to reduce future flood damage. Additionally, the trail system is at continued risk of erosion and subsequent damage, and the project seeks to stabilize the banks to limit erosion and factors that could lead to more damage. Ultimately, continued investment in this park and trail system supports floodplain management because the existing park system is an excellent use of a floodplain. So while there are impacts to adding fill in the form of bioengineering, these support the greater good of maintaining a park in the floodplain.

STEP 5: Minimize the potential adverse impacts to or within floodplains identified under Step 4; restore and preserve the natural and beneficial values served by floodplains.

▼YES □ NO Were avoidance and minimization measures applied to the proposed action to minimize the short and long-term impacts on the 100-Year floodplain?

☑ **YES** □ **NO** Were measures implemented to restore and preserve the natural and beneficial values of the floodplain?

REMARKS: This project minimized impacts by designing and engineering a

plan to support wetlands and floodplains. Bridge repairs, for example, will raise them, allowing more water to flow under the bridges and therefore producing less damage to the bridges in future flooding events. The use of nature based solutions to support the bank stabilization is further expected to reduce any effects on the wetlands in the project area.

STEP 6: Reevaluate the proposed action to determine first, if it is still practicable in light of its exposure to flood hazards, the extent to which it will aggravate the hazards to others, and its potential to disrupt floodplain values and second, if alternatives preliminarily rejected at Step 3 are practicable in light of the information gained in Steps 4 and 5. FEMA shall not act in a floodplain unless it is the only practicable location.

☑ YES □ NO The floodplain site is the only practicable alternative.

Reviewer: Duane Castaldi Date: June 8, 2022 ⊠ YES □ NO There is no potential for limiting the action to increase the practicability of previously rejected sites outside the floodplain and alternative actions. ☑ YES □ NO Minimization of harm to or within the floodplain can be achieved using all practicable means. The action in a floodplain clearly outweighs the requirement of E.O. 11988 and EO 11990. **REMARKS:** Engineering plans for this project show that no rise to any Base Flood Elevations will result from the proposed work. Permitting conversations with DNR and USACE likewise have shown that there is no net loss of wetlands based on this project. For these reasons, there are no adverse effects associated with this project. STEP 7: Prepare and provide the public with a finding and public explanation of any final decision that the floodplain is the only practicable alternative. Per allowances noted at 44 CFR Part 9.12(d)6, notice provided under Step 2 is understood to meet the requirements of both Steps 2 and 7. Notice was provided as part of a disaster cumulative notice. Publication: Click or tap here to enter text. Date: Click or tap here to enter text. \boxtimes Project-specific notice provided. Publication: Click or tap here to enter text. Date: Click or tap here to enter text. AFTER PROVIDING THE FINAL NOTICE, FEMA SHALL, WITHOUT GOOD CAUSE SHOWN, WAIT AT LEAST 15 DAYS BEFORE CARRYING OUT THE PROPOSED ACTION. STEP 8: Review the implementation and post-implementation phases of the proposed action to ensure that the requirements stated in Section 9.11 are fully implemented. Oversight responsibility shall be integrated into existing processes (44 CFR §9.11). ☑ YES □ NO Was grant conditioned on review of implementation and postimplementation phases to ensure compliance with EO 11988 and EO 11990?. **REMARKS:** For full details, see the Environmental Assessment. The project will require a local floodplain development permit accompanied by a no rise certificate.

Project No.: 88229 PW 593

Disaster/Program: DR-4402-WI / Public Assistance

FAILURE TO COMPLY WITH CONDITIONS ENUMERATED IN THE RECORD OF ENVIRONMENTAL CONSIDERATION MAY JEOPARDIZE FEDERAL FUNDING.

Project Area National Wetlands Inventory and Wisconsin Department of Natural Resources, Surface-water Data Viewer Codes:

PEM1A:

- P: Palustrine system includes all nontidal wetlands by trees, emergent, mosses or lichens, and all such wetlands that occur in tidal areas where salinity due to ocean derived salts is below 0.5 ppt. Wetlands lacking such vegetation are included if they are less than 8 hectares (ha., 20 ac.); do not have an active wave-formed or bedrock shoreline feature; low water a depth less than 2 meters (m., 6.6 ft.) in the deepest part of the basin and have salinity due to ocean derived salts of less than 0.5 ppt.
- EM: Class emergent characterized by erect, rooted, herbaceous hydrophytes, excluding mosses and lichens. Usually dominated by perennial plants.
- 1: Persistent subclass found only in the estuarine and palustrine systems.
- A: Water regime temporary flooded, surface water is present for brief periods, but the water table usually lies below the soil surface. Plants that grow both uplands and wetlands may be of this characteristic.

PEM1C:

- o P: Palustrine system includes all nontidal wetlands by trees, emergent, mosses or lichens, and all such wetlands that occur in tidal areas where salinity due to ocean derived salts is below 0.5 ppt. Wetlands lacking such vegetation are included if they are less than 8 ha. (20 ac.); do not have an active wave-formed or bedrock shoreline feature; low water a depth less than 2 m. (6.6 ft.) in the deepest part of the basin and have salinity due to ocean derived salts of less than 0.5 ppt.
- EM: Class emergent characterized by erect, rooted, herbaceous hydrophytes, excluding mosses and lichens. Usually dominated by perennial plants.
- o 1: Persistent subclass found only in the estuarine and palustrine systems.
- C: Water regime seasonally flooded; surface water is present for extended periods.
 The water table after flooding ceases is variable, extending from saturated to the surface to a water table well below the ground surface.

PFO1A:

- o P: Palustrine system includes all nontidal wetlands by trees, emergent, mosses or lichens, and all such wetlands that occur in tidal areas where salinity due to ocean derived salts is below 0.5 ppt. Wetlands lacking such vegetation are included if they are less than 8 hectares (20 ac.); do not have an active wave-formed or bedrock shoreline feature; low water a depth less than 2 m. (6.6 ft.) in the deepest part of the basin and have salinity due to ocean derived salts of less than 0.5 ppt.
- o FO: Forested class characterized by wood vegetation that is 6 m. (19.8 ft.) tall or taller
- 1: Subclass broad-leaved deciduous; woody angiosperms (trees or shrubs) with wide, flat leaves that are shed during the cold or dry season.
- A: Water regime temporary flooded, surface water is present for brief periods, but the water table usually lies below the soil surface.

PFO1B:

- o P: Palustrine system includes all nontidal wetlands by trees, emergent, mosses or lichens, and all such wetlands that occur in tidal areas where salinity due to ocean derived salts is below 0.5 ppt. Wetlands lacking such vegetation are included if they are less than 8 ha. (20 ac.); do not have an active wave-formed or bedrock shoreline feature; low water a depth less than 2 m. (6.6 ft.) in the deepest part of the basin and have salinity due to ocean derived salts of less than 0.5 ppt.
- o FO: Forested class characterized by wood vegetation that is 6 m. tall or taller.
- 1: Subclass broad-leaved deciduous; woody angiosperms (trees or shrubs) with wide, flat leaves that are shed during the cold or dry season.
- B: Water regime seasonally saturated; the substrate is saturated at or near the surface for extended periods. Surface water is typically absent but may occur for a few days after heavy rain and upland runoff.

PFO1Bd:

- P: Palustrine system includes all nontidal wetlands by trees, emergent, mosses or lichens, and all such wetlands that occur in tidal areas where salinity due to ocean derived salts is below 0.5 ppt. Wetlands lacking such vegetation are included if they are less than 8 ha. (20 ac.); do not have an active wave-formed or bedrock shoreline feature; low water a depth less than 2 m. (6.6 ft.) in the deepest part of the basin and have salinity due to ocean derived salts of less than 0.5 ppt.
- o Fo: Class forested characterized by wood vegetation that is 6 m. (19.8 ft.) tall or taller.
- o 1: Subclass broad-leaved deciduous; woody angiosperms (trees or shrubs) with wide, flat leaves that are shed during the cold or dry season.
- B: Water regime seasonally saturated; the substrate is saturated at or near the surface for extended periods. Surface water is typically absent but may occur for a few days after heavy rain and upland runoff.
- d: Special modifier Partially Drained/Ditched: A partly drained wetland has been altered hydrologically, but soil moisture is still sufficient to support hydrophytes. Drained areas that can no longer support hydrophytes are not considered wetlands. This Modifier is also used to identify wetlands containing, or connected to, ditches. The Partly Drained/Ditched Modifier can be applied even if the ditches are too small to delineate. The Excavated Modifier should be used to identify ditches that are large enough to delineate as separate features; however, the Partly Drained/Ditched Modifier also should be applied to the wetland area affected by the ditching.

PFO1C:

 P: Palustrine system includes all nontidal wetlands by trees, emergent, mosses or lichens, and all such wetlands that occur in tidal areas where salinity due to ocean derived salts is below 0.5 ppt. Wetlands lacking such vegetation are included if they are less than 8 ha. (20 ac.); do not have an active wave-formed or bedrock shoreline

- feature; low water a depth less than 2 m. (6.6 ft.) in the deepest part of the basin and have salinity due to ocean derived salts of less than 0.5 ppt.
- FO: Forested class characterized by wood vegetation that is 6 m. (19.8 ft.) tall or taller.
- 1: Subclass broad-leaved deciduous; woody angiosperms (trees or shrubs) with wide, flat leaves that are shed during the cold or dry season.
- C: Water regime seasonally flooded; surface water is present for extended periods.
 The water table after flooding ceases is variable, extending from saturated to the surface to a water table well below the ground surface.

PSS1/EM1Bd:

- o P: Palustrine system includes all nontidal wetlands by trees, emergent, mosses or lichens, and all such wetlands that occur in tidal areas where salinity due to ocean derived salts is below 0.5 ppt. Wetlands lacking such vegetation are included if they are less than 8 ha. (20 ac.); do not have an active wave-formed or bedrock shoreline feature; low water a depth less than 2 m. (6.6 ft.) in the deepest part of the basin and have salinity due to ocean derived salts of less than 0.5 ppt.
- SS: Class SCRUB-SHRUB includes areas dominated by woody vegetation less than 6
 m. (19.8 ft.) tall. The species include true shrubs, young trees (saplings), and trees or shrubs that are small or stunted because of environmental conditions.
- 1: Subclass broad-leaved deciduous; woody angiosperms (trees or shrubs) with wide, flat leaves that are shed during the cold or dry season.
- EM: Class emergent characterized by erect, rooted, herbaceous hydrophytes, excluding mosses and lichens. Usually dominated by perennial plants.
- 1: Persistent subclass found only in the estuarine and palustrine systems.
- B: Water regime seasonally saturated; the substrate is saturated at or near the surface for extended periods. Surface water is typically absent but may occur for a few days after heavy rain and upland runoff.
- d: Special modifier Partially Drained/Ditched: A partly drained wetland has been altered hydrologically, but soil moisture is still sufficient to support hydrophytes.
 Drained areas that can no longer support hydrophytes are not considered wetlands.

PUBG:

- o P: Palustrine system includes all nontidal wetlands by trees, emergent, mosses or lichens, and all such wetlands that occur in tidal areas where salinity due to ocean derived salts is below 0.5 ppt. Wetlands lacking such vegetation are included if they are less than 8 ha. (20 ac.); do not have an active wave-formed or bedrock shoreline feature; low water a depth less than 2 m. (6.6 ft.) in the deepest part of the basin and have salinity due to ocean derived salts of less than 0.5 ppt.
- UB: Unconsolidated bottom; includes wetlands and deep-water habitats with at least 25% cover of particles smaller than stones (less than 6-7 centimeters (cm)), and a vegetative cover less than 30%.

 G: Water regime intermittently exposed, water covers the substrate throughout the year except in years of extreme drought.


PUBKr:

- o P: Palustrine system includes all nontidal wetlands by trees, emergent, mosses or lichens, and all such wetlands that occur in tidal areas where salinity due to ocean derived salts is below 0.5 ppt. Wetlands lacking such vegetation are included if they are less than 8 ha. (20 ac.); do not have an active wave-formed or bedrock shoreline feature; low water a depth less than 2 m. (6.6 ft.) in the deepest part of the basin and have salinity due to ocean derived salts of less than 0.5 ppt.
- UB: Unconsolidated bottom; includes wetlands and deep-water habitats with at least 25% cover of particles smaller than stones (less than 6-7 cm), and a vegetative cover less than 30%.
- K: Water regime artificially flooded; the amount and duration of are flooding are controlled using pumps or siphons in combination with dikes, berms, or dams. Examples of artificially flooded wetlands are some agricultural lands, wildlife management areas where forests, crops, pioneer plants may be flooded or dewatered to attract wetland wildlife. The artificially flooded water regime modifier should not be used in the riverine system or for impoundments or excavated wetlands unless both water inputs and outputs are controlled to achieve a specific depth and duration of flooding.
- o r: Special modifier artificial substrate describes concrete-lined drainageways, well as Rock Bottom, Unconsolidated Bottom, Rocky Shore, and Unconsolidated Shore where humans have emplaced the substrate material. Jetties and breakwaters are examples of artificial Rocky Shores.

R2UB2H:

- R: Riverine system includes all wetlands and deep-water habitats contained within a channel, with two exceptions: (1) wetlands dominated by trees, shrubs, persistent emergent, emergent mosses, or lichens, and (2) habitats with water containing ocean-derived salts of 0.5 ppt or greater. A channel is an open conduit either naturally or artificially created that periodically or continuously contains moving water, or which forms a connecting link between two bodies of standing water.
- 2: Subsystem lower perennial is characterized by a low gradient. There is no tidal influence and some water flow all year, except during years of extreme drought. The substrate consists of sand and mud. Oxygen deficits may sometimes occur. The fauna is composed mostly of species that reach their maximum abundance in still water, and true planktonic organisms are common. The gradient is lower than that of the upper Perennial Subsystem and the floodplain is well developed.
- UB: Class unconsolidated bottom includes all wetlands and deep-water habitats with at least 25% cover of particles smaller than stones (less than 6-7 cm), and vegetative cover of less than 30%.
- 2: Subclass sand is unconsolidated particles smaller than stones are sand, although finer or coarser sediments may be intermixed.

0	H: Water regime permanently flooded; water that covers the substrate throughout the year in all years.





City of Middleton


PHEASANT BRANCH CREEK CORRIDOR MASTER PLAN
PUBLIC INPUT MEETING #2 - 9.10.2019

Online Survey


- 370 Participants
- 337 City of Middleton residents
- 50/50 Male/Female
- 18-29 years old : 2%
- 30-39 years old : 16%
- 40-49 years old : 20%
- 50-59 years old : 21%
- 60-69 years old : 25%
- 70-79 years old : 16%
- 80-89 years old : 0.004% (1 respondent)




How often do you visit the Pheasant Branch Creek Corridor?




Why do you visit the Corridor?




How do you access the Creek Corridor?




What activities would you like to occur within the Corridor that currently do not exist?




What do you feel makes the Corridor a special place in Middleton? (Please select one)




How important is Creek Corridor access during the winter season?




Which benefit of the corridor is most important to you? (Please select one)




What potential improvements do you consider priorities? (Please select up to your top three)



What potential activity do you consider a priority?




The City is always exploring grant opportunities to supplement city funds. If grants are not available or awarded, do you support the city borrowing funds to finance Corridor improvements?




PUBLIC INPUT MEETING #1:

How do you currently use the Pheasant Branch Creek Corridor?




PUBLIC INPUT MEETING #1:

What are your concerns about the Pheasant Branch Creek Corridor?




PUBLIC INPUT MEETING #1:

What are opportunities for the Pheasant Branch Creek Corridor?



Public Input Summary

- Corridor is valued by the community and other users
- Keep the corridor as natural as possible
- Accommodate various users
- Important place where citizens and families interact
- Opportunity to replace what was lost & make improvements!







Trail Alignment Options



Trail Alignment Options




Trail Alignment Options




Trail Sections - Existing



Trail Sections - Realigned Trail



Trail Sections — Split-Use Trail



Vegetation Restoration



Herbaceous Floodplain Restoration



- Deming to Parmenter
- Remove existing invasive plants
- Re-grading slopes to a plantable gradient with floodplain benches
- Wetland floodplain mix near water
- Drier prairie species upslope

Sand Prairie Restoration



- Areas with large sand deposits from 2018 flood
- Rather than remove sand, establish a sand prairie/ecosystem

Emergent Wetland

- One existing wetland
- Planned for wetlands or oxbows created by channel reconstruction
- Provides beneficial habitat, control runoff, and aide in stormwater capture/storage





Mesic Woodland Restoration





- On north-facing, shady areas
- Shade tolerant woodland species
- Remnant species existing: maiden hair fern, alternate- leaved dogwood
- Clear and manage invasive species to stimulate existing natives species

Oak Savanna Restoration

- Largest area proposed
- Most upland areas proposed as oak savanna
- Many existing oak canopy trees with invasive tree and shrub species beneath
- Very little sunlight reaching ground preventing oak regeneration, limiting diversity & creates erosion
- Clear invasive species & re-seeding restoration
- Managed by prescribed fire





Floodplain Restoration





- Woodland areas abutting creek
- Severe soil erosion and tree loss during 2018 flood
- Existing large canopy trees: black walnut, cottonwood, silver maple & invasive black locust
- Clear trees, especially invasives, will restore native herbaceous community, shrub layer and stimulate oak regeneration
- Control invasive groundcover



RESTORATION & IMPROVEMENTS MASTER PLAN CITY OF MIDDLETON PHEASANT BRANCH CREEK CORRIDOR

PUBLIC INPUT SESSION

AGENDA

June 20, 7:00 p.m. – 8:00 p.m. Kromrey Middle School Cafetorium

4					ω			2			-	
• 8					S	٠		H			X	
4. Wrap-upDescribe next steps in the City's process	Reporter provides summary to the large group	Participants use green dots to locate opportunities Each participant receives 5 dots Recorder writes a description of the opportunity next to the dots	 Each participant receives 5 dots Recorder writes a description of the concern next to the dots 	Participants use red dots to highlight areas of concern	3. Concerns & Opportunities	Reporter provides summary to the large group	Each participant shares what activities they enjoy within the Corridor Recorder writes responses on flip charts, make note of common activities	2. How do you currently use the Pheasant Branch Creek Corridor?	Orientation to workshop objectives and schedule	Welcoming comments: Review of project purpose and timeline	1. Welcome and Introduction	
7:55 – 8:00 5 min.				30 min.	7:25 - 7:55	5 min.	10 min.	7:10 - 7:25	5 min.	5 min.	7:00 - 7:10	

Complete evaluations (see back of agenda)




PHEASANT BRANCH CREEK CORRIDOR RESTORATION & IMPROVEMENTS MASTER PLAN

WORKSHOP EVALUATION FORM

participation efforts. Please answer these questions and return this evaluation form at the "check-in" table before you leave. Thanks so much for your participation! Before you leave, we'd like to get your impressions of this Public Input Session. We will use your answers and the other input we have received today to prepare for future public

On a scale of 1 to 10, how would you rate the overall usefulness of this event?



2. What were the most significant outcomes of this input session for you?

3. How could we have improved this event?

4 Please offer any comments, suggestions, or opinions you have on the City's park and open space planning process in the space provided below



CITY OF MIDDLETON

PHEASANT BRANCH CREEK CORRIDOR RESTORATION & IMPROVEMENTS MASTER PLAN

ROLES OF FACILITATOR, RECORDER,
AND REPORTER
RULES FOR BRAINSTORMING

FACILITATOR

- Help keep the group on task
- Watch the time to assure that the group completes its task
- Assure that everyone is able to participate (no one is dominating, no one is excluded)
- Remind people to listen as others are talking
- Encourage people to respect different perspectives and views

RECORDER

- Listen for key words
- Capture the basic ideas and essence of discussion
- Write rapidly
- Write legibly
- Number each sheet, reference topic, group
- Do not worry about spelling

REPORTER

- Be sure you understand what you are expected to report
- Listen carefully to the discussion
- Report out key points as requested at the end of the session
- "Recorder" and "Reporter" can be the same person

RULES OF BRAINSTORMING

- Do not judge ideas (good or bad)
- Don't dismiss anything as "impossible"
- Repeated ideas are fine
- "Piggybacking" off of someone else's idea is fine
- The more ideas, the better
- Everyone's opinion is valid



CITY OF MIDDLETON PHEASANT BRANCH CREEK CORRIDOR RESTORATION & IMPROVEMENTS MASTER PLAN

PUBLIC INPUT SESSION #2

AGENDA

September 10, 2019 7:00 p.m. – 8:30 p.m. Kromrey Middle School Cafetorium

5. Wrap Up and Questions 8:1	4. Ecological Restoration (Jens Jensen, Jensen Ecology)	 3. Trail Alignment Options (Lynda Fink, KL Engineering) No Change – Existing Trail Repair (five bridges) Realigned Trail (three bridges) Realigned Trail w/Split Use Trail (four bridges) Trail sections 	2. Public Input Meeting #1 and Survey Summary (Jeff Maloney, Vandewalle) 7:1	Welcome and Introduction (Matt Amundson, City of Middleton) Welcoming comments: Review of project purpose and timeline Orientation to meeting objectives and schedule
8:15 - 8:30	7:55 – 8:15	7:25 – 7:55	7:10 - 7:25	7:00 – 7:10 5 min. 5 min.

If you have not participated in the on-line survey regarding bridge design and streambank stabilization, please stop by the station on your way out to provide input.



RESTORATION & IMPROVEMENTS MASTER PLAN PHEASANT BRANCH CREEK CORRIDOR CITY OF MIDDLETON

MEETING FEEDBACK FORM

this evaluation form at the "check-in" table before you leave. Thank you for your participation!	Before you leave, please provide your written feedback to the presentation today and return
"check-in"	ovide your
table before you	written feedback
leave.	k to the
Thank you for	presentation
your	today
participation!	and return

ack to the pouleave. Tand provice and provice trail (four burners) ch? (Circle in space burners)	, σ		4		'n		2			H	# @
please provide your written feedback to the presentation form at the "check-in" table before you leave. Thank you fo form at the "check-in" table before you leave. Thank you fo glignment do you prefer? (Circle one and provide reason, if alignment do you prefer? (Circle one and provide reason, if glignment do you prefer? (Circle one and provide reason, if glignment do you prefer? (Circle one the trail (four bridges) C-Realigned Trail w/Split Use Trail (four bridges) Sort a 3' wide gravel shoulder on the trail where possible? sired) Journal of the ecological restoration approach? (Circle one & provide the ecological restoration approach? (Circle one & provide sired) Lowing in order of priority (Write 1-4 in space below) Lowing in order of priority (Write 1-4 in space below) Lowing in order of priority (Write 1-4 in space below)		Bridges	Rank the fol		Do you supp		Do you suppreason, if de		A - No Cha		efore you leav
wide your written feedback to the presentation check-in" table before you leave. Thank you fo you prefer? (Circle one and provide reason, if Trail Repair (five bridges) B-Realigned Trail w/Split Use Trail (four bridges) gravel shoulder on the trail where possible? grical restoration approach? (Circle one & proving priority) per of priority (Write 1-4 in space below) mbank StabilizationTrailEcologer prof priority (Write 1-4 in space below) mbank StabilizationTrailEcologer wavfinding/Interpreserure spaces	lowing in ord		lowing in ord	ō	ort the ecolo	О	oort a 3' wide sired)	C- Real	nge – Existing	alignment do	/e, please pro form at the "
e bridges) before you leave. Thank you fo rcle one and provide reason, if e bridges) be bridges) be Frealigned con the trail where possible? r on the trail where possible? r on the trail where below) vrite 1-4 in space below) Vrite 1-4 in space below) Vrite 1-4 in space below) Vrite 1-4 in space below)	er of priority (V atdoor Gatherin	nbank Stabiliza	er of priority (V		gical restoratio		gravel shoulde	gned Trail w/Sp	Trail Repair (fiv	you prefer? (Ci	vide your writte check-in" table
he presentation e. Thank you fo ovide reason, if ovide reason, if B-Realigned	Vrite 1-4 in spaces		Vrite 1-4 in spac		n approach? (C		r on the trail wh	olit Use Trail (fou	e bridges)	rcle one and pr	en feedback to t before you leav
	ce below) Wavfinding/Interpretive Signage	Ecological Restoration	ce below)		ircle one & prov		here possible?	ur bridges)	B-Realigned Trail (three bridges)	ovide reason, if	he presentatione. Thank you fo

6. Other Comments

Birding Areas



CITY OF MIDDLETON PHEASANT BRANCH CREEK CORRIDOR RESTORATION & IMPROVEMENTS MASTER PLAN

PUBLIC INPUT SESSION #2 FEEDBACK SUMMARY September 10, 2019 7:00 p.m. – 8:30 p.m. Kromrey Middle School Cafetorium

Before you leave, please provide your written feedback to the presentation today and return this evaluation form at the "check-in" table before you leave. Thank you for your participation!

Which trail alignment do you prefer? (Circle one and provide reason, if desired)

A – No Change – Existing Trail Repair (five bridges) - 2
B-Realigned Trail (three bridges) – 5
C-Realigned Trail w/Split Use Trail (four bridges) -15

Realigned with current path width - 2

Do you support a 3' wide gravel shoulder on the trail where possible? (Circle one & provide reason, if desired)

Yes-7

No - 10

No preference/no response - 6

Yes, depends on cost - 1

'n Do you support the ecological restoration approach? (Circle one & provide reason, if desired)

Yes - 23

No.

Yes, depends on cost -1

4
Rank
the f
following in
ing in o
n or
der
of p
riori
1 (V
order of priority (Write
14
space below
e below)
-2
2 respondents
S

Bridges - 1.59

Streambank Stabilization - 3.45

Responses Weighted: 1=4pts, 2=3pts, 3=2pts, 4=1pt Average by rank per respondent

Trail - 2.4

Ecological Restoration - 2.54

need to do all 1 person-whatever the experts conclude makes the most sense, 1 person- can't prioritize,

5 Rank the following in order of priority (Write 1-4 in space below) 21-22 Respondents

Bathrooms - 1.62

Outdoor Gathering Spaces - 2.62

Wayfinding/Interpretive Signage - 2.86

Birding Areas (22 Respondents) - 2.95

None of the above/No Response - II

Note: The 21-22 respondents is due to one respondent only ranking birding and none of the other options.

6. Other Comments

- filling in!! Need to stabilize bare slope areas as soon as possible, active erosion leads to hugest??? sediment loads into Lake Mendota-much worse than pre-flood ??? lake is
- shooting our of culverts like a jet Streambank restoration at park street does not seem to solve the problem of water
- . Stabilization and flood mitigation are biggest issue for me. Otherwise you end up doing it all again in 10 yrs
- . further catastrophic flooding, then it will fail no matter how thorough start; and results would inform future investment. If the design does not account for It shouldn't be necessary to wait for full funding for parts of the eco restoration to
- . the front. Thank you. Next public meeting please a microphone if you're answering a question come up to
- . Will the new restoration result in warmer water in the creek? Do you foresee any negative results?
- Current 10' width is appropriate for existing uses
- There should be signage directing walkers to face oncoming traffic & bikes to stay to riding up behind them. the right on the trail. This would eliminate the possibility of walkers being his by bikes
- Thanks for the interesting options & the chance to ask lots of questions
- Need cost estimates for all items
- Next time there are meetings have them in a smaller room with a microphone


7. Summary of Dot Exercise


Bridge Design Preference

- Bridge A 0
- Bridge B − 0
- Bridge C-7
- Bridge D − 12

Streambank Stabilization Preference

- Sheet Piling 2
- Gabion Baskets 1
- Stone Rip Rap -1
- Toewood 1
- Native Vegetation 16





Appendix F: Public Notice

Federal Emergency Management Agency PUBLIC NOTICE

Notice of Availability of the Draft Environmental Assessment for

Pheasant Branch Creek Trail, Bridges, and Streambank Restoration Project - Deming Way to North of Century Avenue, Dane County, Wisconsin

Environmental Assessment (EA) for the Pheasant Branch Creek Trail, Bridges, and Streambank Restoration Project – Deming Way to North of Century Avenue (FEMA Disaster #DR-4402-WI, Project # 88229, PW 593).

Interested persons are hereby notified that the Federal Emergency Management Agency (FEMA)/Department of Homeland Security (DHS) is proposing to assist in funding a project located in Dane County, Wisconsin. In accordance with the National Environmental Policy Act (NEPA) of 1969 and the implementing regulations of FEMA, an EA is being prepared to assess the potential impacts of each of the proposed alternatives on the human and natural environment. This also provides public notice to invite public comments on the proposed project in accordance with Executive Order 11988, Floodplain Management, and Executive Order 11990, Protection of Wetlands. In addition, this notice and the draft EA provide information to the public on potential impacts on historic and cultural resources from the proposed undertaking, as outlined in the National Historic Preservation Act (NHPA) of 1966.

This EA is available for agency and public review and comment for a period of 30 days. The EA is available on FEMA's website at https://www.fema.gov/about/news-multimedia/events. The EA is also available on the City's website on the Conservancy Lands &Trails page at https://www.cityofmiddleton.us/171/Conservancy-Lands-Trails and the City's main website at https://cityofmiddleton.us. Interested parties may request an electronic copy of the EA from any of those websites.

Those without internet access can review the EA on a computer available to the public during normal business hours at the Middleton Public Library, 7425 Hubbard Avenue, Middleton, WI 53562 or the Middleton City Hall, 7426 Hubbard Avenue, Middleton, WI 53562.

Written comments regarding this environmental action should be received no later than 5 p.m. on August 6, 2022 by mail to Duane Castaldi, Regional Environmental Officer, FEMA Region V, 536 South Clark Street, 6th Floor, Chicago, IL 60605-1521; or by email at *FEMA-R5-Environmental@fema.dhs.gov*. If no substantive comments are received by the above deadline, the draft EA and associated Finding of No Significant Impact (FONSI) will become final and be published by FEMA. Substantive comments will be addressed as appropriate in the final documents.

The public may request a copy of the final environmental documents from Duane Castaldi at the address listed above.

Appendix G: Permits



DEPARTMENT OF THE ARMY U.S. ARMY CORPS OF ENGINEERS, ST. PAUL DISTRICT 180 FIFTH STREET EAST, SUITE 700 ST. PAUL, MN 55101-1678

June 21, 2021

Regulatory File No. MVP-2021-00848-SJW

City of Middleton c/o Mark Wegner 7426 Hubbard Avenue Middleton, Wisconsin 53562

Dear Mr. Wegner:

We are responding to your request for authorization to permanently discharge fill material below the plane of the ordinary high water mark (OHWM) of Pheasant Branch in the City of Middleton for bank stabilization and erosion control purposes. The proposed work is located in the SE ½ SW ½ of Section 02, Township 07 North, Range 08 East, Dane County, Wisconsin.

Project authorization:

The regulated activities associated with this project include the permanent discharge of fill material (rock riprap) below the plane of the OHWM along 3,395 linear feet (0.27 acre) of Pheasant Branch. In addition, the project would include the permanent discharge of fill material below the plane of the OHWM onto 3,200 square feet (0.07 acre) of aquatic bed for the installation of toe wood/root wad structures, five boulder clusters, two cross vane structures, and for repairs to one riffle structure. We have determined that these activities are authorized by a Nationwide Permit (NWP) or a Regional General Permit (RGP), specifically, NWP 13, Bank Stabilization. This work is shown on the enclosed figures, labeled MVP-2021-00848-SJW: Page 1 of 21 through 21 of 21.

Your project exceeds the limitations established in the general permit related to the 500 linear foot threshold for rock riprap outlined in NWP 13 – Bank Stabilization. However, based on a case-specific review, we have determined the proposed activity will result in no more than minimal adverse effects and a waiver has been granted.

Conditions of your permit:

You must ensure the authorized work is performed in accordance with the enclosed General Permit terms, General Conditions, and St. Paul District Regional Conditions.

You are also required to complete and return the enclosed Compliance Certification form within 30 days of completing your project. Please email the completed form to the contact identified in the last paragraph.

A change in location or project plans may require re-evaluation of your project. Proposed changes should be coordinated with this office prior to construction. Failure to comply with all terms and conditions of this permit invalidates this authorization and could result in a violation of Section 301 of the Clean Water Act or Section 10 of the Rivers and Harbors Act. You must also obtain all local, State, and other Federal permits that apply to this project.

Water Quality Certification:

You must also comply with the enclosed Water Quality Certification conditions associated with this General Permit.

Permit expiration:

The 2017 NWP is valid until March 18, 2022 unless modified, suspended, or revoked. If the work has not been completed by that time, you should contact this office to verify that the permit is still valid. Furthermore, if you commence or are under contract to commence this activity before the date of General Permit expiration, modification, or revocation, you have 12 months to complete the activity under the present terms and conditions of the General Permit.

Jurisdictional determination:

No jurisdictional determination was requested or prepared for this project. While not required, you may request a jurisdictional determination from the contact identified in the last paragraph.

Contact Information:

If you have any questions, please contact me in our Stevens Point field office at (651) 290-5878 or by email at samuel.j.woboril@usace.army.mil.

Sincerely,

Samuel J. Woboril Lead Project Manager

CC:

Weston Matthews, Wisconsin Department of Natural Resources Aaron Steber, Cardno

PHEASANT BRANCH STREAMBANK STABILIZATION MAINSTEM POND TO CENTURY AVENUE

CITY PROJECT 18-125n CITY OF MIDDLETON

18

19

20


21


Sheet	List Table	-
Sheet Number	Sheet Title	
1	TITLE SHEET AND SHEET INDEX	
2	PROJECT OVERVIEW MAINSTEM POND TO PARMENTER STREET	
3	PROJECT OVERVIEW TO PARMENTER TO PARK STREET	
4	PROJECT OVERVIEW PARK STREET TO CENTURY AVENUE	
5	PROPOSED PLAN 0+00 TO 6+50	
6	PROPOSED PLAN 6+50 TO 12+00	
7	PROPOSED PLAN 12+00 TO 15+50	
8	PROPOSED PLAN 15+50 TO 23+50	
9	PROPOSED PLAN 23+50 TO 29+00	
10	PROPOSED PLAN 29+00 TO 36+50	
11	PROPOSED PLAN 36+50 TO 41+50	
12	PROPOSED PLAN 41+50 TO 47+50	
13	PROPOSED PLAN 47+50 TO 51+50	
14	PROPOSED PLAN 51+50 TO 59+50	
15	PROPOSED PLAN 59+50 TO 67+50	
16	PROPOSED PLAN 67+50 TO 73+00	

PROPOSED PLAN 73+00 TO 80+00 PROPOSED PLAN 80+00 TO 86+00 PROPOSED PLAN 86+00 TO 92+50 PROPOSED PLAN 92+50 TO 98+50 PROPOSED PLAN 98+50 TO 105+00 22-28 EXISTING CROSS SECTIONS PROPOSED CROSS SECTIONS 29-33 34-36 37-40 EROSION CONTROL / PLANTING PLAN





Call before you dig.








PHEASANT BRANCH STREAMBANK STABILIZATION MAINSTEM POND TO CENTURY AVENUE TITLE SHEET AND SHEET INDEX
























































BEFORE THE WISCONSIN DEPARTMENT OF NATURAL RESOURCES

Application of the United States Department of the Army,) Corps of Engineers, for Water Quality Certification for the) Final Regulations Pertaining to the Issuance, Reissuance, and Modification of Nationwide Permits

On January 6, 2017, the United States Department of the Army, Corps of Engineers (COE), published its final notice regarding the Issuance of Nationwide Permits (NWPs) in the Federal Register (agency docket number COE-2015-0017). The publication includes new, existing, and modified NWPs. Publication of these NWPs serves as the Corps' application to the State for water quality certification (WQC) under Section 401 of the Federal Clean Water Act (CWA).

The Wisconsin Department of Natural Resources (WDNR) has examined the final regulations pursuant to Section 401, CWA, and Chapter NR 299, Wisconsin Administrative Code (Wis. Adm. Code).

The WDNR has determined the following conditions for the NWPs are required to ensure compliance with state water quality standards enumerated ins. 299.04, Wis. Adm. Code. The certification contained herein shall expire on March 19, 2022.

Section 401Certification does not release the permittee from obtaining all other necessary federal, state, and local permits, licenses, certificates, approvals, registrations, charters, or similar forms of permission required by law. It does not limit any other state permit, license, certificate, approval, registration, charter, or similar form of permission required by law that imposes more restrictive requirements. It does not eliminate, waive, or vary the permittee's obligation to comply with all other laws and state statutes and rules throughout the construction, installation, and operation of the project. This Certification does not release the permittee from any liability, penalty, or duty imposed by Wisconsin or federal statutes, regulations, rules, or local ordinances, and it does not convey a property right or an exclusive privilege.

This Certification does not replace or satisfy any environmental review requirements, including those under the Wisconsin Environmental Policy Act (WEPA) or the National Environmental Policy Act (NEPA).

Note: The specific language in the NWPs is not included in this document. Copies of complete nationwide permits published in the Federal Register on January 6, 2017, may be obtained from your local COE field office.

STATE CONDITIONS AND LIMITATIONS OF CERTIFICATION

GENERAL CONDITIONS:

1. The permittee shall allow the WDNR reasonable entry and access to the discharge site to inspect the discharge for compliance with the certification and applicable laws.

- 2. If any of these §401 water quality certification conditions are found invalid or unenforceable, the water quality certification is denied for all activities to which that condition applies.
- 3. Water quality certification is denied without prejudice for activities involving the temporary stockpiling of dredged or fill material in waters of the state, including wetlands.
- 4. No discharges of dredged or fill material below the ordinary high water mark of a navigable stream as defined bys. 310.03(5), Wis. Adm. Code, may take place during fish spawning periods or times when nursery areas would be adversely impacted. These periods are:
- September 15th through May 15th for all trout streams and upstream to the first dam or barrier on the Root River (Racine County), the Kewaunee River (Kewaunee County), and Strawberry Creek (Door County). To determine if a waterway is a trout stream, you may use the WDNR website trout maps at http://dnr.wi.gov/topic/fishing/trout/streammaps.html.
- March 1st through June 15th for ALL OTHER waters.
- 5. Unless specifically exempt from state statute and federal Pre-Construction Notification (PCN) requirements, Applicants seeking authorization under these NWPs shall complete the Joint State/Federal Permit Application on the department e-permitting site at http://dnr.wi.gov/Permits/Water/.

Nationwide Permits Granted Water Quality Certification:

- NWP 3 Maintenance
- NWP 4 Fish and Wildlife Harvesting, Enhancement, and Attraction Devices and Activities
- NWP 5 Scientific Measurement Devices
- NWP 6 Survey Activities
- NWP 13 Bank Stabilization
- NWP 15 U.S. Coast Guard Approved Bridges
- NWP 16 Return Water From Upland Contained Disposal Areas
- NWP 18 Minor Discharges
- NWP 20 -Response Operations for Oil or Hazardous Substances
- NWP 22 Removal of Vessels
- NWP 25 Structural Discharges
- NWP 27 -Aquatic Habitat Restoration, Enhancement, and Establishment Activities
- NWP 28 Modifications of Existing Marinas
- NWP 30 Moist Soil Management for Wildlife
- NWP 31- Maintenance of Existing Flood Control Facilities
- NWP 35 Maintenance Dredging of Existing Basins
- NWP 36 Boat Ramps
- NWP 37 Emergency Watershed Protection and Rehabilitation
- NWP 38 Cleanup of Hazardous and Toxic Waste
- NWP 45 Repair of Uplands Damaged by Discrete Events
- NWP 53 Removal of Low-Head Dams
- NWP 54 Living Shorelines

Nationwide Permits for which Water Quality Certification is Partially Denied

WQC is certified or denied without prejudice as indicated below for the activities authorized by the following NWPs. Certified activities are subject to WQC conditions 1-5 above. If activities are denied without prejudice, the applicant must apply to the WDNR for an individual 401 WQC.

- NWP 7 Outfall Structures and Associated Intake Structures
 - WQC denied: Where the effluent from the outfall is not regulated under the WPDES permit program. WPDES permit information is available at: http://dnr.wi.gov/topic/wastewater/PermitApplications.html
 - WQC certified: All other NWP 7 activities.
- NWP 32 Completed Enforcement Actions
 - o WQC denied: If WDNR is not a party to the agreement or if WDNR has not concurred in writing with the settlement agreement.
 - WQC certified: All other NWP 32 activities.
- NWP 39 Commercial and Institutional Developments
 - WQC denied: Discharges of dredged or fill material for the construction of the following attendant features: yards, recreation facilities, stormwater management facilities or wastewater management facilities.
 - o WQC certified: All other NWP 39 activities.
- NWP 41- Reshaping Existing Drainage Ditches
 - o WQC denied: If any portion of the project will occur in or adjacent to a trout stream or any perennial tributaries to a trout stream. To determine if a waterway is a trout stream, you may use the WDNR website trout maps at http://dnr.wi.gov/topic/fishing/trout/streammaps.html.
 - o WQC certified: All other NWP 41 activities.
- NWP 42 Recreational Activities
 - o WQC denied: If the project involves the placement of any dredged or fill material into Wisconsin navigable waters as defined ins. NR 310.03(5), Wis. Adm. Code.
 - o WQC certified: All other NWP 42 activities.
- NWP 44 Mining Activities
 - o WQC denied: If the project involves the placement of any dredged or fill material into Wisconsin navigable waters as defined ins. NR 310.03(5), Wis. Adm. Code.
- NWP 46 Discharges in Ditches
 - o WQC denied: If the project involves the placement of any dredged or fill material into Wisconsin navigable waters as defined ins. NR 310.03(5), Wis. Adm. Code.
 - o WQC certified: All other NWP 46 activities.
- NWP 51- Land-Based Renewable Energy Generation Facilities
 - WQC denied: Discharges of dredged or fill material for the construction of the following attendant features: yards, recreation facilities, stormwater management facilities or wastewater management facilities.
 - o WQC certified: All other NWP 51 activities.

<u>Water Quality Certification Is Also Denied for the Nationwide Permits Revoked by the Corps</u> of Engineers in Wisconsin and Listed Below:

- NWP 8 Oils and Gas Structures on the Outer Continental Shelf
- NWP 12 Utility Line Activities
- NWP 14 Linear Transportation Projects
- NWP 15 U.S. Coast Guard Approved Bridges
- NWP 21- Surface Coal Mining Activities
- NWP 23 -Approved Categorical Exclusions
- NWP 24 Indian Tribe or State Administered Section 404 Programs
- NWP 34 Cranberry Production Activities
- NWP 49 Coal Re-mining Activities
- NWP 50 Underground Coal Mining Activities

Nationwide Permits Denied Water Quality Certification Without Prejudice At This Time:

The following NWP categories are denied Water Quality Certification (WQC) in their entirety and require an individual Section 401 WQC for all activities under these NWPs. In instances where a state has denied the 401 WQC for discharges under a particular NWP, permittees must furnish the District Engineer for the COE with an individual 401 WQC.

Each category was reviewed and it was determined that: potential water quality and beneficial use impacts would be beyond that considered minimal; the activity was not likely to occur in Wisconsin; the NWP doesn't align with state general permit standards required by statute (NWP 29, 40, 43); inadequate data was available for WDNR to fully evaluate potential water quality and beneficial use impacts; or the category was empty (Reserved).

- NWP 17 Hydropower Projects
- NWP 19 Minor Dredging
- NWP 26 Reserved
- NWP 29 Residential Developments
- NWP 33 Temporary Construction, Access and Dewatering
- NWP 40 Agricultural Activities
- NWP 43 Stormwater Management Facilities
- NWP 47 Reserved
- NWP 48 Existing Commercial Shellfish Aquaculture Activities
- NWP 52 Water-Based Renewable Energy Generation Pilot Projects

Note: State water quality certification is not required for the following Section 10 only NWPs: 1-Aids to Navigation, 2 - Structures in Artificial Canals, 9 - Structures in Fleeting and Anchorage Areas, 10 - Mooring Buoys, 11 - Temporary Recreational Structures, 28 - Modifications of Existing Marinas, 35 - Maintenance Dredging of Existing Basins.

NOTICE OF APPEAL RIGHTS

If you believe that you have a right to challenge this decision, you should know that Wisconsin Statutes and administrative rules establish time periods within which requests to review Department decisions must be filed.

To request a contested case hearing pursuant to section 227.42, Wisconsin Statutes, you have 30 days after the decision is mailed, or otherwise served by the Department, to serve a petition for hearing on the Secretary of the Department of Natural Resources.

This determination becomes final in accordance with the provisions of s. NR 299.05(7), Wisconsin Administrative Code, and is judicially reviewable when final. For judicial review of a decision pursuant to Sections 227.52 and 227.53, Wisconsin Statutes, you have 30 days after the decision becomes final to file your petition with the appropriate circuit court and to serve the petition on the Secretary of the Department of Natural Resources. The petition must name the Department of Natural Resources as the respondent.

Reasonable accommodation, including the provision of informational material in an alternative format, will be provided for qualified individuals with disabilities upon request.

This notice is provided pursuant to section 227.48(2), Wisconsin Statutes.

Dated at Madison, Wisconsin _____

STATE OF WISCONSIN
DEPARTMENT OF NATURAL RESOURCES

Cathy Stepp, Secretary



of Engineers ®	
St. Paul District	
	COMPLIANCE CERTIFICATION
Regulatory File Number:	MVP-2021-00848-SJW
Name of Permittee:	Mark Wegner – City of Middleton
County/State:	Dane County, Wisconsin
Date of Issuance:	June 21, 2021
Upon completion of the activity authorized by this permit and any mitigation required by the permit, sign this certification and return it to the Corps contact identified in your verification letter within 30 days.	
Please note that your permitted activity is subject to a compliance inspection by a U.S. Army Corps of Engineers representative. If you fail to comply with this permit, you are subject to permit suspension, modification, or revocation.	
By signing below, the permittee is certifying that the work authorized by the above referenced permit has been completed in accordance with the terms and conditions of the permit, and any required mitigation was completed in accordance with the permit conditions.	
Signature of Permittee	Date

State of Wisconsin DEPARTMENT OF NATURAL RESOURCES 3911 Fish Hatchery Rd Fitchburg, WI, 53711

Tony Evers, Governor Preston D. Cole, Secretary Telephone 608-266-2621 Toll Free 1-888-936-7463 TTY Access via relay - 711



06/23/2021

Mark Wegner 7426 Hubbard Ave. Middleton, WI 53562 [sent electronically] IP-SC-2021-13-01703-04

RE: Application to Changing stream course and bank stabilization in the City of MIDDLETON, Dane County

Dear Mr. Wegner:

The Department of Natural Resources has completed its review of your application for a permit to realign a section of stream channel and stabilize banks of Pheasant Branch located in the SE 1/4, SW 1/4, Section 02, Township 07, Range 08E, City of MIDDLETON, Dane County. You will be pleased to know your application is approved.

I am attaching a copy of your permit, which lists the many important conditions that must be followed to protect water quality and habitat. A copy of the permit must be posted for reference at the project site. Please read your permit conditions carefully so that you are fully aware of what is expected of you.

Please note you are required to submit photographs of the completed project within 7 days after you've finished construction. This helps both of us to document the completion of the project and compliance with the permit conditions.

Your next step will be to notify me of the date on which you plan to start construction and again after your project is complete.

If you have any questions about your permit, please call me at (608) 228-8107 or email Jeff.Schure@wisconsin.gov.

Sincerely,

Jeff J Schure
Jeff Schure

Water Management Specialist

Email CC: U.S. Army Corps of Engineers County Zoning Administrator DNR Conservation Warden Aaron Steber, Cardno

STATE OF WISCONSIN DEPARTMENT OF NATURAL RESOURCES

CHANNEL CHANGES/Stabilization PERMIT IP-SC-2021-13-01703-04

Application of Mark Wegner is hereby granted under Sections Ch 30.195(1) and Ch 30.208, Wisconsin Statutes, to change the channel and stabilize banks on Pheasant Branch located in the SE 1/4, SW 1/4, Section 02, Township 07, Range 08E, City of MIDDLETON, Dane County, subject to the following conditions:

PERMIT

- 1. You must notify Jeff Schure at phone (608) 228-8107 or email Jeff.Schure@wisconsin.gov before starting construction and again not more than 5 days after the project is complete.
- 2. You must complete the project as described **on or before June 23, 2026**. If you will not complete the project by this date, you must submit a written request for an extension prior to expiration of the initial time limit specified in the permit. Your request must identify the requested extension date. The Department shall extend the time limit for an individual permit or contract for no longer than an additional 5 years if you request the extension before the initial time limit expires. You may not begin or continue construction after the original permit expiration date unless the Department extends the permit in writing or grants a new permit.
- 3. This permit does not authorize any work other than what you specifically describe in your application and plans, and as modified by the conditions of this permit. If you wish to alter the project or permit conditions, you must first obtain written approval of the Department.
- 4. Before you start your project, you must first obtain any permit or approval that may be required for your project by local zoning ordinances and by the U.S. Army Corps of Engineers. You are responsible for contacting these local and federal authorities to determine if they require permits or approvals for your project. These local and federal authorities are responsible for determining if your project complies with their requirements.
- 5. Upon reasonable notice, you shall allow access to your project site during reasonable hours to any Department employee who is investigating the project's construction, operation, maintenance or permit compliance.
- 6. The Department may modify or revoke this permit for good cause, including if the project is not completed according to the terms of the permit or if the Department determines the activity is detrimental to the public interest.
- 7. You must post a copy of this permit at a conspicuous location on the project site, visible from the waterway, for at least five days prior to construction, and remaining at least five days after construction. You must also have a copy of the permit and approved plan available at the project site at all times until the project is complete.
- 8. Your acceptance of this permit and efforts to begin work on this project signify that you have read, understood, and agreed to follow all conditions of this permit.
- 9. You must submit a series of photographs to the Department, within one week of completing work on the site. The photographs must be taken from different vantage points and depict all work authorized by this permit.
- 10. You, your agent, and any involved contractors or consultants may be considered a party to the violation pursuant to Section 30.292, Wis. Stats., for any violations of Chapter 30, Wisconsin Statutes, or this permit.
- 11. Construction shall be accomplished in such a manner as to minimize erosion and siltation into surface waters. Erosion control measures (such as silt fence and straw bales) must meet or exceed the technical standards of ch. NR 151, Wis. Adm. Code. The technical standards are found at: http://dnr.wi.gov/topic/stormwater/standards/const_standards.html .
- 12. All equipment used for the project including but not limited to tracked vehicles, barges, boats, hoses, sheet pile and pumps shall be de-contaminated for invasive and exotic viruses and species prior to use and after use.

The following steps must be taken every time you move your equipment to avoid transporting invasive and exotic viruses and species. To the extent practicable, equipment and gear used on infested waters shall not be used on other non-infested waters.

- 1. **Inspect and remove** aquatic plants, animals, and mud from your equipment.
- 2. **Drain all water** from your equipment that comes in contact with infested waters, including but not limited to tracked vehicles, barges, boats, hoses, sheet pile and pumps.
- 3. **Dispose** of aquatic plants, animals in the trash. Never release or transfer aquatic plants, animals, or water from one waterbody to another.
 - 4. **Wash your equipment** with hot (>140° F) and/or high-pressure water,
 - OR -

Allow your equipment to dry thoroughly for 5 days.

FINDINGS OF FACT

- 1. Mark Wegner, 7426 Hubbard Ave., Middleton, WI 53562, filed an application with this Department on 04/28/2021, under sections Ch 30.195(1) and 30.208, Wisconsin Statutes, to change the channel and add stream stabilization practices on Pheasant Branch located in the SE 1/4, SW 1/4, Sec. 02, T. 07, R. 08E, City of MIDDLETON, Dane County.
- 2. Stream banks along Pheasant Branch Creek in the City of Middleton, Dane County, WI suffered extensive damage during the August 2018 historic flood event as well as during various 2019 flood events. Cardno preformed a flood damage assessment identifying areas of high erosion risk and sediment loss along the banks of the waterway. Proposed bank stabilization, reshaping the banks and realignment of the channel in sections of stream will dissipate energy and increase flood-flow capacity.
- 3. The Department has completed an investigation of the project site and has evaluated the project as described in the application and plans.
- 4. Pheasant Branch is a navigable water and no bulkhead exists at the project site.
- 5. The proposed project, if constructed in accordance with this permit will not adversely affect water quality, will not increase water pollution in surface waters and will not cause environmental pollution as defined in s. 283.01(6m), Wis. Stats.
- 6. The proposed project will not impact wetlands if constructed in accordance with this permit.
- 7. The Department of Natural Resources has determined that the agency's review of the proposed project constitutes an equivalent analysis action under s. NR 150.20(2), Wis. Adm. Code. The Department has considered the impacts on the human environment, alternatives to the proposed projects and has provided opportunities for public disclosure and comment. The Department has completed all procedural requirements of s. 1.11(2)(c), Wis. Stats., and NR 150, Wis. Adm. Code for this project.
- 8. The Department of Natural Resources has completed all procedural requirements and the project as permitted will comply with all applicable requirements of Sections 30.195(1), 30.12 and 30.208, Wisconsin Statutes and Chapters NR 102, 103, of the Wisconsin Administrative Code.

The applicant was responsible for fulfilling the procedural requirements for publication of notices under s. 30.208(5)(c)1m., Stats., and was responsible for publication of the notice of pending application under s.30.208(3)(a), Stats. or the notice of public informational hearing under s.30.208(3)(c), Stats., or both. S. 30.208(3)(e), Stats., provides that if no public hearing is held, the Department must issue its decision within 30 days of the 30-day public comment period, and if a public hearing is held, the Department must issue its decision within 20 days after the 10-day period for public comment after the public hearing. S. 30.208(5)(bm), Stats., requires the Department to consider the date on which the department publishes a notice on its web site as the date of notice.

10. The activity will not cause environmental pollution as defined in s. 299.01(4).

- 11. The newly relocated stream channel is considered navigable and public as a result of this authorization and project. The newly relocated stream channel is considered navigable for local zoning purposes and local permits/approvals are required for work proposed within the shoreland zone of this waterway.
- 12. No material injury will result to the riparian rights of any riparian owners of real property that abuts any water body that is affected by the activity.

CONCLUSIONS OF LAW

1. The Department has authority under the above indicated Statutes and Administrative Codes, to issue a permit for the construction and maintenance of this project.

NOTICE OF APPEAL RIGHTS

If you believe that you have a right to challenge this decision, you should know that the Wisconsin statutes and administrative rules establish time periods within which requests to review Department decisions shall be filed. For judicial review of a decision pursuant to sections 227.52 and 227.53, Wis. Stats., you have 30 days after the decision is mailed, or otherwise served by the Department, to file your petition with the appropriate circuit court and serve the petition on the Department. Such a petition for judicial review shall name the Department of Natural Resources as the respondent.

To request a contested case hearing of any individual permit decision pursuant to section 30.209, Wis. Stats., you have 30 days after the decision is mailed, or otherwise served by the Department, to serve a petition for hearing on the Secretary of the Department of Natural Resources, P.O. Box 7921, Madison, WI, 53707-7921. The petition shall be in writing, shall be dated and signed by the petitioner, and shall include as an attachment a copy of the decision for which administrative review is sought. If you are not the applicant, you must simultaneously provide a copy of the petition to the applicant. If you wish to request a stay of the project, you must provide information, as outlined below, to show that a stay is necessary to prevent significant adverse impacts or irreversible harm to the environment. If you are not the permit applicant, you must provide a copy of the petition to the permit applicant at the same time that you serve the petition on the Department.

The filing of a request for a contested case hearing is not a prerequisite for judicial review and does not extend the 30-day period for filing a petition for judicial review.

A request for contested case hearing must meet the requirements of section 30.209, Wis. Stats., and sections NR 2.03, 2.05, and 310.18, Wis. Admin. Code, and if the petitioner is not the applicant the petition must include the following information:

- 1. A description of the objection that is sufficiently specific to allow the department to determine which provisions of this section may be violated if the proposed permit or contract is allowed to proceed.
- 2. A description of the facts supporting the petition that is sufficiently specific to determine how the petitioner believes the project, as proposed, may result in a violation of Chapter 30, Wis. Stats.
- 3. A commitment by the petitioner to appear at the administrative hearing and present information supporting the petitioner's objection.

If the petition contains a request for a stay of the project, the petition must also include information showing that a stay is necessary to prevent significant adverse impacts or irreversible harm to the environment.

Dated at the South Central Region Headquarters, Wisconsin on 06/23/2021.

STATE OF WISCONSIN DEPARTMENT OF NATURAL RESOURCES For the Secretary

By: Jeff J Schure

Jeff Schure

Water Management Specialist

State of Wisconsin DEPARTMENT OF NATURAL RESOURCES 3911 Fish Hatchery Rd Fitchburg, WI, 53711

Tony Evers, Governor Preston D. Cole, Secretary Telephone 608-266-2621 Toll Free 1-888-936-7463 TTY Access via relay - 711



08/01/2022

Mark Wegner 7426 Hubbard Ave Middleton, WI 53562 GP-SC-2022-13-02398, 2408-12

Dear Mr. Wegner:

Thank you for submitting an application for a General Permit to place 6 clear span bridges over Pheasant Branch Creek located in the NW 1/4, NE 1/4, Sec. 12, T. 07, R. 08E, City of MIDDLETON, Dane County.

You have certified that your project meets the eligibility criteria for this activity. Based upon your signed certification you may proceed with your project. Please take this time to re-read the permit standards and conditions. You are responsible for meeting all general permit eligibility standards and permit conditions. This includes notifying the Department before starting the project and submitting photographs within one week of project completion. We have not reviewed your plans for compliance with installation and construction standards. You are responsible for ensuring that the project meets all eligibility standards described on the attached checklist. Please note that your project must be complete within 3 years of the date of this letter.

The Department conducts routine and annual compliance monitoring inspections. Our staff may follow up and inspect your project to verify compliance with state statutes and codes. If you need to modify your project please contact your local Water Management Specialist, Jeff Schure at (608) 228-8107 or email Jeff.Schure@wisconsin.gov to discuss your proposed modifications. If you fail to comply with state statutes and code, the Department has the authority to pursue enforcement which could include site restoration and fines.

The Department of Natural Resources appreciates your willingness to comply with waterway regulations, which help to protect the water quality, fish and wildlife habitat, natural scenic beauty, and recreational value of Wisconsin's water resources for future generations. You are responsible for obtaining any other local, state, or federal permits that are required before starting your project.

Sincerely,

Jeff J Schure

Jeff Schure Water Management Specialist

Copy to:

USACE Project Manager County Zoning Administrator

ELIGIBILITY CRITERIA

Eligibility criteria:

- 1. Accumulated brush, debris or other obstructions that are trapped in or underneath the structure will be regularly removed to prevent upstream flooding and to maintain structural integrity.
- 2. Erosion control measures shall meet or exceed the technical standards for erosion control approved by the department under subch. V of ch. NR 151. Any area where topsoil is exposed during placement, repair or removal of a structure shall be immediately seeded and mulched to stabilize disturbed areas and prevent soils from being eroded and washed into the waterway. These standards can be found at: http://dnr.wi.gov/topic/stormwater/standards/.
- 3. The plans ensure that any area where topsoil is exposed during the placement, repair or removal of the structure will be immediately seeded and mulched to stabilize disturbed areas and prevent soils from being eroded and washed into the waterway.
- 4. Unless part of a permanent storm water management system, all temporary erosion and sediment control practices will be removed upon final site stabilization. All areas disturbed during removal of temporary erosion and sediment control practices will be restored.
- 5. All grading, excavation and land-disturbance activities in the plans and specs documents will be confined to the minimum area necessary for the placement, repair or removal of the structure and will not exceed 10,000 square feet. Note: If the project includes any grading, excavation, or land-disturbance activity in excess of 10,000 square feet you may also need to receive approval under a Grading General or Individual permit in addition to this permit.
- 6. The project plans minimize adverse impacts on fish movement, fish spawning, egg incubation periods and high stream flows, the project may not occur during the following time periods:
 - a. September 15 through May 15 for trout streams and navigable tributaries to trout streams.
 - b. March 15 through May 15 for ALL waters located south of state highway 29.
 - c. April 1 through June 1 for ALL waters located north of state highway 29.

Note: Per ch. NR 1.02(7), the department identifies and classifies trout streams to ensure adequate protection and proper management of this unique resource. To determine if a waterway is a trout stream, you may use the Designated Waters Theme on DNR's Surface Water Data Viewer: http://dnr.wi.gov/topic/surfacewater/swdv/

Note: The applicant may request that these time period restrictions be waived by the department on a case-by-case basis, by submitting a written statement signed by the local department fisheries biologist, documenting consultation about the proposed dredging project, and that the local department fisheries biologist has determined that the requirements of this paragraph are not necessary to protect fish spawning for the proposed project.

- 7. All equipment used for the project including but not limited to tracked vehicles, barges, boats, hoses, sheet pile and pumps shall be de-contaminated for invasive and exotic viruses and species prior to use and after use.
- 8. The following steps must be taken every time you move your equipment to avoid transporting invasive and exotic viruses and species. To the extent practicable, equipment and gear used on infested waters shall not be used on other non-infested waters.
 - a. Inspect and remove aquatic plants, animals, and mud from your equipment.
- b. Drain all water from your equipment that comes in contact with infested waters, including but not limited to tracked vehicles, barges, boats, hoses, sheet pile and pumps.
- c. Dispose of aquatic plants, animals in the trash. Never release or transfer aquatic plants, animals, or water from one waterbody to another.
- d. Wash your equipment with hot (>104° F) or high pressure water, steam clean or allow your equipment to dry thoroughly for 5 days.
- 9. Follow the most recent department approved washing and disinfection protocols and department approved best management practices to avoid the spread of invasive species as outlined in NR 40, Wis. Adm. Code. These protocols and

practices can be found on the Department website at http://dnr.wi.gov/topic/Invasives/bmp.html Keyword: "equipment operator" and at http://dnr.wi.gov/topic/Invasives/documents/EquipOper.pdf

- 10. All equipment used for the project shall be designed and properly sized to minimize the amount of sediment that can escape into the water.
- 11. Submit a series of photographs to the department within one week of placing the structure on this site and within one week of stabilizing disturbed areas on the site after removal of the structure. The photographs shall be taken from different vantage points and depict all work authorized by the permit.

SELF CERTIFICATION CONDITIONS

- 1. You must notify Jeff Schure at phone (608) 228-8107 or email Jeff.Schure@wisconsin.gov before starting construction and again not more than 5 days after the project is complete.
- 2. You must complete the project as described on or before August 1, 2025. If you will not complete the project by this date, there is no opportunity for an extension, and you must apply for a new permit.
- 3. Your signed certification does not authorize any work other than what you specifically describe in your application and plans, and as modified by the conditions of your signed certification. If you wish to alter the project, you must first obtain written approval of the Department.
- 4. Before you start your project, you must first obtain any permit or approval that may be required for your project by local zoning ordinances and by the U.S. Army Corps of Engineers. You are responsible for contacting these local and federal authorities to determine if they require permits or approvals for your project. These local and federal authorities are responsible for determining if your project complies with their requirements.
- 5. Upon reasonable notice, you shall allow access to your project site during reasonable hours to any Department employee who is investigating the project's construction, operation, maintenance or permit compliance.
- 6. The Department may modify or revoke your signed certification for good cause, including if the project is not completed according to the terms of the eligibility standards and conditions for the activity or if the Department determines the activity is detrimental to the public interest.
- 7. You must post a copy of your signed certification at a conspicuous location on the project site, visible from the waterway, for at least five days prior to construction, and remaining at least five days after construction. You must also have a copy of your signed certification and plan available at the project site at all times until the project is complete.
- 8. Your acceptance of this letter and efforts to begin work on this project signify that you have read, understood, and agreed to follow all conditions of your signed certification.
- 9. You shall maintain the project in good condition and in compliance with the terms and conditions of your signed certification, NR 320, Wis. Admin. Code, and s. 30.206, Stats.
- 10. This project shall comply with all conditions identified in Wisconsin Administrative Code NR 320 and identified in the Instructions for the General Permit application.
- 11. You must submit a series of photographs to the Department, within one week of completing work on the site. The photographs must be taken from different vantage points and depict all work authorized by this permit.
- 12. You, your agent, and any involved contractors or consultants may be considered a party to the violation pursuant to Section 30.292, Wis. Stats., for any violations of Chapter 30, Wisconsin Statutes, or this permit.
- 13. Construction shall be accomplished in such a manner as to minimize erosion and siltation into surface waters. Erosion control measures (such as silt fence and straw bales) must meet or exceed the technical standards of ch. NR 151, Wis. Admin. Code. The technical standards are found at: http://dnr.wi.gov/topic/stormwater/standards/const_standards.html.

14. All equipment used for the project, including but not limited to tracked vehicles, barges, boats, silt or turbidity curtain, hoses, sheet pile, and pumps shall be de-contaminated for invasive and exotic viruses and species prior to use and after use.

The following steps must be taken every time you move your equipment to avoid transporting invasive and exotic viruses and species. To the extent practicable, equipment and gear used on infested waters shall not be used on other non-infested waters.

- 1. Inspect and remove aquatic plants, animals, and mud from your equipment.
- 2. Drain all water from your equipment that comes in contact with infested waters, including but not limited to tracked vehicles, barges, boats, silt or turbidity curtain, hoses, sheet pile and pumps.
- 3. Dispose of aquatic plants, animals in the trash. Never release or transfer aquatic plants, animals, or water from one waterbody to another.
 - 4. Wash your equipment with hot (>104° F) and/or high pressure water,

- OR -

Allow your equipment to dry thoroughly for 5 days.

FINDINGS OF FACT

- 1. The Department has determined that your signed certification of the project site and project plans meet the standards in s. 30.206, Stats. and ch. NR 320, Wis. Adm. Code., to qualify for this General Permit.
- 2. The proposed project will not injure public rights or interests, cause environmental pollution as defined in s. 299.01(4), Wis. Stats., or result in material injury to the rights of any riparian owner, if constructed in accordance with your signed certification.
- 3. The Department and the applicant have completed all procedural requirements, and the project as described in your signed certification will comply with all applicable requirements of Section 30.206, Wis. Stats., and Chapters NR 102, 103, 150, 299, 310 and 320 if carried out as proposed.

CONCLUSIONS OF LAW

- 1. The Department has authority under ch. 30, Wis. Stats., and ch. NR 320, Wis. Adm. Code, to grant approval for the construction and maintenance of this project.
- 2. The Department has complied with s. 1.11, Wis. Stats.